

ROCKY MOUNTAIN ARSENAL

2022 RCRA Landfills and Groundwater Monitoring Report

**Revision 0
June 17, 2022**

**U.S. Department of the Army
Shell Oil Company**

Prepared by:



Navarro Research and Engineering, Inc.

This page intentionally left blank.

TABLE OF CONTENTS

SECTION	PAGE
1.0 INTRODUCTION	1
2.0 METHODOLOGY	2
2.1 Type I, Type II, and Post-Storm Inspections	2
2.1.1 HWL Inspections	2
2.1.2 ELF Inspections	2
2.2 Maintenance and Repair Activities	3
2.3 LCS/LDS Sump Inspection, Sampling and Analysis	3
2.3.1 HWL LCS/LDS Sumps.....	3
2.3.2 ELF LCS/LDS Sumps.....	3
2.4 ALR Evaluation	4
2.5 Groundwater Sampling	4
2.5.1 HWL Groundwater Sampling.....	4
2.5.2 ELF Groundwater Sampling.....	4
3.0 PRECIPITATION DATA.....	4
4.0 HWL CAP ASSESSMENT, MAINTENANCE AND REPAIR ACTIONS.....	5
4.1 HWL Cap Inspections.....	5
4.2 HWL Inspection Observations and Associated Repairs	5
4.3 HWL Erosion/Settlement Monuments.....	6
4.4 HWL Vegetation.....	6
5.0 ELF CAP ASSESSMENT, MAINTENANCE AND REPAIR ACTIONS.....	7
5.1 ELF Cap Inspections.....	7
5.2 ELF Inspection Observations and Associated Repairs	7
5.3 ELF Erosion/Settlement Monuments.....	8
5.4 ELF Anchor Trench Drains	9
5.5 ELF Vegetation.....	9
6.0 LCS/LDS AND GROUNDWATER MONITORING.....	9
6.1 HWL LCS/LDS Operations.....	9
6.1.1 HWL LCS/LDS Inspections and Maintenance.....	10
6.1.2 HWL ALR Comparison	10
6.1.3 HWL Wastewater Management Quantities	11
6.1.4 HWL LCS/LDS Wastewater Quality.....	11
6.2 HWL Groundwater Monitoring and Assessment	13
6.2.1 CAMU Groundwater Flow Direction	13
6.2.2 HWL Impacts on Groundwater Quality.....	13



6.3	ELF LCS/LDS Operations.....	14
6.3.1	ELF LCS/LDS Inspections and Maintenance.....	14
6.3.2	ELF ALR Comparison.....	14
6.3.3	ELF Wastewater Management Quantities	15
6.3.4	ELF LCS/LDS Wastewater Quality.....	15
6.4	ELF Groundwater Monitoring and Assessment	16
6.4.1	CAMU Groundwater Flow Direction	16
6.4.2	ELF Impacts on Groundwater Quality.....	16
7.0	ROUTINE AND NON-ROUTINE ACTIONS	16
7.1	Routine Actions	16
7.2	Non-Routine Actions	17
7.3	O&M Change Notices.....	17
8.0	RECOMMENDATIONS AND CORRECTIVE MEASURES.....	17
9.0	COSTS AND BUDGETS	17
10.0	CONCLUSIONS.....	18
11.0	REFERENCES	18

TABLES

4.1-1	HWL Inspections
5.1-1	ELF Inspections
6.1.2-1	HWL Average Daily LDS Flow Rate and ALR Comparison
6.1.3-1	HWL Wastewater Production
6.1.4-1	HWL LCS and LDS Sump Sample Events (January 2021 through December 2021)
6.3.2-1	ELF Average Daily LDS Flow Rate and ALR Comparison
6.3.3-1	ELF Wastewater Production
9.0-1	Costs and Budgets

FIGURES

4.2-1	HWL Routine Activities Map
5.2-1	ELF Routine Activities Map

APPENDICES

A	Precipitation Data (May 01, 2021 through April 30, 2022)
B-1	HWL Inspection Documentation
B-2	ELF Inspection Documentation
C-1	HWL Maintenance Documentation
C-2	ELF Maintenance Documentation
D	HWL and ELF Erosion/Settlement Monument Survey Data
E	Monthly Flow Summaries
F-1	Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021
F-2	Enhanced Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021
G	NRAP Log



LIST OF ACRONYMS

ALR	Action Leakage Rate
AMA	Army Maintained Area
CAMU	Corrective Action Management Unit
CFS	Confined Flow System
CUSUM	Cumulative Sum
ELF	Enhanced Hazardous Waste Landfill
gpad	gallons per acre per day
HWL	Hazardous Waste Landfill
ICs	Indicator Compounds
LCS	Leachate Collection System
LDS	Leak Detection System
LRCH	Leachate Riser Control House
LS/LF	Leachate Storage and Loadout Facility
Navarro	Navarro Research and Engineering, Inc.
NRAP	Non-Routine Action Plan
O&M	Operations and Maintenance
OCN	O&M Change Notice
OMC	Operations and Maintenance Contractor
PCGMP	Post-Closure Groundwater Monitoring Plan
PCGMR	Post-Closure Groundwater Monitoring Report
PCWMP	Post-Closure Wastewater Management Plan
PCP	Post-Closure Plan
RCRA	Resource Conservation and Recovery Act
RMA	Rocky Mountain Arsenal
SOP	Standard Operating Procedure
UFS	Unconfined Flow System

EXECUTIVE SUMMARY

This 2022 *RCRA Landfills and Groundwater Monitoring Report* for the Rocky Mountain Arsenal Federal Facility Site was prepared in accordance with the *Hazardous Waste Landfill (HWL) Post-Closure Plan (PCP)*, Revision 4 (Navarro 2019) and the *Enhanced Hazardous Waste Landfill (ELF) PCP*, Revision 1 (Navarro 2020). The purpose of this report is to provide a summary of post-closure care activities that occurred during the 2022 reporting period of May 1, 2021 through April 30, 2022, and to provide recommendations for the post-closure care during the 2023 reporting period of May 1, 2022 through April 30, 2023. The activities presented in this report include the following items applicable to both the HWL and ELF:

- Army Maintained Area inspection results and maintenance activities, both routine and non-routine
- Leachate Collection System (LCS) and Leak Detection System (LDS) operation and maintenance (O&M)
- Action Leakage Rate analysis
- LCS/LDS wastewater management quantities
- LCS/LDS wastewater quality assessment
- Groundwater monitoring and assessment

Section 1.0 of the HWL PCP and ELF PCP state that post-closure, as required by the Resource Conservation and Recovery Act (RCRA), will begin following the physical completion of the respective caps and will continue for a minimum of 30 years after those dates. The Army and regulatory agencies participated in the final inspection meeting and site-walk of the HWL on May 20, 2009, and a final inspection meeting and site-walk of the ELF on May 26, 2010. Thus, the HWL post-closure period began May 21, 2009, and the ELF post-closure period began on May 27, 2010.

The Army's Operations and Maintenance Contractor (OMC), Navarro Research and Engineering, Inc. (Navarro), inspected, repaired, and maintained the HWL facility in accordance with the HWL PCP and the associated appendices. Similarly, the OMC staff inspected, repaired, and maintained the ELF facility in accordance with the ELF PCP and the associated appendices. The OMC Covers Manager evaluated the observations noted during the inspections and initiated routine maintenance and non-routine actions as appropriate.

The condition of the HWL soil cap and vegetation were good for the reporting period. Vegetation establishment continued to do well and provide substantial cover. The Army will continue to monitor the HWL for development of perennial grass species and control of annual weeds will remain a priority. Tumbleweeds were a nuisance and will continue to require management. The OMC Inspectors did not observe erosion in high stormwater flow areas or on channel sideslopes during the reporting period. The lack of erosion was an indication of improved soil stability.

The condition of the ELF cap was good for the reporting period. Establishment of desirable grass species is improving. The Army will continue to monitor the ELF for development of perennial grass species, especially in the reseeded areas. Tumbleweeds were a nuisance and will

continue to require management. The OMC Inspectors did not observe erosion in high stormwater flow areas or on channel sideslopes during the reporting period. The lack of erosion was an indication of improved soil stability.

The OMC Sample Technicians performed quarterly groundwater monitoring of the HWL and ELF. Sump wastewater was sampled prior to evacuating the sumps. Results of the groundwater monitoring and LCS/LDS monitoring are reported on a calendar year basis. This report includes the methods, results, and conclusions for the HWL and ELF groundwater and LCS/LDS monitoring performed in the calendar year of 2021.

Groundwater flow directions across the entire Corrective Action Management Unit (CAMU) were consistent over the four quarters of calendar year 2021 post-closure monitoring and are consistent with previous groundwater monitoring events within the CAMU area.

Dieldrin and lead were the only indicator compounds (ICs) detected in the downgradient HWL wells. Statistical evaluations indicated that neither dieldrin, nor lead, exceeded their respective prediction limits. Therefore, the groundwater quality around the HWL has not been affected by waste placement operations, closure, and post-closure O&M of the landfill.

There was one LDS analytical result in 2021 that required regulatory agency notification per the HWL PCP. Copper was detected above the Watch List Trigger Level in a sample collected from sump LDS1 on March 1, 2021. The Army notified the regulatory agencies of the exceedance, and Non-Routine Action Plan (NRAP)-2022-001 was issued in January 2022. The regulatory agencies approved the NRAP on February 3, 2022.

Lead was the only IC detected in the downgradient ELF wells, and the lead concentrations were below the calculated prediction limit. Therefore, the groundwater quality around the ELF has not been affected by waste placement operations, closure, and post-closure O&M of the landfill.

The ELF LDS sumps were not sampled in 2021, therefore there were no detections during the reporting period that required regulatory agency notification.

The costs for operating, inspecting, and maintaining the HWL and ELF over the reporting period, including groundwater sampling, LCS/LDS sampling, LCS/LDS O&M, and wastewater disposal, totaled \$415,317. Complete budgets for post-closure care of the HWL and ELF for May 2022 through April 2023 have not been approved as of the issuance of this report due to the timing of the annual funding cycle, which typically occurs near the end of the calendar year. However, the combined budgets for the period of December 2021 to November 2022 total \$594,513.

In summary, and based on the information presented in this report, the HWL and ELF were in compliance with all performance standards and no corrective measures were required for this reporting period. Plans to maintain the integrity of the caps include continued diligence with weed control and tumbleweed management, overseeding where necessary, inspection for erosion and burrowing animal holes, and monitoring the groundwater and LCS/LDS wastewater quality.

1.0 INTRODUCTION

This 2022 *RCRA Landfills and Groundwater Monitoring Report* for the Rocky Mountain Arsenal (RMA) Federal Facility Site was prepared in accordance with the *Hazardous Waste Landfill (HWL) Post-Closure Plan (PCP)*, Revision 4 (Navarro 2019) and the *Enhanced Hazardous Waste Landfill (ELF) PCP*, Revision 1 (Navarro 2020).

The purpose of this report is to provide a summary of post-closure care activities that occurred during the 2022 reporting period of May 1, 2021 through April 30, 2022, and to provide recommendations for the post-closure care during the 2023 reporting period of May 1, 2022 through April 30, 2023. The activities presented in this report include the following items applicable to both the HWL and ELF:

- Army Maintained Area (AMA) inspection results and maintenance activities, both routine and non-routine
- Leachate Collection System (LCS) and Leak Detection System (LDS) operation and maintenance (O&M)
- Action Leakage Rate (ALR) analysis
- LCS/LDS wastewater management quantities
- LCS/LDS wastewater quality assessment
- Groundwater monitoring and assessment

Remediation wastes were disposed in the Corrective Action Management Unit (CAMU) HWL and ELF facilities. State regulations (6 Code of Colorado Regulations 1007-3, Section 264.552) require that areas within the CAMU where remediation wastes remain in place after closure be managed and contained to control, minimize, or eliminate future releases to the extent necessary to protect human health and the environment. During the HWL closure period, a cap was constructed over the HWL as required by the *HWL Closure Plan* (TtEC 2006). Likewise, a cap was constructed over the ELF during the ELF closure phase, as required by the *ELF Closure Plan* (TtEC 2008). The HWL and ELF facilities also include stormwater drainage channels, wastewater conveyance systems, and groundwater monitoring wells. The Army will maintain the integrity of both landfills and their supporting systems for the duration of their respective post-closure periods.

The Army contracted Navarro Research and Engineering, Inc. (Navarro), to perform the work of the Operations and Maintenance Contractor (OMC). The OMC is responsible for inspecting, repairing, and maintaining the HWL facility in accordance with the HWL PCP and the associated appendices. Similarly, the OMC is responsible for inspecting, repairing, and maintaining the ELF facility in accordance with the ELF PCP and the associated appendices. The OMC Covers Manager evaluated the observations noted during the inspections and initiated routine maintenance and non-routine actions as appropriate.

As required by Section 3.9 of the HWL PCP and ELF PCP, this report for 2022 documents maintenance related activities performed between May 1, 2021 and April 30, 2022, as well as groundwater and LCS/LDS analytical data for samples collected between January 1, 2021 and December 31, 2021.

Section 1.0 of the HWL PCP and ELF PCP states that post-closure, as required by the Resource Conservation and Recovery Act (RCRA), will begin following the physical completion of the respective caps and will continue for a minimum of 30 years after those dates. The Army and regulatory agencies participated in the final inspection meeting and site-walk of the HWL on May 20, 2009, and a final inspection meeting and site-walk of the ELF on May 26, 2010. Thus, the HWL post-closure period began May 21, 2009, and the ELF post-closure period began on May 27, 2010.

The HWL and ELF facilities are located adjacent to each other within the northwest quadrant of Section 25, within the boundaries of the Rocky Mountain Arsenal National Wildlife Refuge perimeter fence. The U.S. Fish and Wildlife Service manages the Rocky Mountain Arsenal National Wildlife Refuge. The two facilities are surrounded by a common fence, which defines the AMA for the HWL and ELF. This AMA includes both landfills and surrounding support facilities and occupies roughly 130 acres. The ground surface elevation of the facilities generally ranges between 5,200 and 5,300 feet above mean sea level. No 100-year floodplains have been identified in this area.

This report addresses all components of the HWL and ELF facilities. Refer to the HWL PCP and ELF PCP for additional detail regarding each component.

2.0 METHODOLOGY

The OMC inspected, repaired, and maintained the HWL facility in accordance with the HWL PCP and the associated appendices. Similarly, the OMC inspected, repaired, and maintained the ELF facility in accordance with the ELF PCP and the associated appendices. The OMC Covers Manager evaluated the observations noted during the inspections and initiated routine maintenance and non-routine actions as appropriate.

2.1 Type I, Type II, and Post-Storm Inspections

2.1.1 HWL Inspections

Standard Operating Procedure (SOP) HWL-001, presented in Appendix A of the HWL PCP, details the procedures for inspecting the HWL soil cap and infrastructure features. The SOP provides procedures for Type I and Type II inspections, as well as a procedure for measuring the loss of cap soil thickness. The OMC Inspectors conducted Type I inspections quarterly, and Type II inspections semiannually. Post-storm inspections are required after rain events in which the RMA receives more than one inch of precipitation in a 24-hour period. There was one significant storm event on May 30, 2021 where the RMA received 1.13 inches of rain in a 24-hour period. The OMC Inspectors performed a post-storm inspection on June 2, 2021. Results of the HWL inspections are discussed in Section 4.1.

2.1.2 ELF Inspections

SOP ELF-001, presented in Appendix A of the ELF PCP, details the procedures for inspecting the ELF soil cap and infrastructure features. The SOP includes procedures for Type I and Type II inspections, as well as a procedure for measuring the loss of cap soil thickness. The OMC Inspectors conducted Type I inspections quarterly, and Type II inspections semiannually. Post-storm inspections are required after rain events in which the RMA receives more than one inch of precipitation in a 24-hour period. There was one significant storm event on May 30, 2021

where the RMA received 1.13 inches of rain in a 24-hour period. The OMC Inspectors performed a post-storm inspection on June 2, 2021. Results of the ELF inspections are discussed in Section 5.1.

2.2 Maintenance and Repair Activities

Table 3.0-1 of the HWL PCP lists examples of routine maintenance and repair activities for the HWL, and Table 3.0-2 of the HWL PCP lists conditions requiring Non-Routine Actions. Likewise, Table 3.0-1 of the ELF PCP lists examples of routine maintenance and repair activities for the ELF, and Table 3.0-2 of the ELF PCP lists conditions requiring Non-Routine Actions. Routine and non-routine maintenance and repair activities are discussed in Sections 4.2 and 5.2 of this report.

2.3 LCS/LDS Sump Inspection, Sampling and Analysis

2.3.1 HWL LCS/LDS Sumps

The OMC Wastewater Operator performed quarterly inspections of the HWL LCS and LDS Wastewater Conveyance System in accordance with the *HWL Post-Closure Wastewater Management Plan* (PCWMP), presented in Appendix C of the HWL PCP Revision 4 (Navarro 2019). The OMC Samplers sampled the HWL LCS and LDS liquids and shipped them to Applied Research and Development Laboratory in Mount Vernon, Illinois for analysis in accordance with the *HWL Post-Closure Groundwater Monitoring Plan* (PCGMP), presented in Appendix B of the HWL PCP Revision 4 (Navarro 2019).

Sample events at the LCS and LDS sumps are initiated when the wastewater levels reach the respective High-Level setting as defined in Section 3.1.1 of the HWL PCWMP. Once a sample is collected from the sump, the wastewater is pumped to the HWL lift station. Pumping stops when the wastewater level reaches the sump's Low-Level setting as defined in Section 3.1.1 of the HWL PCWMP. Each sump is sampled independently based on the wastewater level. If the wastewater needs to be removed from a sump for other operational reasons, samples will be collected from a sump before wastewater is pumped out, regardless of the sump level. There were no additional samples collected for operational reasons during this reporting period.

Analytical results and data evaluation for HWL post-closure LCS and LDS wastewater sampling performed from January through December of 2021 are presented in the *Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021* (HWL PCGMR), provided in Appendix F-1 of this report.

2.3.2 ELF LCS/LDS Sumps

The OMC Wastewater Operator performed quarterly inspections of the ELF LCS and LDS Wastewater Conveyance System in accordance with the ELF PCWMP (Navarro 2020), presented in Appendix C of the ELF PCP. The OMC is responsible for sampling the ELF LCS and LDS liquids in accordance with the ELF PCGMP (Navarro 2020), presented in Appendix B of the ELF PCP. However, there were no samples collected from the ELF LCS or LDS sumps during this reporting period because the sump levels did not reach their respective High-Levels.

2.4 ALR Evaluation

The ALR is the liquid flow rate that, when withdrawn from the LDS sumps, warrants follow-up actions. The ALR represents the capacity of the LDS to transmit flow and is independent of the sources of the liquids flowing into the system.

The monthly flow rate data were converted to an average daily flow rate for each of the HWL and ELF LDS sumps. The average daily flow rates for the HWL LDS sumps were compared with the ALRs identified in the *HWL Post-Closure Action Leakage Rate/Response Action Plan* presented in Appendix D of the HWL PCP, and the Non-Routine Action Trigger Levels presented in Table 3.0-2 of the HWL PCP Revision 4 (Navarro 2019). Likewise, the average daily flow rates for the ELF LDS sumps were compared with the ALRs identified in the *ELF Post-Closure Action Leakage Rate/Response Action Plan* (Navarro 2020) presented in Appendix D of the ELF PCP, and the Non-Routine Action Trigger Levels presented in Table 3.0-2 of the ELF PCP. Results of the HWL ALR comparison and ELF ALR comparison are presented in Section 6.1.2 and 6.3.2, respectively.

2.5 Groundwater Sampling

2.5.1 HWL Groundwater Sampling

The OMC implemented the HWL PCGMP, presented in Appendix B of the HWL PCP, quarterly with inspection and sampling of groundwater monitoring wells in the HWL groundwater monitoring well network. The network of groundwater monitoring wells, both upgradient and downgradient of the HWL is intended to monitor for existing hazardous constituents in the groundwater, and to monitor for potential releases of hazardous constituents from the HWL. Analytical results and data evaluation for post-closure groundwater sampling performed from January through December of 2021 are presented in the HWL PCGMR provided in Appendix F-1 of this report.

2.5.2 ELF Groundwater Sampling

The OMC implemented the ELF PCGMP, presented in Appendix B of the ELF PCP, quarterly with inspection and sampling of groundwater monitoring wells in the ELF groundwater monitoring well network. The network of groundwater monitoring wells, both upgradient and downgradient of the ELF is intended to monitor for existing hazardous constituents in the groundwater, and to monitor for potential releases of hazardous constituents from the ELF. Analytical results and data evaluation for post-closure groundwater sampling performed from January through December of 2021 are presented in the *Enhanced Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021* (ELF PCGMR) provided in Appendix F-2 of this report.

3.0 PRECIPITATION DATA

The OMC collected precipitation data from a rain gauge located near the Lime Basins RCRA-Equivalent Cover in Section 36, which is located approximately 1.5 miles south of the HWL and ELF. The data are presented in Appendix A. Total precipitation measured at the rain gauge between May 1, 2021 and April 30, 2022 was 8.34 inches. The HWL PCP and ELF PCP define a significant storm event as an event in which more than 1.0 inch of precipitation falls in a 24-hour period. There was one significant storm event on May 30, 2021 where the RMA received 1.13 inches of rain in a 24-hour period.

4.0 HWL CAP ASSESSMENT, MAINTENANCE AND REPAIR ACTIONS

The HWL soil cap and vegetation were in good condition for the reporting period. Vegetation establishment continued to do well and provide adequate cover. The Army will continue to monitor the HWL for development of perennial grass species. The OMC Inspectors did not observe erosion in high stormwater flow areas or on channel sideslopes during the reporting period. The lack of erosion was an indication of improved soil stability, especially when compared to early post-closure years as the vegetation was still becoming established.

4.1 HWL Cap Inspections

The OMC Inspectors inspected the HWL cap quarterly and semiannually during this reporting period. One post-storm inspection was also performed. Table 4.1-1 presents the dates and types of inspections performed.

Table 4.1-1: HWL Inspections

DATE	INSPECTION TYPE	NOTE
June 2, 2021	Post-Storm	Inspection after receiving > 1" of rain in 24-hr period
July 7, 2021	Type I	Regularly scheduled quarterly inspection.
October 5, 2021	Type II	Regularly scheduled semiannual inspection.
January 12, 2022	Type I	Regularly scheduled quarterly inspection.
April 26, 2022	Type II	Regularly scheduled semiannual inspection.

The OMC Inspectors evaluated the condition of the soil cap surface for evidence of erosion, cracking, subsidence, ponding of rainwater, and the presence of burrowing animals. The OMC Inspectors also inspected other features such as the vegetative cover, engineering and access controls, surface water controls, and erosion/settlement monuments. Specific inspection items are listed on forms SOP HWL 001-1 and SOP HWL 001-2, contained in Appendix A of the HWL PCP. Copies of the completed inspection forms are provided in Appendix B-1.

4.2 HWL Inspection Observations and Associated Repairs

The OMC Inspectors identified the issues listed below during the Type I and Type II inspections. The resulting maintenance and repair activities are discussed following each observation. The OMC staff also recognized weedy species during routine vegetation inspections often performed independently of the Type I and Type II inspections. These observations triggered weed control efforts that are also described below. Documentation of HWL maintenance activities are provided in Appendix C-1. The locations of maintenance actions are illustrated on Figure 4.2-1.

- Excessive buildup of tumbleweeds was observed in the articulated concrete block channels, the perimeter channels, and along the perimeter fence. The OMC staff removed tumbleweeds from the perimeter fence in December of 2021 and mowed tumbleweed piles on the north perimeter road in March of 2022 to provide access to sumps and monitoring wells on the east side of the landfill. Tumbleweed maintenance will continue to be a point of emphasis in 2022 and will be discussed in the 2023 RCRA Landfills and Groundwater Monitoring Report.

- Thistles were occasionally identified throughout the site. OMC personnel used a combination of herbicides to spot spray thistles, killing the plants and minimizing the spread of additional weed seed.
- Annual weedy species were identified in some areas. OMC staff mowed the annual weedy species in August of 2021 to control further the weed population and to encourage the growth of desirable perennial grasses.

The OMC Inspectors identified the maintenance items listed below as improvements that were necessary to facilitate effective O&M of the HWL. These maintenance items were not the result of inspection observations.

- In October 2021, ground clear herbicide was applied by the OMC weed control subcontractor on the perimeter roads, the sump manhole access roads, around bollards, and in working areas so that personnel can work safely in these areas.
- In July 2021, OMC personnel harvested hairy golden aster (*Heterotheca villosa*) seed from a small patch of land on the west side of Building 130. The OMC Vegetation Expert had identified the hairy golden aster growing near B-130 in 2020 and earmarked the area as a source of seed for the native perennial. The OMC weed control subcontractor sprayed the area with the herbicide Esplanade® in the fall of 2020 to eliminate cheatgrass from the seedbank prior to harvesting. The OMC staff used this seed to hand broadcast the top corners of the HWL downchutes, the southwest support area of the HWL, and the south slope below the articulated concrete block terrace channel in November 2021.

4.3 HWL Erosion/Settlement Monuments

During the Type II inspections performed in October 2021 and April 2022, the OMC Inspectors measured erosion/settlement monuments to quantify soil thickness loss. The measured soil thickness loss for all nine monuments ranged from 0.0 to 1.75 inches, which is below the Non-Routine Action trigger level of 0.4 feet (or 4.8 inches) and the compliance level of 1.0 foot. The OMC Inspectors also surveyed the position of each monument as part of the semiannual inspections. Survey data are included in Appendix D, together with data collected during prior surveys for reference.

4.4 HWL Vegetation

Established areas of seeded vegetation on the HWL cap continue to do well and provide substantial cover, limiting soil erosion. Much of the growth of annual weedy species that has occurred in the past has been controlled or naturally diminished. Established perennial grass species have been able to spread having been released from the competition of weedy species. On the other aspects and on top of the HWL, cool season grass species, especially Western Wheatgrass (*Pascopyrum smithii*) continue to dominate the plant community. However, there is diversity of seeded native grasses established. Blue grama (*Chondrosum gracile*) and buffalo grass (*Buchloe dactyloides*) are common warm season grass species. Broadleaf weedy species, especially Kochia (*Bassia scoparia*), and prickly lettuce (*Lactuca seriola*) that were abundant in localized areas in previous years have also diminished in both stature and extent. Cheatgrass (*Bromus tectorum*), is also much less abundant and appears to have been controlled effectively by herbicide treatment. Monitoring of cheatgrass will continue, as will investigation of control methods.

Vegetative litter continues to persist on the HWL. This year, standing dead vegetation was not as prevalent on the HWL when compared to previous years. However, the litter is providing soil erosion protection.

The oscillations in plant community composition and production associated with early successional communities or highly disturbed areas have been reduced in the maturing plant community after thirteen growing seasons. The Army will continue to consider methods to promote stability and continued development of the plant community, such as control of annual weeds, reseeding, fertilization, and introduction of biological controls for perennial weeds.

5.0 ELF CAP ASSESSMENT, MAINTENANCE AND REPAIR ACTIONS

The ELF cap was in good condition for the reporting period. Establishment of desirable grass species is improving. The Army will continue to monitor the ELF for development of perennial grass species, especially in overseeded areas. The OMC Inspectors did not observe erosion in high stormwater flow areas or on channel sideslopes during the reporting period. The lack of erosion was an indication of improved soil stability, especially when compared to early post-closure years as the vegetation was still becoming established.

5.1 ELF Cap Inspections

The OMC Inspectors inspected the ELF cap quarterly and semiannually during this reporting period. One post-storm inspection was also performed. Table 5.1-1 presents the dates and types of inspections performed during this reporting period.

Table 5.1-1: ELF Inspections

DATE	INSPECTION TYPE	NOTE
June 2, 2021	Post-Storm	Inspection after receiving > 1" of rain in 24-hr period
July 7, 2021	Type I	Regularly scheduled quarterly inspection.
October 5, 2021	Type II	Regularly scheduled semiannual inspection.
January 12, 2022	Type I	Regularly scheduled quarterly inspection.
April 26, 2022	Type II	Regularly scheduled semiannual inspection.

The OMC Inspectors evaluated the condition of the soil cap surface for evidence of erosion, cracking, subsidence, ponding of rainwater, and the presence of burrowing animals. The OMC also inspected other features such as the vegetative cover, trench drain outlets, engineering and access controls, surface water controls, erosion/settlement monuments, and the Leachate Storage and Loadout Facility (LS/LF) building. Specific inspection items are listed on forms SOP ELF 001-1 and SOP ELF 001-2, contained in Appendix A of the ELF PCP. Copies of the completed inspection forms are provided in Appendix B-2.

5.2 ELF Inspection Observations and Associated Repairs

The OMC identified the inspection observations listed below during the Type I and Type II inspections. The resulting maintenance and repair activities are discussed following each observation. The OMC Inspectors also recognized weedy species during routine vegetation

inspections often performed independently of the Type I and Type II inspections. Documentation of ELF maintenance activities are provided in Appendix C-2. The locations of maintenance actions are illustrated on Figure 5.2-1.

- The OMC Inspectors identified an area of sinkholes in the east perimeter channel during the spring 2021 Type II inspection. These holes were backfilled with soil from the Long-Term Cover Soil Stockpile area in July of 2021.
- Excessive buildup of tumbleweeds was observed in the articulated concrete block channels, the perimeter channels, and along the perimeter fence. The OMC staff removed tumbleweeds from the perimeter fence in December of 2021. Tumbleweed maintenance will continue to be a point of emphasis in 2022 and will be discussed in the 2023 RCRA Landfills and Groundwater Monitoring Report.
- Thistles were occasionally identified throughout the site. OMC personnel used a combination of herbicides to spot spray thistles, killing the plants and minimizing the spread of additional weed seed.
- Annual weedy species were identified in some areas. OMC staff mowed the annual weedy species in August of 2021 to control further the weed population and to encourage the growth of desirable perennial grasses.

The OMC Inspectors identified the maintenance items listed below as improvements that were necessary to facilitate effective O&M of the ELF. These maintenance items were not the result of inspection observations.

- In October 2021, ground clear herbicide was applied by the OMC weed control subcontractor on the perimeter roads, the sump manhole access roads, around bollards, and in working areas so that personnel can work safely in these areas.
- In July 2021, OMC personnel harvested hairy golden aster (*Heterotheca villosa*) seed from a small patch of land on the west side of Building 130. The OMC Vegetation Expert had identified the hairy golden aster growing near B-130 in 2020 and earmarked the area as a source of seed for the native perennial. The OMC weed control subcontractor sprayed the area with the herbicide Esplanade® in the fall of 2020 to eliminate cheatgrass from the seedbank prior to harvesting. OMC used this seed in November 2021 to hand broadcast the top corners of the ELF downchutes, the west and south slopes above the terrace channels, and between the southeast perimeter channel and road.
- An OMC vendor replaced the weather stripping on the LS/LF building garage door in August of 2021.

5.3 ELF Erosion/Settlement Monuments

During the Type II Inspections performed in October 2021 and April 2022, the OMC Inspectors measured erosion/settlement monuments to quantify soil thickness loss. The measured soil thickness loss for all eight monuments ranged from 0.00 to 3.0 inches, which is below the Non-Routine Action trigger level of 0.4 feet (4.8 inches) and the compliance level of 1.0 foot. The OMC Inspectors also surveyed the position of each monument as part of the semiannual inspections. Survey data are included in Appendix D, together with data collected during prior surveys for reference.

5.4 ELF Anchor Trench Drains

The OMC Inspectors inspected the ELF anchor trench drain outfalls in accordance with the SOP for evidence of flow, erosion, seepage, moisture, or bare/sparse vegetation. The inspections were documented on Type I and Type II inspection forms provided in Appendix B-2. Three outfalls on the south slope had indications of moisture after the significant storm event during the post-storm inspection conducted in June 2021. All outfalls were free of flow and indications of moisture during the remaining inspections performed during this reporting period.

5.5 ELF Vegetation

Seeded vegetation on the ELF cap continues to improve and provide greater cover. Plants of established seeded species are developing and reproducing. Sand dropseed (*Sporobolus cryptandrus*), blue gramma (*Chondrosum gracile*) and buffalo grass (*Buchloe dactyloides*) are common warm season seeded species. Cool season grass species, especially western wheatgrass (*Pascopyrum smithii*) continue to provide more abundant cover on the ELF cap than in years past. Perennial grass species are increasing on the portion of the south face between the perimeter channel and the mid-slope drainage channel that has been sparsely covered by perennial seeded species. This increase may be due to control of the cheatgrass (*Bromus tectorum*) in this area with herbicide treatments. During the fall of 2021, OMC staff broadcast hairy golden aster (*Heterotheca villosa*) seed over bare portions of the south and west slopes of the ELF. The Army will continue to evaluate the results of the seeding through the 2022 growing season, and if necessary additional seeding will be considered. This year, standing dead vegetation was more prevalent on the top aspects of the ELF. This area may be improved by mowing and is a suggested maintenance activity.

The oscillations in plant community composition and production associated with early successional communities or highly disturbed areas have been reduced in the maturing plant community after twelve growing seasons. Most of the area has developed a stable and sustainable plant community.

The area near the gas vent layer's perimeter continues to have sparse vegetation cover by both annual and perennial vegetation. This condition is unlikely to improve because the soil thickness in this zone above the gas vent layer's filter fabric is too thin to support plant growth, especially in hot, dry weather.

The Army will continue to monitor the ELF for development of perennial grass species. Maintenance activities will be conducted at regular and necessary intervals. The OMC staff seeded bare areas of the site in the fall of 2017, 2018, and 2021. The areas will be evaluated for additional seeding activities and herbicide applications during 2022. Cheatgrass areas will continue to be mapped and herbicide treatment will remain a priority for any areas identified.

6.0 LCS/LDS AND GROUNDWATER MONITORING

6.1 HWL LCS/LDS Operations

The OMC Wastewater Operator used flowmeter data to calculate monthly flow rates. Flow meters recorded the actual volume removed from the sumps and these data were downloaded daily into the RMA Environmental Database. The monthly flow summaries are provided in

Appendix E. On a quarterly basis, the Wastewater Operator also inspected the manholes for damage accumulation of excessive liquid buildup.

6.1.1 HWL LCS/LDS Inspections and Maintenance

The OMC Wastewater Operator inspected and maintained the HWL LCS/LDS in accordance with Sections 3.1.3 and 3.1.4 of the HWL PCWMP contained in Appendix C of the HWL PCP. The OMC Wastewater Operator and maintenance staff performed the following routine maintenance and repair activities on the HWL LCS/LDS.

- Performed monthly inspections on the HWL emergency lights and fire extinguishers
- Performed quarterly inspections on the lift station liner leak detection and conveyance pipelines leak detection
- Performed quarterly inspections on the HWL LCS/LDS Wastewater Conveyance System
- Performed quarterly inspections for grounding and tool safety inspections and first aid kits
- Performed weekly LS/LF tank inspections
- Transferred wastewater from the HWL LCS/LDS sumps to the Lift Station, and then to the storage tanks in the LS/LF building as needed
- Clean Harbors collected wastewater for off-site shipment and disposal
- Reset the GFI buttons on the sump panels, as necessary
- Investigated the connector fittings and zone splitters (in the hand hole) due to moisture causing a resistance issue. A repair light was triggered on the leak detection panel. The connector fittings were repaired.
- Heater 1 failed at the Lift Station panel and tripped the main panel breaker. The heater circuit was shut off and the power to the main panel breaker was restored. The faulty heater was replaced.

The OMC Wastewater Operator documented system inspections on inspection forms included in the HWL PCWMP. Copies of the completed quarterly inspection forms are provided in Appendix B-1. Also, a system maintenance database was used to document inspections and maintenance activities. The Wastewater O&M Reports, provided in Appendix C-1, were generated by the database, and include log entries for inspections and maintenance activities.

6.1.2 HWL ALR Comparison

Each month the OMC Wastewater Operator calculated the wastewater collection rate in each LDS sump and compared that rate to the ALR for the respective sump as described in the *HWL Post-Closure Action Leakage Rate/Response Action Plan*, provided in Appendix D of the HWL PCP. The average daily flow rate was calculated as the volume of liquid pumped from the sump during the month, divided by the acreage of surface area served by the sump; divided by the number of days in the month. This average value is defined as the average daily flow rate and is expressed as gallons per acre per day (gpac). This average daily flow rate was then compared to the ALR and 85 percent of the ALR for the HWL to determine whether any response action is necessary. Table 6.1.2-1 presents the comparisons and conclusions for HWL LDS sumps 1 through 4. In all cases, the average daily flow rates were much lower than the ALR and the Non-

Routine Action trigger level of 85 percent of the ALR. Hence, the performance standards and Non-Routine Action trigger levels for leak detection liquids were not exceeded. Appendix E provides the monthly flow summaries used to calculate the average daily flow rates for each of the sumps.

6.1.3 HWL Wastewater Management Quantities

When wastewater in the HWL LCS and LDS sumps reached the High-Level switch settings of 30 inches and 20 inches of head, respectively, the OMC Wastewater Operator transferred the wastewater from the affected sump to the lift station, and then to the two storage tanks located in the LS/LF building. Wastewater was stored in these tanks until a tanker truck arrived to transport the material off site for disposal. The OMC hazardous waste disposal subcontractor transported approximately 23,114 gallons of HWL wastewater off-site for disposal between May 2021 and April 2022. That equates to a 5.2 percent increase in wastewater compared to the previous period of May 2020 to April 2021 when 21,968 gallons of wastewater were shipped off site. The Army expects the trend in HWL wastewater production to decrease in the following years. Refer to Table 6.1.3-1 for historical HWL wastewater volumes.

Table 6.1.3-1: HWL Wastewater Production

REPORTING YEAR	REPORTING PERIOD	WASTEWATER QUANTITY (gallons)
2010	May 2009 to April 2010	88,543
2011	May 2010 to April 2011	57,628
2012	May 2011 to April 2012	56,417
2013	May 2012 to April 2013	48,104
2014	May 2013 to April 2014	45,161
2015	May 2014 to April 2015	28,037
2016	May 2015 to April 2016	30,736
2017	May 2016 to April 2017	28,077
2018	May 2017 to April 2018	21,490
2019	May 2018 to April 2019	26,116
2020	May 2019 to April 2020	21,661
2021	May 2020 to April 2021	21,968
2022	May 2021 to April 2022	23,114

6.1.4 HWL LCS/LDS Wastewater Quality

Analytical data from the HWL LCS/LDS wastewater sampling is provided in this report in accordance with Section 3.9 of the HWL PCP. The HWL PCP requires the reporting of wastewater analytical data for the 12-month period from January 1 to December 31 that precedes the submittal of this report. For this report, the reporting period for HWL LCS/LDS wastewater quality is January 1, 2021 to December 31, 2021. The purpose of the samples collected from the LCS/LDS sumps is to meet the requirements of the HWL PCP, to evaluate the chemistry of the

wastewater to determine potential leakage from the HWL, and to characterize the leachate for disposal.

Refer to Table 6.1.4-1 for sample dates and triggers for the reporting period of January 2021 through December 2021.

Table 6.1.4-1: HWL LCS and LDS Sump Sample Events (January 2021 through December 2021)

DATE	LCS1	LDS1	LCS2	LDS2	LCS3	LDS3	LCS4	LDS4
March 2021		High Level	High Level		High Level			
May 2021	High Level						High Level	
August 2021			High Level					
October 2021	High Level							High Level
November 2021			High Level	High Level				

A summary of analytical results from post-closure LCS/LDS wastewater monitoring at the HWL is provided in the following subsections. Refer to the 2021 HWL PCGMR, provided in Appendix F-1 of this report, for additional details regarding the methods, results and conclusions of post-closure LCS/LDS wastewater sampling performed between January and December of 2021.

6.1.4.1 HWL LCS Analytical Results

Analytical results from the LCS leachate samples were consistent with wastes placed in the landfill and were within the chemical groups used in determining potential groundwater impacts.

The indicator compounds (ICs) detected in the HWL LCS sumps in 2021 include benzene, dichlorodifluoromethane, dicyclopentadiene, dieldrin, and diisopropylmethyl phosphonate (DIMP). Analytical results from the LCS sump samples are included in Appendix F-1.

6.1.4.2 HWL LDS Analytical Results

It is common for analytes to be detected in HWL LDS sump samples. Typically, the detections are attributed to contaminants in the LCS clay liner material and consolidation water, rather than indications of leaks in the liner system. The soil used to construct the compacted clay liners of the HWL contained low levels of RMA contaminants that only became detectable after they were mobilized in water and analyzed using a method that had a much lower method reporting limit than what can be achieved in soil analyses.

Analytes detected in the LDS sumps are presented in Appendix F-1 of this report. The ICs detected in the HWL LDS sumps include dieldrin and DIMP.

There was one LDS analytical result in 2021 that required regulatory agency notification per the HWL PCP. Copper was detected above the Watch List Trigger Level in a sample collected from sump LDS1 on March 1, 2021. The Army notified the regulatory agencies of the exceedance, and Non-Routine Action Plan (NRAP)-2022-001 was issued in January 2022. The regulatory agencies approved the NRAP on February 3, 2022. An NRAP log is provided in Appendix G.

6.2 HWL Groundwater Monitoring and Assessment

Like the reporting requirements for HWL LCS/LDS wastewater sampling, Section 3.9 of the HWL PCP requires analytical data from the post-closure groundwater sampling to be reported in this report for the 12-month period from January 1 to December 31 that precedes the submittal of this report. For this report, the reporting period for post-closure groundwater monitoring is January 1, 2021 to December 31, 2021. The purpose of the post-closure groundwater sampling is to meet the requirements of the HWL PCP, to monitor groundwater flow directions and groundwater quality beneath and around the HWL, and to monitor for potential releases of hazardous constituents from the HWL.

The OMC Sample Technicians sampled the HWL groundwater quarterly. The 2021 HWL PCGMR provided in Appendix F-1 presents the methods, results, and conclusions of post-closure groundwater monitoring performed over four quarterly sampling events in the calendar year of 2021.

6.2.1 CAMU Groundwater Flow Direction

The OMC Sample Technicians measured water levels quarterly at 68 wells to evaluate the groundwater flow directions in the unconfined flow system (UFS) and confined flow system (CFS) in the area of the CAMU. The OMC Hydrogeologist used this information to evaluate groundwater flow for significant changes in flow direction over time. The water level data are presented in tabular and graphical form in Appendix F-1 of this report. The groundwater in the UFS and CFS flows to the north-northwest and is consistent with previous groundwater monitoring events for the HWL.

6.2.2 HWL Impacts on Groundwater Quality

The OMC staff compared the results from the water quality sampling completed during 2021 post-closure groundwater monitoring period to the prediction limits calculated from the 2020 sampling results to determine if groundwater quality was impacted by the HWL in 2021. Dieldrin and lead were the only ICs detected in the downgradient wells. Lead was detected in UFS wells 25087 and 25194 at concentrations ranging from 3 to 4.1 µg/L. Lead was not detected in any of the three CFS wells. The lead detections did not exceed the 2021 prediction limit of 15 µg/L. Dieldrin was detected at a concentration of 0.00426 µg/L in downgradient well 25087. Dieldrin was detected at concentrations ranging from 0.0158 to 0.0235 µg/L in downgradient well 25194. Dieldrin concentrations in wells 25087 and 25194 did not exceed the 2021 prediction limit of 0.05 µg/L.

Further evaluation of dieldrin included an intrawell comparison performed using a combined Shewhart-Cumulative Sum (CUSUM) control chart to determine whether the HWL impacted the presence of dieldrin in groundwater at well 25194. The control chart, and a corresponding evaluation of the chart, is included in the HWL PCGMR in Appendix F-1.

The HWL PCP also provides for the use of trend analysis to evaluate groundwater quality. Further evaluation of dieldrin concentrations using Mann-Kendall trend analysis shows that for data collected from 2015 through 2021, dieldrin concentrations have exhibited a decreasing trend. Supporting documentation related to the Mann-Kendall trend analysis is provided in the 2021 HWL PCGMR in Appendix F-1.

Based on the statistical evaluations and trend analysis presented in the 2021 HWL PCGMR, the groundwater quality in the vicinity of the HWL does not appear to have been affected by operations, closure, and post-closure O&M of the landfill.

6.3 ELF LCS/LDS Operations

The OMC Wastewater Operator used flowmeter data to calculate monthly flow rates. The ELF flowmeters indicated that there was no flow from the ELF sumps during this reporting period. The monthly flow summaries are provided in Appendix E. On a quarterly basis, the Wastewater Operator also inspected the sump level in the LRCH buildings and inspected the piping for damage.

6.3.1 ELF LCS/LDS Inspections and Maintenance

The OMC Wastewater Operator inspected and maintained the ELF LCS/LDS and associated buildings in accordance with Sections 3.1.3 and 3.1.4 of the *ELF Post-Closure Wastewater Management Plan*, contained in Appendix C of the ELF PCP. The OMC Wastewater Operator and maintenance staff performed the following routine maintenance and repair activities on the ELF LCS/LDS.

- Performed quarterly inspections on the LB LRCH building, the WP LRCH building, and the LS/LF building
- Performed quarterly inspections on the ELF LCS/LDS Wastewater Conveyance System
- Recorded monthly sump and tank levels for the ELF LCS/LDS and LS/LF building
- Performed weekly LS/LF tank inspections
- Performed monthly inspections on emergency/exit lights in the LS/LF building and both LRCH buildings
- Performed quarterly inspections for grounding and tool safety inspections and first aid kits
- Replaced the level probes in sumps WP LDS1 and WP LCS

The OMC Wastewater Operator documented system inspections on inspection forms included in the *ELF Post-Closure Wastewater Management Plan*. Copies of the completed quarterly inspection forms are provided in Appendix B-2. Also, a system maintenance database was used to document inspections and maintenance activities. The Wastewater O&M Reports, provided in Appendix C-2, were generated by the database, and include log entries for inspections and maintenance activities.

6.3.2 ELF ALR Comparison

Each month the OMC Wastewater Operator calculated the wastewater collection rate in each LDS sump and compared that rate to the ALR for the respective sump as described in the *ELF*

Post-Closure Action Leakage Rate/Response Action Plan, provided in Appendix D of the ELF PCP. The average daily flow rate was calculated as the volume of liquid pumped from the sump during the month, divided by the acreage of surface area served by the sump; divided by the number of days in the month. This average value is defined as the average daily flow rate and is expressed as gpad. This average daily flow rate was compared to the ALR, and 85 percent and 50 percent of the ALR to determine whether any response action is necessary. Table 6.3.2-1 presents the comparisons and conclusions for the four sumps. In all cases the average daily flow rates were 0.0 gpad, which was much less than the ALR and the Non-Routine Action trigger levels of 50 and 85 percent of the ALR. Hence, the performance standards and Non-Routine Action trigger levels for leak detection liquids were not exceeded. Appendix E provides the monthly flow summaries used to calculate the average daily flow rates for each of the sumps.

6.3.3 ELF Wastewater Management Quantities

When wastewater in the ELF LCS and LDS sumps reaches the High-Level switch settings of 24 inches of head, the OMC Wastewater Operator will transfer the wastewater to two storage tanks located in the LS/LF building. However, the wastewater levels in the ELF LCS or LDS sumps did not reach their respective High Levels during this reporting period. Therefore, no ELF wastewater was transported off-site for disposal between May 2021 and April 2022. This is the second full year in a row that the ELF has produced zero gallons of wastewater. Refer to Table 6.3.3-1 for historical ELF wastewater volumes.

Table 6.3.3-1: ELF Wastewater Production

REPORTING YEAR	REPORTING PERIOD	WASTEWATER QUANTITY (gallons)
2011	May 2010 to April 2011	9,841
2012	May 2011 to April 2012	7,516
2013	May 2012 to April 2013	9,349
2014	May 2013 to April 2014	3,904
2015	May 2014 to April 2015	3,279
2016	May 2015 to April 2016	3,973
2017	May 2016 to April 2017	2,714
2018	May 2017 to April 2018	1,256
2019	May 2018 to April 2019	2,421
2020	May 2019 to April 2020	6,483
2021	May 2020 to April 2021	0
2022	May 2021 to April 2022	0

6.3.4 ELF LCS/LDS Wastewater Quality

There are no analytical data from the ELF LCS/LDS wastewater sampling to provide in this report in accordance with Section 3.9 of the ELF PCP. The ELF PCP requires the reporting of wastewater analytical data for the 12-month period from January 1 to December 31 that precedes

the submittal of this report. For this report, the reporting period for ELF LCS/LDS wastewater quality is January 1, 2021 to December 31, 2021. During this reporting period, there were no samples collected from either the ELF LCS or LDS sumps because these sumps never reached their respective High Level settings.

6.4 ELF Groundwater Monitoring and Assessment

Like the reporting requirements for ELF LCS/LDS wastewater sampling, Section 3.9 of the ELF PCP requires analytical data from the post-closure groundwater sampling to be reported in this report for the 12-month period from January 1 to December 31 that precedes the submittal of this report. For this report, the reporting period for post-closure groundwater monitoring is January 1, 2021 to December 31, 2021. The purpose of the post-closure groundwater sampling is to meet the requirements of the ELF PCP, to monitor groundwater flow directions and groundwater quality beneath and around the ELF, and to monitor for potential releases of hazardous constituents from the ELF.

The OMC Sample Technicians sampled the ELF groundwater quarterly. The 2021 ELF PCGMR, provided in Appendix F-2, presents the methods, results, and conclusions of post-closure groundwater monitoring performed over four quarterly sampling events in the calendar year of 2021.

6.4.1 CAMU Groundwater Flow Direction

Refer to Section 6.2.1 for a description of groundwater flow in the CAMU area, including the ELF. Water level data are presented in tabular and graphical form in Appendix F-2 of this report.

6.4.2 ELF Impacts on Groundwater Quality

The OMC staff compared the results from the water quality sampling completed during 2021 post-closure groundwater monitoring period to the prediction limits calculated from the 2020 sampling results to determine if groundwater quality was impacted by the ELF in 2021. Lead was the only IC detected (July 2021 event) in the downgradient wells. Lead was detected in wells 25092 and 26099 at concentrations ranging from 3.1 µg/L to 3.2 µg/L. The range of values is below the prediction limit value of 26.3 µg/L. Historically, lead was detected in downgradient wells prior to waste being placed in the ELF in April 2006.

No ICs exceeded the calculated 2021 prediction limits. Based on the statistical evaluation, groundwater quality around the ELF has not been affected by operations, closure, and post-closure O&M of the landfill.

7.0 ROUTINE AND NON-ROUTINE ACTIONS

7.1 Routine Actions

The OMC staff and their subcontractors performed routine maintenance and repairs on the HWL and ELF caps and wastewater conveyance systems. These O&M activities ensured that the systems continue to function as designed. The OMC staff identified routine maintenance and repair actions during inspections, which are discussed in Sections 4.2, 5.2, 6.1.1 and 6.3.1 of this report. Figure 4.2-1 illustrates the locations of routine activities performed on the HWL cap and surrounding areas, while Figure 5.2-1 shows the locations of routine maintenance and repair

activities performed on the ELF cap and surrounding areas. Wastewater conveyance system O&M activities were performed at the HWL sump manholes and lift station, and the ELF LRCH buildings and LS/LF building.

7.2 Non-Routine Actions

The implementation of non-routine actions is described in the HWL PCP and ELF PCP. Both PCPs provide criteria for non-routine actions and a mechanism for consultation between the parties and documentation of the consultative outcome. This process is described in Section 3.5 of both PCPs. There was one NRAP applicable to the HWL and no NRAPs applicable to the ELF for this reporting period.

- NRAP-2022-001 (Navarro 2022) was approved by the regulatory agencies in February 2022 and documents the Copper concentration above the watch list trigger level in the wastewater sample collected from sump HWL LDS1 in March 2021.

7.3 O&M Change Notices

The Army occasionally identifies enhancements to the post-closure O&M of the landfills which require changes to portions of the PCPs. These changes are typically the result of new conditions or improvements that have come from operational experience. In these cases, the Army institutes the *RVO SOP ENGR.004.RA O&M Change Notice Procedure*, Revision 0 (RVO 2012). There were no OCNs for either the HWL or ELF that were applicable to this reporting period.

8.0 RECOMMENDATIONS AND CORRECTIVE MEASURES

There were no recommendations offered for the 2023 reporting period other than the inspection and maintenance activities already required by the PCPs. Grass establishment and weed control are improving within the HWL and ELF AMA, but the Army will continue to be diligent with activities that may promote the establishment of desirable species. Inspection and maintenance of the stormwater drainage structures and access roads will continue to be a priority, as well as removing the tumbleweed accumulation in the channels and along the fence line. Observations for burrowing animal holes will also remain a priority.

The HWL and ELF met all compliance standards; therefore, no corrective measures were necessary, and none are planned for the reporting period of 2023.

9.0 COSTS AND BUDGETS

Table 9.0-1 shows the costs incurred between May 2021 and April 2022, as well as the current budgets established for O&M of the HWL and ELF.

The costs for operating, inspecting, and maintaining the HWL and ELF over the reporting period, including groundwater sampling, LCS/LDS sampling, LCS/LDS O&M, and wastewater disposal, totaled \$415,317. Complete budgets for post-closure care of the HWL and ELF for May 2022 through April 2023 have not been approved as of the issuance of this report due to the timing of the annual funding cycle, which typically occurs near the end of the calendar year. However, the combined budgets for the period of December 2021 to November 2022 total \$594,513.

Table 9.0-1: Costs and Budgets

TASK	COSTS		BUDGETS	
	INCURRED	PERIOD	VALUE	PERIOD
HWL (Inspection, Maintenance, LCS/LDS and Groundwater Sampling, and Off-Site Wastewater Disposal)	\$274,224	May 2021 – Apr 2022	\$343,841	Dec 2021 – Nov 2022
ELF (Inspection, Maintenance, LCS/LDS and Groundwater Sampling, and Off-Site Wastewater Disposal)	\$141,093	May 2021 – Apr 2022	\$250,672	Dec 2021 – Nov 2022
TOTAL	\$415,317		\$594,513	

10.0 CONCLUSIONS

In summary, and based on the information presented in this report, the HWL and ELF were in compliance with all performance standards and no corrective measures were required. Keys to maintaining the integrity of the landfills include continued diligence with weed control and tumbleweed maintenance, overseeding where necessary, inspection for erosion and burrowing animal holes, and monitoring the groundwater and LCS/LDS wastewater quality.

11.0 REFERENCES

Navarro (Navarro Research and Engineering, Inc.)

2022 (Feb 3) NRAP-2022-001.

2020 (Apr 2) *Enhanced Hazardous Waste Landfill Post-Closure Plan*. Revision 1.

2019 (Dec 9) *Hazardous Waste Landfill Post-Closure Plan*. Revision 4.

RVO (Remediation Venture Office)

2012 (Jan) *RVO SOP ENGR.004.RA O&M Change Notice Procedure*. Revision 0.

TtEC (TetraTech EC, Inc.)

2008 (July) *Enhanced Hazardous Waste Landfill Closure Plan*. Revision 0.

2006 (Aug) *Hazardous Waste Landfill Closure Plan*. Revision 0.

TABLES

This page intentionally left blank.

Table 6.1.2-1: HWL Average Daily LDS Flow Rate and ALR Comparison

SUMP NO.	MONTH	AVERAGE DAILY FLOW RATE (gpad)	COMPARISON TO 85% ALR (>, <, or =)	85% ALR (gpad)	COMPARISON TO ALR (>, <, or =)	ALR (gpad)	CONCLUSION
HWL LDS1	May 2021	0.00	<	112	<	132	No exceedance
	June 2021	0.00	<	112	<	132	No exceedance
	July 2021	0.00	<	112	<	132	No exceedance
	Aug. 2021	0.00	<	112	<	132	No exceedance
	Sept. 2021	0.00	<	112	<	132	No exceedance
	Oct. 2021	0.00	<	112	<	132	No exceedance
	Nov. 2021	0.00	<	112	<	132	No exceedance
	Dec. 2021	0.00	<	112	<	132	No exceedance
	Jan. 2022	0.00	<	112	<	132	No exceedance
	Feb. 2022	0.00	<	112	<	132	No exceedance
	March 2022	0.00	<	112	<	132	No exceedance
	April 2022	0.00	<	112	<	132	No exceedance
HWL LDS2	May 2021	0.00	<	111	<	131	No exceedance
	June 2021	0.00	<	111	<	131	No exceedance
	July 2021	0.00	<	111	<	131	No exceedance
	Aug. 2021	0.00	<	111	<	131	No exceedance
	Sept. 2021	0.00	<	111	<	131	No exceedance
	Oct. 2021	0.00	<	111	<	131	No exceedance
	Nov. 2021	0.00	<	111	<	131	No exceedance
	Dec. 2021	0.00	<	111	<	131	No exceedance
	Jan. 2022	2.53	<	111	<	131	No exceedance
	Feb. 2022	0.00	<	111	<	131	No exceedance
	March 2022	0.00	<	111	<	131	No exceedance
	April 2022	0.00	<	111	<	131	No exceedance

Table 6.1.2-1: HWL Average Daily LDS Flow Rate and ALR Comparison

SUMP NO.	MONTH	AVERAGE DAILY FLOW RATE (gpad)	COMPARISON TO 85% ALR (>, <, or =)	85% ALR (gpad)	COMPARISON TO ALR (>, <, or =)	ALR (gpad)	CONCLUSION
HWL LDS3	May 2021	0.00	<	111	<	131	No exceedance
	June 2021	0.00	<	111	<	131	No exceedance
	July 2021	0.00	<	111	<	131	No exceedance
	Aug. 2021	0.00	<	111	<	131	No exceedance
	Sept. 2021	0.00	<	111	<	131	No exceedance
	Oct. 2021	0.00	<	111	<	131	No exceedance
	Nov. 2021	0.00	<	111	<	131	No exceedance
	Dec. 2021	0.00	<	111	<	131	No exceedance
	Jan. 2022	0.00	<	111	<	131	No exceedance
	Feb. 2022	0.00	<	111	<	131	No exceedance
	March 2022	0.00	<	111	<	131	No exceedance
	April 2022	0.00	<	111	<	131	No exceedance
HWL LDS4	May 2021	0.00	<	111	<	131	No exceedance
	June 2021	0.00	<	111	<	131	No exceedance
	July 2021	0.00	<	111	<	131	No exceedance
	Aug. 2021	0.00	<	111	<	131	No exceedance
	Sept. 2021	0.00	<	111	<	131	No exceedance
	Oct. 2021	0.00	<	111	<	131	No exceedance
	Nov. 2021	2.21	<	111	<	131	No exceedance
	Dec. 2021	0.00	<	111	<	131	No exceedance
	Jan. 2022	0.00	<	111	<	131	No exceedance
	Feb. 2022	0.00	<	111	<	131	No exceedance
	March 2022	0.00	<	111	<	131	No exceedance
	April 2022	0.00	<	111	<	131	No exceedance

Table 6.3.2-1: ELF Average Daily LDS Flow Rate and ALR Comparison


SUMP NO.	MONTH	AVERAGE DAILY FLOW RATE (gpad)	COMPARISON TO 50% ALR (>, <, or =)	50% ALR (gpad)	COMPARISON TO 85% ALR (>, <, or =)	85% ALR (gpad)	COMPARISON TO ALR (>, <, or =)	ALR (gpad)	CONCLUSION
ELF WP LDS1	May 2021	0.00	<	65	<	110.5	<	130	No exceedance
	June 2021	0.00	<	65	<	110.5	<	130	No exceedance
	July 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Aug. 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Sept. 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Oct. 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Nov. 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Dec. 2021	0.00	<	65	<	110.5	<	130	No exceedance
	Jan. 2022	0.00	<	65	<	110.5	<	130	No exceedance
	Feb. 2022	0.00	<	65	<	110.5	<	130	No exceedance
	March 2022	0.00	<	65	<	110.5	<	130	No exceedance
	April 2022	0.00	<	65	<	110.5	<	130	No exceedance
ELF WP LDS2	May 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	June 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	July 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Aug. 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Sept. 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Oct. 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Nov. 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Dec. 2021	0.00	<	79.5	<	135.2	<	159	No exceedance
	Jan. 2022	0.00	<	79.5	<	135.2	<	159	No exceedance
	Feb. 2022	0.00	<	79.5	<	135.2	<	159	No exceedance
	March 2022	0.00	<	79.5	<	135.2	<	159	No exceedance
	April 2022	0.00	<	79.5	<	135.2	<	159	No exceedance

Table 6.3.2-1: ELF Average Daily LDS Flow Rate and ALR Comparison

SUMP NO.	MONTH	AVERAGE DAILY FLOW RATE (gpad)	COMPARISON TO 50% ALR (>, <, or =)	50% ALR (gpad)	COMPARISON TO 85% ALR (>, <, or =)	85% ALR (gpad)	COMPARISON TO ALR (>, <, or =)	ALR (gpad)	CONCLUSION
ELF LB LDS1	May 2021	0.00	<	130	<	221	<	260	No exceedance
	June 2021	0.00	<	130	<	221	<	260	No exceedance
	July 2021	0.00	<	130	<	221	<	260	No exceedance
	Aug. 2021	0.00	<	130	<	221	<	260	No exceedance
	Sept. 2021	0.00	<	130	<	221	<	260	No exceedance
	Oct. 2021	0.00	<	130	<	221	<	260	No exceedance
	Nov. 2021	0.00	<	130	<	221	<	260	No exceedance
	Dec. 2021	0.00	<	130	<	221	<	260	No exceedance
	Jan. 2022	0.00	<	130	<	221	<	260	No exceedance
	Feb. 2022	0.00	<	130	<	221	<	260	No exceedance
	March 2022	0.00	<	130	<	221	<	260	No exceedance
	April 2022	0.00	<	130	<	221	<	260	No exceedance
ELF LB LDS2	May 2021	0.00	<	159	<	270.3	<	318	No exceedance
	June 2021	0.00	<	159	<	270.3	<	318	No exceedance
	July 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Aug. 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Sept. 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Oct. 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Nov. 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Dec. 2021	0.00	<	159	<	270.3	<	318	No exceedance
	Jan. 2022	0.00	<	159	<	270.3	<	318	No exceedance
	Feb. 2022	0.00	<	159	<	270.3	<	318	No exceedance
	March 2022	0.00	<	159	<	270.3	<	318	No exceedance
	April 2022	0.00	<	159	<	270.3	<	318	No exceedance

FIGURES


This page intentionally left blank.





LEGEND:

- x — PERIMETER FENCE/ARMY MAINTAINED AREA BOUNDARY
- == CHANNELS AND DOWNCHUTES
- EM-HWL08 EROSION/SETTLEMENT MONUMENT
- 25098 GROUNDWATER MONITORING WELL
- ROAD
- CONTOURS
- GROUND CLEAR HERBICIDE
- OVERSEED
- MOWED
- OVERSEED/MOWED

NOTE:
REMOVED TUMBLE WEEDS FROM THE PERIMETER FENCE.



		
ROCKY MOUNTAIN ARSENAL COMMERCE CITY, COLORADO		
PROJECT NAME		
2022 RCRA LANDFILLS AND GROUNDWATER MONITORING REPORT		
TITLE		
HWL ROUTINE ACTIVITIES MAP		
CAD FILE:	DATE	FIGURE NUMBER
Figure 4.2-1.DWG	05.25.22	4.2-1



APPENDICES

A	Precipitation Data (May 01, 2021 through April 30, 2022)
B-1	HWL Inspection Documentation
B-2	ELF Inspection Documentation
C-1	HWL Maintenance Documentation
C-2	ELF Maintenance Documentation
D	HWL and ELF Erosion/Settlement Monument Survey Data
E	Monthly Flow Summaries
F-1	Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021
F-2	Enhanced Hazardous Waste Landfill Post-Closure Groundwater Monitoring Report Calendar Year 2021
G	NRAP Log

This page intentionally left blank.

APPENDIX A

Precipitation Data

(May 01, 2021 through April 30, 2022)

This page intentionally left blank.

Appendix A - Precipitation Data (May 1, 2021 through April 30, 2022)

Note 1: The reporting period for this table is May 1, 2021 through April 30, 2022.

Note 2: Data presented in this table were collected from a rain gauge located on the Lime Basins RCRA-Equivalent Cover in Section 35.

Note 3: This table provides precipitation data for all dates when precipitation was recorded. For dates not shown, there was no recorded precipitation.

Note 4: The yellow highlighted box indicates a significant storm event where one inch or greater of rain fell in a 24- hour period.

Note 5: The red highlighted box indicates that this recorded precipitation is the result of maintenance performed on the rain gauge and this value has been excluded in the total amount of precipitation for this reporting period.

Date	Daily Precipitation (in)
May 3, 2021	0.19
May 4, 2021	0.87
May 5, 2021	0.01
May 9, 2021	0.13
May 10, 2021	0.03
May 10, 2021	0.03
May 11, 2021	0.26
May 12, 2021	0.14
May 17, 2021	0.02
May 18, 2021	0.28
May 19, 2021	0.11
May 24, 2021	0.33
May 30, 2021	1.13
May 31, 2021	0.04
June 6, 2021	0.02
June 19, 2021	0.03
June 20, 2021	0.01
June 21, 2021	0.12
June 24, 2021	0.01
June 25, 2021	0.11
June 26, 2021	0.26
June 29, 2021	0.13
July 1, 2021	0.09
July 2, 2021	0.41
July 22, 2021	0.01
July 30, 2021	0.08
July 31, 2021	0.01
August 3, 2021	0.01
August 19, 2021	0.02
August 20, 2021	0.03
September 1, 2021	0.01
September 11, 2021	0.01
September 13, 2021	0.04
September 20, 2021	0.03
September 28, 2021	0.01

Date	Daily Precipitation (in)
September 29, 2021	0.16
September 30, 2021	0.01
October 12, 2021	0.01
October 25, 2021	0.78
October 26, 2021	0.01
November 2, 2021	0.01
December 10, 2021	0.07
December 15, 2021	0.02
December 24, 2021	0.01
December 31, 2021	0.13
January 1, 2022	0.09
January 5, 2022	0.08
January 6, 2022	0.16
January 21, 2022	0.02
January 25, 2022	0.21
January 27, 2022	0.12
February 1, 2022	0.05
February 2, 2022	0.11
February 11, 2022	0.33
February 12, 2022	0.01
February 16, 2022	0.22
February 17, 2022	0.04
February 22, 2022	0.02
February 23, 2022	0.06
February 24, 2022	0.11
March 5, 2022	0.12
March 6, 2022	0.12
March 9, 2022	0.02
March 10, 2022	0.02
March 16, 2022	0.35
March 17, 2022	0.41
March 29, 2022	0.13
April 10, 2022	0.05
April 17, 2022	0.04
Total:	8.34

This page intentionally left blank.

APPENDIX B-1

HWL Inspection Documentation

This page intentionally left blank.

POST-STORM

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman and Carl Mackey</u>						Inspection Date(s): <u>June 2, 2021</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0.04 inches</u> Weather Conditions: <u>Sunny, temp of 75°</u> Acceptable/Unacceptable for Inspection (circle one)											
Post-Storm Inspection: Recent Significant Storm Event? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Drive-around inspection performed after significant storm event? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>June 1, 2021</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>						Date(s) of Significant Storm Event: <u>May 30, 2021</u>			Total Precipitation (in): <u>1.13 inches</u>		
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION <small>Indicate recommended action, if required.</small>		CONFIRMATION THAT ACTION IS COMPLETE <small>(Initial and Date)</small>	
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1*	Erosion rills or gullies		X					none			
1.2*	Sheet erosion or plant pedestalling		X					none			
1.3*	Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		X					none			
1.4	Surface salts, crusting, or evidence of compaction			X				N/A			
1.5	Excessive animal trails or tire tracks/ruts			X				N/A			
1.6	Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)			X				N/A			

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		X					none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism			X				N/A	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet			X				N/A	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet			X				N/A	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged			X				N/A	
3.2 Debris has collected along the perimeter fence			X				N/A	
3.3 Warning signs are not legible from 25 feet			X				N/A	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		X					none	
4.0 LCS/LDS and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LCS/LDS manholes		X					none	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.			X				N/A	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells			X				N/A	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel		X					none	
6.2* Excessive siltation in the channel		X					none	
6.3* Debris present in the channel		X					none	
6.4* Erosion rills or gullies in the channel		X					none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB			X				N/A	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		X					none	
6.7 Damaged box culverts			X				N/A	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Handwritten notes in blue ink:
KAS
6-15-21

Inspector

Name: <i>Michael W. Jones</i>	Signature: <i>[Signature]</i>	Date: <i>6/8/21</i>
-------------------------------	-------------------------------	---------------------

Covers Manager Review of Inspection Documentation

Name: <i>Kim Hoffman</i>	Signature: <i>[Signature]</i>	Date: <i>6-15-21</i>
--------------------------	-------------------------------	----------------------

Covers Manager Confirmation of Completed Actions

Name: <i>Michael W. Jones</i>	Signature: <i>[Signature]</i>	Date: <i>7/20/21</i>
-------------------------------	-------------------------------	----------------------

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

Inspector Name(s): <u>K. Hoffmann, C. Mackey, A. Mackelvey</u>						Inspection Date(s): <u>7-7-2021</u>						
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>shiny, calm winds, 80's</u> <div style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px;">Acceptable/Unacceptable for Inspection (<i>circle one</i>)</div>												
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>								Date(s) of Significant Storm Event: <u>N/A</u>		Total Precipitation (in): <u>N/A</u>		
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____												
INSPECTION ITEM			CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.		CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)	
	Y	N	N/A	Y	N	N/A						
1.0 Surface Conditions												
1.1* Erosion rills or gullies		✓				✓	none					
1.2* Sheet erosion or plant pedestalling		✓				✓	none					
1.3* Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none					
1.4 Surface salts, crusting, or evidence of compaction		✓				✓	none					
1.5 Excessive animal trails or tire tracks/ruts		✓				✓	none					
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none					

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence		✓				✓	none	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	
4.0 LCS/LDS and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LCS/LDS manholes		✓				✓	none	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel		✓				✓	none	
6.2* Excessive siltation in the channel		✓				✓	none	
6.3* Debris present in the channel		✓				✓	none	
6.4* Erosion rills or gullies in the channel		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

✓ 3-8-21

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>[Signature]</u>	Date: <u>3-8-21</u>
Covers Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>[Signature]</u>	Date: <u>7/9/21</u>
Covers Manager Confirmation of Completed Actions		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

**FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM**

Inspector Name(s): <u>M. Jones, K. Hoffman, V. Stewart</u>						Inspection Date(s): <u>1-12-2022</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>sunny, calm winds, 30's</u> <div style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px;">Acceptable/Unacceptable for Inspection (<i>circle one</i>)</div>											
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>								Date(s) of Significant Storm Event: <u>N/A</u>		Total Precipitation (in): <u>N/A</u>	
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)			
	Y	N	N/A	Y	N	N/A					
1.0 Surface Conditions											
1.1* Erosion rills or gullies		✓				✓	none				
1.2* Sheet erosion or plant pedestalling		✓				✓	none				
1.3* Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none				
1.4 Surface salts, crusting, or evidence of compaction		✓				✓	none				
1.5 Excessive animal trails or tire tracks/ruts		✓				✓	none				
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none				

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence	✓				✓		humble weeds have collected along fence line	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	
4.0 LCS/LDS and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LCS/LDS manholes		✓				✓	none	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel		✓				✓	none	
6.2* Excessive siltation in the channel		✓				✓	none	
6.3* Debris present in the channel	✓				✓		tumble weeds have collected in channels	
6.4* Erosion rills or gullies in the channel		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

FORM SOP HWL 001-1
HWL CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

yes 1-13-22

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>Kim Hoffman</u>	Date: <u>1-13-22</u>
Covers Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>Michael W. Jones</u>	Date: <u>1/27/22</u>
Covers Manager Confirmation of Completed Actions		
Name:	Signature:	Date:

**FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM**

Inspector Name(s): <u>K. Hoffman</u>						Inspection Date(s): <u>10-5-21</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>sunny, calm w/ no S, 60's</u> (Acceptable/Unacceptable for Inspection (<u>circle one</u>))											
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u>								Date(s) of Significant Storm Event: <u>N/A</u>		Total Precipitation (in.): <u>N/A</u>	
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)		
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1	Erosion rills or gullies		✓				✓	none			
1.2	Sheet erosion or plant pedestalling		✓				✓	none			
1.3	Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none			
1.4	Surface salts, crusting, or evidence of compaction		✓				✓	none			
1.5	Excessive animal trails or tire tracks/ruts		✓				✓	none			
1.6	Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none			

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7 Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
2.3 Deep rooted, noxious or undesirable weeds		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence		✓				✓	none	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4 Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
3.5 Cap perimeter survey monuments appear to be disturbed (Inspect every five years, in conjunction with the CERCLA Five Year Review for legibility and to confirm record locations)			✓			✓	not inspected this inspection.	
4.0 LCS/LDS and LS/LF Monitoring								
4.1 Erosion rills or gullies, or burrowing animal holes around the LCS/LDS manholes		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1 Impeded drainage or ponding in a channel or downchute		✓				✓	none	
6.2 Excessive siltation in a channel or downchute		✓				✓	none	
6.3 Debris present in a channel or downchute		✓				✓	none	
6.4 Erosion rills or gullies in a channel or downchute		✓				✓	none	

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6 Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

INSPECTION ITEM	EM-HWL01	EM-HWL02	EM-HWL03	EM-HWL04	EM-HWL05	EM-HWL06	EM-HWL07	EM-HWL08	EM-HWL09
7.0 Erosion/Settlement Monuments: <i>Inspect monuments for damage and legibility, and record the soil thickness loss, if any.</i>									
7.1 Was the monument free of damage and legible?	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N
7.2 Measured Soil Thickness Loss (inches)	0.25	1.5	1.75	1.25	0.75	0.75	1	0.25	1.75

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Handwritten: 10-7-21

Inspector		
Name: <i>Kim Hoffman</i>	Signature: <i>Kim Hoffman</i>	Date: <i>10-7-21</i>
Covers Manager Review of Inspection Documentation		
Name: <i>Michael W. Jones</i>	Signature: <i>Michael W. Jones</i>	Date: <i>10/8/21</i>
Covers Manager Confirmation of Completed Actions		
Name: <i>N/A</i>	Signature: <i>N/A</i>	Date: <i>N/A</i>

**FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM**

Inspector Name(s): <u>K. Hoffman</u>						Inspection Date(s): <u>4-26-22</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>Sunny, calm winds, 70's</u> Acceptable/Unacceptable for Inspection (circle one)											
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u>								Date(s) of Significant Storm Event:		Total Precipitation (in.):	
								<u>N/A</u>		<u>N/A</u>	
Attachments: <input type="checkbox"/> Photographs <input checked="" type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)		
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1	Erosion rills or gullies		✓				✓	none			
1.2	Sheet erosion or plant pedestalling		✓				✓	none			
1.3	Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none			
1.4	Surface salts, crusting, or evidence of compaction		✓				✓	none			
1.5	Excessive animal trails or tire tracks/ruts		✓				✓	none			
1.6	Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none			

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7 Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
2.3 Deep rooted, noxious or undesirable weeds		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence	✓	yes	4-27-22		✓		tumble weeds have accumulated along some of the fence	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4 Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
3.5 Cap perimeter survey monuments appear to be disturbed (Inspect every five years, in conjunction with the CERCLA Five Year Review for legibility and to confirm record locations)			✓			✓	not inspected this year	
4.0 LCS/LDS and LS/LF Monitoring								
4.1 Erosion rills or gullies, or burrowing animal holes around the LCS/LDS manholes		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1 Impeded drainage or ponding in a channel or downchute		✓				✓	none	
6.2 Excessive siltation in a channel or downchute		✓				✓	none	
6.3 Debris present in a channel or downchute	✓				✓		see Note 1.	
6.4 Erosion rills or gullies in a channel or downchute		✓				✓	none	

FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6 Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

INSPECTION ITEM	EM-HWL01	EM-HWL02	EM-HWL03	EM-HWL04	EM-HWL05	EM-HWL06	EM-HWL07	EM-HWL08	EM-HWL09
7.0 Erosion/Settlement Monuments: <i>Inspect monuments for damage and legibility, and record the soil thickness loss, if any.</i>									
7.1 Was the monument free of damage and legible?	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N
7.2 Measured Soil Thickness Loss (inches)	0.5	1.5	1.75	1	0.5	0.5	0.5	Ø	1.25


FORM SOP HWL 001-2
HWL CAP TYPE II INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Erosion Management: EM-HWL01 would benefit to have seed planted around repaired soil. It is bare, but no erosion was noted at time of inspection.


Note 1: significant tumbleweed accumulation was observed due to high winds over the past few months. Please see attached figure for location information.

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>Kim Hoffman</u>	Date: <u>4-27-22</u>
Covers Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>Michael W. Jones</u>	Date: <u>5/10/22</u>
Covers Manager Confirmation of Completed Actions		
Name:	Signature:	Date:



- LEGEND:**
- UPPER VANTAGE PATHS FOR MONTHLY AND SEMIANNUAL INSPECTIONS
 - LOWER VANTAGE PATH FOR SEMIANNUAL INSPECTIONS
 - xx — PERIMETER FENCE/ARMY MAINTAINED AREA BOUNDARY
 - == ROAD
 - ▬ CHANNELS AND DOWNCHUTES
 - EM-HWL08 EROSION/SETTLEMENT MONUMENT
 - △ SURVEY MONUMENTS

▬ : tumble weed accumulation



<p>Program Manager Rocky Mountain Arsenal U.S. Army COMMITTED TO PROTECTION OF THE ENVIRONMENT</p>		
<p>ROCKY MOUNTAIN ARSENAL COMMERCE CITY, COLORADO</p>		
<p>NAVARRO Research and Engineering, Inc.</p>		
<p>PROJECT NAME HWL POST-CLOSURE PLAN</p>		
<p>TITLE LOCATION OF CAP FEATURES</p>		
CAD FILE: FugSOP-HWL001-1.dwg	DATE 07.29.19	FIGURE NUMBER SPO HWL 001-1

This page intentionally left blank.

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman</u>							Inspection Date(s): <u>7-1-2021</u>	
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
	Y	N	N/A	Y	N	N/A		
1 Warning signs are not legible (Confined Space, Buried Pipe/Conduit, etc.)		✓				✓		
2 Extreme temperature inside LCS/LDS manholes		✓				✓		
3 Excessive liquid in LCS/LDS manholes		✓				✓		
4 Improper operation/condition of LCS/LDS pumps or instrumentation		✓				✓		
5 Improper operation/condition of lift station pumps or instrumentation		✓				✓		
6 Excessive liquid in lift station secondary containment		✓				✓		
7 Blockage of leachate collection or leak detection discharge piping		✓				✓		
8 Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
9 LS/LF tank levels are above high level set points.		✓				✓		
10 LS/LF tanks are damaged or leaking.		✓				✓		
11 Indication of leaks in the indoor piping system in the LS/LF.		✓				✓		

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

12	Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓		
13	Heating system in the LS/LF is malfunctioning.		✓				✓		

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>[Signature]</u>	Date: <u>7-7-21</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>[Signature]</u>	Date: <u>7/9/21</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>E. Hoffman</u>				Inspection Date(s): <u>10-5-21</u>				
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
	Y	N	N/A	Y	N	N/A		
1 Warning signs are not legible (Confined Space, Buried Pipe/Conduit, etc.)		✓				✓	<div style="transform: rotate(-45deg); font-size: 2em; font-weight: bold;"> YES 10-5-21 </div>	
2 Extreme temperature inside LCS/LDS manholes		✓				✓		
3 Excessive liquid in LCS/LDS manholes		✓				✓		
4 Improper operation/condition of LCS/LDS pumps or instrumentation		✓				✓		
5 Improper operation/condition of lift station pumps or instrumentation		✓				✓		
6 Excessive liquid in lift station secondary containment		✓				✓		
7 Blockage of leachate collection or leak detection discharge piping		✓				✓		
8 Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
9 LS/LF tank levels are above high level set points.		✓				✓		
10 LS/LF tanks are damaged or leaking.		✓				✓		
11 Indication of leaks in the indoor piping system in the LS/LF.		✓				✓		

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

12	Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓			
13	Heating system in the LS/LF is malfunctioning.		✓				✓			

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>Kim Hoffman</u>	Date: <u>10-5-21</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>Michael W. Jones</u>	Date: <u>10/8/21</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>K. Hoffman</u>							Inspection Date(s): <u>1-11-2022</u>		
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other									
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
		Y	N	N/A	Y	N	N/A		
1	Warning signs are not legible (Confined Space, Buried Pipe/Conduit, etc.)		✓				✓	Not 1-11-22	
2	Extreme temperature inside LCS/LDS manholes		✓				✓		
3	Excessive liquid in LCS/LDS manholes		✓				✓		
4	Improper operation/condition of LCS/LDS pumps or instrumentation		✓				✓		
5	Improper operation/condition of lift station pumps or instrumentation		✓				✓		
6	Excessive liquid in lift station secondary containment		✓				✓		
7	Blockage of leachate collection or leak detection discharge piping		✓				✓		
8	Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
9	LS/LF tank levels are above high level set points.		✓				✓		
10	LS/LF tanks are damaged or leaking.		✓				✓		
11	Indication of leaks in the indoor piping system in the LS/LF.		✓				✓		

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

12	Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓		
13	Heating system in the LS/LF is malfunctioning.		✓				✓		

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

yes 1-11-22

Inspector

Name: *Kim Hoffman*

Signature: *Kim Hoffman*

Date: *1-11-22*

Treatment Operations Manager Review of Inspection Documentation

Name: *Michael W. Jones*

Signature: *Michael W. Jones*

Date: *1/27/22*

Treatment Operations Manager Review of Inspection Documentation

Name: *N/A*

Signature: *N/A*

Date: *N/A*

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman</u>				Inspection Date(s): <u>4-5-22</u>				
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
	Y	N	N/A	Y	N	N/A		
1 Warning signs are not legible (Confined Space, Buried Pipe/Conduit, etc.)		✓				✓	YES 4-5-22	
2 Extreme temperature inside LCS/LDS manholes		✓				✓		
3 Excessive liquid in LCS/LDS manholes		✓				✓		
4 Improper operation/condition of LCS/LDS pumps or instrumentation		✓				✓		
5 Improper operation/condition of lift station pumps or instrumentation		✓				✓		
6 Excessive liquid in lift station secondary containment		✓				✓		
7 Blockage of leachate collection or leak detection discharge piping		✓				✓		
8 Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
9 LS/LF tank levels are above high level set points.		✓				✓		
10 LS/LF tanks are damaged or leaking.		✓				✓		
11 Indication of leaks in the indoor piping system in the LS/LF.		✓				✓		

HWL LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

12	Indication that the LS/LF secondary containment is damaged or inadequate.		✓					✓	
13	Heating system in the LS/LF is malfunctioning.		✓					✓	

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Inspector		
Name: <u>Kim Hoffmann</u>	Signature: <u>[Signature]</u>	Date: <u>4-5-22</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>[Signature]</u>	Date: <u>4/6/22</u>
Treatment Operations Manager Review of Inspection Documentation		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

APPENDIX B-2
ELF Inspection Documentation

This page intentionally left blank.

POST-STORM

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman and Carl Mackey</u>						Inspection Date(s): <u>June 2, 2021</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0.04 inches</u> Weather Conditions: <u>Sunny, temp of 75°</u> Acceptable /Unacceptable for Inspection (<i>circle one</i>)											
Post-Storm Inspection: Recent Significant Storm Event? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Drive-around inspection performed after significant storm event? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>June 1, 2021</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>						Date(s) of Significant Storm Event: <u>May 30, 2021</u>		Total Precipitation (in): <u>1.13 inches</u>			
Attachments: <input type="checkbox"/> Photographs <input checked="" type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.		CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)	
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1* Erosion rills or gullies			X					None			
1.2* Sheet erosion or plant pedestalling			X					None			
1.3* Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage			X					None			
1.4 Surface salts, crusting, or evidence of compaction				X				N/A			
1.5 Excessive animal trails or tire tracks/ruts				X				N/A			
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)				X				N/A			

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		X					None	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism			X				N/A	
1.9 Anchor Trench Drain outfalls exhibit flow, erosion, seepage, moisture or bare/ sparse vegetation.			X				See Note 1. No action required.	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet			X				N/A	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet			X				N/A	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged			X				N/A	
3.2 Debris has collected along the perimeter fence			X				N/A	
3.3 Warning signs are not legible from 25 feet			X				N/A	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		X					None	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.0 LRCH and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LRCH Buildings		X					None	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.			X				N/A	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells			X				N/A	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel	X						Note 2.	Repaired Sept 5/10/22 July 2021. MJ 5/10/22
6.2* Excessive siltation in the channel		X					None	
6.3* Debris present in the channel		X					None	
6.4* Erosion rills or gullies in the channel		X					None	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB			X				N/A	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		X					None	
6.7 Damaged box culverts			X				N/A	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Note 1: Three of the four anchor trench drain outfalls on the south face of the ELF were wet following the significant rain event on May 30, 2021. No response action is required.

Note 2: An area of sinkholes in the east perimeter channel was observed during the April 2021 Type II inspection. This observation item has not been repaired.

Inspector

Name: *Michael W. Jones*

Signature: *[Signature]*

Date: *6/8/21*

Cover Manager Review of Inspection Documentation

Name: *Kim Hoffman*

Signature: *[Signature]*

Date: *6-15-21*

Cover Manager Confirmation of Completed Actions

Name: *Michael W. Jones*

Signature: *[Signature]*

Date: *7/20/21*

**FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM**

Inspector Name(s): <u>K. Hoffman, C. Mackey, A. Mackelvey</u>						Inspection Date(s): <u>7-7-2021</u>		
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>sunny, calm winds, 80s</u> Acceptable/Unacceptable for Inspection (circle one)								
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>						Date(s) of Significant Storm Event: <u>N/A</u> Total Precipitation (in): <u>N/A</u>		
Attachments: <input type="checkbox"/> Photographs <input checked="" type="checkbox"/> Figures <input type="checkbox"/> Other: _____								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.0 Surface Conditions								
1.1* Erosion rills or gullies		✓				✓	none	
1.2* Sheet erosion or plant pedestalling		✓				✓	none	
1.3* Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none	
1.4 Surface salts, crusting, or evidence of compaction		✓				✓	none	
1.5 Excessive animal trails or tire tracks/ruts		✓				✓	none	
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
1.9 Anchor Trench Drain outfalls exhibit flow, erosion, seepage, moisture or bare/ sparse vegetation.		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence		✓				✓	none	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.0 LRCH and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LRCH Buildings		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel	✓				✓		Note 1.	Repaired July 2021. MJ 7/20/21
6.2* Excessive siltation in the channel		✓				✓	none	
6.3* Debris present in the channel		✓				✓	none	
6.4* Erosion rills or gullies in the channel		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Note 1 : An area in the east perimeter channel was observed to have sinkholes during the April 2021 type II inspection. This observation has not been repaired. See attached figure for location information.

Inspector

Name: Kim Hoffman

Signature: Kim Hoffman

Date: 7-8-21

Cover Manager Review of Inspection Documentation

Name: Michael W. Jones

Signature: Michael W. Jones

Date: 7/9/21

Cover Manager Confirmation of Completed Actions


Name: Michael W. Jones


Signature: Michael W. Jones

Date: 7/20/21



- LEGEND:**
- UPPER VANTAGE PATHS FOR TYPE I AND TYPE II INSPECTIONS
 - LOWER VANTAGE PATH FOR TYPE II INSPECTIONS
 - - - PERIMETER FENCE/ARMY MAINTAINED AREA BOUNDARY
 - == ROAD
 - - - CHANNELS AND DOWNCHUTES
 - ⊗ EM-ELF01 EROSION/SETTLEMENT MONUMENT
 - △ SURVEY MONUMENTS
 - ⊙ TRENCH DRAIN OUTFALL



 Program Manager Rocky Mountain Arsenal U.S. ARMY COMMITTED TO PROTECTION OF THE ENVIRONMENT		
ROCKY MOUNTAIN ARSENAL COMMERCE CITY, COLORADO		
NAVARRO Research and Engineering, Inc.		
PROJECT NAME ELF POST-CLOSURE PLAN		
TITLE LOCATION OF CAP FEATURES		
CAD FILE: FIG-SOP ELF 001-1.DWG	DATE 10.07.18	FIGURE NUMBER SOP ELF 001-1

This page intentionally left blank.

**FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM**

Inspector Name(s): <u>M. Jones, K. Hoffmann, V. Stewart</u>						Inspection Date(s): <u>1-12-2022</u>		
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>sunny, calm winds, 30's</u> Acceptable /Unacceptable for Inspection (<i>circle one</i>)								
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u> <i>Note: Post-storm event inspection items are indicated with a * next to the Inspection Item number.</i>						Date(s) of Significant Storm Event: <u>N/A</u> Total Precipitation (in): <u>N/A</u>		
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.0 Surface Conditions								
1.1* Erosion rills or gullies		✓			✓		none	
1.2* Sheet erosion or plant pedestalling		✓			✓		none	
1.3* Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓			✓		none	
1.4 Surface salts, crusting, or evidence of compaction		✓			✓		none	
1.5 Excessive animal trails or tire tracks/ruts		✓			✓		none	
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓			✓		none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
1.7* Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
1.9 Anchor Trench Drain outfalls exhibit flow, erosion, seepage, moisture or bare/ sparse vegetation.		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence	✓				✓		tumble weeds have collected	
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4* Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Initial and Date)
	Y	N	N/A	Y	N	N/A		
4.0 LRCH and LS/LF Monitoring								
4.1* Erosion rills or gullies, or burrowing animal holes around the LRCH Buildings		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1* Impeded drainage or ponding in the channel		✓				✓	none	
6.2* Excessive siltation in the channel		✓				✓	none	
6.3* Debris present in the channel	✓				✓		tumble weeds have collected	
6.4* Erosion rills or gullies in the channel		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6* Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

FORM SOP ELF 001-1
ELF CAP TYPE I INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

4501 1-13-22

Inspector		
Name: <i>Kim Hoffman</i>	Signature: <i>Kim Hoffman</i>	Date: <i>1-13-22</i>
Cover Manager Review of Inspection Documentation		
Name: <i>Michael W. Jones</i>	Signature: <i>Michael W. Jones</i>	Date: <i>1/27/22</i>
Cover Manager Confirmation of Completed Actions		
Name:	Signature:	Date:

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

Inspector Name(s): <u>K. Hoffman</u>						Inspection Date(s): <u>10-5-21</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>surging, calm winds, 60's</u> Acceptable /Unacceptable for Inspection (<i>circle one</i>)											
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u>								Date(s) of Significant Storm Event: <u>N/A</u>		Total Precipitation (in): <u>N/A</u>	
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION <small>Indicate recommended action, if required.</small>		CONFIRMATION THAT ACTION IS COMPLETE <small>(Initial and Date)</small>	
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1	Erosion rills or gullies		✓				✓	none			
1.2	Sheet erosion or plant pedestalling		✓				✓	none			
1.3	Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none			
1.4	Surface salts, crusting, or evidence of compaction		✓				✓	none			
1.5	Excessive animal trails or tire tracks/ruts		✓				✓	none			

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none	
1.7 Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
1.9 Anchor Trench Drain outfalls exhibit flow, erosion, seepage, moisture or bare/ sparse vegetation.		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
2.3 Deep rooted, noxious or undesirable weeds		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence		✓				✓	none	

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4 Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	
3.5 Cap perimeter survey monuments appear to be disturbed (Inspect every five years, in conjunction with the CERCLA Five Year Review for legibility and to confirm record locations)			✓			✓	not inspected this inspection.	
4.0 LRCH and LS/LF Monitoring								
4.1 Erosion rills or gullies, or burrowing animal holes around the LRCH Buildings		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1 Impeded drainage or ponding in a channel or downchute		✓				✓	none	
6.2 Excessive siltation in a channel or downchute		✓				✓	none	
6.3 Debris present in a channel or downchute		✓				✓	none	

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
6.4 Erosion rills or gullies in a channel or downchute		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6 Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

INSPECTION ITEM	EM-ELF01	EM-ELF02	EM-ELF03	EM-ELF04	EM-ELF05	EM-ELF06	EM-ELF07	EM-ELF08
7.0 Erosion/Settlement Monuments: <i>Inspect monuments for damage and legibility, and record the soil thickness loss, if any.</i>								
7.1 Was the monument free of damage and legible?	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N
7.2 Measured Soil Thickness Loss (inches)	3.5	3.0	3.25	3	Ø	2	1.5	0.75

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

451 10-7-21

Inspector		
Name: <u>Kim Hoffman</u>	Signature: <u>[Signature]</u>	Date: <u>10-7-21</u>
Cover Manager Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>[Signature]</u>	Date: <u>10/8/21</u>
Cover Manager Confirmation of Completed Actions		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

Inspector Name(s): <u>K. Hoffman</u>						Inspection Date(s): <u>4-26-22</u>					
Field Conditions: Previous 24-Hour Precipitation: <u>0</u> Weather Conditions: <u>sunny, calm winds, 30's</u> Acceptable /Unacceptable for Inspection (<i>circle one</i>)											
Post-Storm Inspection: Recent Significant Storm Event? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Drive-around inspection performed after significant storm event? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Drive-around inspection date (taken from Logbook): <u>N/A</u>								Date(s) of Significant Storm Event: <u>N/A</u>		Total Precipitation (in): <u>N/A</u>	
Attachments: <input type="checkbox"/> Photographs <input checked="" type="checkbox"/> Figures <input type="checkbox"/> Other: _____											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION <small>Indicate recommended action, if required.</small>		CONFIRMATION THAT ACTION IS COMPLETE <small>(Initial and Date)</small>	
		Y	N	N/A	Y	N	N/A				
1.0 Surface Conditions											
1.1	Erosion rills or gullies		✓				✓	none			
1.2	Sheet erosion or plant pedestalling		✓				✓	none			
1.3	Depressions, ponding areas, sedimentation, or other conditions that could interrupt cap drainage		✓				✓	none			
1.4	Surface salts, crusting, or evidence of compaction		✓				✓	none			
1.5	Excessive animal trails or tire tracks/ruts		✓				✓	none			

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
1.6 Burrowing animal holes (localized burrows greater than 3 inches in diameter, or widespread burrows of any size)		✓				✓	none	
1.7 Seepage, differential settlement, cracking, subsidence, sliding, creep, or other signs of slope instability		✓				✓	none	
1.8 Intrusive damage such as unplanned excavation, drilling, grading, damage to engineering or access controls, vandalism		✓				✓	none	
1.9 Anchor Trench Drain outfalls exhibit flow, erosion, seepage, moisture or bare/ sparse vegetation.		✓				✓	none	
2.0 Vegetative Cover								
2.1 Bare area or areas of poor growth greater than 100 square feet		✓				✓	none	
2.2 Areas of poor vigor, disease, over grazing, stress, burned, or discoloration greater than 100 square feet		✓				✓	none	
2.3 Deep rooted, noxious or undesirable weeds		✓				✓	none	
3.0 Engineering and Access Controls								
3.1 The perimeter fence is damaged		✓				✓	none	
3.2 Debris has collected along the perimeter fence	✓				✓		unruly weeds have accumulated along some fence line.	

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
3.3 Warning signs are not legible from 25 feet		✓				✓	none	
3.4 Damage to the Access Road such as potholes, washouts or burrowing		✓				✓	none	
3.5 Cap perimeter survey monuments appear to be disturbed (Inspect every five years, in conjunction with the CERCLA Five Year Review for legibility and to confirm record locations)			✓			✓	not inspected this year	
4.0 LRCH and LS/LF Monitoring								
4.1 Erosion rills or gullies, or burrowing animal holes around the LRCH Buildings		✓				✓	none	
4.2 LS/LF Building secondary containment is damaged or not intact. Storage tanks are leaking.		✓				✓	none	
5.0 Groundwater Monitoring								
5.1 Damage to monitoring wells		✓				✓	none	
6.0 Surface Water Controls								
6.1 Impeded drainage or ponding in a channel or downchute		✓				✓	none	
6.2 Excessive siltation in a channel or downchute		✓				✓	none	
6.3 Debris present in a channel or downchute	✓				✓		Note 1.	

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE
	Y	N	N/A	Y	N	N/A		
6.4 Erosion rills or gullies in a channel or downchute		✓				✓	none	
6.5 Areas of degraded Articulated Concrete Block (ACB) or extensively cracked grout around ACB		✓				✓	none	
6.6 Subsidence or undercutting of the downchutes or perimeter drainage channels		✓				✓	none	
6.7 Damaged box culverts		✓				✓	none	

INSPECTION ITEM	EM-ELF01	EM-ELF02	EM-ELF03	EM-ELF04	EM-ELF05	EM-ELF06	EM-ELF07	EM-ELF08
7.0 Erosion/Settlement Monuments: <i>Inspect monuments for damage and legibility, and record the soil thickness loss, if any.</i>								
7.1 Was the monument free of damage and legible?	Y N	Y N	Y N	Y N	Y N	Y N	Y N	Y N
7.2 Measured Soil Thickness Loss (inches)	3	3	3	2.75	0	1.75	1.25	0.75

FORM SOP ELF 001-2
ELF CAP TYPE II INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations, and photographs, or attach as appropriate.

Note 1: Tumbleweeds have accumulated in channels and along some of the fence line. See attached figure for location information.

Inspector


Name: <u>King Hoffman</u>	Signature: <u>King Hoffman</u>	Date: <u>4-27-22</u>
---------------------------	--------------------------------	----------------------

Cover Manager Review of Inspection Documentation

Name: <u>Michael W. Jones</u>	Signature: <u>Michael W. Jones</u>	Date: <u>5/10/22</u>
-------------------------------	------------------------------------	----------------------

Cover Manager Confirmation of Completed Actions

Name:	Signature:	Date:
-------	------------	-------




LEGEND:

- UPPER VANTAGE PATHS FOR TYPE I AND TYPE II INSPECTIONS
- LOWER VANTAGE PATH FOR TYPE II INSPECTIONS
- - - PERIMETER FENCE/ARMY MAINTAINED AREA BOUNDARY
- == ROAD
- - - CHANNELS AND DOWNCHUTES
- ⊗ EM-ELF01 EROSION/SETTLEMENT MONUMENT
- △ SURVEY MONUMENTS
- ⊙ TRENCH DRAIN OUTFALL

tumble weed accumulation



 Program Manager Rocky Mountain Arsenal U.S. Army COMMITTED TO PROTECTION OF THE ENVIRONMENT		
ROCKY MOUNTAIN ARSENAL COMMERCE CITY, COLORADO		
NAVARRO Research and Engineering, Inc.		
PROJECT NAME ELF POST-CLOSURE PLAN		
TITLE LOCATION OF CAP FEATURES		
CAD FILE: FIG-SOP ELF 001-1.DWG	DATE 10.07.18	FIGURE NUMBER SOP ELF 001-1

This page intentionally left blank.

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman</u>				Inspection Date(s): <u>7-1-2021</u>				
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
	Y	N	N/A	Y	N	N/A		
1. Improper operation/condition of instrumentation and valves		✓				✓	<div style="transform: rotate(-45deg); transform-origin: center;"> 7-1-2021 JSH </div>	
2. Improper operation of leachate collection and leak detection pumps		✓				✓		
3. Excessive liquid in LRCHs or LS/LF.		✓				✓		
4. Blockage of leachate collection leak detection discharge piping		✓				✓		
5. Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
6. Flow meters or level indicators are malfunctioning.		✓				✓		
7. LS/LF tank levels are above high level set points.		✓				✓		
8. LS/LF tanks are damaged or leaking.		✓				✓		
9. Indication of leaks in the indoor piping system in the LRCHS or LS/LF.		✓				✓		
10. Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓		
11. Heating system in the LRCHs or LS/LF is malfunctioning.		✓				✓		

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations with GPS coordinates, and photographs, or attach as appropriate.

451 7-1-21

Inspector		
Name: Kim Hoffman	Signature: Kim Hoffman	Date: 7-1-21
Operations Engineer Review of Inspection Documentation		
Name: Michael W. Jones	Signature: Michael W. Jones	Date: 7/9/21
Operations Manager Review of Implementation		
Name: N/A	Signature: N/A	Date: N/A

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>K. Hoffman</u>						Inspection Date(s): <u>10-5-21</u>					
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other											
INSPECTION ITEM		CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)		
		Y	N	N/A	Y	N	N/A				
1	Improper operation/condition of instrumentation and valves		✓				✓	<div style="transform: rotate(-45deg); font-size: 2em; font-weight: bold;"> N/A 10-5-21 </div>			
2	Improper operation of leachate collection and leak detection pumps		✓				✓				
3	Excessive liquid in LRCHs or LS/LF.		✓				✓				
4	Blockage of leachate collection leak detection discharge piping		✓				✓				
5	Collapse of leachate collection or leak detection sump riser pipe		✓				✓				
6.	Flow meters or level indicators are malfunctioning.		✓				✓				
7.	LS/LF tank levels are above high level set points.		✓				✓				
8.	LS/LF tanks are damaged or leaking.		✓				✓				
9.	Indication of leaks in the indoor piping system in the LRCHS or LS/LF.		✓				✓				
10.	Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓				
11.	Heating system in the LRCHs or LS/LF is malfunctioning.		✓				✓				

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations with GPS coordinates, and photographs, or attach as appropriate.

461 10-5-21

Inspector		
Name: <u>Kim Hoffmann</u>	Signature: <u>[Signature]</u>	Date: <u>10-5-21</u>
Operations Engineer Review of Inspection Documentation		
Name: <u>Michael W. Jones</u>	Signature: <u>[Signature]</u>	Date: <u>10/8/21</u>
Operations Manager Review of Implementation		
Name: <u>N/A</u>	Signature: <u>N/A</u>	Date: <u>N/A</u>

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspector Name(s): <u>Kim Hoffman</u>								Inspection Date(s): <u>1-11-2022</u>	
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other									
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)	
	Y	N	N/A	Y	N	N/A			
1. Improper operation/condition of instrumentation and valves		✓				✓	<div style="transform: rotate(-45deg); font-size: 2em; font-weight: bold;">YES 1-11-22</div>		
2. Improper operation of leachate collection and leak detection pumps		✓				✓			
3. Excessive liquid in LRCHs or LS/LF.		✓				✓			
4. Blockage of leachate collection leak detection discharge piping		✓				✓			
5. Collapse of leachate collection or leak detection sump riser pipe		✓				✓			
6. Flow meters or level indicators are malfunctioning.		✓				✓			
7. LS/LF tank levels are above high level set points.		✓				✓			
8. LS/LF tanks are damaged or leaking.		✓				✓			
9. Indication of leaks in the indoor piping system in the LRCHS or LS/LF.		✓				✓			
10. Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓			
11. Heating system in the LRCHs or LS/LF is malfunctioning.		✓				✓			

**ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM
QUARTERLY INSPECTION FORM**

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations with GPS coordinates, and photographs, or attach as appropriate.

4501 1-11-22

Inspector

Name: King Hoffman

Signature: King Hoffman

Date: 1-11-22

Operations Engineer Review of Inspection Documentation

Name: Michael W. Jones

Signature: Michael W. Jones

Date: 1/27/22

Operations Manager Review of Implementation

Name: N/A

Signature: N/A

Date: N/A

**ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM
QUARTERLY INSPECTION FORM**

Inspector Name(s): <u>Kim Hoffman</u>				Inspection Date(s): <u>4-5-22</u>				
Attachments: <input type="checkbox"/> Photographs <input type="checkbox"/> Figures <input type="checkbox"/> Other								
INSPECTION ITEM	CONDITION IS PRESENT			REPEAT OR CHRONIC CONDITION			OBSERVATION Indicate recommended action, if required.	CONFIRMATION THAT ACTION IS COMPLETE (Signature and Date)
	Y	N	N/A	Y	N	N/A		
1. Improper operation/condition of instrumentation and valves		✓				✓	YES 4-5-22	
2. Improper operation of leachate collection and leak detection pumps		✓				✓		
3. Excessive liquid in LRCHs or LS/LF.		✓				✓		
4. Blockage of leachate collection leak detection discharge piping		✓				✓		
5. Collapse of leachate collection or leak detection sump riser pipe		✓				✓		
6. Flow meters or level indicators are malfunctioning.	✓				✓		W/LCS level probe malfunctioning - sent to R	Probe was replaced in April 2022. MH 5/18/22
7. LS/LF tank levels are above high level set points.		✓				✓	YES 4-5-22	
8. LS/LF tanks are damaged or leaking.		✓				✓		
9. Indication of leaks in the indoor piping system in the LRCHS or LS/LF.		✓				✓		
10. Indication that the LS/LF secondary containment is damaged or inadequate.		✓				✓		
11. Heating system in the LRCHs or LS/LF is malfunctioning.		✓				✓		

ELF LCS/LDS AND WASTEWATER CONVEYANCE SYSTEM QUARTERLY INSPECTION FORM

Inspection Notes: For areas with deficiencies, provide identifying labels for deficient areas, descriptions of deficiencies, approximate dimensions of the areas, locations with GPS coordinates, and photographs, or attach as appropriate.

yes 4-5-22



Inspector		
Name: <i>Kim Hoffmann</i>	Signature: <i>Kim Hoffmann</i>	Date: <i>4-5-22</i>
Operations Engineer Review of Inspection Documentation		
Name: <i>Michael W. Jones</i>	Signature: <i>Michael W. Jones</i>	Date: <i>4/6/22</i>
Operations Manager Review of Implementation		
Name: <i>Michael W. Jones</i>	Signature: <i>Michael W. Jones</i>	Date: <i>5/19/22</i>

APPENDIX C-1



HWL Maintenance Documentation

This page intentionally left blank.



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: HWL O&M
Task: maintenance	Date: 6-1-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel performed a drive around post-storm inspection due to the RMA receiving 1.13" of rain on 5-30-21. No observations were made.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8-17-21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: HWL O&M
Task: maintenance	Date: 7-14-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel spot sprayed Canada thistle on and around the HWL using the herbicides Rifle-D and Milestone.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: HWL O&M
Task: maintenance	Date: 8-5-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
<p>OMC personnel mowed tall weedy vegetation at the toe of the north slope and on the west support areas of the HWL. OMC used a John Deere tractor and batwing mower borrowed from the USFWS.</p>	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: Weed Wranglers	Project: HWL O&M
Task: maintenance	Date: 10-25-21
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
Weed Wranglers was onsite to spray Plainview SC® as a ground clear treatment at the HWL. Roadways, around wells, and other working surfaces were sprayed.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21

CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: HWL O&M
Task: maintenance	Date: 11-3-21
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
<p>OMC personnel used the hairy golden aster seed harvested from onsite to seed poorly established areas on the HWL. The top corners of the four downchutes, the southwest support area, and the south slope below the ACB terrace channel were broadcast seeded by hand.</p>	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21

**CONTRACTOR DAILY QUALITY CONTROL REPORT**

Project Information	
Subcontractor: N/A	Project: HWL O&M
Task: maintenance	Date: 3-30-22
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel mowed tumbleweeds on the north perimeter road. This road was inaccessible due to the tumbleweed accumulation. OMC used a John Deere tractor and batwing mower borrowed from the USFWS.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Caps and Covers Lead/Navarro
Signature: 	Date: 5-18-22
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 5/19/22

**Landfill Wastewater Treatment System
Operations and Maintenance Report
Beginning Date 05/01/2021 Ending Date 04/30/2022**

Date	Start of Down Time	Plant Down Time (Hrs)	Summary of Significant Events
05/12/2021		0.00	Pumped Lift Station to LT402. The Samplers sampled HWL LCS1 and LCS4 on 5-11-21 and the Lift Station was at High Level. Lift Station started at 6.7 feet and ended at 4.9 feet. LT402 started at 40.5 inches and ended at 79.0 inches. The lab received the samples so HWL LCS1 and LCS4 were pumped to Low Level. The Lift Station started at 4.9 feet and ended at 5.8 feet. LCS1 started at 21.5 inches and ended at 13.1 inches. LCS4 started at 26.9 inches and ended at 11.6 inches. LT402 started at 78.9 inches and ended at 105.5 inches. LT401 started at 10.5 inches and ended at 58.1 inches. init:kh
05/13/2021		0.00	Pumped Lift Station to LT401. Lift station started at 5.9 feet and ended at 3.6 feet. LT401 started at 58.1 inches and ended at 103.0 inches. init:kh
05/20/2021		0.00	Clean Harbors was onsite to remove leachate from LT402. LT402 started at 105.0 inches and ended at 11.4 inches. Approximately 4,708 gallons of leachate was removed for offsite disposal. init:kh
05/24/2021		0.00	Clean Harbors was onsite to remove leachate from LT401. LT 401 started at 101.7 inches and ended at 10.5 inches. Approximately 4,587 gallons of leachate was removed for offsite disposal. init:kh
06/30/2021		0.00	Replaced level probe in ELF WP LDS1. init:kh
08/10/2021		0.00	Pumped HWL LCS2 to LT401. LCS2 hit High Level and was sampled on 8-3-21. LT401 started at 10.0 inches and ended at 42.8 inches. Lift Station started at 4.2 feet and ended at 3.9 feet. LCS2 started at 29.4 inches and ended at 8.4 inches. init:kh
08/25/2021		0.00	Reset GFI on HWL LDS4. init:kh
10/19/2021		0.00	Pumped HWL LCS1 and LDS4 to LT401. These sumps reached High Level and were sampled on 10-12-21. Lift Station started at 5.3 feet and ended at 3.7 feet. LT401 started at 42.5 inches and ended at 102.5 inches. LCS1 started at 28.4 inches and ended at 13.0 inches. LDS4 started at 14.9 inches and ended at 10.5 inches. init:kh
10/27/2021		0.00	Clean Harbors was onsite to remove leachate from LT401. LT 401 started at 101.9 inches and ended at 10.3 inches. Approximately 4,607 gallons of leachate was removed for offsite disposal. init:kh
12/09/2021		0.00	Pumped HWL LCS2 and LDS2 to low level after high level sampling event performed on 12-1-21. Lift Station started at 4.4 feet and ended at 3.2 feet. LCS2 started at 28.7 inches and ended at 9.6 inches. LDS2 started at 18.4 inches and ended at 10.5 inches. LT401 started at 10.0 inches and ended at 72.8 inches. init:kh
02/10/2022		0.00	OMC maintenance personnel investigated the leak protection at the HWL. There were a couple of bad connectors due to moisture being introduced. These connectors were repaired. init:kh

**Landfill Wastewater Treatment System
Operations and Maintenance Report
Beginning Date 05/01/2021 Ending Date 04/30/2022**



Date	Start of Down Time	Plant Down Time (Hrs)	Summary of Significant Events
02/24/2022		0.00	Pumped HWL LCS1 and LCS4 to low level after high level sampling event. LT401 started at 72.9" and ended at 105.2". LT402 started at 11.2" and ended at 65.9". LCS1 started at 24.4" and ended at 13.0". LCS4 started at 27.3" and ended at 11.1". Lift Station started at 5.1 feet and ended at 5.7 feet. init:kh
02/28/2022		0.00	Heater 1 failed at Lift Station panel and tripped the main panel breaker. Shut off heater circuit and restored panel to breaker. init:kh
03/01/2022		0.00	Pumped Lift Station to LT402. Lift Station started at 5.7 feet and ended at 3.9 feet. LT402 started at 65.7 in and ended at 103.8 in. Clean Harbors removed leachate for offsite disposal. LT402 started at 103.8 in and ended at 11.2 in. Approximately 4,658 gallons of leachate were removed. init:kh
03/02/2022		0.00	Clean Harbors removed leachate for offsite disposal. LT401 started at 104.7" and ended at 13.1". Approximately 4,607 gallons were removed. init:kh
03/24/2022		0.00	Replaced a heater at the Lift Station panel that went faulty in February 2022. init:kh
04/06/2022		0.00	Pumped HWL LCS2 to low level after high level sampling event. LCS2 started at 24.7" and ended at 8.7". Lift Station started at 4.9 feet and ended at 4.5 feet. LT401 started at 12.8" and ended at 39.8". init:kh
04/18/2022		0.00	Installed a new level probe in ELF WP LCS1. The probe read 0.1 to 0.3" and the pump was dry when it was pulled out of the sump. init:kh
04/20/2022		0.00	Pumped HWL LDS1 and LDS3 to low level after high level sampling event. LDS1 started at 17.1" and ended at 10.0". LDS3 started at 14.9" and ended at 9.6". Lift Station started at 5.1 feet and ended at 3.1 feet. LT401 started at 39.6" and ended at 85.7". init:kh
Total Down Time Hours:		0.00	

APPENDIX C-2



ELF Maintenance Documentation

This page intentionally left blank.



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 6-1-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel performed a drive around post-storm inspection due to the RMA receiving 1.13" of rain on 5-30-21. No observations were made.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 7-14-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel spot sprayed Canada thistle on and around the ELF using the herbicides Rifle-D and Milestone.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 7-20-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel used soil from the Long Term Stockpile to repair the sinkholes identified in the ELF east perimeter channel during the spring Type II 2021 inspection.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8/17/21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 7-28-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
<p>OMC personnel used a walk behind mower with bag to collect golden hairy aster seed from the west side of Building 130. This area was sprayed with Esplanade last fall to ensure a weed free seed harvest. This seed is intended to be spread on the ELF in the fall of 2021.</p>	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8-17-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 8-5-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel mowed tall weedy vegetation on the east support areas of the ELF and around the perimeter road. OMC used a John Deere tractor and batwing mower borrowed from the USFWS.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 8/17/21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 8/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: Overhead Door Company	Project: ELF O&M
Task: maintenance	Date: 8-24-2021
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
Overhead Door Company was onsite to replace the weather stripping on the LSLF garage door. Stormwater was entering the building and this maintenance activity will potentially prevent precipitation collecting inside the building.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21



CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: Weed Wranglers	Project: ELF O&M
Task: maintenance	Date: 10-25-21
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
Weed Wranglers was onsite to spray Plainview SC® as a ground clear treatment at the ELF. Roadways, around wells, and other working surfaces were sprayed.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21

CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 11-3-21
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
<p>OMC personnel used the hairy golden aster seed harvested from onsite to seed poorly established areas on the ELF. The top corners of the four downchutes, the west and south slopes above the ACB terrace channel, and outside of the southeast perimeter channel were broadcast seeded by hand.</p>	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21

CONTRACTOR DAILY QUALITY CONTROL REPORT

Project Information	
Subcontractor: N/A	Project: ELF O&M
Task: maintenance	Date: 12-2-21
Weather AM: acceptable field conditions	Weather PM: acceptable field conditions
Activities Inspected and Observed:	
OMC personnel used the tumble weed fence cleaner to remove tumble weeds from the west, south, and east interior perimeter fence. The exterior west perimeter fence was also cleaned.	
Summary Meetings and Discussions Held or Attended, including Job Safety:	
N/A	
Comments:	
N/A	
Additional Documentation Submitted:	
N/A	
Sign Off:	
Inspector Name: Kim Hoffman	Title/company: Site Inspector/CDM Smith
Signature: 	Date: 12-16-21
Reviewer Name: Mike Jones	Title/company: Caps and Covers Manager/Navarro
Signature: 	Date: 12/17/21

This page intentionally left blank.

**Landfill Wastewater Treatment System
Operations and Maintenance Report
Beginning Date 05/01/2021 Ending Date 04/30/2022**

Date	Start of Down Time	Plant Down Time (Hrs)	Summary of Significant Events
05/12/2021		0.00	Pumped Lift Station to LT402. The Samplers sampled HWL LCS1 and LCS4 on 5-11-21 and the Lift Station was at High Level. Lift Station started at 6.7 feet and ended at 4.9 feet. LT402 started at 40.5 inches and ended at 79.0 inches. The lab received the samples so HWL LCS1 and LCS4 were pumped to Low Level. The Lift Station started at 4.9 feet and ended at 5.8 feet. LCS1 started at 21.5 inches and ended at 13.1 inches. LCS4 started at 26.9 inches and ended at 11.6 inches. LT402 started at 78.9 inches and ended at 105.5 inches. LT401 started at 10.5 inches and ended at 58.1 inches. init:kh
05/13/2021		0.00	Pumped Lift Station to LT401. Lift station started at 5.9 feet and ended at 3.6 feet. LT401 started at 58.1 inches and ended at 103.0 inches. init:kh
05/20/2021		0.00	Clean Harbors was onsite to remove leachate from LT402. LT402 started at 105.0 inches and ended at 11.4 inches. Approximately 4,708 gallons of leachate was removed for offsite disposal. init:kh
05/24/2021		0.00	Clean Harbors was onsite to remove leachate from LT401. LT 401 started at 101.7 inches and ended at 10.5 inches. Approximately 4,587 gallons of leachate was removed for offsite disposal. init:kh
06/30/2021		0.00	Replaced level probe in ELF WP LDS1. init:kh
08/10/2021		0.00	Pumped HWL LCS2 to LT401. LCS2 hit High Level and was sampled on 8-3-21. LT401 started at 10.0 inches and ended at 42.8 inches. Lift Station started at 4.2 feet and ended at 3.9 feet. LCS2 started at 29.4 inches and ended at 8.4 inches. init:kh
08/25/2021		0.00	Reset GFI on HWL LDS4. init:kh
10/19/2021		0.00	Pumped HWL LCS1 and LDS4 to LT401. These sumps reached High Level and were sampled on 10-12-21. Lift Station started at 5.3 feet and ended at 3.7 feet. LT401 started at 42.5 inches and ended at 102.5 inches. LCS1 started at 28.4 inches and ended at 13.0 inches. LDS4 started at 14.9 inches and ended at 10.5 inches. init:kh
10/27/2021		0.00	Clean Harbors was onsite to remove leachate from LT401. LT 401 started at 101.9 inches and ended at 10.3 inches. Approximately 4,607 gallons of leachate was removed for offsite disposal. init:kh
12/09/2021		0.00	Pumped HWL LCS2 and LDS2 to low level after high level sampling event performed on 12-1-21. Lift Station started at 4.4 feet and ended at 3.2 feet. LCS2 started at 28.7 inches and ended at 9.6 inches. LDS2 started at 18.4 inches and ended at 10.5 inches. LT401 started at 10.0 inches and ended at 72.8 inches. init:kh
02/10/2022		0.00	OMC maintenance personnel investigated the leak protection at the HWL. There were a couple of bad connectors due to moisture being introduced. These connectors were repaired. init:kh

**Landfill Wastewater Treatment System
Operations and Maintenance Report
Beginning Date 05/01/2021 Ending Date 04/30/2022**

Date	Start of Down Time	Plant Down Time (Hrs)	Summary of Significant Events
02/24/2022		0.00	Pumped HWL LCS1 and LCS4 to low level after high level sampling event. LT401 started at 72.9" and ended at 105.2". LT402 started at 11.2" and ended at 65.9". LCS1 started at 24.4" and ended at 13.0". LCS4 started at 27.3" and ended at 11.1". Lift Station started at 5.1 feet and ended at 5.7 feet. init:kh
02/28/2022		0.00	Heater 1 failed at Lift Station panel and tripped the main panel breaker. Shut off heater circuit and restored panel to breaker. init:kh
03/01/2022		0.00	Pumped Lift Station to LT402. Lift Station started at 5.7 feet and ended at 3.9 feet. LT402 started at 65.7 in and ended at 103.8 in. Clean Harbors removed leachate for offsite disposal. LT402 started at 103.8 in and ended at 11.2 in. Approximately 4,658 gallons of leachate were removed. init:kh
03/02/2022		0.00	Clean Harbors removed leachate for offsite disposal. LT401 started at 104.7" and ended at 13.1". Approximately 4,607 gallons were removed. init:kh
03/24/2022		0.00	Replaced a heater at the Lift Station panel that went faulty in February 2022. init:kh
04/06/2022		0.00	Pumped HWL LCS2 to low level after high level sampling event. LCS2 started at 24.7" and ended at 8.7". Lift Station started at 4.9 feet and ended at 4.5 feet. LT401 started at 12.8" and ended at 39.8". init:kh
04/18/2022		0.00	Installed a new level probe in ELF WP LCS1. The probe read 0.1 to 0.3" and the pump was dry when it was pulled out of the sump. init:kh
04/20/2022		0.00	Pumped HWL LDS1 and LDS3 to low level after high level sampling event. LDS1 started at 17.1" and ended at 10.0". LDS3 started at 14.9" and ended at 9.6". Lift Station started at 5.1 feet and ended at 3.1 feet. LT401 started at 39.6" and ended at 85.7". init:kh
Total Down Time Hours:		0.00	

APPENDIX D

HWL and ELF Erosion/Settlement Monument Survey Data

This page intentionally left blank.

CHANGE IN HWL EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					SPRING 2010 SURVEY				FALL 2010 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 4/09/10				Date of survey: 9/30/10				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	A12943	189774.1	2185140.6	5298.0	Ahwlem1	189774.1	2185140.5	5297.9	0.2	-0.2	-0.1	0.0	-0.1	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	A12944	189637.2	2184809.8	5302.5	Ahwlem2	189637.2	2184809.8	5302.4	-0.1	0.0	-0.1	-0.1	0.1	-0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	A12936	189626.0	2185058.0	5307.7	Ahwlem3	189626.0	2185058.1	5307.7	0.1	0.1	-0.1	0.0	0.1	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	A12937	189570.7	2185177.9	5301.6	Ahwlem4	189570.7	2185177.9	5301.6	0.1	0.0	-0.2	0.0	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	A12942	189342.4	2184932.0	5311.5	Ahwlem5	189342.4	2184931.9	5311.4	0.2	-0.1	-0.1	0.0	-0.1	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	A12938	189355.9	2185079.9	5309.1	Ahwlem6	189356.0	2185079.9	5309.1	0.2	-0.1	-0.1	0.0	0.0	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	A12941	189150.6	2184866.4	5309.9	Ahwlem7	189150.6	2184866.4	5309.8	-0.4	-0.3	-0.1	0.0	0.0	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	A12939	189192.2	2185133.8	5308.0	Ahwlem8	189192.2	2185133.8	5308.0	0.3	-0.1	-0.1	0.0	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	A12940	189037.2	2184990.3	5306.8	Ahwlem9	189037.3	2184990.3	5306.8	0.0	-0.1	-0.1	0.0	0.0	0.0

RECORD CONDITION SURVEY					FALL 2010 SURVEY				SPRING 2011 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 9/30/10				Date of survey: 4/24/11				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	Ahwlem1	189774.1	2185140.5	5297.9	a1015	189774.1	2185140.6	5297.9	0.2	-0.1	-0.2	0.0	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	Ahwlem2	189637.2	2184809.8	5302.4	a1016	189637.2	2184809.8	5302.4	-0.1	0.0	-0.1	0.0	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	Ahwlem3	189626.0	2185058.1	5307.7	a1014	189626.0	2185058.0	5307.6	0.1	0.0	-0.1	0.1	-0.1	-0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	Ahwlem4	189570.7	2185177.9	5301.6	a1013	189570.6	2185177.9	5301.6	0.1	0.0	-0.2	-0.1	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	Ahwlem5	189342.4	2184931.9	5311.4	a1010	189342.3	2184931.9	5311.4	0.1	-0.1	-0.1	0.0	0.0	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	Ahwlem6	189356.0	2185079.9	5309.1	a1011	189356.0	2185079.9	5309.1	0.2	-0.1	-0.1	0.0	0.0	-0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	Ahwlem7	189150.6	2184866.4	5309.8	a1009	189150.7	2184866.4	5309.9	-0.4	-0.4	-0.1	0.0	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	Ahwlem8	189192.2	2185133.8	5308.0	a1012	189192.3	2185133.8	5307.9	0.4	-0.1	-0.1	0.0	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	Ahwlem9	189037.3	2184990.3	5306.8	a1008	189037.2	2184990.3	5306.8	0.0	-0.2	-0.1	0.0	-0.1	0.0

RECORD CONDITION SURVEY					SPRING 2011 SURVEY				FALL 2011 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 4/24/11				Date of survey: 10/12/11				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	a1015	189774.1	2185140.6	5297.9	9	189774.0	2185140.6	5297.9	0.1	-0.1	-0.2	-0.1	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	a1016	189637.2	2184809.8	5302.4	10	189637.2	2184809.8	5302.4	-0.1	0.0	-0.2	0.0	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	a1014	189626.0	2185058.0	5307.6	7	189625.9	2185058.0	5307.5	0.1	0.0	-0.2	-0.1	0.0	-0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	a1013	189570.6	2185177.9	5301.6	8	189570.6	2185177.8	5301.5	0.1	-0.1	-0.2	0.0	0.0	-0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	a1010	189342.4	2184931.9	5311.4	6	189342.4	2184931.9	5311.3	0.1	-0.1	-0.2	0.0	0.1	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	a1011	189356.0	2185079.9	5309.1	5	189355.9	2185079.9	5309.1	0.1	-0.1	-0.1	-0.1	0.0	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	a1009	189150.6	2184866.4	5309.9	2	189150.6	2184866.4	5309.8	-0.4	-0.3	-0.2	0.0	0.0	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	a1012	189192.3	2185133.8	5307.9	4	189192.2	2185133.7	5307.9	0.3	-0.2	-0.1	-0.1	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	a1008	189037.2	2184990.3	5306.8	3	189037.2	2184990.3	5306.8	0.0	-0.2	-0.1	0.0	0.0	0.0

RECORD CONDITION SURVEY					FALL 2011 SURVEY				Spring 2012 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 10/12/11				Date of survey: 5/09/12				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	9	189774.0	2185140.6	5297.9	4322	189774.1	2185140.6	5297.9	0.2	-0.1	-0.2	0.1	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	10	189637.2	2184809.8	5302.4	4320	189637.2	2184809.8	5302.4	-0.1	0.0	-0.2	0.0	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	7	189625.9	2185058.0	5307.5	4321	189626.0	2185058.0	5307.6	0.1	0.0	-0.1	0.1	0.0	0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	8	189570.6	2185177.8	5301.5	4323	189570.6	2185177.8	5301.6	0.1	-0.1	-0.2	0.0	0.0	0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	6	189342.4	2184931.9	5311.3	4319	189342.4	2184931.9	5311.4	0.1	-0.1	-0.1	0.0	0.0	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	5	189355.9	2185079.9	5309.1	4324	189356.0	2185079.8	5309.1	0.2	-0.2	-0.1	0.1	-0.1	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	2	189150.6	2184866.4	5309.8	4318	189150.7	2184866.4	5309.8	-0.3	-0.3	-0.2	0.1	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	4	189192.2	2185133.7	5307.9	4325	189192.2	2185133.7	5307.9	0.3	-0.2	-0.1	0.0	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	3	189037.2	2184990.3	5306.8	4317	189037.2	2184990.3	5306.7	0.0	-0.2	-0.2	0.0	0.0	-0.1

RECORD CONDITION SURVEY					Spring 2012 SURVEY				Fall 2012 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 5/09/12				Date of survey: 9/20/12				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	4322	189774.1	2185140.6	5297.9	n1017	189774.1	2185140.5	5297.9	0.2	-0.2	-0.2	0.0	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	4320	189637.2	2184809.8	5302.4	n1018	189637.3	2184809.8	5302.3	-0.1	-0.1	-0.2	0.0	-0.1	-0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	4321	189626.0	2185058.0	5307.6	n1016	189626.0	2185058.0	5307.5	0.1	0.0	-0.3	0.0	0.0	-0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	4323	189570.6	2185177.8	5301.6	n1015	189570.6	2185177.8	5301.5	0.1	-0.1	-0.3	0.0	0.0	-0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	4319	189342.4	2184931.9	5311.4	n1014	189342.4	2184931.9	5311.3	0.2	-0.1	-0.2	0.1	0.0	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	4324	189356.0	2185079.8	5309.1	n1013	189356.0	2185079.8	5309.0	0.2	-0.2	-0.2	0.0	0.0	-0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	4318	189150.7	2184866.4	5309.8	n1010	189150.7	2184866.4	5309.7	-0.3	-0.4	-0.2	0.0	0.0	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	4325	189192.2	2185133.7	5307.9	n1012	189192.3	2185133.7	5307.8	0.4	-0.2	-0.2	0.1	0.0	-0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	4317	189037.2	2184990.3	5306.7	n1011	189037.3	2184990.3	5306.7	0.1	-0.2	-0.2	0.1	0.0	0.0

CHANGE IN HWL EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Fall 2012 SURVEY				Spring 2013 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 9/20/12				Date of survey: 5/07/13				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	n1017	189774.1	2185140.5	5297.9	EM01	189774.1	2185140.6	5297.8	0.2		-0.1		-0.3	
EM-HWL02	A12274	189637.3	2184809.8	5302.5	n1018	189637.3	2184809.8	5302.3	EM02	189637.2	2184809.8	5302.3	-0.1		0.0		-0.2	
EM-HWL03	A12275	189625.9	2185058.0	5307.8	n1016	189626.0	2185058.0	5307.5	EM03	189626.0	2185058.0	5307.5	0.1		0.0		-0.2	
EM-HWL04	A12277	189570.5	2185177.9	5301.8	n1015	189570.6	2185177.8	5301.5	EM04	189570.6	2185177.8	5301.5	0.1		-0.1		-0.3	
EM-HWL05	A12279	189342.2	2184932.0	5311.5	n1014	189342.4	2184931.9	5311.3	EM05	189342.4	2184931.9	5311.3	0.2		-0.1		-0.2	
EM-HWL06	A12278	189355.8	2185080.0	5309.2	n1013	189356.0	2185079.8	5309.0	EM06	189356.0	2185079.9	5309.0	0.2		-0.1		-0.2	
EM-HWL07	A12280	189151.0	2184866.7	5310.0	n1010	189150.7	2184866.4	5309.7	EM07	189150.7	2184866.4	5309.7	-0.3		-0.3		-0.2	
EM-HWL08	A12281	189191.9	2185133.9	5308.0	n1012	189192.3	2185133.7	5307.8	EM08	189192.3	2185133.8	5307.8	0.4		-0.1		-0.2	
EM-HWL09	A12282	189037.2	2184990.5	5306.9	n1011	189037.3	2184990.3	5306.7	EM09	189037.3	2184990.3	5306.7	0.0		-0.2		-0.2	

RECORD CONDITION SURVEY					Spring 2013 SURVEY				Fall 2013 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 5/07/13				Date of survey: 9/19/13				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.6	5297.8	EM01	189774.1	2185140.6	5297.8	0.2		-0.1		-0.3	
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.8	5302.3	EM02	189637.3	2184809.8	5302.3	-0.1		-0.1		-0.3	
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.0	5307.5	EM03	189626.0	2185058.0	5307.5	0.1		0.0		-0.3	
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185177.8	5301.5	EM04	189570.7	2185177.8	5301.4	0.2		-0.1		-0.3	
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184931.9	5311.3	EM05	189342.4	2184931.9	5311.3	0.2		-0.1		-0.3	
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185079.9	5309.0	EM06	189356.0	2185079.9	5309.0	0.2		-0.2		-0.2	
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.4	5309.7	EM07	189150.7	2184866.4	5309.7	-0.4		-0.4		-0.2	
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.3	2185133.8	5307.8	EM08	189192.2	2185133.7	5307.8	0.3		-0.2		-0.2	
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.3	2184990.3	5306.7	EM09	189037.3	2184990.3	5306.7	0.1		-0.2		-0.2	

RECORD CONDITION SURVEY					Fall 2013 SURVEY				Spring 2014 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 9/19/13				Date of survey: 5/29/14				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.6	5297.8	EM01	189774.1	2185140.7	5297.7	0.3		0.0		-0.4	
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.3	2184809.8	5302.3	EM02	189637.3	2184809.9	5302.2	0.0		0.1		-0.3	
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.0	5307.5	EM03	189626.0	2185058.2	5307.4	0.2		0.2		-0.3	
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185177.8	5301.4	EM04	189570.7	2185178.0	5301.4	0.2		0.1		-0.4	
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184931.9	5311.3	EM05	189342.4	2184932.1	5311.3	0.2		0.1		-0.2	
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185079.9	5309.0	EM06	189356.0	2185080.0	5308.9	0.2		0.0		-0.3	
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.4	5309.7	EM07	189150.7	2184866.6	5309.6	-0.3		-0.2		-0.4	
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.7	5307.8	EM08	189192.3	2185133.9	5307.7	0.4		0.0		-0.3	
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.3	2184990.3	5306.7	EM09	189037.3	2184990.4	5306.6	0.1		0.0		-0.3	

RECORD CONDITION SURVEY					Spring 2014 SURVEY				Fall 2014 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 5/29/14				Date of survey: 10/17/14				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.7	EM01	189774.1	2185140.7	5297.8	0.2		0.0		-0.3	
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.3	2184809.9	5302.2	EM02	189637.2	2184809.9	5302.3	-0.1		0.1		-0.2	
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.4	EM03	189626.0	2185058.1	5307.4	0.1		0.2		-0.3	
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185178.0	5301.4	EM04	189570.6	2185178.0	5301.4	0.1		0.1		-0.4	
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.3	EM05	189342.4	2184932.1	5311.3	0.1		0.1		-0.3	
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185080.0	5308.9	EM06	189355.9	2185080.0	5308.9	0.1		0.0		-0.3	
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.6	5309.6	EM07	189150.6	2184866.5	5309.7	-0.4		-0.2		-0.3	
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.8	EM08	189192.2	2185133.9	5307.8	0.3		0.0		-0.2	
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.3	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.6	0.0		-0.1		-0.2	

RECORD CONDITION SURVEY					Fall 2014 SURVEY				Spring 2015 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 10/17/14				Date of survey: 5/29/15				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.8	EM01	189774.1	2185140.7	5297.8	0.3		0.1		-0.2	
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.3	EM02	189637.3	2184809.9	5302.2	0.0		0.1		-0.3	
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.1	5307.4	EM03	189626.0	2185058.2	5307.4	0.1		0.2		-0.3	
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.4	EM04	189570.7	2185178.0	5301.5	0.2		0.1		-0.3	
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.3	EM05	189342.4	2184932.1	5311.3	0.2		0.1		-0.3	
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185080.0	5308.9	EM06	189356.0	2185080.0	5309.0	0.2		0.0		-0.2	
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.5	5309.7	EM07	189150.7	2184866.5	5309.7	-0.3		-0.2		-0.2	
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.8	EM08	189192.2	2185133.9	5307.8	0.3		0.0		-0.2	
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.7	0.0		-0.1		-0.2	

CHANGE IN HWL EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Spring 2015 SURVEY				Fall 2015 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 5/29/15				Date of survey: 12/9/15				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.8	EM01	189774.1	2185140.7	5297.7	0.3	0.0	-0.4	0.0	0.0	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.3	2184809.9	5302.2	EM02	189637.3	2184809.9	5302.2	0.0	0.1	-0.3	0.0	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.4	EM03	189626.1	2185058.2	5307.4	0.2	0.2	-0.4	0.0	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185178.0	5301.5	EM04	189570.7	2185178.0	5301.3	0.1	0.1	-0.5	0.0	0.0	-0.2
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.3	EM05	189342.4	2184932.1	5311.1	0.2	0.1	-0.4	0.0	0.0	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185080.0	5309.0	EM06	189356.0	2185080.0	5308.8	0.2	0.0	-0.4	0.0	0.0	-0.2
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.5	5309.7	EM07	189150.7	2184866.5	5309.6	-0.3	-0.2	-0.4	0.0	0.0	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.8	EM08	189192.3	2185133.9	5307.6	0.4	0.0	-0.4	0.0	0.0	-0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.7	EM09	189037.3	2184990.4	5306.6	0.1	0.0	-0.3	0.1	0.0	-0.1

RECORD CONDITION SURVEY					Fall 2015 SURVEY				Spring 2016 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 12/9/15				Date of survey: 6/20/16				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.7	EM01	189774.1	2185140.7	5297.7	0.2	0.0	-0.3	0.0	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.3	2184809.9	5302.2	EM02	189637.2	2184809.9	5302.2	-0.1	0.1	-0.4	-0.1	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.1	2185058.2	5307.4	EM03	189626.0	2185058.2	5307.5	0.1	0.2	-0.3	-0.1	0.0	0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185178.0	5301.3	EM04	189570.7	2185178.0	5301.4	0.1	0.1	-0.4	0.0	0.0	0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.1	EM05	189342.4	2184932.1	5311.3	0.2	0.1	-0.2	-0.1	0.0	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185080.0	5308.8	EM06	189356.0	2185079.9	5308.9	0.2	-0.1	-0.3	0.0	-0.1	0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.7	2184866.5	5309.6	EM07	189150.7	2184866.5	5309.7	-0.3	-0.2	-0.3	0.0	0.0	0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.6	EM08	189192.2	2185133.9	5307.7	0.3	0.0	-0.3	-0.1	0.0	0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.3	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.6	0.0	0.0	-0.3	-0.1	0.0	0.1

RECORD CONDITION SURVEY					Spring 2016 SURVEY				Fall 2016 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 6/20/16				Date of survey: 1/18/17				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.7	EM01	189774.1	2185140.6	5297.7	0.2	0.0	-0.4	0.0	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.2	2184809.9	5302.2	-0.1	0.1	-0.3	0.0	0.0	0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.5	EM03	189626.0	2185058.1	5307.5	0.1	0.1	-0.3	0.0	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185178.0	5301.4	EM04	189570.6	2185178.0	5301.4	0.1	0.1	-0.4	0.0	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.3	EM05	189342.4	2184932.0	5311.2	0.2	0.0	-0.3	0.0	0.0	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185079.9	5308.9	EM06	189355.9	2185080.0	5308.9	0.1	0.0	-0.3	-0.1	0.0	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.7	EM07	189150.6	2184866.5	5309.6	-0.4	-0.2	-0.3	0.0	0.0	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.7	0.3	0.0	-0.3	0.0	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.6	-0.1	-0.1	-0.3	0.0	0.0	0.0

RECORD CONDITION SURVEY					Fall 2016 SURVEY				Spring 2017 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 6/20/16				Date of survey: 5/17/17				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.6	5297.7	EM01	189774.1	2185140.7	5297.7	0.2	0.0	-0.4	0.0	0.1	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.3	2184810.0	5302.2	0.0	0.1	-0.3	0.1	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.1	5307.5	EM03	189626.0	2185058.2	5307.4	0.1	0.2	-0.4	0.1	0.1	-0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.4	EM04	189570.7	2185178.1	5301.3	0.1	0.2	-0.5	0.1	0.1	-0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.0	5311.2	EM05	189342.4	2184932.1	5311.3	0.2	0.1	-0.3	0.0	0.0	0.0
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189356.0	2185080.0	5308.9	0.2	0.0	-0.3	0.1	0.1	-0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.9	2184866.4	5309.5	-0.1	-0.3	-0.4	0.3	-0.1	-0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.7	0.4	0.0	-0.3	0.0	0.1	-0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.5	5306.5	0.0	0.0	-0.3	0.1	0.1	-0.1

RECORD CONDITION SURVEY					Spring 2017 SURVEY				Fall 2017 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 5/17/17				Date of survey: 11/10/17				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA N	DELTA E	DELTA EL	DELTA N	DELTA E	DELTA EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.7	EM01	189774.1	2185140.7	5297.7	0.2	0.0	-0.4	0.0	-0.1	0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.3	2184810.0	5302.2	EM02	189637.2	2184809.9	5302.2	-0.1	0.1	-0.3	0.0	-0.1	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.4	EM03	189626.0	2185058.1	5307.4	0.1	0.1	-0.3	0.0	-0.1	0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.7	2185178.1	5301.3	EM04	189570.6	2185178.0	5301.4	0.1	0.1	-0.3	-0.1	-0.1	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.1	5311.3	EM05	189342.4	2184932.0	5311.2	0.2	0.0	-0.3	0.0	-0.1	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189356.0	2185080.0	5308.9	EM06	189355.9	2185080.0	5308.9	0.2	-0.1	-0.3	0.0	-0.1	0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.9	2184866.5	5309.5	EM07	189150.7	2184866.5	5309.6	-0.3	-0.2	-0.4	-0.3	0.1	0.1
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.8	0.3	0.0	-0.3	0.0	-0.1	0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.5	5306.5	EM09	189037.3	2184990.4	5306.6	0.0	-0.1	-0.3	0.0	-0.1	0.0

CHANGE IN HWL EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Fall 2017 SURVEY				Spring 2018 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 11/10/17				Date of survey: 06/18/18				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.7	5297.7	EM01	189774.1	2185140.7	5297.7	0.2		0.0	-0.3	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.1	2184810.0	5302.2	-0.2		0.1	-0.3	-0.1	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.1	5307.4	EM03	189626.0	2185058.2	5307.4	0.1		0.2	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.4	EM04	189570.6	2185178.0	5301.4	0.0		0.1	-0.3	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.4	2184932.0	5311.2	EM05	189342.3	2184932.1	5311.3	0.1		0.1	-0.2	-0.1	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189355.9	2185080.0	5309.0	0.1		0.0	-0.2	0.0	0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.6	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.8	EM08	189192.2	2185133.9	5307.9	0.3		0.0	-0.2	0.0	0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.3	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.6	-0.1		0.0	-0.3	-0.1	0.0

RECORD CONDITION SURVEY					Spring 2018 SURVEY				Fall 2018 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 06/18/18				Date of survey: 12/14/18				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.7	EM01	189774.1	2185140.7	5297.7	0.2		0.0	-0.3	0.0	0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.1	2184810.0	5302.2	-0.2		0.1	-0.3	0.0	0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.4	EM03	189626.0	2185058.2	5307.4	0.1		0.2	-0.4	0.0	0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.3	EM04	189570.6	2185178.0	5301.4	0.0		0.1	-0.3	0.0	0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.1	EM05	189342.3	2184932.1	5311.3	0.1		0.1	-0.2	-0.1	0.2
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189355.9	2185080.0	5309.0	0.1		0.0	-0.2	0.0	0.2
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.6	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.9	0.3		0.0	-0.2	0.0	0.2
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.5	EM09	189037.2	2184990.4	5306.6	-0.1		0.0	-0.3	0.0	0.1

RECORD CONDITION SURVEY					Fall 2018 SURVEY				Spring 2019 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 12/14/18				Date of survey: 05/16/19				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.7	EM01	189774.0	2185140.7	5297.6	0.2		0.0	-0.5	0.0	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.2	2184809.9	5302.1	-0.2		0.1	-0.4	0.0	-0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.4	EM03	189625.9	2185058.2	5307.4	0.0		0.2	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.4	EM04	189570.6	2185178.1	5301.4	0.1		0.2	-0.4	0.0	-0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.1	EM05	189342.3	2184932.1	5311.2	0.1		0.1	-0.4	0.0	-0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5309.0	EM06	189355.9	2185080.0	5308.8	0.1		0.0	-0.4	0.0	-0.2
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.5	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.9	EM08	189192.2	2185133.9	5307.7	0.3		0.0	-0.3	0.0	-0.2
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.5	-0.1		0.0	-0.3	0.0	-0.1

RECORD CONDITION SURVEY					Spring 2019 SURVEY				Fall 2019 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 05/16/19				Date of survey: 01/14/20				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.6	EM01	189774.0	2185140.7	5297.7	0.1		0.0	-0.4	0.0	0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.1	EM02	189637.2	2184809.9	5302.2	-0.1		0.1	-0.3	0.0	0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189625.9	2185058.2	5307.4	EM03	189625.9	2185058.2	5307.4	0.0		0.2	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.4	EM04	189570.5	2185178.0	5301.3	0.0		0.1	-0.4	-0.1	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.2	EM05	189342.3	2184932.1	5311.2	0.1		0.1	-0.3	0.0	0.0
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.8	EM06	189355.9	2185080.0	5308.9	0.1		0.0	-0.3	0.0	0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.6	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.6	0.2		0.0	-0.4	-0.1	-0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.5	EM09	189037.2	2184990.4	5306.5	-0.1		0.0	-0.3	0.0	0.0

RECORD CONDITION SURVEY					Fall 2019 SURVEY				Spring 2020 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 01/14/20				Date of survey: 04/23/20				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.7	EM01	189774.0	2185140.7	5297.6	0.1		0.0	-0.5	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.2	2184809.8	5302.2	-0.1		0.0	-0.4	0.1	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189625.9	2185058.2	5307.4	EM03	189625.9	2185058.2	5307.4	0.0		0.2	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.3	EM04	189570.5	2185178.0	5301.3	0.0		0.1	-0.4	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.2	EM05	189342.3	2184932.1	5311.1	0.1		0.1	-0.4	0.0	0.0
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189355.8	2185080.0	5308.9	0.1		0.0	-0.3	-0.1	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.5	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.1	2185133.9	5307.6	EM08	189192.2	2185133.9	5307.7	0.3		0.0	-0.3	0.1	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.5	EM09	189037.1	2184990.4	5306.5	-0.1		0.0	-0.4	0.0	0.0

CHANGE IN HWL EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Spring 2020 SURVEY				Fall 2020 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 04/23/20				Date of survey: 10/01/20				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.6	EM01	189774.0	2185140.7	5297.7	0.1		0.0	-0.4	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.8	5302.2	EM02	189637.2	2184809.9	5302.1	-0.1		0.1	-0.4	-0.1	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189625.9	2185058.2	5307.4	EM03	189626.0	2185058.2	5307.3	0.1		0.2	-0.4	0.1	-0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.5	2185178.0	5301.3	EM04	189570.6	2185178.0	5301.3	0.1		0.1	-0.5	0.1	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.1	EM05	189342.3	2184932.1	5311.2	0.1		0.1	-0.3	0.0	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.8	2185080.0	5308.9	EM06	189355.9	2185080.0	5308.9	0.1		0.0	-0.3	0.1	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.5	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.1	2185133.9	5307.7	0.2		0.0	-0.4	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.1	2184990.4	5306.5	EM09	189037.2	2184990.4	5306.6	-0.1		-0.1	-0.3	0.0	0.1

RECORD CONDITION SURVEY					Fall 2020 SURVEY				Spring 2021 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 10/01/20				Date of survey: 05/25/21				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.7	EM01	189774.0	2185140.7	5297.6	0.1		0.0	-0.5	0.0	0.0
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.1	EM02	189637.2	2184809.9	5302.1	-0.1		0.1	-0.4	0.0	0.0
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.2	5307.3	EM03	189625.9	2185058.2	5307.4	0.0		0.2	-0.3	0.0	0.1
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.3	EM04	189570.6	2185178.1	5301.4	0.0		0.2	-0.4	0.0	0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.2	EM05	189342.3	2184932.1	5311.2	0.1		0.1	-0.3	0.0	0.0
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189355.9	2185080.0	5308.8	0.1		0.0	-0.4	0.0	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.6	5309.6	-0.4		-0.2	-0.3	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.1	2185133.9	5307.7	EM08	189192.2	2185133.9	5307.8	0.3		0.0	-0.3	0.1	0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.5	0.0		-0.1	-0.3	0.0	-0.1

RECORD CONDITION SURVEY					Spring 2021 SURVEY				Fall 2021 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 05/25/21				Date of survey: 12/02/21				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.0	2185140.7	5297.6	EM01	189774.1	2185140.6	5297.7	0.2		-0.1	-0.4	0.0	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.1	EM02	189637.2	2184809.9	5302.2	-0.1		0.1	-0.3	0.0	0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189625.9	2185058.2	5307.4	EM03	189626.0	2185058.1	5307.4	0.1		0.2	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.1	5301.4	EM04	189570.6	2185178.0	5301.3	0.0		0.1	-0.4	0.0	-0.1
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.2	EM05	189342.3	2184932.1	5311.1	0.1		0.1	-0.4	0.0	0.0
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.8	EM06	189355.9	2185080.0	5308.9	0.1		-0.1	-0.3	0.0	0.0
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.5	5309.6	-0.4		-0.2	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.8	EM08	189192.2	2185133.9	5307.7	0.3		0.0	-0.3	0.0	0.0
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.6	-0.1		0.0	-0.3	0.0	0.1

RECORD CONDITION SURVEY					Fall 2021 SURVEY				Spring 2022 SURVEY				RESULTS					
Date of survey: 11/12/08					Date of survey: 12/02/21				Date of survey: 05/19/22				CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL
EM-HWL01	A12276	189773.9	2185140.7	5298.1	EM01	189774.1	2185140.6	5297.6	EM01	189774.0	2185140.7	5297.6	0.1		0.0	-0.5	-0.1	-0.1
EM-HWL02	A12274	189637.3	2184809.8	5302.5	EM02	189637.2	2184809.9	5302.2	EM02	189637.1	2184809.8	5302.1	-0.2		0.0	-0.4	-0.1	-0.1
EM-HWL03	A12275	189625.9	2185058.0	5307.8	EM03	189626.0	2185058.1	5307.4	EM03	189626.0	2185058.1	5307.4	0.1		0.1	-0.4	0.0	0.0
EM-HWL04	A12277	189570.5	2185177.9	5301.8	EM04	189570.6	2185178.0	5301.3	EM04	189570.6	2185177.9	5301.3	0.1		0.0	-0.4	0.0	0.0
EM-HWL05	A12279	189342.2	2184932.0	5311.5	EM05	189342.3	2184932.1	5311.1	EM05	189342.3	2184932.0	5311.2	0.0		0.0	-0.3	0.0	0.1
EM-HWL06	A12278	189355.8	2185080.0	5309.2	EM06	189355.9	2185080.0	5308.9	EM06	189355.9	2185080.0	5308.8	0.1		-0.1	-0.4	0.0	-0.1
EM-HWL07	A12280	189151.0	2184866.7	5310.0	EM07	189150.6	2184866.5	5309.6	EM07	189150.6	2184866.4	5309.6	-0.4		-0.3	-0.4	0.0	0.0
EM-HWL08	A12281	189191.9	2185133.9	5308.0	EM08	189192.2	2185133.9	5307.7	EM08	189192.2	2185133.8	5307.6	0.3		-0.1	-0.4	0.0	-0.1
EM-HWL09	A12282	189037.2	2184990.5	5306.9	EM09	189037.2	2184990.4	5306.6	EM09	189037.2	2184990.4	5306.3	-0.1		-0.1	-0.5	0.0	-0.3

CHANGE IN ELF EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					FALL 2010 SURVEY Date of survey: 9/30/10				SPRING 2011 SURVEY Date of survey: 4/28/11				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	Aelfem1	188086.9	2185027.4	5287.8	a1004	188086.9	2185027.4	5287.8	0.0		-0.1	0.0	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	Aelfem2	187933.6	2184981.5	5297.1	a1005	187933.6	2184981.4	5297.1	0.0		0.0	0.0	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	Aelfem3	187817.7	2185028.3	5303.4	a1006	187817.8	2185028.3	5303.4	0.1		0.0	0.0	0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	Aelfem4	187781.1	2185204.8	5303.6	a1007	187781.2	2185204.8	5303.6	0.1		-0.1	0.0	0.1	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	Aelfem5	187481.5	2184463.0	5302.4	a1003	187481.6	2184463.0	5302.3	0.1		0.0	-0.1	0.1	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	Aelfem6	187611.7	2184518.4	5307.6	Monument damage. No survey.				N/A		N/A	N/A	N/A	N/A
ELF-EM7	EM7	187727.8	2184471.4	5304.4	Aelfem7	187727.8	2184471.4	5304.4	a1001	187727.9	2184471.4	5304.3	0.1		0.0	-0.1	0.1	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	Aelfem8	187806.3	2184332.0	5298.2	Monument damage. No survey.				N/A		N/A	N/A	N/A	N/A

RECORD CONDITION SURVEY					SPRING 2011 SURVEY Date of survey: 4/28/11				FALL 2011 SURVEY Date of survey: 10/12/11				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	a1004	188086.9	2185027.4	5287.8	11	188087.0	2185027.4	5287.7	0.1		0.0	0.0	0.0	-0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	a1005	187933.6	2184981.4	5297.1	12	187933.5	2184981.4	5297.1	0.0		-0.1	0.0	-0.1	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	a1006	187817.8	2185028.3	5303.4	13	187817.8	2185028.3	5303.4	0.2		0.0	0.0	0.1	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	a1007	187781.2	2185204.8	5303.6	14	187781.2	2185204.8	5303.5	0.1		0.0	-0.1	0.0	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	a1003	187481.6	2184463.0	5302.3	18	187481.5	2184463.0	5302.3	-0.1		0.0	0.0	-0.1	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	Monument damage. No survey.				15	187611.6	2184518.3	5307.6	-0.1		0.0	-0.1	N/A	N/A
ELF-EM7	EM7	187727.8	2184471.4	5304.4	a1001	187727.9	2184471.4	5304.3	16	187727.9	2184471.3	5304.3	0.1		-0.1	-0.1	0.0	-0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	Monument damage. No survey.				17	187806.4	2184331.9	5298.1	0.0		-0.1	-0.1	N/A	N/A

RECORD CONDITION SURVEY					FALL 2011 SURVEY Date of survey: 10/12/11				Spring 2012 SURVEY Date of survey: 5/09/12				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	11	188087.0	2185027.4	5287.7	4309	188087.0	2185027.4	5287.7	0.1		0.0	0.0	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	12	187933.5	2184981.4	5297.1	4310	187933.6	2184981.4	5297.0	0.0		-0.1	-0.1	0.1	-0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	13	187817.8	2185028.3	5303.4	4311	187817.7	2185028.3	5303.4	0.0		0.0	0.0	-0.1	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	14	187781.2	2185204.8	5303.5	4312	187781.1	2185204.8	5303.5	0.0		0.0	-0.1	-0.1	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	18	187481.5	2184463.0	5302.3	4314	187481.5	2184463.0	5302.2	-0.1		0.0	0.0	0.0	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	15	187611.6	2184518.3	5307.6	4313	187611.7	2184518.3	5307.5	0.0		0.0	-0.2	0.1	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	16	187727.9	2184471.3	5304.3	4315	187727.9	2184471.4	5304.3	0.1		0.0	-0.1	0.0	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	17	187806.4	2184331.9	5298.1	4316	187806.4	2184332.0	5298.1	0.0		0.0	-0.1	0.0	0.0

RECORD CONDITION SURVEY					Spring 2012 SURVEY Date of survey: 5/09/12				Fall 2012 SURVEY Date of survey: 9/20/12				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	4309	188087.0	2185027.4	5287.7	n1009	188087.0	2185027.4	5287.7	0.1		-0.1	-0.1	0.0	-0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	4310	187933.6	2184981.4	5297.0	n1006	187933.6	2184981.4	5297.0	0.0		0.0	-0.1	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	4311	187817.7	2185028.3	5303.4	n1007	187817.7	2185028.3	5303.3	0.1		-0.1	-0.1	0.0	-0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	4312	187781.1	2185204.8	5303.5	n1008	187781.1	2185204.8	5303.5	0.0		-0.1	-0.1	0.0	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	4314	187481.5	2184463.0	5302.2	n1002	187481.6	2184463.0	5302.1	0.0		0.0	-0.2	0.1	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	4313	187611.7	2184518.3	5307.5	n1003	187611.7	2184518.3	5307.4	0.0		-0.1	-0.3	0.0	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	4315	187727.9	2184471.4	5304.3	n1004	187727.9	2184471.4	5304.2	0.0		-0.1	-0.3	0.0	-0.2
ELF-EM8	EM8	187806.3	2184332.0	5298.2	4316	187806.4	2184332.0	5298.1	n1005	187806.4	2184332.0	5298.0	0.1		-0.1	-0.2	0.0	-0.1

RECORD CONDITION SURVEY					Fall 2012 SURVEY Date of survey: 9/20/12				Spring 2013 SURVEY Date of survey: 5/07/13				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	n1009	188087.0	2185027.4	5287.7	EM1	188087.0	2185027.4	5287.7	0.1		0.0	0.0	0.1	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	n1006	187933.6	2184981.4	5297.0	EM2	187933.6	2184981.4	5296.9	0.0		-0.1	-0.2	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	n1007	187817.7	2185028.3	5303.3	EM3	187817.8	2185028.3	5303.3	0.2		-0.1	-0.1	0.1	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	n1008	187781.1	2185204.8	5303.5	EM4	187781.2	2185204.9	5303.5	0.2		0.0	-0.1	0.1	0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	n1002	187481.6	2184463.0	5302.1	EM5	187481.6	2184463.0	5302.2	0.0		0.0	-0.2	0.0	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	n1003	187611.7	2184518.3	5307.4	EM6	187611.6	2184518.3	5307.4	-0.1		0.0	-0.3	0.0	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	n1004	187727.9	2184471.4	5304.2	EM7	187728.0	2184471.4	5304.2	0.1		0.0	-0.2	0.1	0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	n1005	187806.4	2184332.0	5298.0	EM8	187806.3	2184332.0	5298.0	0.0		0.0	-0.2	-0.1	0.0

CHANGE IN ELF EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Spring 2013 SURVEY Date of survey: 9/07/13				Fall 2013 SURVEY Date of survey: 9/19/13				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.4	5287.7	EM1	188087.1	2185027.4	5287.7	0.1		-0.1		0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.4	5296.9	EM2	187933.5	2184981.3	5297.0	0.0		-0.1		0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.3	5303.3	EM3	187817.8	2185028.3	5303.3	0.1		0.0		0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.3	2185204.9	5303.5	EM4	187780.9	2185204.9	5303.5	-0.1		0.0		-0.3	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.0	5302.2	EM5	187481.4	2184463.0	5302.2	-0.1		-0.1		-0.2	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.3	5307.4	EM6	187611.6	2184518.3	5307.4	-0.1		0.0		-0.3	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187728.0	2184471.4	5304.2	EM7	187727.9	2184471.4	5304.2	0.1		0.0		-0.2	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.0	5298.0	EM8	187806.4	2184331.9	5298.0	0.1		-0.1		-0.1	0.0

RECORD CONDITION SURVEY					Fall 2013 SURVEY Date of survey: 9/19/13				Spring 2014 SURVEY Date of survey: 5/29/14				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.1	2185027.4	5287.7	EM1	188087.0	2185027.5	5287.6	0.1		0.1		-0.2	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.3	5297.0	EM2	187933.6	2184981.5	5296.9	0.0		0.0		-0.2	0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.3	5303.3	EM3	187817.8	2185028.4	5303.2	0.2		0.1		-0.2	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187780.9	2185204.9	5303.5	EM4	187781.3	2185204.9	5303.4	0.2		0.1		-0.2	0.3
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.4	2184463.0	5302.2	EM5	187481.5	2184463.1	5302.0	0.0		0.1		-0.3	0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.3	5307.4	EM6	187611.6	2184518.4	5307.3	0.0		0.1		0.0	0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.4	5304.2	EM7	187728.0	2184471.5	5304.1	0.1		0.0		-0.4	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184331.9	5298.0	EM8	187806.5	2184332.1	5297.9	0.1		0.1		-0.3	0.1

RECORD CONDITION SURVEY					Spring 2014 SURVEY Date of survey: 5/29/14				Fall 2014 SURVEY Date of survey: 10/19/14				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.6	0.0		0.0		-0.2	-0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.6	2184981.5	5297.0	0.0		0.0		-0.1	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.3	0.1		0.1		-0.1	-0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.3	2185204.9	5303.4	EM4	187781.1	2185204.9	5303.5	0.1		0.0		-0.1	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.5	2184463.1	5302.1	0.0		0.1		-0.2	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.3	EM6	187611.6	2184518.4	5307.4	0.0		0.1		-0.3	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187728.0	2184471.5	5304.1	EM7	187727.8	2184471.5	5304.1	0.0		0.1		-0.3	-0.2
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.5	2184332.1	5297.9	EM8	187806.4	2184332.1	5298.0	0.1		0.1		-0.2	0.0

RECORD CONDITION SURVEY					Fall 2014 SURVEY Date of survey: 10/19/14				Spring 2015 SURVEY Date of survey: 5/29/15				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.7	0.1		0.1		-0.1	0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5297.0	EM2	187933.6	2184981.5	5296.9	0.1		0.1		-0.2	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.3	EM3	187817.8	2185028.4	5303.3	0.1		0.1		-0.1	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185204.9	5303.5	EM4	187781.1	2185205.0	5303.5	0.1		0.1		-0.1	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.1	EM5	187481.6	2184463.1	5302.1	0.1		0.1		-0.2	0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.4	EM6	187611.7	2184518.4	5307.4	0.0		0.1		-0.3	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.5	5304.1	EM7	187727.9	2184471.5	5304.2	0.1		0.1		-0.2	0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5298.0	EM8	187806.5	2184332.1	5298.0	0.1		0.1		-0.1	0.0

RECORD CONDITION SURVEY					Spring 2015 SURVEY Date of survey: 5/29/15				Fall 2015 SURVEY Date of survey: 12/9/15				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.7	EM1	188087.0	2185027.5	5287.5	0.1		0.1		-0.3	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.6	2184981.5	5296.8	0.0		0.0		-0.3	-0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.4	5303.3	EM3	187817.9	2185028.4	5303.1	0.2		0.1		-0.3	0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.5	EM4	187781.2	2185205.0	5303.3	0.1		0.1		-0.2	0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.1	5302.1	EM5	187481.5	2184463.2	5302.0	0.0		0.1		-0.4	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.7	2184518.4	5307.4	EM6	187611.6	2184518.4	5307.2	0.0		0.1		-0.5	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.5	5304.2	EM7	187728.0	2184471.5	5304.0	0.1		0.1		-0.4	0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.5	2184332.1	5298.0	EM8	187806.4	2184332.1	5297.8	0.1		0.0		-0.4	-0.1

CHANGE IN ELF EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Fall 2015 SURVEY Date of survey: 12/9/15				Spring 2016 SURVEY Date of survey: 6/20/16				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.5	EM1	188087.0	2185027.5	5287.6	0.1		0.1	-0.2	-0.1	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.8	EM2	187933.6	2184981.5	5296.9	0.0		0.1	-0.2	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.1	EM3	187817.8	2185028.4	5303.2	0.1		0.1	-0.2	-0.1	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.2	2185205.0	5303.3	EM4	187781.1	2185204.9	5303.4	0.0		0.0	-0.2	-0.1	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.2	5302.0	EM5	187481.6	2184463.1	5302.1	0.0		0.1	-0.3	0.0	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.2	EM6	187611.6	2184518.4	5307.3	0.0		0.1	-0.4	0.0	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187728.0	2184471.5	5304.0	EM7	187727.9	2184471.5	5304.1	0.0		0.1	-0.4	-0.1	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.8	EM8	187806.4	2184332.1	5297.9	0.1		0.1	-0.3	0.0	0.0

RECORD CONDITION SURVEY					Spring 2016 SURVEY Date of survey: 6/20/16				Fall 2016 SURVEY Date of survey: 1/18/17				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.6	0.1		0.0	-0.2	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.6	2184981.5	5296.9	0.0		0.0	-0.2	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.4	5303.2	EM3	187817.8	2185028.4	5303.2	0.1		0.1	-0.2	0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185204.9	5303.4	EM4	187781.2	2185204.9	5303.5	0.1		0.1	-0.1	0.0	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.1	5302.1	EM5	187481.6	2184463.1	5302.1	0.0		0.1	-0.3	0.0	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.3	EM6	187611.6	2184518.4	5307.4	0.0		0.1	-0.3	0.0	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.5	5304.1	EM7	187727.9	2184471.5	5304.1	0.1		0.1	-0.3	0.0	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.9	EM8	187806.4	2184332.1	5298.0	0.1		0.1	-0.2	0.0	0.0

RECORD CONDITION SURVEY					Fall 2016 SURVEY Date of survey: 6/20/16				Spring 2017 SURVEY Date of survey: 05/17/17				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.6	0.1		0.1	-0.2	0.0	0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.7	2184981.5	5296.8	0.1		0.1	-0.2	0.1	0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.4	5303.2	EM3	187817.8	2185028.4	5303.1	0.1		0.1	-0.3	0.0	0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.2	2185204.9	5303.5	EM4	187781.2	2185205.0	5303.4	0.1		0.1	-0.2	0.0	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.1	5302.1	EM5	187481.6	2184463.1	5302.0	0.1		0.1	-0.4	0.0	0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.3	EM6	187611.7	2184518.5	5307.3	0.0		0.2	-0.4	0.1	0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.5	5304.1	EM7	187727.9	2184471.6	5304.1	0.1		0.1	-0.4	0.0	0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5298.0	EM8	187806.4	2184332.1	5297.9	0.1		0.1	-0.3	0.1	-0.1

RECORD CONDITION SURVEY					Spring 2017 SURVEY Date of survey: 05/17/17				Fall 2017 SURVEY Date of survey: 11/10/17				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.7	0.1		0.1	-0.1	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.7	2184981.5	5296.8	EM2	187933.6	2184981.5	5296.9	0.0		0.1	-0.2	-0.1	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.8	2185028.4	5303.1	EM3	187817.7	2185028.4	5303.2	0.1		0.1	-0.2	0.0	-0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.2	2185205.0	5303.4	EM4	187781.2	2185204.9	5303.4	0.1		0.0	-0.2	0.0	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.1	5302.0	EM5	187481.6	2184463.1	5302.1	0.0		0.1	-0.3	0.0	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.7	2184518.5	5307.3	EM6	187611.6	2184518.4	5307.3	0.0		0.1	-0.4	-0.1	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.6	5304.1	EM7	187727.9	2184471.5	5304.1	0.0		0.1	-0.3	0.0	-0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.9	EM8	187806.4	2184332.1	5297.9	0.1		0.1	-0.3	0.0	0.0

RECORD CONDITION SURVEY					Fall 2017 SURVEY Date of survey: 11/10/17				Spring 2018 SURVEY Date of survey: 06/18/18				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.7	EM1	188086.9	2185027.5	5287.6	0.0		0.1	-0.2	0.0	-0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.6	2184981.6	5296.9	0.0		0.1	-0.2	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.1	0.0		0.1	-0.3	-0.1	0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.2	2185204.9	5303.4	EM4	187781.1	2185205.0	5303.4	0.0		0.1	-0.2	-0.1	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.6	2184463.1	5302.1	EM5	187481.5	2184463.2	5302.0	-0.1		0.2	-0.4	-0.1	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.3	EM6	187611.6	2184518.5	5307.2	-0.1		0.2	-0.5	-0.1	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.5	5304.1	EM7	187727.8	2184471.6	5304.0	0.0		0.2	-0.5	0.0	-0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.9	EM8	187806.3	2184332.2	5297.8	0.0		0.1	-0.4	-0.1	-0.1

CHANGE IN ELF EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Spring 2018 SURVEY Date of survey: 06/18/18				Fall 2018 SURVEY Date of survey: 12/14/18				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.6	EM1	188086.9	2185027.5	5287.6	0.0		0.1	-0.2	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.6	5296.9	EM2	187933.5	2184981.5	5296.8	0.0		0.1	-0.3	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.1		0.1	-0.2	0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.4	EM4	187781.1	2185205.0	5303.4	0.0		0.1	-0.2	0.0	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.2	5302.0	EM5	187481.5	2184463.1	5302.0	0.0		0.1	-0.4	0.0	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.5	5307.2	EM6	187611.6	2184518.4	5307.2	-0.1		0.1	-0.5	0.0	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.0	EM7	187727.8	2184471.6	5304.0	0.0		0.1	-0.4	0.0	-0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.2	5297.8	EM8	187806.3	2184332.1	5297.8	0.0		0.1	-0.3	0.0	0.1

RECORD CONDITION SURVEY					Fall 2018 SURVEY Date of survey: 12/14/18				Spring 2019 SURVEY Date of survey: 05/16/19				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.6	EM1	188086.9	2185027.5	5287.6	0.0		0.1	-0.2	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.8	EM2	187933.6	2184981.5	5296.8	0.0		0.1	-0.3	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.1		0.1	-0.3	0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.4	EM4	187781.1	2185205.0	5303.4	0.0		0.1	-0.2	0.0	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.5	2184463.1	5302.0	0.0		0.1	-0.4	0.0	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.2	EM6	187611.6	2184518.5	5307.2	-0.1		0.1	-0.5	0.0	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.0	EM7	187727.8	2184471.6	5304.0	0.0		0.1	-0.4	0.0	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.1	5297.8	EM8	187806.3	2184332.1	5297.8	0.0		0.1	-0.4	0.0	0.0

RECORD CONDITION SURVEY					Spring 2019 SURVEY Date of survey: 05/16/19				Fall 2019 SURVEY Date of survey: 01/14/20				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.6	EM1	188087.0	2185027.5	5287.7	0.1		0.1	-0.1	0.0	0.1
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.8	EM2	187933.5	2184981.5	5296.8	0.0		0.1	-0.3	0.0	0.0
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.0		0.1	-0.2	0.0	0.0
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.4	EM4	187781.1	2185204.9	5303.4	0.0		0.1	-0.2	-0.1	0.0
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.5	2184463.1	5302.0	0.0		0.1	-0.4	0.0	0.0
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.5	5307.2	EM6	187611.6	2184518.4	5307.2	-0.1		0.1	-0.5	0.0	0.0
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.0	EM7	187727.8	2184471.6	5304.0	0.0		0.1	-0.4	0.0	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.1	5297.8	EM8	187806.3	2184332.1	5297.8	0.0		0.1	-0.3	0.0	0.0

RECORD CONDITION SURVEY					Fall 2019 SURVEY Date of survey: 01/14/20				Spring 2020 SURVEY Date of survey: 04/23/20				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.5	5287.7	EM1	188086.9	2185027.5	5287.7	0.0		0.1	-0.1	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.5	2184981.5	5296.8	EM2	187933.6	2184981.5	5296.9	0.0		0.1	-0.2	0.0	0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.1		0.1	-0.2	0.0	0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185204.9	5303.4	EM4	187781.0	2185205.0	5303.5	0.0		0.1	-0.1	0.0	0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.5	2184463.2	5302.1	0.0		0.1	-0.3	0.0	0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.2	EM6	187611.7	2184518.4	5307.3	0.0		0.1	-0.4	0.1	0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.0	EM7	187727.8	2184471.6	5304.1	0.0		0.1	-0.4	0.0	0.0
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.1	5297.8	EM8	187806.4	2184332.1	5297.9	0.1		0.1	-0.3	0.0	0.0

RECORD CONDITION SURVEY					Spring 2020 SURVEY Date of survey: 04/23/20				Fall 2020 SURVEY Date of survey: 10/01/20				RESULTS					
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY		
													DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.7	EM1	188086.9	2185027.5	5287.6	0.0		0.1	-0.2	0.0	0.0
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.9	EM2	187933.6	2184981.5	5296.8	0.0		0.1	-0.3	0.0	-0.1
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.0		0.1	-0.3	0.0	-0.1
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.5	EM4	187781.1	2185205.0	5303.4	0.0		0.1	-0.2	0.0	-0.1
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.2	5302.1	EM5	187481.5	2184463.1	5302.0	-0.1		0.1	-0.4	0.0	-0.1
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.7	2184518.4	5307.3	EM6	187611.6	2184518.4	5307.2	-0.1		0.1	-0.5	-0.1	-0.1
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.1	EM7	187727.8	2184471.5	5304.0	0.0		0.1	-0.4	0.0	-0.1
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.9	EM8	187806.3	2184332.1	5297.9	0.0		0.1	-0.3	0.0	0.0

CHANGE IN ELF EROSION/SETTLEMENT MONUMENT POSITION

RECORD CONDITION SURVEY					Fall 2020 SURVEY				Spring 2021 SURVEY				RESULTS											
					Date of survey: 10/01/20				Date of survey: 05/25/21				CHANGE RELATIVE TO RECORD CONDITION				CHANGE RELATIVE TO PRIOR SURVEY							
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	DELTA	N	DELTA	E	DELTA	EL	DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.6	EM1	188086.9	2185027.5	5287.7	0.0	0	0.1	-0.1	0.0	0.0	0.0	0.0	0.0	0.0	0.1	
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.6	2184981.5	5296.8	EM2	187933.5	2184981.5	5297.0	0.0	0	0.1	-0.1	0.0	0.0	0.0	0.0	0.0	0.1		
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.1	0	0.1	-0.2	0.0	0.0	0.0	0.0	0.1			
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.4	EM4	187781.1	2185205.0	5303.5	0.0	0	0.1	-0.1	0.0	0.0	0.0	0.0	0.1			
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.5	2184463.2	5302.0	-0.1	0	0.1	-0.3	0.0	0.0	0.0	0.0	0.0			
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.2	EM6	187611.6	2184518.4	5307.2	-0.1	0	0.1	-0.5	0.0	0.0	0.0	0.0	0.0			
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.5	5304.0	EM7	187727.8	2184471.6	5304.0	0.0	0	0.1	-0.4	0.0	0.0	0.1	0.0	0.0			
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.1	5297.9	EM8	187806.4	2184332.1	5297.8	0.1	0	0.1	-0.4	0.0	0.0	0.0	0.0	0.0			

RECORD CONDITION SURVEY					Spring 2021 SURVEY <i>Date of survey: 05/25/21</i>				Fall 2021 SURVEY <i>Date of survey: 12/02/21</i>				RESULTS											
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY								
													DELTA	N	DELTA	E	DELTA	EL	DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188086.9	2185027.5	5287.7	EM1	188087.0	2185027.4	5287.5	0.1		0.0	-0.3		0.1	-0.1		-0.2			
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.5	2184981.5	5297.0	EM2	187933.5	2184981.6	5296.8	-0.1		0.1	-0.3		0.0	0.0		-0.2			
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.7	2185028.4	5303.2	0.1		0.1	-0.2		0.0	0.0		0.0			
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.1	2185205.0	5303.5	EM4	187781.2	2185205.0	5303.3	0.1		0.1	-0.2		0.1	0.0		-0.1			
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.2	5302.0	EM5	187481.5	2184463.1	5302.0	-0.1		0.1	-0.4		0.0	-0.1		-0.1			
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.4	5307.2	EM6	187611.6	2184518.5	5307.3	0.0		0.2	-0.4		0.0	0.1		0.0			
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.8	2184471.6	5304.0	EM7	187727.9	2184471.5	5304.0	0.0		0.1	-0.5		0.1	-0.1		-0.1			
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.4	2184332.1	5297.8	EM8	187806.3	2184332.1	5297.8	0.0		0.1	-0.4		-0.1	0.0		0.0			

RECORD CONDITION SURVEY					Fall 2021 SURVEY <i>Date of survey: 12/02/21</i>				Spring 2022 SURVEY <i>Date of survey: 05/19/22</i>				RESULTS											
Mon't No.	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	Point No.	Grid Northing	Grid Easting	Elevation	CHANGE RELATIVE TO RECORD CONDITION			CHANGE RELATIVE TO PRIOR SURVEY								
													DELTA	N	DELTA	E	DELTA	EL	DELTA	N	DELTA	E	DELTA	EL
ELF-EM1	EM1	188086.9	2185027.4	5287.8	EM1	188087.0	2185027.4	5287.5	EM1	188087.0	2185027.4	5287.5	0.1		0.0		-0.3		0.0		0.0		0.0	
ELF-EM2	EM2	187933.6	2184981.4	5297.1	EM2	187933.5	2184981.6	5296.8	EM2	187933.5	2184981.5	5296.8	0.0		0.1		-0.3		0.1		-0.1		0.0	
ELF-EM3	EM3	187817.7	2185028.3	5303.4	EM3	187817.7	2185028.4	5303.2	EM3	187817.6	2185028.3	5303.1	-0.1		0.0		-0.3		-0.1		-0.1		-0.1	
ELF-EM4	EM4	187781.1	2185204.9	5303.6	EM4	187781.2	2185205.0	5303.3	EM4	187781.1	2185204.9	5303.2	0.0		0.0		-0.4		-0.1		-0.1		-0.1	
ELF-EM5	EM5	187481.5	2184463.0	5302.4	EM5	187481.5	2184463.1	5302.0	EM5	187481.4	2184463.1	5301.9	-0.1		0.1		-0.5		-0.1		0.0		-0.1	
ELF-EM6	EM6	187611.7	2184518.3	5307.7	EM6	187611.6	2184518.5	5307.3	EM6	187611.5	2184518.3	5307.2	-0.1		0.0		-0.5		-0.1		-0.2		-0.1	
ELF-EM7	EM7	187727.8	2184471.4	5304.4	EM7	187727.9	2184471.5	5304.0	EM7	187727.9	2184471.5	5303.8	0.1		0.0		-0.6		0.1		0.0		0.0	
ELF-EM8	EM8	187806.3	2184332.0	5298.2	EM8	187806.3	2184332.1	5297.8	EM8	187806.3	2184332.0	5297.9	-0.1		0.0		-0.3		0.0		-0.1		0.0	

APPENDIX E
Monthly Flow Summaries

This page intentionally left blank.

Monthly HWL LCS and LDS Sump Volume Readings

May 2021 through April 2022

Date	HWL LCS1		HWL LCS2		HWL LCS3		HWL LCS4		HWL LDS1		HWL LDS2		HWL LDS3		HWL LDS4	
	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)
May-21	1572800.0	0.0	1283900.0	2000.0	374000.0	0.0	1248900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
June-21	1574200.0	1400.0	1283900.0	0.0	374000.0	0.0	1253900.0	5000.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
July-21	1574200.0	0.0	1283900.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
August-21	1574200.0	0.0	1283900.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
September-21	1574200.0	0.0	1286300.0	2400.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
October-21	1574200.0	0.0	1286300.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	1910.0	0.0
November-21	1575700.0	1500.0	1286300.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	2374.0	464.0
December-21	1575700.0	0.0	1286300.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	23538.0	0.0	23222.0	0.0	2374.0	0.0
January-22	1575700.0	0.0	1288600.0	2300.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	24088.0	550.0	23222.0	0.0	2374.0	0.0
February-22	1575700.0	0.0	1288600.0	0.0	374000.0	0.0	1253900.0	0.0	28738.0	0.0	24088.0	0.0	23222.0	0.0	2374.0	0.0
March-22	1577100.0	1400.0	1288600.0	0.0	374000.0	0.0	1259000.0	5100.0	28738.0	0.0	24088.0	0.0	23222.0	0.0	2374.0	0.0
April-22	1577100.0	0.0	1289600.0	1000.0	374000.0	0.0	1259000.0	0.0	28738.0	0.0	24088.0	0.0	23222.0	0.0	2374.0	0.0

Monthly ELF LCS and LDS Sump Volume Readings

May 2021 through April 2022

Date	ELF WPLCS		ELF LBLCS		ELF WPLDS1		ELF WPLDS2		ELF LBLDS1		ELF LBLDS2	
	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)	Totalizer Volume (gal.)	Increase in Volume (gal.)
May-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
June-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
July-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
August-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
September-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
October-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
November-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
December-21	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
January-22	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
February-22	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
March-22	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0
April-22	15116.0	0.0	601920.0	0.0	46581.0	0.0	135715.0	0.0	40233.0	0.0	35484.0	0.0

APPENDIX F-1

**Hazardous Waste Landfill
Post-Closure Groundwater Monitoring Report
Calendar Year 2021**

This page intentionally left blank.

ROCKY MOUNTAIN ARSENAL

HAZARDOUS WASTE LANDFILL
POST-CLOSURE GROUNDWATER MONITORING REPORT

CALENDAR YEAR 2021

Revision 0
June 17, 2022

U.S. Department of the Army
Shell Oil Company

Prepared by:



Navarro Research and Engineering, Inc.

This page intentionally left blank.

CONTENTS

Section	Page
EXECUTIVE SUMMARY	ES-1
1.0 INTRODUCTION	1
2.0 GROUNDWATER MONITORING RESULTS	1
2.1 Monitoring Well Activities	1
2.2 Water Level Monitoring	1
2.3 Analytical Results	2
2.3.1 HWL Network Wells Analytical Results.....	3
2.3.2 Supplemental Operational Monitoring Wells Analytical Results.....	6
2.3.3 HWL LCS and LDS Sumps Analytical Results	7
2.4 Analytical Data Review	9
2.4.1 Precision.....	9
2.4.2 Accuracy/Bias	10
2.4.3 Representativeness	12
2.4.4 Completeness	12
2.4.5 Comparability	13
2.4.6 Summary	13
2.4.7 Data Usability Evaluation	13
3.0 STATISTICAL EVALUATIONS	13
3.1 2021 Prediction Limits and the Current HWL Water Quality Data	14
3.2 2022 Prediction Limits and the Future HWL Water Quality Data	15
4.0 SUMMARY	16
5.0 REFERENCES	17



TABLES

Table 2.2-1	HWL Water Level Monitoring Network
Table 2.2-2	2021 Water Level Measurements Summary
Table 2.3-1	HWL Water Quality Monitoring Networks
Table 2.3-2	Water Quality Monitoring Analyte List
Table 2.3-3	Quality Control Samples
Table 2.3-4	Non-Routine Action Plan Notifications
Table 3.0-1	HWL Groundwater Monitoring Well Usage
Table 3.0-2	Prediction Limits for HWL 2021 Water Quality Monitoring
Table 3.0-3	Prediction Limits for HWL 2022 Water Quality Monitoring

FIGURES

Figure 2.2-1	Well/Piezometer/Sump Location Map, 2021 Groundwater Monitoring
Figure 2.2-2	Potentiometric Surface for the Unconfined Flow System, April 2021
Figure 2.2-3	Potentiometric Surface for the Lower Sandstone Unit and Equivalent Units, April 2021
Figure 2.3-1	Indicator Compounds Detection Map, 2021 Groundwater Monitoring
Figure 2.3-2	Indicator Compounds Detection Map, 2021 HWL Leachate Collection and Leak Detection Systems
Figure 3.1-1	Shewhart-CUSUM Control Chart for Dieldrin Concentrations in Well 25194

SUPPORTING DOCUMENTATION

(available on Data CD)

HWL Data Quality Assurance

- HWL 2021 Accuracy/Bias Evaluation Results
- HWL 2021 Data Usability Summary
- HWL 2021 Investigative Data
- HWL 2021 Precision Results
- HWL 2021 QC Blank Summary

HWL Statistical Evaluations

- HWL 2022 Prediction Limit ChemStat Documentation
- HWL Well 25194 Mann-Kendall Trend Analysis – Dieldrin



ACRONYMS

amsl	Above Mean Sea Level
ARDL	Applied Research and Development Laboratory
CAMU	Corrective Action Management Unit
CFS	Confined Flow System
CUSUM	Cumulative Sum
ELF	Enhanced Hazardous Waste Landfill
HWL	Hazardous Waste Landfill
IC	Indicator Compound
IQR	Interquartile Range
LCS	Leachate Collection System
LDS	Leak Detection System
MRL	Method Reporting Limit
MS	Matrix Spike
µg/L	Microgram(s) per liter
NRAP	Non-Routine Action Plan
OCN	Operational Change Notice
O&M	Operations and Maintenance
OMC	Operations and Maintenance Contractor
PARCC	Precision, Accuracy, Representativeness, Completeness, and Comparability
PCGMP	Post-Closure Groundwater Monitoring Plan
QC	Quality Control
RMA	Rocky Mountain Arsenal
RMAED	Rocky Mountain Arsenal Environmental Database
RPD	Relative Percent Difference
SOM	Supplemental Operational Monitoring
SQAPP	Sampling Quality Assurance Project Plan
UCL	Upper Confidence Limit
UFS	Unconfined Flow System

(Note: All chemical codes are listed in Table 2.3-2)



This page intentionally left blank.



EXECUTIVE SUMMARY

The post-closure groundwater monitoring program for the Hazardous Waste Landfill (HWL) is designed to monitor groundwater flow directions, groundwater quality beneath and in the vicinity of the HWL and evaluate the potential for hazardous constituent releases into the groundwater sourced from the landfill.

This report covers the post-closure monitoring at the HWL for calendar year 2021 quarterly groundwater sampling events conducted in January, July, October, and the annual sampling event in April and May. Groundwater flow directions beneath the HWL were consistent over the four quarters of 2021 post-closure monitoring and are consistent with previous groundwater monitoring events within the Corrective Action Management Unit area. As previously presented, a more pronounced groundwater high is present along the west side of the HWL consistent with recharge from the perimeter ditch located in the vicinity.

The wells sampled as part of the HWL 2021 post-closure groundwater monitoring include seven downgradient monitoring wells, four upgradient monitoring wells, and six Supplemental Operational Monitoring (SOM) wells. Downgradient wells 25086 and 25088 and SOM wells 25098 and 25100 were dry and not sampled in April 2021. The groundwater samples were tested for a standard list of analytes including indicator compounds (ICs). The ICs selected for the monitoring program include 1,1,1-trichloroethane, 1,1-dichloroethane, 1,1-dichloroethene, 1,2-dichloroethane, arsenic, benzene, bicycloheptadiene, carbon tetrachloride, chromium, chloroform, dichlorodifluoromethane, dicyclopentadiene, dieldrin, diisopropylmethyl phosphonate (DIMP), mercury, and lead.

The ICs detected in the upgradient wells include 1,1-dichloroethene, carbon tetrachloride, and chloroform, while ICs detected downgradient of the HWL include dieldrin and lead. Dieldrin was detected during all four quarters in downgradient well 25194 at concentrations ranging from 0.0158 micrograms per liter ($\mu\text{g/L}$) to 0.0235 $\mu\text{g/L}$. Lead was detected downgradient in two unconfined flow system wells at concentrations ranging from 3 to 4.1 $\mu\text{g/L}$. The levels of dieldrin and lead in the downgradient wells were below their prediction limit values of 0.05 $\mu\text{g/L}$ and 15 $\mu\text{g/L}$, respectively.

The ICs detected in the SOM wells include 1,1,1-trichloroethane, 1,1-dichloroethene, 1,1-dichloroethane, 1,2-dichloroethane, carbon tetrachloride, chloroform, DIMP, dieldrin, and lead. The analytes detected in the SOM wells, with the exception of SOM well 25203, are associated with the North Plants-Bedrock Ridge contaminant plume. Well 25203, located on the southwest side of the HWL, monitors the shallow flow system. No ICs were detected in well 25203 in 2021. The analytical data from SOM wells are not used in the HWL statistical evaluations.

The ICs detected in the leachate collection system (LCS) sumps include, benzene, dichlorodifluoromethane, dicyclopentadiene, dieldrin, and DIMP. The results from the LCS samples are consistent with wastes placed in the landfills, and the chemical groups used to determine the potential impacts on the groundwater.

The ICs detected in the leak detection system (LDS) sumps include dieldrin and DIMP.



LDS1 2021 analytical results that required Regulatory Agency notification in accordance with the *Hazardous Waste Landfill Post-Closure Plan* (Navarro 2019a) include:

- Copper was detected above the Watch List Trigger Level in the LDS1 sample collected on March 1, 2021. The regulatory agencies were notified of the exceedance and Non-Routine Action Plan (NRAP)-2022-001 was issued in January 2022. It was approved by the regulatory agencies on February 3, 2022.

As a component of the data review process, the analytical data were evaluated against the data quality indicators of precision, accuracy, representativeness, completeness, and comparability (PARCC). Based on the findings of the PARCC evaluation, the sample results are considered valid and usable for their intended purpose. Data quality requirements were met for the analytical data, and the data are appropriate for use in evaluation of the water quality conditions present at the site.

Based on statistical evaluations and trend analysis, the groundwater quality around the HWL has not been affected by post-closure operations and maintenance of the landfill. The dieldrin concentrations in downgradient well 25194 are believed to be pre-existing contamination by the Army, which was investigated in accordance with NRAP-2016-004 and the *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Sampling and Analysis Plan* (Navarro 2016). Results of the investigation were documented in the *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Data Summary Report* (Navarro 2019c). At present, no corrective actions were identified as a result of the investigation.

1.0 INTRODUCTION

The Post-Closure Groundwater Monitoring Report for the 2021 quarterly groundwater sampling events conducted in January, July, and October; and annual groundwater sampling event in April and May documents the analytical results and data evaluation of the Hazardous Waste Landfill (HWL) post-closure groundwater monitoring performed at the Rocky Mountain Arsenal (RMA). Background information related to the HWL monitoring approach including site-specific characterization, applicable regulatory requirements, laboratory methods, statistical evaluation procedure, and monitoring program development are presented in the *Hazardous Waste Landfill Post-Closure Groundwater Monitoring Plan* (HWL PCGMP) (Navarro 2019b), the *Rocky Mountain Arsenal Sampling Quality Assurance Project Plan* (SQAPP) (Navarro 2019d), and previous annual groundwater reports.

The groundwater monitoring program defined in this document is specifically designed to monitor groundwater flow directions and groundwater quality beneath and around the HWL, and to monitor for potential releases of hazardous constituents from the HWL. Groundwater monitoring for the HWL was completed as required by the HWL PCGMP (Navarro 2019b).

2.0 GROUNDWATER MONITORING RESULTS

A summary of water level monitoring, and analytical results for the 2021 post-closure groundwater monitoring at the HWL are presented in the following sections. Also included is an evaluation of the Leachate Collection System (LCS) and Leak Detection System (LDS) wastewater analytical data.

2.1 Monitoring Well Activities

The RMA Operations and Maintenance Contractor (OMC) field crew inspected the monitoring wells and well pads prior to each sampling event. As part of the annual sampling event, the casing height was measured prior to sampling monitoring wells with dedicated pumps. The casing height and total depths were measured for monitoring wells without dedicated pumps. The inspection information, casing heights, and total depths are documented in the OMC records.

Water level monitoring wells 25018 and 25019 were damaged in April 2021 during a prescribed burn east of the HWL. The above-ground portions of the wells were repaired in June. New tops of casings were surveyed, and water levels were recorded at both locations.

2.2 Water Level Monitoring

Water levels were measured in 68 wells quarterly to evaluate the unconfined flow system (UFS) and confined flow system (CFS) flow conditions in the area of the Corrective Action Management Unit (CAMU) and to identify any significant changes in flow direction in the area of the CAMU. The wells used in HWL post-closure groundwater monitoring are presented in Table 2.2-1 and Figure 2.2-1.

Water level monitoring measurements are provided in Table 2.2-2. Figures 2.2-2 and 2.2-3 represent the April 2021 water table elevations for the UFS and the Denver Formation Lower Sandstone Unit within the UFS and CFS, respectively. The potentiometric surface of the UFS in

the vicinity of the HWL shows that across the entire CAMU, groundwater flow is generally to the north and northwest (Figure 2.2-2). No significant variations in groundwater flow directions have been identified during post-closure monitoring.

Figure 2.2-2 shows a more pronounced groundwater high along the west side of the HWL similar to the observed water table in 2020. This configuration of the water table is consistent with recharge from the grass-lined perimeter channel located along the west side of the HWL. This interpretation is further supported by the increasing trend in water elevations in other monitoring wells located on the west side of the HWL.

The potentiometric surface of the Denver Formation lower sandstone unit indicates flow from the CFS into UFS downgradient of the HWL and illustrates the water table across the area and the interaction between the two flow systems. Groundwater flow in the lower sandstone unit of the CFS merges with the UFS on the north, west, and east sides of the HWL and Enhanced Hazardous Waste Landfill (ELF). Currently, the zone where the UFS and CFS merge is illustrated by a dashed line for the approximate boundary indicating the lower sandstone unit in Figure 2.2-3. South of the line, the flow is confined to semi-confined, while north of the line the flow is unconfined where the confining unit is not present (TtFW 2004).

Water levels measured in well 25021, south and upgradient of the ELF, are not consistent with other monitoring wells within the CAMU area suggesting the screened zone is not hydraulically connected with the lower sandstone unit mapped in this report. Therefore, the water level measurement for well 25021 is not used in contouring the potentiometric surface for the lower sandstone unit.

2.3 Analytical Results

The HWL water quality network wells and Supplemental Operational Monitoring (SOM) wells are identified in Table 2.3-1. Wells 25086 and 25088 were installed dry as noted in the HWL PCGMP (Navarro 2019b). The wells are only sampled if groundwater levels are within the well screen and adequate groundwater is available. Wells 25086 and 25088 were dry during all 2021 sampling events. The groundwater and leachate samples collected at the HWL were submitted to Applied Research and Development Laboratory (ARDL) in Mount Vernon, Illinois for analysis of the analytes listed in Table 2.3-2. Included in this table are the 16 indicator compounds (ICs) evaluated during quarterly sampling events, and the full suite of analytes evaluated during the annual sampling event.

The groundwater samples were tested for the ICs listed in Table 2.3-2. The ICs are highlighted in bold text in Table 2.3-2.

The ICs selected as part of the monitoring program include the following:

- Arsenic
- Benzene (C₆H₆)
- Bicycloheptadiene (BCHPD)
- Carbon tetrachloride (CCL₄)
- Chloroform
- Dichlorodifluoromethane (CCL₂F₂)
- 1,1-dichloroethene (11DCE)
- Dicyclopentadiene (DCPD)
- Diisopropylmethyl phosphonate (DIMP)
- Dieldrin

- Chromium
- 1,1-dichloroethane (11DCLE)
- 1,2- dichloroethane (12DCLE)
- Lead
- Mercury
- 1,1,1-trichloroethane (111TCE)

The ICs detected in the HWL network wells, SOM wells and sumps are shown on Figures 2.3-1 and 2.3-2, respectively. Table 2.3-3 lists the quality control (QC) samples including field blanks and duplicates that were collected and analyzed as part of the quarterly and annual groundwater monitoring events in accordance with the SQAPP (Navarro 2019d).

The full suite of analytes detected in the HWL network wells, SOM wells, and sumps during the pre-operational, operational, closure, and post-closure monitoring periods are summarized in the Supporting Documentation folder.

2.3.1 HWL Network Wells Analytical Results

The wells sampled during the 2021 quarterly events in January, July, and October 2021, and the annual post-closure groundwater monitoring event in April and May at the HWL include the following upgradient and downgradient wells screened in the UFS and CFS.

<u>Upgradient</u>		<u>Downgradient</u>	
UFS	CFS	UFS	CFS
25102	25034	25086	25083
25121	25101	25087	25183
		25088	25195
		25194	

Well 25194 was bailed, rather than pumped, due to the low water volume all four quarters. During the fourth quarter, the well was bailed dry and only 2 gallons were removed prior to sampling, with sampling taking place over a 2-day period once enough water was available for collection. Wells 25086 and 25088 were dry during all sampling events in 2021. Well 25086 has been dry since monitoring began in 1996, while well 25088 has been dry most of the time with the exception two quarters during both 2015 and 2016.

2.3.1.1 Upgradient HWL Network Wells

Upgradient monitoring well 25102 was sampled quarterly and as part of the annual sampling in April. Upgradient monitoring wells 25034, 25101, and 25121 were sampled annually in April. The following ICs were detected in the upgradient wells:

UFS

Well 25102

- No detections

Well 25121

- Carbon tetrachloride – 2.84 µg/L (April)
- Chloroform – 0.226 µg/L (April)

CFS

Well 25034

- 1,1-Dichloroethene – 6.68 µg/L (April)
- Carbon tetrachloride – 0.196 µg/L (April)
- Chloroform – 0.377 µg/L (April)

Well 25101 – No detections

Detections of 1,1-dichloroethene, carbon tetrachloride, and chloroform in wells 25034 and 25121 are consistent with contaminants associated with the North Plants-Bedrock Ridge plumes. Concentrations of 1,1-dichloroethene in well 25034 have an increasing statistical trend, with the exception of a nondetection in 2015 (see the Excel file 25034 Summary.xlsx in Supporting Documentation Data Usability subfolder). The concentrations of carbon tetrachloride and chloroform continue to show a decreasing statistical trend in well 25121 (see the Excel file 25121 Summary.xlsx in Supporting Documentation Data Usability subfolder). Detections of 1,1-dichloroethene and carbon tetrachloride in these upgradient HWL wells suggest the wells are in the flow path of the North Plants-Bedrock Ridge plume on the eastern edge of the HWL. An increase or change in the concentrations suggests variability within the plume.

Additional compounds detected in upgradient wells include the following:

- | | |
|------------|---------------------|
| • Aluminum | • Kjeldahl nitrogen |
| • Ammonia | • Magnesium |
| • Barium | • Manganese |
| • Boron | • Nitrate |
| • Bromide | • Potassium |
| • Calcium | • Selenium |
| • Chloride | • Silver |
| • Copper | • Sodium |
| • Fluoride | • Sulfate |
| • Iron | • Zinc |

2.3.1.2 Downgradient HWL Network Wells

Downgradient HWL network wells 25085, 25087, 25183, 25194, and 25195 are sampled as part of the monitoring network. Monitoring well 25086 and 25088 continued to be dry in 2021 and were not sampled. Dieldrin and lead were the only ICs detected in the downgradient wells:

UFS

Well 25087

- Dieldrin
 - 0.00426 µg/L (July)
- Lead
 - 4.1 µg/L (May)
 - 3.4 µg/L (July)

Well 25194

- Dieldrin
 - 0.0235 µg/L (January)
 - 0.023 µg/L (April)
 - 0.0204 µg/L (July)
 - 0.0158 µg/L (October)
- Lead
 - 3 µg/L (July)

CFS

Well 25085

- No detections

Well 25183

- No detections

Well 25195

- No detections

Additional compounds detected in downgradient wells in 2021 include the following:

- | | |
|--------------------|---------------------|
| • alpha-Endosulfan | • Kjeldahl nitrogen |
| • Aluminum | • Magnesium |
| • Ammonia | • Manganese |
| • Barium | • Methoxychlor |
| • Boron | • Nitrate |
| • Bromide | • Potassium |
| • Calcium | • Selenium |
| • Chloride | • Silver |
| • Copper | • Sodium |
| • Endrin ketone | • Sulfate |
| • Fluoride | • Thallium |
| • Iron | • Zinc |
| • Isodrin | |

Of the additional compounds detected in the downgradient wells, aluminum, boron, barium, calcium, chloride, copper, endrin ketone, fluoride, isodrin, iron, Kjeldahl nitrogen, magnesium, methoxychlor, nitrate, potassium, selenium, sodium, sulfate, silver and zinc were detected in well 25194. As discussed in Section 3.1, potential sources of dieldrin in well 25194 were investigated further in 2017 in accordance with a Non-Routine Action Plan (NRAP-2016-004) and the *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Sampling and Analysis Plan* (Navarro 2016). Results of the investigation were documented in the *Hazardous Waste Landfill Groundwater Monitoring Wells*

25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Data Summary Report
(Navarro 2019c).

2.3.2 Supplemental Operational Monitoring Wells Analytical Results

SOM network wells 25091, 25099, 25189, and 25203 are sampled annually. SOM wells 25098 and 25100 were dry in 2021.

The original group of SOM wells was initially installed to identify changes in water quality that may be attributable to Cell 1 and Cell 2 liner construction as part of the LCS/LDS sump systems and provide additional water quality data in the vicinity of the HWL. Due to network changes approved in DCN-GWMON-009, all the designated SOM wells with the exception of 25203 are used to monitor the North Plants-Bedrock Ridge western plume boundary and evaluate potential impacts of the plume to the HWL groundwater monitoring program. The analytical data from the SOM wells are not used in the HWL statistical evaluations.

Well 25203, located on the southwestern side of the HWL, supports monitoring the UFS in this area. No ICs were detected in well 25203.

The ICs detected in the SOM wells 25091, 25099, and 25189 include:

- 1,1,1-Trichloroethane
- 1,1-Dichloroethene
- 1,1-Dichloroethane
- 1,2-Dichloroethane
- Carbon tetrachloride
- Chloroform
- DIMP
- Dieldrin
- Lead

Additional compounds detected in the SOM wells 25091, 25099, and 25189 include:

- Aluminum
- Ammonia
- Boron
- Barium
- Calcium
- Chloride
- Copper
- Fluoride
- Kjeldahl nitrogen
- Magnesium
- Nitrate
- Selenium
- Sodium
- Sulfate
- Zinc

Additional compounds detected in SOM well 25203 include:

- Aluminum
- Ammonia
- Boron
- Calcium
- Chloride
- Copper
- Fluoride
- Magnesium
- Manganese
- Nitrate
- Selenium
- Sodium
- Sulfate
- Zinc

2.3.3 HWL LCS and LDS Sumps Analytical Results

Per the HWL PCGMP (Navarro 2019b) sump sampling shall be performed prior to removal of wastewater from an HWL sump. Wastewater removal may be triggered by a high sump level or other wastewater management consideration.

The samples were collected from the LDS to meet the post-closure monitoring requirements specified in the HWL PCGMP (Navarro 2019b) and were used to evaluate the chemistry of the wastewater to determine potential leakage from the HWL. The ICs detected in the HWL sumps are presented in Figure 2.3-2. Analytical results from the 2021 sampling events at the LCS and LDS sumps are included in the Supporting Documentation folder.

2.3.3.1 LCS Sumps

The ICs detected in the HWL LCS sumps in 2021 include benzene, dichlorodifluoromethane, dicyclopentadiene, dieldrin, and DIMP.

The LCS analytical results are not used in the prediction limit calculations. The concentrations of ICs detected in the LCS sumps are consistent with wastes placed in the landfills, and the chemical groups used to determine potential groundwater impacts.

2.3.3.2 LDS Sumps

It is common for analytes to be detected in HWL LDS sump samples. Typically, the detections are attributed to contaminants in the LCS clay liner material and consolidation water, rather than indications of leaks in the liner system. The soil used to construct the compacted clay liners of the HWL contained low levels of RMA contaminants that only became detectable after they were mobilized in water and analyzed using methods with much lower method reporting limits (MRL) than what can be achieved in soil sample analyses.

The ICs detected in the HWL LDS sumps include dieldrin and DIMP. The concentrations of ICs detected in the LDS sumps included:

LDS1

No detections

LDS2

No detections

LDS3

Water levels were not high enough in 2021 to initiate sampling.

LDS4

- Dieldrin
 - 0.026 µg/L (October)
- DIMP
 - 1.26 µg/L (October)

Additional compounds detected in the LDS HWL sumps include the following:

- | | |
|--|----------------------|
| • alpha-Chlordane | • Endrin |
| • alpha-Endosulfan | • Fluoride |
| • Aluminum | • gamma-Chlordane |
| • Ammonia | • Heptachlor epoxide |
| • Barium | • Iron |
| • Boron | • Isodrin |
| • Bromide | • Kjeldahl nitrogen |
| • Calcium | • Magnesium |
| • Chloride | • Manganese |
| • Copper | • Nickel |
| • Dichlorodiphenyl dichloroethane (PPDDD) | • Potassium |
| • Dichlorodiphenyl dichloroethene (PPDDE) | • Silver |
| • Dichlorodiphenyl trichloroethane (PPDDT) | • Sodium |
| | • Sulfate |
| | • Zinc |

Table 2.3-4 below lists the 2021 analytical results that required Regulatory Agency notification in accordance with Table 3.0-2 of the *Hazardous Waste Landfill Post-Closure Plan* (Navarro 2019a). Copper exceeded the Watch List Trigger Level (HWL PCGMP Table 3.2.5-2). The Regulatory Agencies were notified of the single exceedance in 2022 via email with an accompanying NRAP.

Table 2.3-4 Non-Routine Action Plan Notifications

Analyte	NRAP Number	Classification	Sample Date	Concentration (µg/L)	Method Reporting Limit (µg/L)	Watch List Trigger (µg/L)
Location – LDS1						
Copper	2022-001	Watch List	3/1/2021	49.5	0.10	41.3

2.4 Analytical Data Review

The objective of the data review process is to determine whether the analytical results are acceptable for use in making decisions for the project. As a component of the data review process, the analytical data are evaluated against the data quality indicators Precision, Accuracy, Representativeness, Completeness, and Comparability (PARCC). These five parameters are identified in the SQAPP (Navarro 2019d) as important data quality indicators. The RMA OMC reviewed the PARCC parameters with respect to the data QC goals stated in the SQAPP (Navarro 2019d).

The sample results were evaluated against the data quality requirements and compared to the data quality objectives as presented in the HWL PCGMP (Navarro 2019b) and SQAPP (Navarro 2019d). Data review and verification activities were conducted in accordance with the SQAPP (Navarro 2019d). The evaluation limits discussed below are internal OMC limits based on historical data, and independent of evaluations performed by the laboratory. The results of these evaluations are described below.

The OMC conducted data validation on a representative subset of the HWL groundwater analytical data. Validation checklists were completed, and laboratory case narratives were reviewed to determine potential problems identified by the analysts. The completeness result for all analytes achieves the minimum specification of 90 percent goal. No data were flagged as rejected in 2021.

2.4.1 Precision

Precision is the measure of mutual agreement among measurements. Field precision was evaluated by collection and analysis of duplicate samples using the same analytical methods as investigative samples. Precision was evaluated quantitatively by measuring the variability, in terms of relative percent difference (RPD), between the pairs of results for the investigative and duplicate samples. The RPD values provide a relative measure of precision; lower RPD values indicate better precision between the results. Relative percent difference values less than or equal to 35 percent are considered acceptable. The RPD for a duplicate investigative sample pair is calculated using the following steps:

- Identify the field and laboratory duplicate investigative sample pair results.
- Identify parameters detected in both results for the pair identified in Step 1.
- Calculate the RPD value for the detected parameters identified in Step 2 using the following equation:

$$RPD = \frac{|x - y|}{\frac{(x + y)}{2}} \times 100$$

where:

x = Investigative sample result

y = Duplicate sample result

The duplicate/investigative pairs are evaluated for comparability. The RPD upper evaluation limit is 35 percent for all analytes. The investigative and duplicate results will be considered comparable if any of the following statements are true:

- If both sample results are less than the MRL
- If both sample results are greater than the MRL; but less than or equal to twice the MRL
- If both sample results are greater than twice the MRL and the RPD is less than or equal to the specified upper RPD limit
- If both sample results are greater than the MRL; one result is less than or equal to twice the MRL; one result is greater than twice the MRL; and the RPD is less than or equal to the specified upper limit
- If one sample result is less than the MRL; and one result is greater than the MRL and less than or equal to twice the MRL

The investigative and duplicate results will be considered not comparable if any of the following statements are true:

- If both sample results are greater than twice the MRL and the RPD is greater than the specified upper RPD limit
- If both sample results are greater than the MRL; one result is less than or equal to twice the MRL; one result is greater than twice the MRL; and the RPD is greater than the specified upper limit
- If one sample result is less than the MRL; and one result is greater than twice the MRL

A total of 453 duplicate pair analyses of HWL target analytes were performed. Duplicate and investigative results are considered comparable in 448 cases and not comparable in 5 cases. The RPD values for duplicate pairs identified as comparable and not comparable are provided in Excel files within the Supporting Documentation folder. The non-comparable investigative and duplicate data will be assigned a “Z” data qualifier with the comment “Duplicate and investigative values are not comparable.” The data are considered acceptable for their intended use and no additional action in addition to the data qualification is considered necessary.

2.4.2 Accuracy/Bias

Accuracy is the degree of agreement between an observed value (sample result) and an accepted reference value. Bias is the systematic or persistent distortion of a measurement process that causes errors in one direction (high or low). The terms accuracy and bias are used interchangeably. Accuracy/bias is indicated by percent recovery calculated from laboratory spike data using the following formula:

$$\text{Recovery Rate (\%)} = \frac{\text{Measured Value}}{\text{True Value}} \times 100$$

where:

Measured value = Value after the spike minus the value before the spike

True value = Value of the spike added

Accuracy/bias will be calculated based on results of laboratory control spikes and matrix spikes (MS). Laboratory control spikes utilize laboratory grade water with some additions of inorganic constituents to mimic RMA water. Matrix spikes utilize RMA water to account for matrix-related interferences.

The calculated recovery rate is compared to the lower and upper recovery rate limits specific to each analyte based on historical data. The 25th and 75th percentiles for each analyte are calculated. The interquartile range (IQR) is calculated by subtracting the 25th percentile value from the 75th percentile value. The lower and upper recovery warning limits for each analyte are determined by subtracting and adding 1.5 times the IQR to the 25th and 75th percentile values, respectively. The lower and upper recovery control limits are determined by subtracting and adding three times the IQR to the 25th and 75th percentile values, respectively. Data will not be qualified solely on a recovery rate outside the calculated recovery limits. Additional factors must be present to justify the data qualification. The historical spike recoveries used for the calculation of recovery evaluation limits for matrix spikes and laboratory control spikes are included in the Supporting Documentation folder.

The data utilized for the recovery rate calculations are limited to the spike values for the analytical lots of the investigative data included in the Supporting Documentation folder. Matrix spike values exceeding four times the spiked amount are excluded from the calculation since the MS could possibly be diluted out due to the high original concentration. Analyses with an ampersand (@) flag code (i.e., value is estimated) or “B” flag code (i.e., analyte found in the method blank or QC blank as well as the sample) were also excluded from recovery rate calculations. The spike recoveries used in the calculations are also included in the Supporting Documentation folder.

The average recovery rate for the 1,533 MS analyses was 87.3 percent. Recovery rates outside the lower or upper warning limits were observed in 47 analyses. Recovery rates outside the lower or upper control limits were observed in 12 analyses. A listing of the MS sample results outside the evaluation limits is included in the Supporting Documentation folder.

The average recovery rate for the 1,533 corresponding laboratory control spike analyses was 97.4 percent. Recovery rates outside the lower or upper warning limits were observed in 11 analyses. Recovery rates outside the lower or upper control limits were observed in four analyses. The laboratory control spike sample results outside the warning or control limits are included in the Supporting Documentation folder.

Laboratory control spike and MS recoveries outside the designated warning limits in both instances were observed in a single analysis, while laboratory control spike and MS recoveries

outside the designated control limits in both instances were not observed. No issues were identified requiring data qualification. Charts including the evaluation limits and spike recoveries for the HWL are included in the Supporting Documentation folder.

2.4.3 Representativeness

Representativeness refers to the selection and implementation of analytical methods, sampling protocols, and sample locations to ensure the analytical data results are representative of the media being sampled (e.g., water, soil, etc.) and the conditions being measured.

Representativeness is evaluated by reviewing monitoring program design and implementation, as well as field and laboratory blank samples. Design of the monitoring program is reviewed qualitatively to assess whether the objectives were satisfied. Implementation of the monitoring program is reviewed qualitatively to evaluate whether the planned procedures were followed. A quantitative review of the quality QC blank results indicates whether influences outside the measurement systems have affected the analyses and interpretation of the media and conditions.

Sample locations, sampling frequency, and sample collection procedures applied during groundwater monitoring are described in the HWL PCGMP (Navarro 2019b). The program is designed to provide water quality data in the area of the landfill and implemented as defined in the PCGMP. Thus, the data are judged representative of the water quality characteristics for the program.

Field blanks are collected and analyzed to evaluate possible cross contamination of the investigative samples. Rinse blanks are not required since dedicated equipment is used to sample the wells and sumps. The number of QC samples collected, and QC results evaluated for qualification are included in Table 2.3-3 and are also provided in the Supporting Documentation folder.

A total of 73 field blank analyses were performed. There were no field blank analyses above the MRL. No qualification of the data is required.

In addition, the laboratories prepared and analyzed method blanks as part of their analytical protocols. Method blanks measure potential contamination from laboratory sources such as glassware, reagents and laboratory water. There were 1,726 method blank analyses in 2021 with two detections above the MRL. Data qualification is not necessary as the associated investigative data is below the MRL.

2.4.4 Completeness

Completeness is the amount of valid data obtained from a measurement system compared to the amount that were expected and needed to meet the project goals. Valid analytical data are those data that have been identified as usable and included in the Rocky Mountain Arsenal Environmental Database (RMAED). The SQAPP (Navarro 2019d) sets the completeness goal for the sampling program at 90 percent.

In 2021, there were no rejected data. The analytical results of monitoring are representative of the groundwater quality with the exception of qualified data. Rejected data are not removed

from the RMAED; however, they are not used to evaluate the HWL groundwater data. Data qualified as “@” are not filtered out of the database. While not rejected, these qualified data are considered estimated due to the concentration being above the linear range of the instrument.

Completeness was calculated at 100 percent. The completeness goal of 90 percent was achieved. All results were determined to be acceptable by the laboratory.

2.4.5 Comparability

Comparability is the confidence with which one data set can be evaluated relative to another. Standard sampling and analysis techniques, based on certified analytical methods approved by the OMC or promulgated SW-846 methods, and standard procedures for sample collection were used throughout the groundwater monitoring programs at the HWL. Consistent procedures for the reporting and management of the data generated were also followed. All data are considered comparable.

2.4.6 Summary

The purpose of the PARCC evaluation is to evaluate whether the data are usable and adequate to properly characterize the water quality conditions present at the site. Based on the findings of the PARCC evaluation, the sample results are considered valid and usable for their intended purpose. Qualified data are not rejected but should be appropriately considered when used. Data quality requirements were sufficiently met for the analytical data, and data are appropriate for use in evaluation of the water quality conditions present at the site. The primary objectives of the sampling program were met.

2.4.7 Data Usability Evaluation

A data usability evaluation was conducted on 2,390 records. The evaluation identified four statistical outliers. The data are considered acceptable for their intended use and no additional action is considered necessary.

The Mann-Kendall test for trends identified 103 decreasing analyte trends and 117 increasing analyte trends. A listing of the identified outliers and trends is included on the attached data CD in the HWL 2021 Data Usability Summary folder (HWL Data_Usability_Summary_FY21.xlsx).

The evaluation did not positively identify data quality issues; thus, the data are considered to be of acceptable quality and meets or exceeds the established data quality objectives. The data are of the correct type, quality, and quantity to support the intended use.

3.0 STATISTICAL EVALUATIONS

The statistical evaluation of data includes comparing upgradient water quality to downgradient compliance wells utilizing prediction intervals that are calculated for each IC using upgradient water quality data. The prediction limits discussed in this section refer to the upper limit of each analyte-specific prediction interval. Comparison of downgradient water quality data to prediction limits should provide an indication whether groundwater has been impacted by the HWL.

The wells used to calculate prediction limits and statistical evaluations are presented in Table 3.0-1. A prediction interval was calculated for each IC, which included upgradient water quality data through the 2020 post-closure monitoring period. Section 3.1 presents the results of the statistical evaluations for the HWL. The general approach for determining and evaluating prediction limits for the HWL is consistent with United States Environmental Protection Agency guidance document, *Statistical Analysis of Groundwater Monitoring Data at RCRA Facilities, Unified Guidance* (EPA 2009).

The MRLs can change based on the analytical method re-certification every three years as required by the SQAPP. In January 2021, the MRL for dieldrin was lowered to 0.00252, and this revised MRL is reflected in Table 3.0-2.

ChemStat software is utilized to calculate the prediction limit values, and statistical software output is available in the Supporting Documentation folder. The prediction limit values for 2022 are included in Table 3.0-3. If a compound is not detected in any sample, the prediction limit for the analyte is the 99 percent upper confidence limit (UCL) of the MRL. For the purpose of this report, the 99 percent UCL is defined as 1.3 times the MRL.

3.1 2021 Prediction Limits and the Current HWL Water Quality Data

Table 3.0-2 presents the 2021 prediction limits that were calculated from upgradient well data collected during the pre-operational, operational, closure, and post-closure groundwater monitoring periods (1996-2020).

The downgradient results from the water quality sampling completed during the 2021 post-closure groundwater monitoring period were compared with the prediction limits presented in Table 3.0-2 to determine if groundwater quality was impacted by the HWL in 2021.

Dieldrin and lead were the only ICs detected in the downgradient wells. Lead was detected in UFS wells 25087 and 25194 at concentrations ranging from 3 to 4.1 µg/L. Lead was not detected in any of the three CFS wells. The lead detections did not exceed the 2021 prediction limit (15 µg/L). Dieldrin was detected at a concentration of 0.00426 µg/L in downgradient well 25087. Dieldrin was detected at concentrations ranging from 0.0158 to 0.0235 µg/L in downgradient well 25194. Dieldrin concentrations in wells 25087 and 25194 did not exceed the 2021 prediction limit of 0.05 µg/L.

Further evaluation of dieldrin included an intrawell comparison performed using a combined Shewhart-CUSUM control chart to determine whether the HWL impacted the presence of dieldrin in groundwater at well 25194. The plotted data were collected quarterly from July 2011 through October 2021, with the initial eight dieldrin samples in well 25194 used as the baseline. The baseline data were determined to be from a normal distribution with no outliers. These data were used to calculate the cumulative sum (CUSUM) and control limit. The EPA guidance, *Statistical Analysis of Groundwater Monitoring Data at RCRA Facilities, Unified Guidance* (EPA 2009), recommends using a control limit equal to five (h=5) standard deviations above the mean value for baseline data. The combined Shewhart-CUSUM control chart for dieldrin is included as Figure 3.1-1.

Figure 3.1-1 shows that the dieldrin concentrations began to decrease after April 2016, although the CUSUM continued to increase. Groundwater levels appear higher in well 25194, beginning in July 2015, which may have mobilized residual contamination that the Army believes existed prior to construction of the HWL. In 2021, measured dieldrin concentrations did not exceed the control limit, and the calculated CUSUM only exceeded the control limit in the sample collected in April 2019 as the CUSUM has generally been decreasing since December 2017.

Interpretation of the current control chart shows an apparent decreasing trend, as is also evident in measured concentrations, because the calculated CUSUM is less than the control limit (Figure 3.1-1). Fluctuations in dieldrin concentrations may indicate variability related to the water level changes. Additionally, the recent dieldrin concentrations in well 25194 are higher than those measured in LDS3 during the post-closure period, which is the nearest LDS sump to well 25194, indicating that the sump is not a likely source of groundwater contamination in this well.

Control charts are useful in evaluating the potential for future impacts to groundwater based on comparisons to baseline data. It should be noted that no baseline data were collected for well 25194 or its predecessor before the HWL was constructed, and the dieldrin concentrations observed since the remedy may be within the historical range of the suspected pre-existing contamination. The intrawell comparison was included in the PCGMP as another method to evaluate groundwater data in the HWL monitoring wells in addition to the use of prediction limits.

The HWL PCP also provides for the use of trend analysis to evaluate groundwater quality. Further evaluation of dieldrin concentrations using Mann-Kendall trend analysis shows that for data collected from 2013 through 2021, dieldrin concentrations have exhibited a decreasing trend. Supporting documentation related to the Mann-Kendall trend analysis is provided in the Supporting Documentation folder.

The source of dieldrin in well 25194 was evaluated in accordance with NRAP-2016-004 and the *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Sampling and Analysis Plan* (Navarro 2016). The results of the evaluation were presented in the *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Data Summary Report* (Navarro 2019c). The Data Summary Report noted that the source of dieldrin detected in well 25194 during routine quarterly sampling was not definitively identified and recommended the continuation of routine sampling in accordance with the HWL PCGMP.

Based on these statistical evaluations and trend analysis, it is concluded that groundwater quality in the vicinity of the HWL has not been affected by operations, closure, or post-closure operations and maintenance (O&M) of the landfill.

3.2 2022 Prediction Limits and the Future HWL Water Quality Data

Table 3.0-3 presents the upper prediction limits that will be applied to downgradient wells 25085, 25087, 25183, 25194, and 25195 for the 2022 sampling events. The MRLs can change based on the method re-certification required every three years by the SQAPP. The MRL for

dieldrin was lowered in January 2021. The prediction limits calculated for 2022 were not affected by MRL changes as presented in Table 3.0-3.

4.0 SUMMARY

The following summary is based on the groundwater and wastewater monitoring results for the 2021 post-closure monitoring at the HWL:

- The groundwater in the UFS and CFS flows to the north-northwest and is consistent with previous groundwater monitoring events for the HWL.
- Based on the findings of the PARCC evaluation, the analytical data collected are of acceptable quality for intended uses.
- 1,1-Dichloroethene, carbon tetrachloride and chloroform were detected in the upgradient wells.
- Dieldrin and lead were the only ICs detected in the downgradient wells.
- The LCS sample results indicate that the ICs used in the statistical evaluations for the HWL are appropriate for the types of contaminants present in the HWL leachate. The ICs detected in the LCS are representative of the waste placed in the HWL.
- The ICs detected in 2021 in the HWL LDS sumps include dieldrin and DIMP.
- Copper was detected above the Watch List Trigger Level in sump LDS1 during the quarterly sampling event in March 2021 at a concentration of 49.5 µg/L. The regulatory agencies were notified of the exceedance via email on January 17, 2022 with the transmittal of NRAP-2022-001, which was discussed at the January 26, 2022 quarterly meeting and approved by the regulatory agencies on February 3, 2022.
- No ICs detected in downgradient monitoring wells exceeded the calculated 2021 prediction limits.
- Statistical evaluations indicated that no detected ICs exceeded their respective prediction limits. The combined Shewhart-CUSUM control chart for dieldrin showed concentrations did not exceed the control limit or the UPL, and the calculated CUSUM did not exceed the control limit, thus indicating a general downward trend in dieldrin. Based on statistical trend analysis of dieldrin using the Mann-Kendall test, dieldrin concentrations also show a decreasing trend since 2013.
- Fluctuations in dieldrin concentrations may indicate variability related to the water level changes. Additionally, the recent dieldrin concentrations in well 25194 are higher than those measured in the nearest LDS sump LDS3 where dieldrin was not detected in 2020, and do not corroborate any type of release from the HWL to groundwater.
- Prediction limit values for all ICs were re-evaluated for 2022. No prediction limits were adjusted.

Based on the statistical evaluations and trend analysis, groundwater quality in the vicinity of the HWL has not been affected by operations, closure, or post-closure O&M of the landfill.

5.0 REFERENCES

EPA (U.S. Environmental Protection Agency)

- 2009 *Statistical Analysis of Groundwater Monitoring Data at RCRA Facilities Unified Guidance*, EPA 530/R-09-007. March.

Navarro (Navarro Research and Engineering, Inc.)

- 2019a *Hazardous Waste Landfill, Post Closure Plan*, Revision 4. December 9, 2019.
- 2019b *Hazardous Waste Landfill, Post-Closure Groundwater Monitoring Plan*. Revision 4. December 9, 2019.
- 2019c *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Data Summary Report*. Revision 0. November 18, 2019.
- 2019d *Rocky Mountain Arsenal Sampling Quality Assurance Project Plan*. Revision 2. January 30, 2019.
- 2016 *Hazardous Waste Landfill Groundwater Monitoring Wells 25194 and 25184 Subsurface Soil and Landfill Stormwater Runoff Sampling and Analysis Plan*. Revision 0. November 17, 2016.

TtFW (Tetra Tech FW, Inc.)

- 2004 *Hazardous Waste Landfill and Landfill Wastewater Treatment System Annual Groundwater Monitoring Report for July 2002–June 2003*. Revision 0. April 1, 2004.

This page intentionally left blank.



TABLES

This page intentionally left blank.

Table 2.2-1. HWL Water Level Monitoring Network

Well ID	Aquifer	Top of Casing Elevation (feet amsl)	Bottom of Screen Elevation (feet amsl)
<i>Unconfined Flow System</i>			
25003	Alluvial	5194.26	5151.60
25041	Alluvial	5210.81	5179.61
25048	Alluvial	5190.01	5150.20
25054	Alluvial	5207.94	5168.10
26178	Alluvial	5214.73	5181.56
26182	Alluvial	5217.22	5174.27
26184	Alluvial	5214.94	5173.84
25018 ²	Alluvial/Denver Formation	5195.61	5148.30
25059	Alluvial/Denver Formation	5208.97	5162.97
25184 ¹	Alluvial/Denver Formation	5206.83	5179.24
25189	Alluvial/Denver Formation	5202.30	5141.30
25194	Alluvial/Denver Formation	5215.60	5179.40
25203	Alluvial/Denver Formation	5236.10	5176.10
25004	Denver Formation	5264.96	5183.20
25015	Denver Formation	5197.23	5154.50
25022	Denver Formation	5263.66	5211.70
25023	Denver Formation	5265.08	5197.40
25027	Denver Formation	5224.84	5179.00
25032	Denver Formation	5254.89	5220.20
25086	Denver Formation	5212.53	5183.14
25087	Denver Formation	5209.75	5141.37
25088	Denver Formation	5209.61	5190.87
25091	Denver Formation	5217.43	5132.51
25092	Denver Formation	5246.11	5179.49
25098	Denver Formation	5212.80	5184.34
25099	Denver Formation	5212.40	5139.73
25100	Denver Formation	5216.99	5185.87
25102	Denver Formation	5243.61	5171.62
25105	Denver Formation	5255.46	5204.69
25106	Denver Formation	5261.43	5188.97
25120	Denver Formation	5237.95	5177.80
25121	Denver Formation	5251.67	5179.06
25122	Denver Formation	5260.58	5219.37
25500	Denver Formation	5258.74	5201.09
25502	Denver Formation	5223.60	5169.10

Table 2.2-1. HWL Water Level Monitoring Network

Well ID	Aquifer	Top of Casing Elevation (feet amsl)	Bottom of Screen Elevation (feet amsl)
26040	Denver Formation	5197.40	5146.40
26051	Denver Formation	5218.60	5158.30
26073	Denver Formation	5225.41	5173.05
26097	Denver Formation	5242.25	5172.70
26099	Denver Formation	5232.31	5232.70
26158	Denver Formation	5214.88	5160.30
26159	Denver Formation	5233.75	5188.00
26164	Denver Formation	5189.26	5136.70
26170	Denver Formation	5184.02	5133.90
26175	Denver Formation	5206.29	5145.43
26176	Denver Formation	5206.02	5159.89
26177	Denver Formation	5214.92	5153.10
26179	Denver Formation	5224.89	5156.24
26180	Denver Formation	5224.57	5170.86
26181	Denver Formation	5217.82	5161.29
26183	Denver Formation	5214.81	5157.29
26186	Denver Formation	5207.79	5140.58
36186	Denver Formation	5286.23	5122.70
Confined Flow System			
25016	Denver Formation	5198.31	5132.10
25017	Denver Formation	5197.67	5117.40
25019 ²	Denver Formation	5193.85	5109.73
25020	Denver Formation	5195.25	5040.27
25021	Denver Formation	5240.10	5111.50
25024	Denver Formation	5265.04	5165.20
25034	Denver Formation	5255.60	5130.60
25085	Denver Formation	5212.91	5134.48
25093	Denver Formation	5245.76	5123.03
25101	Denver Formation	5251.19	5124.83
25123	Denver Formation	5259.86	5123.34
25183	Denver Formation	5206.80	5147.30
25195	Denver Formation	5215.50	5134.50
26150	Denver Formation	5220.96	5111.90
26185	Denver Formation	5208.53	5115.64

Notes: ¹Well 25184 installed per OCN-HWL-2017-001. ²Wells 25018 and 25019 repaired and resurveyed in 2021.
amsl – above mean sea level

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
<i>Unconfined Flow System</i>				
25003	2021-01-18	41.82	5194.26	5152.44
25003	2021-04-12	41.88	5194.26	5152.38
25003	2021-07-20	41.76	5194.26	5152.50
25003	2021-10-20	41.77	5194.26	5152.49
25004	2021-01-18	46.31	5264.96	5218.65
25004	2021-04-12	46.52	5264.96	5218.44
25004	2021-07-19	46.72	5264.96	5218.24
25004	2021-10-21	46.83	5264.96	5218.13
25015	2021-01-18	37.89	5197.23	5159.34
25015	2021-04-12	38.70	5197.23	5158.53
25015	2021-07-20	37.72	5197.23	5159.51
25015	2021-10-20	37.81	5197.23	5159.42
25018	2021-01-18	31.41	5195.62	5164.21
25018	2021-04-12	NA	5195.62	Repaired in June
25018	2021-07-19	31.07	5195.61	5164.54
25018	2021-10-21	31.53	5195.61	5164.08
25022	2021-01-18	43.40	5263.66	5220.26
25022	2021-04-12	43.50	5263.66	5220.16
25022	2021-07-19	43.58	5263.66	5220.08
25022	2021-10-21	43.56	5263.66	5220.10
25023	2021-01-18	46.23	5265.08	5218.85
25023	2021-04-12	46.35	5265.08	5218.73
25023	2021-07-19	46.41	5265.08	5218.67
25023	2021-10-21	46.45	5265.08	5218.63
25027	2021-01-18	44.15	5224.84	5180.69
25027	2021-04-08	44.18	5224.84	5180.66
25027	2021-07-19	44.21	5224.84	5180.63
25027	2021-10-19	44.21	5224.84	5180.63
25032	2021-01-18	28.35	5254.89	DRY
25032	2021-04-08	28.35	5254.89	DRY
25032	2021-07-19	28.35	5254.89	DRY
25032	2021-10-19	28.34	5254.89	DRY
25041	2021-01-18	26.30	5210.81	5184.51
25041	2021-04-12	26.60	5210.81	5184.21
25041	2021-07-19	25.96	5210.81	5184.85
25041	2021-10-21	26.44	5210.81	5184.37
25048	2021-01-18	18.54	5190.01	5171.47
25048	2021-04-12	18.33	5190.01	5171.68
25048	2021-07-19	18.12	5190.01	5171.89

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25048	2021-10-21	18.62	5190.01	5171.39
25054	2021-01-18	34.10	5207.94	5173.84
25054	2021-04-12	33.96	5207.94	5173.98
25054	2021-07-19	33.72	5207.94	5174.22
25054	2021-10-21	34.08	5207.94	5173.86
25059	2021-01-18	30.52	5208.97	5178.45
25059	2021-04-12	30.33	5208.97	5178.64
25059	2021-07-19	30.16	5208.97	5178.81
25059	2021-10-21	30.62	5208.97	5178.35
25086	2021-01-18	29.71	5212.53	DRY
25086	2021-04-08	29.70	5212.53	DRY
25086	2021-07-19	29.71	5212.53	DRY
25086	2021-10-19	29.71	5212.53	DRY
25087	2021-01-18	43.93	5209.75	5165.82
25087	2021-04-08	43.75	5209.75	5166.00
25087	2021-07-19	43.68	5209.75	5166.07
25087	2021-10-19	43.56	5209.75	5166.19
25088	2021-01-18	19.36	5209.61	DRY
25088	2021-04-08	19.37	5209.61	DRY
25088	2021-07-19	19.36	5209.61	DRY
25088	2021-10-19	19.02	5209.61	DRY
25091	2021-01-18	47.94	5217.43	5169.49
25091	2021-04-08	47.70	5217.43	5169.73
25091	2021-07-19	47.64	5217.43	5169.79
25091	2021-10-19	47.65	5217.43	5169.78
25092	2021-01-18	65.27	5246.11	5180.84
25092	2021-04-08	65.15	5246.11	5180.96
25092	2021-07-19	65.26	5246.11	5180.85
25092	2021-10-19	65.24	5246.11	5180.87
25098	2021-01-18	28.86	5212.80	DRY
25098	2021-04-08	28.84	5212.80	DRY
25098	2021-07-19	28.86	5212.80	DRY
25098	2021-10-19	28.83	5212.80	DRY
25099	2021-01-18	44.01	5212.40	5168.39
25099	2021-04-08	43.80	5212.40	5168.60
25099	2021-07-19	43.59	5212.40	5168.81
25099	2021-10-19	43.66	5212.40	5168.74
25100	2021-01-18	31.32	5216.99	DRY
25100	2021-04-08	31.31	5216.99	DRY
25100	2021-07-19	31.31	5216.99	DRY

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25100	2021-10-19	31.31	5216.99	DRY
25102	2021-01-18	63.04	5243.61	5180.57
25102	2021-04-08	62.89	5243.61	5180.72
25102	2021-07-19	63.13	5243.61	5180.48
25102	2021-10-19	63.17	5243.61	5180.44
25105	2021-01-18	37.76	5255.46	5217.70
25105	2021-04-12	37.70	5255.46	5217.76
25105	2021-07-19	37.84	5255.46	5217.62
25105	2021-10-19	37.69	5255.46	5217.77
25106	2021-01-18	56.16	5261.43	5205.27
25106	2021-04-12	56.12	5261.43	5205.31
25106	2021-07-19	56.40	5261.43	5205.03
25106	2021-10-19	56.06	5261.43	5205.37
25120	2021-01-18	48.75	5237.95	5189.20
25120	2021-04-08	48.80	5237.95	5189.15
25120	2021-07-19	48.35	5237.95	5189.60
25120	2021-10-19	47.58	5237.95	5190.37
25121	2021-01-18	71.28	5251.67	5180.39
25121	2021-04-08	71.09	5251.67	5180.58
25121	2021-07-19	71.30	5251.67	5180.37
25121	2021-10-19	71.18	5251.67	5180.49
25122	2021-01-18	39.15	5260.58	DRY
25122	2021-04-08	39.15	5260.58	DRY
25122	2021-07-19	39.15	5260.58	DRY
25122	2021-10-19	39.14	5260.58	DRY
25184	2021-01-18	28.02	5206.83	DRY
25184	2021-04-08	28.02	5206.83	DRY
25184	2021-07-19	28.02	5206.83	DRY
25184	2021-10-19	28.00	5206.83	DRY
25189	2021-01-18	35.76	5202.30	5166.54
25189	2021-04-12	35.25	5202.30	5167.05
25189	2021-07-19	35.37	5202.30	5166.93
25189	2021-10-19	35.53	5202.30	5166.77
25194	2021-01-18	34.58	5215.60	5181.02
25194	2021-04-08	34.33	5215.60	5181.27
25194	2021-07-19	35.80	5215.60	5179.80
25194	2021-10-19	34.35	5215.60	5181.25
25203	2021-01-18	55.56	5236.10	5180.54
25203	2021-04-08	55.35	5236.10	5180.75
25203	2021-07-19	55.44	5236.10	5180.66

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25203	2021-10-19	55.58	5236.10	5180.52
25500	2021-01-18	40.15	5258.74	5180.54
25500	2021-04-12	40.37	5258.74	5180.75
25500	2021-07-19	40.55	5258.74	5180.66
25500	2021-10-19	40.53	5258.74	5180.52
25502	2021-01-18	39.05	5223.60	5218.59
25502	2021-04-12	38.90	5223.60	5218.37
25502	2021-07-19	38.69	5223.60	5218.19
25502	2021-10-21	39.06	5223.60	5218.21
26040	2021-01-18	49.94	5197.40	5184.55
26040	2021-04-08	49.94	5197.40	5184.70
26040	2021-07-20	49.92	5197.40	5184.91
26040	2021-10-20	49.96	5197.40	5184.54
26051	2021-01-18	55.52	5218.60	5147.46
26051	2021-04-08	55.53	5218.60	5147.46
26051	2021-07-20	55.74	5218.60	5147.48
26051	2021-10-20	55.89	5218.60	5147.44
26073	2021-01-18	47.65	5225.41	5163.08
26073	2021-04-08	47.64	5225.41	5163.07
26073	2021-07-20	47.67	5225.41	5162.86
26073	2021-10-20	47.69	5225.41	5162.71
26097	2021-01-20	56.84	5242.25	5177.76
26097	2021-04-08	56.70	5242.25	5177.77
26097	2021-07-20	57.21	5242.25	5177.74
26097	2021-10-20	57.39	5242.25	5177.72
26099	2021-01-18	49.82	5232.31	5185.41
26099	2021-04-08	49.75	5232.31	5185.55
26099	2021-07-20	49.70	5232.31	5185.04
26099	2021-10-19	49.58	5232.31	5184.86
26158	2021-01-18	34.75	5214.88	5182.49
26158	2021-04-08	34.66	5214.88	5182.56
26158	2021-07-20	34.89	5214.88	5182.61
26158	2021-10-20	35.07	5214.88	5182.73
26159	2021-01-18	40.15	5233.75	5203.36
26159	2021-04-12	40.37	5233.75	5203.29
26159	2021-07-19	40.55	5233.75	5202.64
26159	2021-10-19	40.53	5233.75	5202.67
26164	2021-01-18	44.81	5189.26	5144.45
26164	2021-04-08	44.78	5189.26	5144.48
26164	2021-07-20	44.89	5189.26	5144.37

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
26164	2021-10-20	44.89	5189.26	5144.37
26170	2021-01-18	44.02	5184.02	5140.00
26170	2021-04-08	44.05	5184.02	5139.97
26170	2021-07-20	44.09	5184.02	5139.93
26170	2021-10-20	44.12	5184.02	5139.90
26175	2021-01-18	49.15	5206.29	5157.14
26175	2021-04-08	49.02	5206.29	5157.27
26175	2021-07-20	49.19	5206.29	5157.10
26175	2021-10-20	49.29	5206.29	5157.00
26176	2021-01-18	47.31	5206.02	DRY
26176	2021-04-08	47.30	5206.02	DRY
26176	2021-07-20	47.29	5206.02	DRY
26176	2021-10-20	47.29	5206.02	DRY
26177	2021-01-18	56.24	5214.92	5158.68
26177	2021-04-08	56.16	5214.92	5158.76
26177	2021-07-20	56.12	5214.92	5158.80
26177	2021-10-20	55.85	5214.92	5159.07
26178	2021-01-18	34.32	5214.73	DRY
26178	2021-04-08	34.33	5214.73	DRY
26178	2021-07-20	34.33	5214.73	DRY
26178	2021-10-20	34.34	5214.73	DRY
26179	2021-01-18	55.67	5224.89	5169.22
26179	2021-04-08	55.58	5224.89	5169.31
26179	2021-07-20	56.01	5224.89	5168.88
26179	2021-10-20	56.19	5224.89	5168.70
26180	2021-01-18	46.74	5224.57	5177.83
26180	2021-04-08	46.78	5224.57	5177.79
26180	2021-07-20	46.84	5224.57	5177.73
26180	2021-10-20	46.86	5224.57	5177.71
26181	2021-01-18	49.79	5217.82	5168.03
26181	2021-04-08	49.60	5217.82	5168.22
26181	2021-07-20	50.08	5217.82	5167.74
26181	2021-10-20	50.29	5217.82	5167.53
26182	2021-01-18	40.84	5217.22	5176.38
26182	2021-04-08	40.84	5217.22	5176.38
26182	2021-07-20	40.88	5217.22	5176.34
26182	2021-10-20	40.90	5217.22	5176.32
26183	2021-01-18	48.45	5214.81	5166.36
26183	2021-04-08	48.46	5214.81	5166.35
26183	2021-07-20	48.69	5214.81	5166.12

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
26183	2021-10-20	48.85	5214.81	5165.96
26184	2021-01-18	42.49	5214.94	DRY
26184	2021-04-08	42.47	5214.94	DRY
26184	2021-07-20	42.47	5214.94	DRY
26184	2021-10-20	42.46	5214.94	DRY
26186	2021-01-18	42.89	5207.79	5164.90
26186	2021-04-08	42.90	5207.79	5164.89
26186	2021-07-20	43.09	5207.79	5164.70
26186	2021-10-20	43.25	5207.79	5164.54
36186	2021-01-18	49.34	5286.23	5236.89
36186	2021-04-12	49.53	5286.23	5236.70
36186	2021-07-19	44.87	5286.23	5241.36
36186	2021-10-19	45.32	5286.23	5240.91
Confined Flow System				
25016	2021-01-18	43.28	5198.31	5155.03
25016	2021-04-12	43.30	5198.31	5155.01
25016	2021-07-20	43.16	5198.31	5155.15
25016	2021-10-20	43.28	5198.31	5155.03
25017	2021-01-18	45.06	5197.67	5152.61
25017	2021-04-12	44.92	5197.67	5152.75
25017	2021-07-20	45.01	5197.67	5152.66
25017	2021-10-20	45.07	5197.67	5152.60
25019	2021-01-18	32.81	5195.00	5162.19
25019	2021-04-12	NA	5195.00	Repaired in June
25019	2021-07-19	31.67	5193.85	5162.18
25019	2021-10-21	31.73	5193.85	5162.12
25020	2021-01-18	46.98	5195.25	5148.27
25020	2021-04-12	46.74	5195.25	5148.51
25020	2021-07-19	46.72	5195.25	5148.53
25020	2021-10-21	47.24	5195.25	5148.01
25021	2021-01-18	65.94	5240.10	5174.16
25021	2021-04-12	65.52	5240.10	5174.58
25021	2021-07-20	65.64	5240.10	5174.46
25021	2021-10-21	66.09	5240.10	5174.01
25024	2021-01-18	61.87	5265.04	5203.17
25024	2021-04-12	62.22	5265.04	5202.82
25024	2021-07-19	61.97	5265.04	5203.07
25024	2021-10-21	62.36	5265.04	5202.68
25034	2021-01-18	82.97	5255.60	5172.63
25034	2021-04-08	82.76	5255.60	5172.84

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25034	2021-07-19	83.44	5255.60	5172.16
25034	2021-10-19	82.71	5255.60	5172.89
25085	2021-01-18	48.51	5212.91	5164.40
25085	2021-04-08	48.44	5212.91	5164.47
25085	2021-07-19	48.45	5212.91	5164.46
25085	2021-10-19	48.15	5212.91	5164.76
25093	2021-01-18	74.22	5245.76	5171.54
25093	2021-04-08	74.08	5245.76	5171.68
25093	2021-07-19	74.55	5245.76	5171.21
25093	2021-10-19	74.23	5245.76	5171.53
25101	2021-01-18	77.50	5251.19	5173.69
25101	2021-04-08	77.41	5251.19	5173.78
25101	2021-07-19	77.51	5251.19	5173.68
25101	2021-10-19	77.39	5251.19	5173.80
25123	2021-01-18	84.41	5259.86	5175.45
25123	2021-04-08	84.32	5259.86	5175.54
25123	2021-07-19	84.35	5259.86	5175.51
25123	2021-10-19	84.42	5259.86	5175.44
25183	2021-01-18	43.05	5206.80	5163.75
25183	2021-04-08	42.95	5206.80	5163.85
25183	2021-07-19	42.78	5206.80	5164.02
25183	2021-10-19	42.57	5206.80	5164.23
25195	2021-01-18	49.96	5215.50	5165.54
25195	2021-04-08	49.97	5215.50	5165.53
25195	2021-07-19	49.80	5215.50	5165.70
25195	2021-10-19	49.62	5215.50	5165.88
26150	2021-01-18	49.05	5220.96	5171.91
26150	2021-04-08	49.05	5220.96	5171.91
26150	2021-07-20	49.38	5220.96	5171.58
26150	2021-10-20	49.47	5220.96	5171.49
26185	2021-01-18	56.64	5214.88	5151.89
26185	2021-04-08	56.55	5214.88	5151.98
26185	2021-07-20	56.84	5214.88	5151.69
26185	2021-10-20	56.88	5214.88	5151.65

Note: Wells 25018 and 25019 repaired and resurveyed in 2021.

amsl – above mean sea level

Table 2.3-1. HWL Water Quality Monitoring Networks

Well Network	Well Number	Groundwater Flow System	Aquifer	Upgradient/ Downgradient
HWL	25034	Confined	Denver Formation	Upgradient
HWL	25183	Confined	Denver Formation	Downgradient
HWL	25085	Confined	Denver Formation	Downgradient
HWL	25086	Unconfined	Denver Formation	Downgradient (DRY)
HWL	25087	Unconfined	Denver Formation	Downgradient
HWL	25088	Unconfined	Denver Formation	Downgradient (DRY)
HWL	25194	Unconfined	Denver Formation	Downgradient
HWL	25195	Confined	Denver Formation	Downgradient
HWL	25101	Confined	Denver Formation	Upgradient
HWL	25102	Unconfined	Denver Formation	Upgradient
HWL	25121	Unconfined	Denver Formation	Upgradient
SOM	25189	Unconfined	Denver Formation	NA
SOM	25091	Unconfined	Denver Formation	NA
SOM	25098	Unconfined	Denver Formation	NA
SOM	25099	Unconfined	Denver Formation	NA
SOM	25100	Unconfined	Denver Formation	NA
SOM	25203	Unconfined	Denver Formation	NA

Note: Upgradient HWL wells and SOM wells are sampled annually in April.

DRY – Dry well in 2020

HWL – Hazardous Waste Landfill

SOM – Supplemental Operational Monitoring

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
<i>Volatile Organic Compounds by Gas Chromatography/Mass Spectrometry</i>	
1,1,1-Trichloroethane	111TCE
1,1,2-Trichloroethane	112TCE
1,1-Dichloroethane	11DCLE
1,1-Dichloroethene	11DCE
1,2-Dichloroethane	12DCLE
1,2-Dichlorobenzene	12DCLB
1,3-Dichlorobenzene	13DCLB
1,4-Dichlorobenzene	14DCLB
1,2-Dichloropropane	12DCLP
1,2-Dimethylbenzene	12DMB
Acetone	ACET
Acrylonitrile	ACRYLO
Benzene	C6H6
Bicycloheptadiene	BCHPD
Bromodichloromethane	BRDCLM
Bromoform	CHBR3
Bromomethane	CH3BR
Carbon Disulfide	CS2
Carbon tetrachloride	CCL4
Chloroethane	C2H5CL
cis-1,2-Dichloroethene	C12DCE
cis-1,3-Dichloropropene	C13DCP
Dichlorodifluoromethane	CCL2F2
Chlorobenzene	CLC6H5
Chloroform	CHCL3
Chloromethane	CH3CL
Dibromochloromethane	DBRCLM
Dibromochloropropane	DBCP
Dicyclopentadiene	DCPD
Ethylbenzene	ETC6H5
Methylene chloride	CH2CL2
Methyl ethyl ketone	MEK
Methyl isobutyl ketone	MIBK
Methyl-n-butyl ketone	MNBK
Styrene	STYR
1,1,2,2-Tetrachloroethane	TCLEA
trans-1,2-Dichloroethene	T12DCE
trans-1,3-Dichloropropene	T13DCP
Tetrachloroethene	TCLEE
Toluene	MEC6H5
Trichloroethene	TRCLE

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
Vinyl chloride	C2H3CL
Xylenes	XYLEN
Organochlorine Pesticides	
Dichlorodiphenyl dichloroethane	PPDDD
Dichlorodiphenyl dichloroethene	PPDDE
Dichlorodiphenyl trichloroethane	PPDDT
Aldrin	ALDRN
alpha-Endosulfan	AENSLF
alpha-Chlordane	ACLDAN
Dieldrin	DLDRN
Endrin	ENDRN
Endrin aldehyde	ENDRNA
Endrin ketone	ENDRNK
gamma-Chlordane	GCLDAN
Heptachlor	HPCL
Heptachlor epoxide	HPCLE
Hexachlorocyclopentadiene	CL6CP
Isodrin	ISODR
Methoxychlor	MEXCLR
Organosulfur Compounds	
1,4-Oxathiane	OXAT
Benzothiazole	BTZ
Dimethyl disulfide	DMDS
Dithiane	DITH
p-Chlorophenylmethyl sulfide	CPMS
p-Chlorophenylmethyl sulfoxide	CPMSO
p-Chlorophenylmethyl sulfone	CPMSO2
Organophosphorus Compounds by Gas Chromatography	
Dimethyl methyl phosphonate	DMMP
Diisopropyl methyl phosphonate	DIMP
Mercury by Cold Vapor Atomic Absorption	
Mercury	HG
Arsenic by Graphite Furnace Atomic Adsorption	
Arsenic	AS
Metals/Cations by Inductively Coupled Argon Plasma	
Aluminum	AL
Barium	BA
Beryllium	BE
Boron	B
Antimony	SB
Cadmium	CD

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
Calcium	CA
Chromium	CR
Cobalt	CO
Copper	CU
Iron	FE
Lead	PB
Magnesium	MG
Manganese	MN
Nickel	NI
Potassium	K
Selenium	SE
Silver	AG
Sodium	NA
Thallium	TL
Vanadium	V
Zinc	ZN
<i>Cyanide by Colorimetric Method</i>	
Cyanide	CYN
<i>Ammonia</i>	
Ammonia	NH3
<i>Alkalinity</i>	
Alkalinity	ALK
<i>Anions</i>	
Bromide	BR
Chloride	CL
Fluoride	F
Nitrate	NO3
Nitrite	NO2
Sulfate	SO4
<i>Nitrosamines</i>	
n-Nitrosodimethylamine	NNDMEA
<i>Nitrogen-Phosphorus Pesticides</i>	
Atrazine	ATZ
Malathion	MLTHN
Parathion	PRTHN
Supona	SUPONA
Vapona	DDVP
<i>Organic Carbon</i>	
Total organic carbon	TOC
Dissolved organic carbon	DOC

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
<i>Agent Degradation Products by High Performance Liquid Chromatography</i>	
Thiodiglycol	TDGCL
<i>Agent Products by Ion Chromatography</i>	
Isopropyl methylphosphonic acid	IMPA
<i>Kjeldahl Nitrogen</i>	
Nitrogen by Kjeldahl method	N2KJEL
<i>Polychlorinated Biphenyls (PCBs)</i>	
Arochlor 1016	PCB016
Arochlor 1221	PCB221
Arochlor 1232	PCB232
Arochlor 1242	PCB242
Arochlor 1248	PCB248
Arochlor 1254	PCB254
Arochlor 1260	PCB260

Note: Individual analytes in **Bold** are Indicator Compounds.

Table 2.3-3: Quality Control Samples

Sample Type/Site ID	Sample Date(s)
<i>Field Duplicates</i>	
25085	1/19/2021 and 7/12/2021
25091	4/28/2021
25101	4/19/2021
25102	4/21/2021
25195	7/14/2021
<i>Laboratory Duplicates</i>	
25085	4/14/2021
25087	5/6/2021
25091	4/28/2021
25101	4/19/2021
25121	10/25/2021
25195	4/14/2021
25203	4/22/2021
LCS2	3/1/2021
LCS4	5/11/2021
LDS1	3/1/2021 and 3/8/2021
LDS2	12/1/2021
LDS4	10/12/21
<i>Field Blanks</i>	
25099	4/28/21
25195	7/14/21
25203	4/22/21

Table 3.0-1. HWL Groundwater Monitoring Well Usage

Well/ Designation	Data Used to Calculate Current (2021) Prediction Limits ¹			Prediction Limits Applied to Downgradient Wells (Quarterly in 2021)
	Data Used to Calculate Baseline (2009) Prediction Limits		Upgradient Data Post-Closure Monitoring Period 5/21/2009 to 4/23/2020	
	Upgradient/Downgradient Data Pre-operational Monitoring Period 10/1/1996 to 4/30/1999	Upgradient Data Operational/Closure Monitoring Period 5/11/1999 to 5/20/2009		
Upgradient				
25034	X	X	X	
25101	X	X	X	
25102	X	X	X	
25121		X	X	
Upgradient – Abandoned prior to post-closure monitoring				
25008	X			
25033	X			
25037	X	X		
25065	X			
25076B	X			
25081	X	X		
25082	X	X		
Downgradient				
25085	X			X
25087	X			X
25183	Refer to Well 25083 for pre-operational data			X
25194				X
25195				X
25086				Dry wells; no samples collected
25088				
Downgradient – Abandoned prior to post-closure monitoring				
25083	X			

¹ Analytical results from the pre-operational, operational, closure, and post-closure monitoring periods utilized to calculate the current HWL prediction limits are available in the Supporting Documentation folder.

Table 3.0-2. Prediction Limits for HWL 2021 Water Quality Monitoring

Indicator Compound	Current Method Reporting Limit (µg/L)	Proportion of Upgradient Non-detected Sample Values (2006-2020)	Statistical Method Used	Statistical Distribution	Selected Prediction Limit (µg/L)
<i>Volatile Organic Compounds</i>					
1,1,1-Trichloroethane	0.2	97.4	Non-parametric	Unknown	0.395
1,1-Dichloroethane ¹	0.2	100	Non-parametric	Unknown	0.26
1,1-Dichloroethene	0.202	89.8	Non-parametric	Unknown	7.79
1,2-Dichloroethane	0.2	93.9	Non-parametric	Unknown	0.9
Benzene	0.2	99.5	Non-parametric	Unknown	1.17
Bicycloheptadiene ¹	0.219	100	Non-parametric	Unknown	0.28
Carbon tetrachloride	0.2	90.3	Non-parametric	Unknown	11.8
Chloroform	0.2	81.6	Non-parametric	Unknown	4.72
Dichlorodifluoromethane ¹	0.6	100	Non-parametric	Unknown	0.78
Dicyclopentadiene ¹	0.205	100	Non-parametric	Unknown	0.27
<i>Organochlorine Pesticides</i>					
Dieldrin	0.002520 ²	98.5	Non-parametric	Unknown	0.05
<i>Organophosphorus Compounds</i>					
DIMP ¹	0.5	100	Non-parametric	Unknown	0.65
<i>Metals</i>					
Arsenic	1	99.0	Non-parametric	Unknown	3.35
Chromium	10	95	Non-parametric	Unknown	24.1
Lead	3	79.9	Non-parametric	Unknown	15
Mercury ¹	0.2	100	Non-parametric	Unknown	0.26

¹ Because this compound was not detected in any sample, the prediction limit value for this analyte is the 99 percent upper confidence limit (UCL) of the MRL. For the purpose of this report, the 99 percent UCL is defined as 1.3 times the MRL.

² The reporting limits have changed as a result of an MRL study required by the SQAPP for method recertification every three years.

µg/L – micrograms per liter

Table 3.0-3. Prediction Limits for HWL 2022 Water Quality Monitoring


Indicator Compound	Current Method Reporting Limit (µg/L)	Proportion of Upgradient Non-detected Sample Values (2006-2021)	Statistical Method Used	Statistical Distribution	Selected Prediction Limit (µg/L)
<i>Volatile Organic Compounds</i>					
1,1,1-Trichloroethane	0.2	97.5	Non-parametric	Unknown	0.395
1,1-Dichloroethane ¹	0.2	100	Non-parametric	Unknown	0.26
1,1-Dichloroethene	0.202	89.7	Non-parametric	Unknown	7.79
1,2-Dichloroethane	0.2	94.1	Non-parametric	Unknown	0.9
Benzene	0.2	99.5	Non-parametric	Unknown	1.17
Bicycloheptadiene ¹	0.219	100	Non-parametric	Unknown	0.28
Carbon tetrachloride	0.2	89.7	Non-parametric	Unknown	11.8
Chloroform	0.2	81.3	Non-parametric	Unknown	4.72
Dichlorodifluoromethane ¹	0.6	100	Non-parametric	Unknown	0.78
Dicyclopentadiene ¹	0.205	100	Non-parametric	Unknown	0.27
<i>Organochlorine Pesticides</i>					
Dieldrin	0.002520	98.6	Non-parametric	Unknown	0.05
<i>Organophosphorus Compounds</i>					
DIMP ¹	0.5	100	Non-parametric	Unknown	0.65
<i>Metals</i>					
Arsenic	1	99.0	Non-parametric	Unknown	3.35
Chromium	10	95.1	Non-parametric	Unknown	24.1
Lead	3	80.6	Non-parametric	Unknown	15
Mercury ¹	0.2	100	Non-parametric	Unknown	0.26

¹ Because this compound was not detected in any sample, the prediction limit value for this analyte is the 99 percent upper confidence limit (UCL) of the MRL. For the purpose of this report, the 99 percent UCL is defined as 1.3 times the MRL.

µg/L – micrograms per liter

FIGURES


This page intentionally left blank.



Legend

- CAMU Boundary
- Section Lines
- Light Duty Roads
- Unpaved Roads
- Ditches, Canals
- Buildings
- Unsaturated Alluvium
- Water Elevation Contours - 5-foot intervals
- Inferred Water Elevation Contours


Monitoring Well Network	Flow System/Aquifer	
	Unconfined Alluvial	Unconfined Denver
Hazardous Waste Landfill (HWL)		
HWL Supplemental Operations		
Enhanced Hazardous Waste Landfill (ELF)		
Water Level Only		



NAD27-NGVD29 Datum, US Survey Feet, Colorado North Zone
Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM



Figure 2.2-2
Potentiometric Surface of the Unconfined Flow System, Hazardous Waste Landfill



Legend

- Approximate Boundary of the Lower Sandstone Units
- 2014 North Plants/Bedrock Ridge Plume Extent
- CAMU Boundary
- Light Duty Roads
- Unpaved Roads
- Ditches, Canals
- Section Lines
- Buildings
- Unsaturated Alluvium
- Water Elevation Contours - 5-foot Intervals
- Inferred Water Elevation Contours

Monitoring Well Network	Flow System/Aquifer	
	Confined Denver	Unconfined Denver
Hazardous Waste Landfill (HWL)		
HWL Supplemental Operations		
Enhanced Hazardous Waste Landfill (ELF)		
Water Level Only		

NAD27-NGVD29 Datum, US Survey Feet, Colorado North Zone

Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM



Program Manager
Rocky Mountain Arsenal


U.S. Army • COMMITTED TO PROTECTION OF THE ENVIRONMENT •

Figure 2.2-3

Potentiometric Surface for the Lower Sandstone Unit and Equivalent Units, April 2021

M:\projects\hwl_post-closure\2021\mxds\hwl_lwr_sandstoneWL_2021.mxd
6/1/2022





Legend

- Leachate Collection/Leak Detection Systems
- 2014 North Plants/Bedrock Ridge Plume Extent
- Ditches, Canals
- ▭ CAMU Boundary
- Section Lines
- Fences
- Light Duty Roads
- Unpaved Roads
- ▭ Buildings
- ▭ ELF Cells

Note: ¹ Concentrations are in micrograms per liter
² LT - Less than the method detection limit
³ Data shown from calendar year 2021

0 125 250 500 750
Feet

NAD27-NGVD29 Datum, US Survey Feet,
Colorado North Zone

Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM

Program Manager
Rocky Mountain Arsenal


U.S. Army • COMMITTED TO PROTECTION OF THE ENVIRONMENT •

Figure 2.3-2

Indicator Compounds Detection Map 2021 HWL Leachate Collection and Leak Detection Systems

M:\projects\hwl_post-closure\2021\mxd\hwl_ind_detect_lcs_lds_2021.mxd
6/6/2022

Figure 3.1-1
Shewhart-CUSUM Control Chart
for Dieldrin Concentrations in HWL Well 25194



APPENDIX F-2

**Enhanced Hazardous Waste Landfill
Post-Closure Groundwater Monitoring Report
Calendar Year 2021**

This page intentionally left blank.

ROCKY MOUNTAIN ARSENAL

**ENHANCED HAZARDOUS WASTE LANDFILL
POST-CLOSURE GROUNDWATER MONITORING REPORT**

CALENDAR YEAR 2021

**Revision 0
June 17, 2022**

**U.S. Department of the Army
Shell Oil Company**

Prepared by:



Navarro Research and Engineering, Inc.

This page intentionally left blank.

CONTENTS

Section	Page
EXECUTIVE SUMMARY	ES-1
1.0 INTRODUCTION	1
2.0 GROUNDWATER MONITORING RESULTS	1
2.1 Monitoring Well Activities	1
2.2 Water Level Monitoring	1
2.3 Analytical Results	2
2.3.1 ELF Network Wells Analytical Results.....	3
2.3.1.1 Upgradient and Cross-gradient ELF Network Wells.....	3
2.3.1.2 Downgradient ELF Network Wells	4
2.3.2 ELF LCS and LDS Sumps Analytical Results	5
2.3.2.1 LCS Sumps	5
2.3.2.2 LDS Sumps	5
2.4 Analytical Data Review	5
2.4.1 Precision.....	6
2.4.2 Accuracy/Bias	7
2.4.3 Representativeness	8
2.4.4 Completeness	9
2.4.5 Comparability	9
2.4.6 Summary	10
2.4.7 Data Usability Evaluation	10
3.0 STATISTICAL EVALUATIONS	10
3.1 2021 Prediction Limits and the Current ELF Water Quality Data	11
3.2 2022 Prediction Limits and the Future ELF Water Quality Data	11
4.0 SUMMARY	11
5.0 REFERENCES	13



TABLES

Table 2.2-1	ELF Water Level Monitoring Network
Table 2.2-2	2021 Water Level Measurements Summary
Table 2.3-1	ELF Water Quality Monitoring Network
Table 2.3-2	Water Quality Monitoring Analyte List
Table 2.3-3	Quality Control Samples
Table 3.0-1	ELF Groundwater Monitoring Well Usage
Table 3.0-2	Prediction Limits for ELF 2021 Water Quality Monitoring
Table 3.0-3	Prediction Limits for ELF 2022 Water Quality Monitoring

FIGURES

Figure 2.2-1	Well/Piezometer/Sump Location Map, 2021 Groundwater Monitoring
Figure 2.2-2	Potentiometric Surface for the Unconfined Flow System, April 2021
Figure 2.2-3	Potentiometric Surface for the Lower Sandstone Unit and Equivalent Units, April 2021
Figure 2.3-1	Indicator Compounds Detection Map, 2021 Groundwater Monitoring

SUPPORTING DOCUMENTATION (available on Data CD)

ELF Data Quality Assurance

- ELF 2021 Accuracy/Bias Evaluation Results
- ELF 2021 Data Usability Summary
- ELF 2021 Investigative Data
- ELF 2021 Precision Results
- ELF 2021 QC Blank Summary
- ELF 2021 Rejected Data

ELF Statistical Evaluations

- ELF 2022 Prediction Limit ChemStat Documentation



ACRONYMS

amsl	Above Mean Sea Level
ARDL	Applied Research and Development Laboratory
CAMU	Corrective Action Management Unit
CFS	Confined Flow System
ELF	Enhanced Hazardous Waste Landfill
HWL	Hazardous Waste Landfill
IC	Indicator Compound
IQR	Interquartile Range
LBLCS	LB Leachate Collection System
LBLDS	LB Leak Detection System
LCS	Leachate Collection System
LDS	Leak Detection System
MRL	Method Reporting Limit
MS	Matrix Spike
µg/L	Microgram(s) per liter
O&M	Operations and Maintenance
OCN	Operations and Maintenance Change Notice
OMC	Operations and Maintenance Contractor
PARCC	Precision, Accuracy, Representativeness, Completeness, and Comparability
PCGMP	Post-Closure Groundwater Monitoring Plan
QC	Quality Control
RMA	Rocky Mountain Arsenal
RMAED	Rocky Mountain Arsenal Environmental Database
RPD	Relative Percent Difference
SQAPP	Sampling Quality Assurance Project Plan
UCL	Upper Confidence Limit
UFS	Unconfined Flow System
WPLCS	WP Leachate Collection System
WPLDS	WP Leak Detection System

(Note: All chemical codes are listed in Table 2.3-2)



This page intentionally left blank.



EXECUTIVE SUMMARY

The post-closure groundwater monitoring program for the Enhanced Hazardous Waste Landfill (ELF) is designed to monitor groundwater flow directions, groundwater quality beneath and in the vicinity of the ELF and evaluate the potential for hazardous constituent releases into groundwater sourced from the landfill.

This report covers the post-closure monitoring at the ELF for the 2021 calendar year quarterly sampling events conducted in January, July, and October, and the annual sampling event conducted in April and May. Groundwater flow directions beneath the ELF were consistent over the four quarters of 2021 post-closure monitoring and are consistent with the previous groundwater monitoring events within the Corrective Action Management Unit area.

The wells sampled as part of the ELF 2021 post-closure groundwater monitoring include downgradient monitoring wells 25092, 25093, 25102, 25120, and 26099; upgradient monitoring wells 25021, 25022, 25024, 25105, 25106, and 25123; and cross-gradient monitoring well 25121. The groundwater samples were tested for the analytes and indicator compounds (ICs) listed in Table 2.3-2. The ICs selected as part of the monitoring program include 1,1,1-trichloroethane, 1,1-dichloroethane, 1,1-dichloroethene, 1,2-dichloroethane, arsenic, benzene, carbon tetrachloride, chromium, chloroform, dieldrin, diisopropylmethyl phosphonate, mercury, and lead.

The ICs detected in the upgradient wells 25021, 25022, 25024, 25105 and 25106 include arsenic and dieldrin. Carbon tetrachloride and chloroform were detected in cross-gradient well 25121.

Lead was the only IC detected in the downgradient wells 25092 and 26099. The levels of lead in the downgradient wells are below the prediction limit value of 26.3 micrograms per liter ($\mu\text{g/L}$). Historically, lead was detected in downgradient wells prior to waste being placed in the ELF in April 2006.

The ELF LB Leak Detection System (LBLDS) sumps and WP Leak Detection System (WPLDS) sumps were not sampled in 2021. They will be sampled prior to the next waste removal event per the *Enhanced Hazardous Waste Landfill Post-Closure Groundwater Monitoring Plan* (ELF PCGMP) (Navarro 2020).

As a component of the data review process, the analytical data were evaluated against the data quality indicators of precision, accuracy, representativeness, completeness, and comparability (PARCC). Based on the findings of the PARCC evaluation, the sample results are considered valid and usable for their intended purpose. Data quality requirements were met for the analytical data and the data are appropriate for use in evaluation of the water quality conditions present at the site.

Based on statistical evaluations, the groundwater quality around the ELF has not been affected by post-closure operations and maintenance (O&M) of the landfill.

This page intentionally left blank.



1.0 INTRODUCTION

The Post-Closure Groundwater Monitoring Report for 2021 quarterly sampling events conducted in January, July, and November, and the annual sampling event in April and May document the analytical results and data evaluation of the Enhanced Hazardous Waste Landfill (ELF) post-closure groundwater monitoring on the Rocky Mountain Arsenal (RMA). Background information related to the ELF monitoring approach including site-specific characterization, applicable regulatory requirements, laboratory methods, statistical evaluation procedures, and monitoring program development are presented in the *Enhanced Hazardous Waste Landfill Post Closure Groundwater Monitoring Plan* (ELF PCGMP) (Navarro 2020), *Rocky Mountain Arsenal Sampling Quality Assurance Project Plan* (SQAPP) (Navarro 2019), and previous annual groundwater reports.

The groundwater monitoring program defined in this document is specifically designed to monitor groundwater flow directions and groundwater quality beneath and around the ELF, and to monitor for potential releases of hazardous constituents from the ELF. Groundwater monitoring for the ELF was completed as required by the ELF PCGMP (Navarro 2020).

2.0 GROUNDWATER MONITORING RESULTS

A summary of water level monitoring, and analytical results for the 2021 post-closure groundwater monitoring at the ELF are presented in the following sections. Also included is an evaluation of the Leachate Collection System (LCS) and Leak Detection System (LDS) wastewater analytical data.

2.1 Monitoring Well Activities

The RMA Operations and Maintenance Contractor (OMC) field crew inspected the monitoring wells and well pads prior to each sampling event. As part of the annual sampling event, the casing height was measured and documented on the monitoring wells with dedicated pumps. In addition to casing heights, total depths were measured on monitoring wells without dedicated pumps. The casing heights and total depths are documented in the OMC records.

Water level monitoring wells 25018 and 25019 were damaged in April 2021 during a prescribed burn east of the ELF. The above-ground portions of the wells were repaired in June. New tops of casings were surveyed, and water levels were recorded at both locations.

2.2 Water Level Monitoring

Water levels were measured in 68 wells quarterly to evaluate the unconfined flow system (UFS) and confined flow system (CFS) flow conditions in the area of the Corrective Action Management Unit (CAMU) and to identify any significant changes in flow direction in the area of the CAMU. The wells used to monitor water levels in the area of the CAMU are presented in Table 2.2-1 and Figure 2.2-1.

Water level monitoring measurements are provided in Table 2.2-2. Figures 2.2-2 and 2.2-3 represent the April 2021 water table elevation for the UFS and the Denver Formation Lower Sandstone Unit within the UFS and CFS, respectively. The potentiometric surface of the UFS in the vicinity of the ELF shows that across the entire CAMU, groundwater flow is generally to the

north and northwest. No significant variations in groundwater flow directions have been identified during post-closure monitoring.

The potentiometric surface of the Denver Formation lower sandstone unit indicates flow from the CFS into UFS downgradient of the Hazardous Waste Landfill (HWL) and illustrates the water table across the area and the interaction between the two flow systems. Groundwater flow in the lower sandstone unit of the CFS merges with the UFS on the north, west, and east sides of the HWL and ELF. Currently, the zone where the UFS and CFS merge is illustrated by a dashed line for the approximate boundary indicating the lower sandstone unit in Figure 2.2-3. South of the line, the flow is confined to semi-confined, while north of the line the flow is unconfined where the confining unit is not present (TtFW 2004).

Water levels measured in well 25021, south and upgradient of the ELF, are not consistent with other monitoring wells near the ELF suggesting the screened zone is not hydraulically connected with the lower sandstone unit mapped in this report. Therefore, the water level data from well 25021 is not used in contouring the potentiometric surface for the lower sandstone unit. The well, however, will continue to be monitored as part of the upgradient ELF water-quality well network.

2.3 Analytical Results

The ELF water quality network wells are identified in Table 2.3-1. Groundwater and leachate samples collected from the ELF wells were submitted to Applied Research and Development Laboratory (ARDL), Mount Vernon, Illinois for analysis of the parameters listed in Table 2.3-2. Included in this table are the 13 indicator compounds (IC) evaluated during quarterly sampling events, and the full suite of analytes evaluated during the annual sampling event.

The groundwater samples were tested for the ICs listed in Table 2.3-2. The ICs are highlighted in bold text in Table 2.3-2.

The 13 ICs selected as part of the monitoring program include the following:

- Arsenic
- Benzene (C₆H₆)
- Carbon tetrachloride (CCL₄)
- Chloroform
- Chromium
- 1,1-Dichloroethane (11DCLE)
- 1,2- Dichloroethane (12DCLE)
- 1,1-Dichloroethene (11DCE)
- Diisopropylmethyl phosphonate (DIMP)
- Dieldrin
- Lead
- Mercury
- 1,1,1-Trichloroethane (111TCE)

The ICs detected in the ELF network wells are shown on Figures 2.3-1. Table 2.3-3 lists the quality control (QC) samples including field blanks, and duplicates that were collected and analyzed as part of the quarterly and annual groundwater monitoring events in accordance with the SQAPP (Navarro 2019).

The full suite of analytes detected in the ELF network wells and sumps during the pre-operational, operational, closure, and post-closure monitoring periods are summarized in the Supporting Documentation folder.

2.3.1 ELF Network Wells Analytical Results

The wells sampled during the quarterly events in January, July, and October 2021, and the annual post-closure groundwater monitoring event in April and May 2021 at the ELF include the following upgradient and downgradient wells screened in the UFS and CFS.

<u>Upgradient</u>		<u>Downgradient</u>		<u>Cross-Gradient</u>
UFS	CFS	UFS	CFS	UFS
25022	25021	25092	25093	25121
25105	25024	25102		
25106	25123	25120		
		26099		

2.3.1.1 Upgradient and Cross-gradient ELF Network Wells

Upgradient wells 25021, 25022, 25024, 25105, 25106, and 25123—as well as cross-gradient monitoring well 25121—were sampled during the second quarter of 2021, consistent with the monitoring program each year.

The following ICs were detected in the upgradient wells:

UFS

Well 25022

- Dieldrin – 0.00693 µg/L

Well 25105

- No detections

Well 25106

- Arsenic – 5.59 µg/L
- Dieldrin – 0.0212 µg/L

CFS

Well 25021

- Dieldrin – 0.00316 µg/L

Well 25024

- No detections

Well 25123

- No detections

The following ICs were detected in the cross-gradient UFS well:

Well 25121

- Carbon tetrachloride – 2.84 µg/L
- Chloroform – 0.226 µg/L

Detections of chloroform and carbon tetrachloride in cross-gradient well 25121 are consistent with contaminants associated with the North Plants-Bedrock Ridge western plume. Carbon tetrachloride and chloroform have remained stable or have decreased since 2010.

The IC dieldrin was detected in upgradient CFS well 25021 for the first time in 2016. It has been detected each year since. In 2021, dieldrin was the only IC detected in well 25021.

Additional compounds detected in the upgradient wells in 2021 include the following:

- | | |
|----------------------|---|
| • Aluminum | • Iron |
| • Ammonia | • Magnesium |
| • Barium | • Manganese |
| • Boron | • Methoxychlor |
| • Bromide | • Nickel |
| • Calcium | • Nitrate |
| • Chloride | • Kjeldahl nitrogen |
| • Cobalt | • n-Nitrosodimethylamine (NNDMEA) |
| • Copper | • Potassium |
| • Endrin | • Dichlorodiphenyl dichloroethane (PPDDD) |
| • Endrin aldehyde | • Selenium |
| • Fluoride | • Sodium |
| • Heptachlor | • Sulfate |
| • Heptachlor epoxide | • Zinc |
| • Isodrin | |

2.3.1.2 Downgradient ELF Network Wells

Downgradient ELF network wells 25092, 25093, 25102, 25120, and 26099 are sampled quarterly.

Lead was the only IC that was detected in the downgradient wells, and the results for detections only are listed below. In wells 25092 and 26099, lead was detected at concentrations just above the reporting limit of 3 µg/L.

UFS

Well 25092

- Lead 3.2 µg/L (July)

Well 25102

- No detections

Well 25120

- No detections

Well 26099

- Lead 3.1 µg/L (July)

CFS

Well 25093

- No detections



Additional compounds detected in downgradient wells in 2021 include the following:

- Aluminum
- Ammonia
- Barium
- Boron
- Bromide
- Calcium
- Chloride
- Copper
- Fluoride
- Iron
- Kjeldahl nitrogen
- Magnesium
- Manganese
- N-Nitrosodimethylamine
- Nitrate
- Potassium
- Selenium
- Silver
- Sodium
- Sulfate
- Toluene
- Zinc

2.3.2 ELF LCS and LDS Sumps Analytical Results

Per the ELF PCGMP, sump sampling shall be performed prior to removal of wastewater from an ELF sump. Wastewater removal may be triggered by a high sump level or other wastewater management consideration.

Samples are collected from the LDS to meet the post-closure requirements specified in the ELF PCGMP (Navarro 2020) and are used to evaluate wastewater chemistry in order to evaluate potential leakage from the ELF. Water levels within the LDS sumps in 2021 were not high enough to initiate sampling in accordance with the ELF PCGMP. Therefore, a figure has not been included for sump sample results in this report.

2.3.2.1 LCS Sumps

Water levels in sumps LB Leachate Collection System (LBLCS) and WP Leachate Collection System (WPLCS) were not high enough to initiate sampling in accordance with the ELF PCGMP in 2021.

2.3.2.2 LDS Sumps

Water levels in sumps LB Leak Detection System (LBLDS)1, LBLDS2, WP Leak Detection System (WPLDS)1 and WPLDS2 were not high enough to initiate sampling in accordance with the PCGMP in 2021. Since there were no LDS analytical results in 2021, none required regulatory agency notification per Table 3.0-2 of the *Enhanced Hazardous Waste Landfill Post-Closure Plan* (Navarro 2020).

2.4 Analytical Data Review

The objective of the data review process is to determine whether the analytical results are acceptable for use in making decisions for the project. As a component of the data review process, the analytical data are evaluated against the data quality indicators Precision, Accuracy, Representativeness, Completeness, and Comparability (PARCC). The five parameters are identified in the SQAPP (Navarro 2019) as important data quality indicators. The RMA OMC

reviewed the PARCC parameters with respect to the data QC goals stated in the SQAPP (Navarro 2019).

The sample results were evaluated against the data quality requirements and compared to the data quality objectives as presented in the ELF PCGMP (Navarro 2020) and SQAPP (Navarro 2019). Data review and verification activities were conducted in accordance with the SQAPP (Navarro 2019). The evaluation limits discussed below are internal OMC limits based on historical data, and independent of evaluations performed by the laboratory. The results of these evaluations are described below.

The OMC conducted data validation on a representative subset of the ELF groundwater analytical data. Validation checklists were completed, and laboratory case narratives were reviewed to determine potential problems identified by the analysts. The completeness result for all analytes achieves the minimum specification of 90 percent. There were six data points flagged as rejected in 2021.

2.4.1 Precision

Precision is the measure of mutual agreement among measurements. Field precision was evaluated by collection and analysis of duplicate samples using the same analytical methods as investigative samples. Precision was evaluated quantitatively by measuring the variability, in terms of relative percent difference (RPD), between the pairs of results for the investigative and duplicate samples. The RPD values provide a relative measure of precision; lower RPD values indicate better precision between the results. Relative percent difference values less than or equal to 35 percent are considered acceptable. The RPD for a duplicate investigative sample pair is calculated using the following steps:

- Identify the duplicate investigative sample pair results.
- Identify parameters detected in both results for the pair identified in Step 1.
- Calculate the RPD value for the detected parameters identified in Step 2 using the following equation:

$$RPD = \frac{|x - y|}{\frac{(x + y)}{2}} \times 100$$

where:

x = Investigative sample result

y = Duplicate sample result

The duplicate/investigative pairs are evaluated for comparability. The RPD upper evaluation limit is 35 percent for all analytes. The investigative and duplicate results will be considered comparable if any of the following statements are true:

- If both sample results are less than the method reporting limit (MRL)
- If both sample results are greater than the MRL; but less than or equal to twice the MRL
- If both sample results are greater than twice the MRL and the RPD is less than or equal to the specified upper RPD limit

- If both sample results are greater than the MRL; one result is less than or equal to twice the MRL; one result is greater than twice the MRL; and the RPD is less than or equal to the specified upper limit
- If one sample result is less than the MRL; and one result is greater than the MRL and less than or equal to twice the MRL

The investigative and duplicate results will be considered not comparable if any of the following statements are true:

- If both sample results are greater than twice the MRL and the RPD is greater than the specified upper RPD limit
- If both sample results are greater than the MRL; one result is less than or equal to twice the MRL; one result is greater than twice the MRL; and the RPD is greater than the specified upper limit
- If one sample result is less than the MRL; and one result is greater than twice the MRL

A total of 332 duplicate pair analyses of ELF target analytes were performed. The average RPD was 1.2 percent. Duplicate and investigative results are considered comparable in 330 cases and non-comparable in 2 cases.

The precision evaluation values and the RPD values are listed in the Supporting Documentation folder. The non-comparable investigative and duplicate data will be assigned a “Z” data qualifier with the comment “Duplicate and investigative values are not comparable.” The data are considered acceptable for their intended use and no additional action in addition to the data qualification is considered necessary.

2.4.2 Accuracy/Bias

Accuracy is the degree of agreement between an observed value (sample result) and an accepted reference value. Bias is the systematic or persistent distortion of a measurement process that causes errors in one direction (high or low). The terms accuracy and bias are used interchangeably. Accuracy/bias is indicated by percent recovery calculated from laboratory spike data using the following formula:

$$\text{Recovery Rate (\%)} = \frac{\text{Measured Value}}{\text{True Value}} \times 100$$

Where:

Measured Value = Value after the spike minus the value before the spike

True Value = Value of the spike added

Accuracy/bias will be calculated based on results of laboratory control spikes and matrix spikes (MS). Laboratory control spikes utilize laboratory grade water with some additions of inorganic constituents to mimic RMA water. Matrix spikes utilize RMA water to account for matrix-related interferences.

The calculated recovery rate is compared to the lower and upper recovery rate limits specific to each analyte based on historical data. The 25th and 75th percentiles for each analyte are



calculated. The interquartile range (IQR) is calculated by subtracting the 25th percentile value from the 75th percentile value. The lower and upper recovery warning limits for each analyte are determined by subtracting and adding 1.5 times the IQR to the 25th and 75th percentile values, respectively. The lower and upper recovery control limits are determined by subtracting and adding three times the IQR to the 25th and 75th percentile values, respectively. Data will not be qualified solely on a recovery rate outside the calculated recovery limits. Additional factors must be present to justify the data qualification. The historical spike recoveries used for the calculation of recovery evaluation limits for matrix spikes and laboratory control spikes are included in the Supporting Documentation folder.

The data utilized for the recovery rate calculations are limited to the spike values for the analytical lots of the investigative data included in the Supporting Documentation folder. Matrix spike values exceeding four times the spiked amount are excluded from the calculation since the MS could possibly be diluted out due to the high original concentration. Analyses with an ampersand (@) flag code (i.e., value is estimated) or “B” flag code (i.e., analyte found in the method blank or QC blank as well as the sample) were also excluded from recovery rate calculations. The spike recoveries used in the calculations are also included in the Supporting Documentation folder.

The average recovery rate for the 856 MS analyses was 87.7 percent. Recovery rates outside the lower or upper warning limits were observed in 10 analyses. Recovery rates outside the lower or upper control limits were not observed. A listing of the MS sample results outside the warning and control evaluation limits is included in the Supporting Documentation folder.

The average recovery rate for the 856 corresponding laboratory control spike analyses was 96.8 percent. Recovery rates outside the lower or upper warning limits were observed in 30 analyses. Recovery rates outside the lower or upper control limits were observed in three analyses. The laboratory control spike sample results outside the evaluation limits are included in the Supporting Documentation folder.

Laboratory control spike and MS recoveries outside the designated warning limits in both instances were observed in a single analysis, while laboratory control spike and MS recoveries outside the designated control limits in both instances were not observed. No issues were identified requiring data qualification. Charts including the evaluation limits and spike recoveries for the ELF are included in the Supporting Documentation folder.

2.4.3 Representativeness

Representativeness refers to the selection and implementation of analytical methods, sampling protocols and sample locations to ensure that the analytical data results are representative of the media being sampled (e.g., water, soil, etc.) and of the conditions being measured.

Representativeness is evaluated by reviewing monitoring program design and implementation, as well as field and laboratory blank samples. Design of the monitoring program is reviewed qualitatively to assess whether the objectives were satisfied. Implementation of the monitoring program is reviewed qualitatively to evaluate whether the planned procedures were followed. A quantitative review of the QC blank results indicates whether influences outside the measurement systems have affected the analyses and interpretation of the media and conditions.

Sample locations, sampling frequency, and sample collection procedures applied during groundwater monitoring are described in the ELF PCGMP (Navarro 2020). The program is designed to provide water quality data in the area of the landfill and implemented as defined in the work plan. Thus, the data are judged representative of the water quality characteristics for the program.

Field blanks are collected and analyzed to evaluate possible cross contamination of the investigative samples. Rinse blanks are not required since dedicated pumps and tubing are used to sample the wells and sumps. The number of QC samples collected, and QC results evaluated for qualification are included in Table 2.3-3 and the Supporting Documentation folder.

A total of 228 field blank analyses were performed. Field blank results about the MRL were observed in three analyses. Qualification is not required as the investigative value is greater than the field blank value in one analysis and below the MRL for two analyses. Field blank results are included in the Supporting Documentation folder.

In addition, the laboratories prepared and analyzed method blanks as part of their analytical protocols. Method blanks measure potential contamination from laboratory sources such as glassware, reagents and laboratory water. There were 843 method blank analyses in 2021. A single method blank analysis was above the MRL. No qualification is required as the associated investigative value exceeds the method blank detection. Method blank results are included in the Supporting Documentation folder.

2.4.4 Completeness

Completeness is the amount of valid data obtained from a measurement system compared to the amount that was expected and needed to meet the project goals. Valid analytical data are those data that have been identified as usable and included in the RMA Environmental Database (RMAED). The SQAPP (Navarro 2019) sets the completeness goal for the sampling program at 90 percent.

In 2021, six inorganic values were rejected for missed holding times related to delayed sample delivery to the laboratory. The laboratory was instructed to proceed with analysis as the affected analytes are listed in Table 3.2.5-1 in the ELF PCGMP as excluded from reporting requirements. The rejected data are included in the Supporting Documentation folder.

The analytical results of monitoring are representative of the groundwater quality with the exception of qualified data. Rejected data are not removed from the RMAED; however, they are not used to evaluate the ELF groundwater data. Data qualified as “@” are not filtered out of the database. While not rejected, the data are considered estimated due to the concentration being outside the linear range of the instrument.

Completeness was calculated as 99.8 percent. The completeness goal of 90 percent was achieved. All results were determined to be acceptable by the laboratory.

2.4.5 Comparability

Comparability is the confidence with which one data set can be evaluated relative to another. Standard sampling and analysis techniques, based on certified analytical methods approved by

the OMC or promulgated SW-846 methods, and standard procedures for sample collection were used throughout the groundwater monitoring programs at the ELF. Consistent procedures for the reporting and management of the data generated were followed. All data are considered comparable.

2.4.6 Summary

The purpose of the PARCC evaluation is to evaluate whether the data are usable and adequate to properly characterize the water quality conditions present at the site. Based on the findings of the PARCC evaluation, the sample results are considered valid and usable for their intended purpose. Qualified data are not rejected but should be appropriately considered when used. Data quality requirements were sufficiently met for the analytical data, and the data are appropriate for use in evaluation of the water quality conditions present at the site. The primary objectives of the sampling program were met.

2.4.7 Data Usability Evaluation

A data usability evaluation was conducted on 1,356 records. The evaluation identified one statistical outlier. The data are considered acceptable for their intended use and no additional action is considered necessary.

The Mann-Kendall test for trends identified 42 decreasing analyte trends and 53 increasing analyte trends. A listing of the identified outliers and trends is included on the attached data CD in the Data Usability subfolder (Data_Usability_Summary_2021.xlsx).

The evaluation did not positively identify data quality issues; thus, the data are considered to be of acceptable quality and meets or exceeds the established data quality objectives. The data are of the correct type, quality, and quantity to support the intended use.

3.0 STATISTICAL EVALUATIONS

The statistical evaluation of data includes comparing upgradient water quality to downgradient compliance wells utilizing prediction intervals that are calculated for each IC using upgradient water quality data. The prediction limits discussed in this section refer to the upper limit of each analyte-specific prediction interval. Comparison of downgradient water quality data to prediction limits should provide an indication whether groundwater has been impacted by the ELF.

The wells used to calculate prediction limits and statistical evaluations are presented in Table 3.0-1. A prediction interval was calculated for each IC, which included upgradient water quality data through the 2020 post-closure monitoring period. The general approach for determining and evaluating prediction limits for the ELF is consistent with United States Environmental Protection Agency guidance document (EPA 2009).

The MRLs can change based on the analytical method re-certification every three years as required by the SQAPP. In January 2021, the MRL for dieldrin was lowered. The new MRL is reflected in Table 3.0-2.



ChemStat statistical software was utilized to determine the prediction limit values and documentation is available in the Supporting Documentation folder. The prediction limit values for 2022 are included in Table 3.0-3. If a compound is not detected in any sample, the predication limit for the analyte is the 99 percent upper confidence limit (UCL) of the MRL. For the purpose of this report, the 99 percent UCL is defined as 1.3 times the MRL.

3.1 2021 Prediction Limits and the Current ELF Water Quality Data

Table 3.0-2 presents the 2021 prediction limits that were calculated from upgradient well data collected during the pre-operational, operational, closure, and post-closure groundwater monitoring periods (2003–2019).

The downgradient results from the water quality sampling completed during 2021 post-closure groundwater monitoring period were compared with the prediction limit values presented in Table 3.0-2 to determine whether groundwater quality was impacted by the ELF in 2021.

Lead was the only IC detected (July 2021 event) in the downgradient wells. Lead was detected in wells 25092 and 26099 at concentrations ranging from 3.1 µg/L to 3.2 µg/L. The range of values is below the prediction limit value of 26.3 µg/L. Historically, lead was detected in downgradient wells prior to waste being placed in the ELF in April 2006.

Based on the statistical evaluation, it is concluded that the groundwater quality in the vicinity of the ELF has not been affected by operations, closure, or post-closure operations and maintenance (O&M) of the landfill.

3.2 2022 Prediction Limits and the Future ELF Water Quality Data

Table 3.0-3 presents the prediction limit values that will be applied to downgradient wells during 2022 sampling events. The ELF prediction limits will be applied to wells 25092, 25093, 25102, 25120, and 26099. The MRLs can change based on the analytical method re-certification required every three years by the SQAPP (Navarro 2019). The MRL for dieldrin was lowered in January 2021, but it did not impact the prediction limits calculated for 2022 as presented in Table 3.0-3.

4.0 SUMMARY

The following conclusions are based on the groundwater and wastewater monitoring results for the 2021 post-closure groundwater monitoring at the ELF:

- The groundwater in the UFS and CFS flows to the north-northwest and is consistent with the previously monitored groundwater elevations and flow directions for the ELF.
- Based on the findings of the PARCC evaluation, the analytical data collected are of acceptable quality for intended uses.
- Arsenic and dieldrin were detected in the upgradient wells.
- Lead was the only IC detected in two of the five downgradient wells. The detections of lead were below the calculated prediction limit of 26.3 µg/L. Historically, lead was detected in the downgradient wells prior to the placement of waste in the ELF in April 2006.

- Carbon tetrachloride and chloroform were detected in cross-gradient well 25121. Detections of chloroform and carbon tetrachloride in well 25121 are consistent with contaminants associated with the North Plants-Bedrock Ridge western plume.
- In the CFS, dieldrin was detected in upgradient well 25021.
- ELF LCS and LDS sumps were not sampled in 2021. They will be sampled prior to the next waste removal event per the ELF PCGMP.
- No ICs exceeded the calculated 2021 prediction limits. Based on the statistical evaluation, groundwater quality around the ELF has not been affected by operations, closure, or post-closure O&M of the landfill.
- Prediction limit values for all ICs were re-evaluated for 2022 and the values did not change from 2021 to 2022.

Based on the statistical evaluation, it is concluded that the groundwater quality in the vicinity of the ELF has not been affected by operations, closure, or post-closure O&M of the landfill.



5.0 REFERENCES

EPA (U.S. Environmental Protection Agency)

- 2009 *Statistical Analysis of Groundwater Monitoring Data at RCRA Facilities* Unified Guidance, EPA 530/R-09-007. March.

Navarro (Navarro Research and Engineering, Inc.)

- 2020 *Enhanced Hazardous Waste Landfill Post-Closure Plan*. Revision 1. April 2, 2020.
- 2019 *Rocky Mountain Arsenal Sampling Quality Assurance Project Plan*. Revision 2. January 30, 2019.

TtFW (Tetra Tech FW, Inc.)

- 2004 *Hazardous Waste Landfill and Landfill Wastewater Treatment System Annual Groundwater Monitoring Report for July 2002–June 2003*. Revision 0.



This page intentionally left blank.



TABLES

This page intentionally left blank.

Table 2.2-1. ELF Water Level Monitoring Network

Well ID	Aquifer	Top of Casing Elevation (feet amsl)	Bottom of Screen Elevation (feet amsl)
<i>Unconfined Flow System</i>			
25003	Alluvial	5194.26	5151.60
25041	Alluvial	5210.81	5179.61
25048	Alluvial	5190.01	5150.20
25054	Alluvial	5207.94	5168.10
26178	Alluvial	5214.73	5181.56
26182	Alluvial	5217.22	5174.27
26184	Alluvial	5214.94	5173.84
25018 ²	Alluvial/Denver Formation	5195.61	5148.30
25059	Alluvial/Denver Formation	5208.97	5162.97
25189	Alluvial/Denver Formation	5202.30	5141.30
25194	Alluvial/Denver Formation	5215.60	5179.40
25203	Alluvial/Denver Formation	5236.10	5176.10
25004	Denver Formation	5264.96	5183.20
25015	Denver Formation	5197.23	5154.50
25022	Denver Formation	5263.66	5211.70
25023	Denver Formation	5265.08	5197.40
25027	Denver Formation	5224.84	5179.00
25032	Denver Formation	5254.89	5220.20
25086	Denver Formation	5212.53	5183.14
25087	Denver Formation	5209.75	5141.37
25088	Denver Formation	5209.61	5190.87
25091	Denver Formation	5217.43	5132.51
25092	Denver Formation	5246.11	5179.49
25098	Denver Formation	5212.80	5184.34
25099	Denver Formation	5212.40	5139.73
25100	Denver Formation	5216.99	5185.87
25102	Denver Formation	5243.61	5171.62
25105	Denver Formation	5255.46	5204.69
25106	Denver Formation	5261.43	5188.97
25120	Denver Formation	5237.95	5177.80
25121	Denver Formation	5251.67	5179.06
25122	Denver Formation	5260.58	5219.37
25500	Denver Formation	5258.74	5201.09
25502	Denver Formation	5223.60	5169.10
26040	Denver Formation	5197.40	5146.40
26051	Denver Formation	5218.60	5158.30
26073	Denver Formation	5225.41	5173.05
26097	Denver Formation	5242.25	5172.70

Table 2.2-1. ELF Water Level Monitoring Network

Well ID	Aquifer	Top of Casing Elevation (feet amsl)	Bottom of Screen Elevation (feet amsl)
26099	Denver Formation	5232.31	5232.70
26158	Denver Formation	5214.88	5160.30
26159	Denver Formation	5233.75	5188.00
26164	Denver Formation	5189.26	5136.70
26170	Denver Formation	5184.02	5133.90
26175	Denver Formation	5206.29	5145.43
26176	Denver Formation	5206.02	5159.89
26177	Denver Formation	5214.92	5153.10
26179	Denver Formation	5224.89	5156.24
26180	Denver Formation	5224.57	5170.86
26181	Denver Formation	5217.82	5161.29
26183	Denver Formation	5214.81	5157.29
26186	Denver Formation	5207.79	5140.58
36186	Denver Formation	5286.23	5122.70
<i>Confined Flow System</i>			
25016	Denver Formation	5198.31	5132.10
25017	Denver Formation	5197.67	5117.40
25019 ²	Denver Formation	5193.85	5109.73
25020	Denver Formation	5195.25	5040.27
25021	Denver Formation	5240.10	5111.50
25024	Denver Formation	5265.04	5165.20
25034	Denver Formation	5255.60	5130.60
25085	Denver Formation	5212.91	5134.48
25093	Denver Formation	5245.76	5123.03
25101	Denver Formation	5251.19	5124.83
25123	Denver Formation	5259.86	5123.34
25183	Denver Formation	5206.80	5147.30
25195	Denver Formation	5215.50	5134.50
26150	Denver Formation	5220.96	5111.90
26185	Denver Formation	5208.53	5115.64

Notes:

¹Wells 25018 and 25019 repaired and resurveyed in 2021.

amsl – above mean sea level

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
<i>Unconfined Flow System</i>				
25003	2021-01-18	41.82	5194.26	5152.44
25003	2021-04-12	41.88	5194.26	5152.38
25003	2021-07-20	41.76	5194.26	5152.50
25003	2021-10-20	41.77	5194.26	5152.49
25004	2021-01-18	46.31	5264.96	5218.65
25004	2021-04-12	46.52	5264.96	5218.44
25004	2021-07-19	46.72	5264.96	5218.24
25004	2021-10-21	46.83	5264.96	5218.13
25015	2021-01-18	37.89	5197.23	5159.34
25015	2021-04-12	38.70	5197.23	5158.53
25015	2021-07-20	37.72	5197.23	5159.51
25015	2021-10-20	37.81	5197.23	5159.42
25018	2021-01-18	31.41	5195.62	5164.21
25018	2021-04-12	NA	5195.62	Repaired in June
25018	2021-07-19	31.07	5195.61	5164.54
25018	2021-10-21	31.53	5195.61	5164.08
25022	2021-01-18	43.40	5263.66	5220.26
25022	2021-04-12	43.50	5263.66	5220.16
25022	2021-07-19	43.58	5263.66	5220.08
25022	2021-10-21	43.56	5263.66	5220.10
25023	2021-01-18	46.23	5265.08	5218.85
25023	2021-04-12	46.35	5265.08	5218.73
25023	2021-07-19	46.41	5265.08	5218.67
25023	2021-10-21	46.45	5265.08	5218.63
25027	2021-01-18	44.15	5224.84	5180.69
25027	2021-04-08	44.18	5224.84	5180.66
25027	2021-07-19	44.21	5224.84	5180.63
25027	2021-10-19	44.21	5224.84	5180.63
25032	2021-01-18	28.35	5254.89	DRY
25032	2021-04-08	28.35	5254.89	DRY
25032	2021-07-19	28.35	5254.89	DRY
25032	2021-10-19	28.34	5254.89	DRY
25041	2021-01-18	26.30	5210.81	5184.51
25041	2021-04-12	26.60	5210.81	5184.21
25041	2021-07-19	25.96	5210.81	5184.85
25041	2021-10-21	26.44	5210.81	5184.37
25048	2021-01-18	18.54	5190.01	5171.47
25048	2021-04-12	18.33	5190.01	5171.68
25048	2021-07-19	18.12	5190.01	5171.89

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25048	2021-10-21	18.62	5190.01	5171.39
25054	2021-01-18	34.10	5207.94	5173.84
25054	2021-04-12	33.96	5207.94	5173.98
25054	2021-07-19	33.72	5207.94	5174.22
25054	2021-10-21	34.08	5207.94	5173.86
25059	2021-01-18	30.52	5208.97	5178.45
25059	2021-04-12	30.33	5208.97	5178.64
25059	2021-07-19	30.16	5208.97	5178.81
25059	2021-10-21	30.62	5208.97	5178.35
25086	2021-01-18	29.71	5212.53	DRY
25086	2021-04-08	29.70	5212.53	DRY
25086	2021-07-19	29.71	5212.53	DRY
25086	2021-10-19	29.71	5212.53	DRY
25087	2021-01-18	43.93	5209.75	5165.82
25087	2021-04-08	43.75	5209.75	5166.00
25087	2021-07-19	43.68	5209.75	5166.07
25087	2021-10-19	43.56	5209.75	5166.19
25088	2021-01-18	19.36	5209.61	DRY
25088	2021-04-08	19.37	5209.61	DRY
25088	2021-07-19	19.36	5209.61	DRY
25088	2021-10-19	19.02	5209.61	DRY
25091	2021-01-18	47.94	5217.43	5169.49
25091	2021-04-08	47.70	5217.43	5169.73
25091	2021-07-19	47.64	5217.43	5169.79
25091	2021-10-19	47.65	5217.43	5169.78
25092	2021-01-18	65.27	5246.11	5180.84
25092	2021-04-08	65.15	5246.11	5180.96
25092	2021-07-19	65.26	5246.11	5180.85
25092	2021-10-19	65.24	5246.11	5180.87
25098	2021-01-18	28.86	5212.80	DRY
25098	2021-04-08	28.84	5212.80	DRY
25098	2021-07-19	28.86	5212.80	DRY
25098	2021-10-19	28.83	5212.80	DRY
25099	2021-01-18	44.01	5212.40	5168.39
25099	2021-04-08	43.80	5212.40	5168.60
25099	2021-07-19	43.59	5212.40	5168.81
25099	2021-10-19	43.66	5212.40	5168.74
25100	2021-01-18	31.32	5216.99	DRY
25100	2021-04-08	31.31	5216.99	DRY
25100	2021-07-19	31.31	5216.99	DRY

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25100	2021-10-19	31.31	5216.99	DRY
25102	2021-01-18	63.04	5243.61	5180.57
25102	2021-04-08	62.89	5243.61	5180.72
25102	2021-07-19	63.13	5243.61	5180.48
25102	2021-10-19	63.17	5243.61	5180.44
25105	2021-01-18	37.76	5255.46	5217.70
25105	2021-04-12	37.70	5255.46	5217.76
25105	2021-07-19	37.84	5255.46	5217.62
25105	2021-10-19	37.69	5255.46	5217.77
25106	2021-01-18	56.16	5261.43	5205.27
25106	2021-04-12	56.12	5261.43	5205.31
25106	2021-07-19	56.40	5261.43	5205.03
25106	2021-10-19	56.06	5261.43	5205.37
25120	2021-01-18	48.75	5237.95	5189.20
25120	2021-04-08	48.80	5237.95	5189.15
25120	2021-07-19	48.35	5237.95	5189.60
25120	2021-10-19	47.58	5237.95	5190.37
25121	2021-01-18	71.28	5251.67	5180.39
25121	2021-04-08	71.09	5251.67	5180.58
25121	2021-07-19	71.30	5251.67	5180.37
25121	2021-10-19	71.18	5251.67	5180.49
25122	2021-01-18	39.15	5260.58	DRY
25122	2021-04-08	39.15	5260.58	DRY
25122	2021-07-19	39.15	5260.58	DRY
25122	2021-10-19	39.14	5260.58	DRY
25189	2021-01-18	35.76	5202.30	5166.54
25189	2021-04-12	35.25	5202.30	5167.05
25189	2021-07-19	35.37	5202.30	5166.93
25189	2021-10-19	35.53	5202.30	5166.77
25194	2021-01-18	34.58	5215.60	5181.02
25194	2021-04-08	34.33	5215.60	5181.27
25194	2021-07-19	35.80	5215.60	5179.80
25194	2021-10-19	34.35	5215.60	5181.25
25203	2021-01-18	55.56	5236.10	5180.54
25203	2021-04-08	55.35	5236.10	5180.75
25203	2021-07-19	55.44	5236.10	5180.66
25203	2021-10-19	55.58	5236.10	5180.52
25500	2021-01-18	40.15	5258.74	5180.54
25500	2021-04-12	40.37	5258.74	5180.75
25500	2021-07-19	40.55	5258.74	5180.66

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25500	2021-10-19	40.53	5258.74	5180.52
25502	2021-01-18	39.05	5223.60	5218.59
25502	2021-04-12	38.90	5223.60	5218.37
25502	2021-07-19	38.69	5223.60	5218.19
25502	2021-10-21	39.06	5223.60	5218.21
26040	2021-01-18	49.94	5197.40	5184.55
26040	2021-04-08	49.94	5197.40	5184.70
26040	2021-07-20	49.92	5197.40	5184.91
26040	2021-10-20	49.96	5197.40	5184.54
26051	2021-01-18	55.52	5218.60	5147.46
26051	2021-04-08	55.53	5218.60	5147.46
26051	2021-07-20	55.74	5218.60	5147.48
26051	2021-10-20	55.89	5218.60	5147.44
26073	2021-01-18	47.65	5225.41	5163.08
26073	2021-04-08	47.64	5225.41	5163.07
26073	2021-07-20	47.67	5225.41	5162.86
26073	2021-10-20	47.69	5225.41	5162.71
26097	2021-01-20	56.84	5242.25	5177.76
26097	2021-04-08	56.70	5242.25	5177.77
26097	2021-07-20	57.21	5242.25	5177.74
26097	2021-10-20	57.39	5242.25	5177.72
26099	2021-01-18	49.82	5232.31	5185.41
26099	2021-04-08	49.75	5232.31	5185.55
26099	2021-07-20	49.70	5232.31	5185.04
26099	2021-10-19	49.58	5232.31	5184.86
26158	2021-01-18	34.75	5214.88	5182.49
26158	2021-04-08	34.66	5214.88	5182.56
26158	2021-07-20	34.89	5214.88	5182.61
26158	2021-10-20	35.07	5214.88	5182.73
26159	2021-01-18	40.15	5233.75	5203.36
26159	2021-04-12	40.37	5233.75	5203.29
26159	2021-07-19	40.55	5233.75	5202.64
26159	2021-10-19	40.53	5233.75	5202.67
26164	2021-01-18	44.81	5189.26	5144.45
26164	2021-04-08	44.78	5189.26	5144.48
26164	2021-07-20	44.89	5189.26	5144.37
26164	2021-10-20	44.89	5189.26	5144.37
26170	2021-01-18	44.02	5184.02	5140.00
26170	2021-04-08	44.05	5184.02	5139.97
26170	2021-07-20	44.09	5184.02	5139.93

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
26170	2021-10-20	44.12	5184.02	5139.90
26175	2021-01-18	49.15	5206.29	5157.14
26175	2021-04-08	49.02	5206.29	5157.27
26175	2021-07-20	49.19	5206.29	5157.10
26175	2021-10-20	49.29	5206.29	5157.00
26176	2021-01-18	47.31	5206.02	DRY
26176	2021-04-08	47.30	5206.02	DRY
26176	2021-07-20	47.29	5206.02	DRY
26176	2021-10-20	47.29	5206.02	DRY
26177	2021-01-18	56.24	5214.92	5158.68
26177	2021-04-08	56.16	5214.92	5158.76
26177	2021-07-20	56.12	5214.92	5158.80
26177	2021-10-20	55.85	5214.92	5159.07
26178	2021-01-18	34.32	5214.73	DRY
26178	2021-04-08	34.33	5214.73	DRY
26178	2021-07-20	34.33	5214.73	DRY
26178	2021-10-20	34.34	5214.73	DRY
26179	2021-01-18	55.67	5224.89	5169.22
26179	2021-04-08	55.58	5224.89	5169.31
26179	2021-07-20	56.01	5224.89	5168.88
26179	2021-10-20	56.19	5224.89	5168.70
26180	2021-01-18	46.74	5224.57	5177.83
26180	2021-04-08	46.78	5224.57	5177.79
26180	2021-07-20	46.84	5224.57	5177.73
26180	2021-10-20	46.86	5224.57	5177.71
26181	2021-01-18	49.79	5217.82	5168.03
26181	2021-04-08	49.60	5217.82	5168.22
26181	2021-07-20	50.08	5217.82	5167.74
26181	2021-10-20	50.29	5217.82	5167.53
26182	2021-01-18	40.84	5217.22	5176.38
26182	2021-04-08	40.84	5217.22	5176.38
26182	2021-07-20	40.88	5217.22	5176.34
26182	2021-10-20	40.90	5217.22	5176.32
26183	2021-01-18	48.45	5214.81	5166.36
26183	2021-04-08	48.46	5214.81	5166.35
26183	2021-07-20	48.69	5214.81	5166.12
26183	2021-10-20	48.85	5214.81	5165.96
26184	2021-01-18	42.49	5214.94	DRY
26184	2021-04-08	42.47	5214.94	DRY
26184	2021-07-20	42.47	5214.94	DRY

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
26184	2021-10-20	42.46	5214.94	DRY
26186	2021-01-18	42.89	5207.79	5164.90
26186	2021-04-08	42.90	5207.79	5164.89
26186	2021-07-20	43.09	5207.79	5164.70
26186	2021-10-20	43.25	5207.79	5164.54
36186	2021-01-18	49.34	5286.23	5236.89
36186	2021-04-12	49.53	5286.23	5236.70
36186	2021-07-19	44.87	5286.23	5241.36
36186	2021-10-19	45.32	5286.23	5240.91
<i>Confined Flow System</i>				
25016	2021-01-18	43.28	5198.31	5155.03
25016	2021-04-12	43.30	5198.31	5155.01
25016	2021-07-20	43.16	5198.31	5155.15
25016	2021-10-20	43.28	5198.31	5155.03
25017	2021-01-18	45.06	5197.67	5152.61
25017	2021-04-12	44.92	5197.67	5152.75
25017	2021-07-20	45.01	5197.67	5152.66
25017	2021-10-20	45.07	5197.67	5152.60
25019	2021-01-18	32.81	5195.00	5162.19
25019	2021-04-12	NA	5195.00	Repaired in June
25019	2021-07-19	31.67	5193.85	5162.18
25019	2021-10-21	31.73	5193.85	5162.12
25020	2021-01-18	46.98	5195.25	5148.27
25020	2021-04-12	46.74	5195.25	5148.51
25020	2021-07-19	46.72	5195.25	5148.53
25020	2021-10-21	47.24	5195.25	5148.01
25021	2021-01-18	65.94	5240.10	5174.16
25021	2021-04-12	65.52	5240.10	5174.58
25021	2021-07-20	65.64	5240.10	5174.46
25021	2021-10-21	66.09	5240.10	5174.01
25024	2021-01-18	61.87	5265.04	5203.17
25024	2021-04-12	62.22	5265.04	5202.82
25024	2021-07-19	61.97	5265.04	5203.07
25024	2021-10-21	62.36	5265.04	5202.68
25034	2021-01-18	82.97	5255.60	5172.63
25034	2021-04-08	82.76	5255.60	5172.84
25034	2021-07-19	83.44	5255.60	5172.16
25034	2021-10-19	82.71	5255.60	5172.89
25085	2021-01-18	48.51	5212.91	5164.40
25085	2021-04-08	48.44	5212.91	5164.47

Table 2.2-2. 2021 Water Level Measurements Summary

Well ID	Date	Depth to Water (feet amsl)	Top of Casing Elevation (feet amsl)	Water Level Elevation (feet amsl)
25085	2021-07-19	48.45	5212.91	5164.46
25085	2021-10-19	48.15	5212.91	5164.76
25093	2021-01-18	74.22	5245.76	5171.54
25093	2021-04-08	74.08	5245.76	5171.68
25093	2021-07-19	74.55	5245.76	5171.21
25093	2021-10-19	74.23	5245.76	5171.53
25101	2021-01-18	77.50	5251.19	5173.69
25101	2021-04-08	77.41	5251.19	5173.78
25101	2021-07-19	77.51	5251.19	5173.68
25101	2021-10-19	77.39	5251.19	5173.80
25123	2021-01-18	84.41	5259.86	5175.45
25123	2021-04-08	84.32	5259.86	5175.54
25123	2021-07-19	84.35	5259.86	5175.51
25123	2021-10-19	84.42	5259.86	5175.44
25183	2021-01-18	43.05	5206.80	5163.75
25183	2021-04-08	42.95	5206.80	5163.85
25183	2021-07-19	42.78	5206.80	5164.02
25183	2021-10-19	42.57	5206.80	5164.23
25195	2021-01-18	49.96	5215.50	5165.54
25195	2021-04-08	49.97	5215.50	5165.53
25195	2021-07-19	49.80	5215.50	5165.70
25195	2021-10-19	49.62	5215.50	5165.88
26150	2021-01-18	49.05	5220.96	5171.91
26150	2021-04-08	49.05	5220.96	5171.91
26150	2021-07-20	49.38	5220.96	5171.58
26150	2021-10-20	49.47	5220.96	5171.49
26185	2021-01-18	56.64	5214.88	5151.89
26185	2021-04-08	56.55	5214.88	5151.98
26185	2021-07-20	56.84	5214.88	5151.69
26185	2021-10-20	56.88	5214.88	5151.65

amsl – above mean sea level

Table 2.3-1. ELF Water Quality Monitoring Network

Well Number	Groundwater Flow System	Aquifer	Upgradient/ Downgradient
25021	Confined	Denver Formation	Upgradient
25022	Unconfined	Denver Formation	Upgradient
25024	Confined	Denver Formation	Upgradient
25092	Unconfined	Denver Formation	Downgradient
25093	Confined	Denver Formation	Downgradient
25102	Unconfined	Denver Formation	Downgradient
25105	Unconfined	Denver Formation	Upgradient
25106	Unconfined	Denver Formation	Upgradient
25120	Unconfined	Denver Formation	Downgradient
25121	Unconfined	Denver Formation	Cross-gradient
25123	Confined	Denver Formation	Upgradient
26099	Unconfined	Denver Formation	Downgradient

Note:

Well 25106 reclassified as being screened in the Denver Formation based on records evaluation.

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
<i>Volatile Organic Compounds by Gas Chromatography/Mass Spectrometry</i>	
1,1,1-Trichloroethane	111TCE
1,1,2-Trichloroethane	112TCE
1,1-Dichloroethane	11DCLE
1,1-Dichloroethene	11DCE
1,2-Dichloroethane	12DCLE
1,2-Dichlorobenzene	12DCLB
1,3-Dichlorobenzene	13DCLB
1,4-Dichlorobenzene	14DCLB
1,2-Dichloropropane	12DCLP
1,2-Dimethylbenzene	12DMB
1,1,2,2-Tetrachloroethane	TCLEA
Acetone	ACET
Acrylonitrile	ACRYLO
Benzene	C6H6
Bicycloheptadiene	BCHPD
Bromodichloromethane	BRDCLM
Bromoform	CHBR3
Bromomethane	CH3BR
Carbon Disulfide	CS2
Carbon tetrachloride	CCL4
Chlorobenzene	CLC6H5
Chloroethane	C2H5CL
cis-1,2-Dichloroethene	C12DCE
cis-1,3-Dichloropropene	C13DCP
Dichlorodifluoromethane	CCL2F2
Chloroform	CHCL3
Chloromethane	CH3CL
Dibromochloromethane	DBRCLM
Dibromochloropropane	DBCP
Dicyclopentadiene	DCPD
Ethylbenzene	ETC6H5
Methylene chloride	CH2CL2
Methyl ethyl ketone	MEK
Methyl isobutyl ketone	MIBK
Methyl-n-butyl ketone	MNBK
Styrene	STYR
trans-1,2-Dichloroethene	T12DCE
trans-1,3-Dichloropropene	T13DCP
Tetrachloroethene	TCLEE
Trichlorofluoromethane	CCL3F

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
Toluene	MEC6H5
Trichloroethene	TRCLE
Vinyl chloride	C2H3CL
Xylenes	XYLEN
Organochlorine Pesticides	
Dichlorodiphenyl dichloroethane	PPDDD
Dichlorodiphenyl dichloroethene	PPDDE
Dichlorodiphenyl trichloroethane	PPDDT
Aldrin	ALDRN
alpha-Endosulfan	AENSLF
alpha-Chlordane	ACLDAN
Dieldrin	DLDRN
Endrin	ENDRN
Endrin aldehyde	ENDRNA
Endrin ketone	ENDRNK
gamma-Chlordane	GCLDAN
Hexachlorocyclopentadiene	CL6CP
Isodrin	ISODR
Methoxychlor	MEXCLR
Organosulfur Compounds	
1,4-Oxathiane	OXAT
Benzothiazole	BTZ
Dimethyl disulfide	DMDS
Dithiane	DITH
p-Chlorophenylmethyl sulfide	CPMS
p-Chlorophenylmethyl sulfoxide	CPMSO
p-Chlorophenylmethyl sulfone	CPMSO2
Organophosphorus Compounds by Gas Chromatography	
Dimethyl methyl phosphonate	DMMP
Diisopropyl methyl phosphonate	DIMP
Mercury by Cold Vapor Atomic Absorption	
Mercury	HG
Arsenic by Graphite Furnace Atomic Adsorption	
Arsenic	AS
Metals/Cations by Inductively Coupled Argon Plasma	
Aluminum	AL
Barium	BA
Beryllium	BE
Boron	B
Antimony	SB
Cadmium	CD

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
Calcium	CA
Chromium	CR
Cobalt	CO
Copper	CU
Iron	FE
Lead	PB
Magnesium	MG
Manganese	MN
Nickel	NI
Potassium	K
Selenium	SE
Silver	AG
Sodium	NA
Thallium	TL
Vanadium	V
Zinc	ZN
<i>Cyanide by Colorimetric Method</i>	
Cyanide	CYN
<i>Ammonia</i>	
Ammonia	NH3
<i>Alkalinity</i>	
Alkalinity	ALK
<i>Anions</i>	
Bromide	BR
Chloride	CL
Fluoride	F
Nitrate	NO3
Nitrite	NO2
Orthophosphate	PO4ORT
Sulfate	SO4
<i>Nitrosamines</i>	
n-Nitrosodimethylamine	NNDMEA
<i>Nitrogen-Phosphorus Pesticides</i>	
Atrazine	ATZ
Malathion	MLTHN
Parathion	PRTHN
Supona	SUPONA
Vapona	DDVP
<i>Organic Carbon</i>	
Total organic carbon	TOC
Dissolved organic carbon	DOC

Table 2.3-2. Water Quality Monitoring Analyte List

Method/Analyte Name	Test Name
<i>Agent Degradation Products by High Performance Liquid Chromatography</i>	
Thiodiglycol	TDGCL
<i>Agent Products by Ion Chromatography</i>	
Isopropyl methylphosphonic acid	IMPA
<i>Kjeldahl Nitrogen</i>	
Nitrogen by Kjeldahl method	N2KJEL

Note:

Individual analytes in **Bold** are Indicator Compounds.

Table 2.3-3: Quality Control Samples

Sample Type/Site ID	Sample Date(s)
<i>Field Duplicate</i>	
25092	7/14/2021
25093	5/4/2021, 7/14/2021, 10/21/2021
25102	4/21/2021
25105	4/26/2021
26099	10/21/2021
<i>Lab Duplicates</i>	
25022	4/27/2021
25092	4/15/2021
25093	5/4/2021
25105	4/26/2021
25123	4/21/2021
<i>Field Blanks</i>	
25093	1/20/2021 and 5/4/2021
25099	4/28/2021
25195	7/14/2021
25203	4/22/2021

Table 3.0-1. ELF Groundwater Monitoring Well Usage

Well/ Designation	Data Used to Calculate Current (2021) Prediction Limits			Prediction Limits Applied to Downgradient Wells (Quarterly in 2021)
	Data Used to Calculate Baseline (2010) Prediction Limits		Upgradient Data from <u>Post-Closure</u> Monitoring Period used to Calculate Prediction Limits 5/27/2010 to 5/6/2020	
	Upgradient Data from <u>Preoperational</u> Monitoring Period used to Calculate Prediction Limits 10/1/2003 to 3/31/2006	Upgradient Data from <u>Operational/Closure</u> Monitoring Period used to Calculate Prediction Limits 4/1/2006 to 5/26/2010		
Upgradient				
25021	X	X	X	
25022	X	X	X	
25024	X	X	X	
25105	X	X	X	
25106	X	X	X	
25123	X	X	X	
Downgradient				
25092				X
25093				X
25102				X
25120				X
26099				X

Notes:

Well 25121 has been removed from this table. Detection of carbon tetrachloride and chloroform in cross-gradient well 25121 suggests the well is in a flow path with the NP/Bedrock Ridge Plume. In accordance with the ELF PCGMP (Navarro 2020) well 25121 is used to evaluate any cross-gradient potential impacts to the UFS and CFS from the NP/Bedrock Ridge plume contaminants. It is not used to calculate the prediction limits for ELF.

Analytical results from the pre-operational, operational, closure, and post-closure monitoring periods utilized to calculate the current ELF prediction limits are available in the Supporting Documentation folder.

Table 3.0-2. Prediction Limits for ELF 2021 Water Quality Monitoring

Indicator Compound	Current Method Reporting Limit (µg/L)	Proportion of Upgradient Non-detected Sample Values (2003-2020)	Statistical Method Used	Selected Prediction Limit (µg/L)
<i>Volatile Organic Compounds</i>				
1,1,1-Trichloroethane ¹	0.2	100	Non-parametric	0.26
1,1-Dichloroethane ¹	0.2	100	Non-parametric	0.26
1,1-Dichloroethene ¹	0.202	100	Non-parametric	0.26
1,2-Dichloroethane ¹	0.2	100	Non-parametric	0.26
Benzene	0.2	99.1	Non-parametric	0.93
Carbon tetrachloride ¹	0.2	100	Non-parametric	0.26
Chloroform ¹	0.2	100	Non-parametric	0.26
<i>Organochlorine Pesticides</i>				
Dieldrin	0.00252 ²	82.0	Non-parametric	0.107
<i>Organophosphorus Compounds</i>				
DIMP	0.5	98.3	Non-parametric	1.21
<i>Metals</i>				
Arsenic	1	77.9	Non-parametric	11.5
Chromium	10	99.6	Non-parametric	10.4
Lead	3	69.4	Non-parametric	26.3
Mercury ¹	0.2	100	Non-parametric	0.26

Notes:

¹ Because this compound was not detected in any sample, the prediction limit value for this analyte is the 99 percent upper confidence limit (UCL) of the MRL. For purposes of this report, the 99 percent UCL is defined as 1.3 times the MRL.

² The reporting limit decreased slightly as a result of an MRL study required by the SQAPP for method recertification every three years.

ug/L Micrograms per liter

Table 3.0-3. Prediction Limits for ELF 2022 Water Quality Monitoring

Indicator Compound	Current Method Reporting Limit (µg/L)	Proportion of Upgradient Non-detected Sample Values (2003-2021)	Statistical Method Used	Selected Prediction Limit (µg/L)
<i>Volatile Organic Compounds</i>				
1,1,1-Trichloroethane ¹	0.2	100	Non-parametric	0.26
1,1-Dichloroethane ¹	0.2	100	Non-parametric	0.26
1,1-Dichloroethene ¹	0.202	100	Non-parametric	0.26
1,2-Dichloroethane ¹	0.2	100	Non-parametric	0.26
Benzene	0.2	99.2	Non-parametric	0.93
Carbon tetrachloride ¹	0.2	100	Non-parametric	0.26
Chloroform ¹	0.2	100	Non-parametric	0.26
<i>Organochlorine Pesticides</i>				
Dieldrin	0.00252	81.2	Non-parametric	0.107
<i>Organophosphorus Compounds</i>				
DIMP	0.5	98.3	Non-parametric	1.21
<i>Metals</i>				
Arsenic	1	78	Non-parametric	11.5
Chromium	10	99.6	Non-parametric	10.4
Lead	3	70.2	Non-parametric	26.3
Mercury ¹	0.2	100	Non-parametric	0.26


Notes:

¹ Because this compound was not detected in any sample, the prediction limit value for this analyte is the 99 percent upper confidence limit (UCL) of the MRL. For purposes of this report, the 99 percent UCL is defined as 1.3 times the MRL.










ug/L Micrograms per liter

FIGURES


This page intentionally left blank.



Legend

-  CAMU Boundary
 Buildings
 Sumps
 2014 North Plants/
Bedrock Ridge Plume Extent
 Section Lines
 Light Duty Roads
 Unpaved Roads
 Fences
 Ditches, Canals

Monitoring Well Network	Flow System/Aquifer		
	Unconfined Alluvial	Unconfined Denver	Confined Denver
Hazardous Waste Landfill (HWL)		△	○
HWL Supplemental Operations		△	
Enhanced Hazardous Waste Landfill (ELF)		△	○
Water Level Only	□	△	○




Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM

NAD27-NGVD29 Datum, US Survey Feet,
Colorado North Zone



Figure 2.2-1

Well/Piezometer/Sump Location Map
2021 Groundwater Monitoring



Legend

- CAMU Boundary
- Section Lines
- Light Duty Roads
- Unpaved Roads
- Ditches, Canals
- Buildings
- Unsaturated Alluvium
- Water Elevation Contours - 5-foot Intervals
- Inferred Water Elevation Contours

Monitoring Well Network	Flow System/Aquifer	
	Unconfined Alluvial	Unconfined Denver
Hazardous Waste Landfill (HWL)		▲
HWL Supplemental Operations		△
Enhanced Hazardous Waste Landfill (ELF)		▲
Water Level Only	□	▲

NAD27-NGVD29 Datum, US Survey Feet, Colorado North Zone

Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM

Program Manager
Rocky Mountain Arsenal


U.S. Army • COMMITTED TO PROTECTION OF THE ENVIRONMENT •

Figure 2.2-2

Potentiometric Surface of the Unconfined Flow System, Enhanced Hazardous Waste Landfill

April 2021

M:\projects\elf_post-closure\2021\mxds\elf_ufc_fy21.mxd
6/2/2022



Legend

- Approximate Boundary of the Lower Sandstone Units
- 2014 North Plants/Bedrock Ridge Plume Extent
- CAMU Boundary
- Light Duty Roads
- Unpaved Roads
- Ditches, Canals
- Section Lines
- Buildings
- Unsaturated Alluvium
- Water Elevation Contours - 5-foot Intervals
- Inferred Water Elevation Contours

Monitoring Well Network	Flow System/Aquifer	
	Confined Denver	Unconfined Denver
Hazardous Waste Landfill (HWL)		
HWL Supplemental Operations		
Enhanced Hazardous Waste Landfill (ELF)		
Water Level Only		




NAD27-NGVD29 Datum, US Survey Feet, Colorado North Zone

Sources: U.S. Army, RMA GIS, OMC, Shell/AECOM



Figure 2.2-3

Potentiometric Surface for the Lower Sandstone Unit and Equivalent Units, April 2021



Legend

- 2014 North Plants/Bedrock Ridge Plume Extent
- Ditches, Canals
- Section Lines
- Fences
- Light Duty Roads
- Unpaved Roads
- CAMU Boundary
- Buildings

Note: ¹Concentrations are in micrograms per liter
²Data shown from calendar year 2021
³LT - Less than the method detection limit

Monitoring Well Network	Flow System/Aquifer		
	Unconfined Alluvial	Unconfined Denver	Confined Denver
Hazardous Waste Landfill (HWL)		△	○
HWL Supplemental Operations		△	
Enhanced Hazardous Waste Landfill (ELF)		△	○

N

0 250 500 1,000
Feet

NAD27-NGVD29 Datum, US Survey Feet, Colorado North Zone

Program Manager
Rocky Mountain Arsenal

U.S. Army • COMMITTED TO PROTECTION OF THE ENVIRONMENT •

Figure 2.3-1

Indicator Compounds Detection Map 2021 Groundwater Monitoring

M:\projects\hwl_post-closure\2021\mxd\self_ind_ompd_detection_2021_new.mxd
5/25/2022

APPENDIX G

NRAP Log

This page intentionally left blank.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2008-001	Hand seeding of small areas on the SDT RCRA-Equivalent Cover. Amendment will not be applied, the sites will not be irrigated, and minor changes to the seed mix are required based on availability.	SDT RCRA-Equivalent	Unknown	09/20/11 (Issued for concurrence 05/27/08)	09/20/11 (Issued for concurrence 05/27/08)	Comments resolved 06/2008	05/29/08	05/29/08	Concurrence or resolution with all parties.
2009-001	Temperature probe #4 failed and requires replacement. The probe is located near Lysimeter 002 and is approximately 30" bgs. Hand tools will be used to dig a hole adjacent to the temperature probe nest and a new probe will be installed at the appropriate depth. The hole will be filled with spoils from the excavation.	SDT RCRA-Equivalent	06/25/09 07/02/09 07/07/09	07/14/09	07/16/09	07/22/09	07/23/09	07/16/09	All parties concur.
2009-002	The rain gauge at Lysimeter 002 will be replaced with another unit mounted to a stand, separate from the control panel. A hole approximately 24" deep will be dug with hand tools. The stand will be placed in the hole and spoils will be used to backfill around it. A shallow trench (6" deep) will be dug from the new stand to the control panel for the instrument wire.	SDT RCRA-Equivalent	06/29/09	07/30/09	07/30/09	07/30/09	07/30/09	07/30/09	All parties concur.
2009-003	The soil thickness loss at EM-HWL03 exceeds the Non-Routine Action Level. The settlement around this monument is localized and additional soil will be placed in the depression to match the	HWL	09/10/09 09/17/09	09/28/09	09/28/09	10/01/09	10/01/09	10/01/09	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	surrounding grade.								
2009-004	The RMA biomonitoring program requires the installation of starling and kestrel nest boxes within the ICS AMA. Two arrays of starling nest boxes (10 boxes each) will be installed; one on the SDT 2-ft Cover and one on the South Plants 3-ft cover. One kestrel box will be installed near the former intersection of 7 th Avenue and D Street, in a non-cover area. Installation of these nest boxes will require intrusive activities.	SDT 2-ft Cover South Plants 3-ft Cover Non-cover area	12/17/09 01/06/10 01/07/10	01/12/10	01/12/10	01/22/10	02/04/10	02/04/10	All parties concur.
2010-001	Extraction wells in the South Tank Farm Benzene Plume area will be closed and piping will be capped. These activities will be intrusive in the 3-ft Cover.	South Plants 3-ft Cover	N/A	NRAP-2010-001 was terminated after the Water Team agreed not to close extraction wells at this time.					Terminated
2010-002	Some components of the Lime Basins dewatering wells discharge piping have deteriorated and require replacement. Excavations must be made through the RCRA-Equivalent Cover and into the subgrade soil to access the components. Excavations will be made at six well locations. The excavations will be repaired to the requirements of the ICS Project Design with materials removed during excavation, or new materials if those removed do not meet the requirements of the	Lime Basins	05/20/10 06/29/10	07/14/10	07/14/10	07/15/10	07/15/10	07/15/10	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	design.								
2010-003	Significant storm events have created deep erosion gullies around box culvert wing walls and in other locations of concentrated flow into perimeter channels at the HWL and ELF. The soil around these features generally has not withstood concentrated stormwater flow and it is unlikely that vegetation establishment will be robust enough to prevent further erosion. Additional erosion protection, exceeding that required by the original design, is required to maintain the integrity of the perimeter channel slopes where concentrated flow enters them.	HWL/ELF	08/19/10	Unknown	Unknown	08/24/10 (email)	Unknown	Unknown	Failure to locate original document.
2010-004	The Lime Basins Groundwater Treatment Relocation Project requires the transmission of groundwater from the Lime Basins meter building to the Basin A Neck treatment facility via the existing pipeline that was formerly used to carry treated water from the CERCLA Plant to the Basin A Neck recharge trenches. Use of this existing transmission pipeline for the stated purpose requires the installation of a section of piping connecting the existing piping from the Lime Basins meter building to the CERCLA Plant to	ICS Non-Cover	08/02/10 08/11/10	08/11/10	08/11/10	08/25/10	09/23/10	08/23/10	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	the existing piping connecting the CERCLA Plant to the Basin A Neck treatment facility.								
2010-005	The PMC is replacing survey monuments at section corners and mid-section points throughout RMA that were destroyed during remediation activities. Two such monuments will be installed within the ICS Army Maintained Area (AMA) along former 7 th Avenue.	ICS Non-Cover	09/09/10	09/10/10	09/13/10	09/23/10	09/15/10	09/13/10	All parties concur.
2010-006	The RVO requires extension of the fiber optic network to provide data/phone service to the Lime Basins Meter Building. An existing (buried) fiber optic line that formerly serviced the B-312 Fire Station is located near a phone pedestal just southeast of the CERCLA Wastewater Treatment Facility (white circle on attached drawing). This fiber optic line will be located and a new line will be connected to extend to the Lime Basins Meter Building.	ICS Non-Cover	09/09/10	09/09/10	09/09/10	09/09/10 (e-mail)	09/09/10 (e-mail)	09/09/10 (e-mail)	All parties concur.
2010-007	Closure of the Landfill Wastewater Treatment System (LWTS) requires the abandonment of several underground utilities, including the treated water discharge piping. Abandonment of the treated water discharge piping will involve the abandonment of two manholes containing air relief valves, which	HWL Non-Cover	10/04/10	10/04/10	05/02/11	10/05/10 (e-mail)	None	10/05/10 (e-mail)	No record of CDPHE concurrence. All other parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	are within the HWL fence, north of the landfill. Abandonment of the manholes will involve intrusive work inside the Army Maintained Area.								
2010-008	On Thursday, September 30, 2010, URS discovered a potential leak at the Complex Trenches groundwater extraction wellhead (Well #36305). Initial investigation suggests that there may be damage to the groundwater conveyance piping at, or near, the well's pitless adaptor. Further investigation and repair will involve intrusive work (excavation and backfill) inside the Army Maintained Area.	CAT	10/04/10	10/04/10	10/04/10	10/14/10	10/14/10	10/06/10	All parties concur.
2010-009	A telephone pedestal was damaged by a mower during recent weed control work. The pedestal is located on D Street, south of Drainage Crossing 2, between the perimeter road and the fence. Repair will require excavation around the box and cables, which are located within the Army Maintained Area.	ICS Non-Cover	10/18/10	10/18/10	10/18/10	10/27/10	11/10/10	11/10/10	All parties concur.
2010-010	Over-seeding is required on the ELF and in some parts of the HWL and surrounding areas in order to better establish desirable grasses, especially cool season grasses. The area exceeds 11,000 sft and requires	HWL and ELF	11/08/10	11/10/10	11/10/10	11/10/10	11/10/10	11/10/10	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	consultation.								
2010-011	Over-seeding is required on parts of the ICS and Basin F Army Maintained Areas in order to better establish desirable grasses. The area exceeds 11,000 sft and requires consultation.	Basin F, ICS, and Non-Cover	11/09/10	11/10/10	11/10/10	11/10/10	11/10/10	11/10/10	All parties concur.
2010-012	The LLDPE boot cannot be replaced around well DW-9 because a new pitless adaptor was installed. Bentonite will be placed around the liner penetrations as an alternative.	Lime Basins	11/18/10 11/22/10	11/23/10	05/02/11	11/23/10 (e-mail)	11/23/10 (e-mail)	11/23/10 (e-mail)	All parties concur.
2011-001	An ICS perimeter fence gate stop post at the Channel 6 gate was installed incorrectly. The post will be moved to the correct location.	ICS Non-Cover	01/19/11	01/23/11	01/31/11	02/02/11	02/02/11	02/02/11	All parties concur.
2011-002A	Installation of Carsonite marker posts to improve visibility of features that could be obscured by tall vegetation. Installation of the marker posts will require intrusive activities in the covers and in non-cover areas.	Basin F, ICS, and Non-Cover	02/23/11	03/14/11	03/16/11	03/17/11	04/22/11	03/17/11	All parties concur.
2011-002B	Installation of Carsonite marker posts to improve visibility of features that could be obscured by tall vegetation. Installation of the marker posts will require intrusive activities in the caps and in surrounding support areas.	HWL and ELF	02/23/11	03/14/11	03/16/11	03/17/11	04/22/11	03/17/11	All parties concur.
2011-003	Installation of a new rain gauge near the Lime Basins Metering	ICS Non-	03/15/11	03/17/11	03/17/11	03/17/11	04/22/11	03/17/11	All parties



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	Building. The installation will require intrusive activities in a non-cover area west of the Lime Basins cover.	Cover							concur.
2011-004	Re-establish positive drainage downstream of the Channel 4 outlet structure northwest of the Basin A cover. Approximately 400 feet of flowline in the non-cover area will be excavated to promote positive drainage.	ICS Non-Cover	03/24/11	05/04/11	05/04/11	03/28/11 (e-mail)	03/29/11 (e-mail)	03/28/11 (e-mail)	All parties concur.
2011-005	Revegetation of the ELF perimeter channels including amendment, seedbed prep, seeding, and installation of erosion control blankets and erosion control wattles over the seeded areas.	ELF Non-Cover	06/10/11	06/21/11	06/21/11	07/05/11	08/11/11	07/12/11	All parties concur.
2011-006	Documentation of ELF sump sample results at LB LDS2. Monthly sampling was performed per the ELF Post-Closure Groundwater Monitoring Plan. Results of the three-month sampling period and an investigation summary regarding potential causes for the detections are included.	ELF	07/21/11	04/02/12	04/03/12	04/25/12	04/19/12	04/19/12	All parties concur.
2011-007	Rebuild the riprap outlet structure at Channel 4 to improve drainage from the concrete lined channel.	ICS	08/23/11	08/23/11	08/24/11	09/01/11	09/08/11	09/08/11	All parties concur.
2011-008	Removal of barbed wire from the HWL and ELF perimeter fence, and removal of gate on the west	HWL and ELF Non-Cover	08/24/11	08/25/11	08/24/11	09/01/11	09/01/11	09/01/11	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	fence and replacement with chainlink fence fabric.								
2011-009	Removal of a soil feature measuring approximately 50-ft long, 4-ft wide, and 2-ft tall that was left in place along the eastern portion of the former CERCLA Wastewater Treatment Plant site.	ICS Non-Cover	09/16/11	09/20/11	09/20/11	09/22/11	09/22/11	09/22/11	All parties concur.
2011-010	Installation of warning signs adjacent to two cattle guards, one each, on the ICS and Basin F perimeter fences.	ICS and Basin F Non-Cover	09/21/11	09/22/11	09/26/11	09/29/11	09/29/11	09/29/11	All parties concur.
2011-011	Covering exposed portions of the HWL and ELF gravel drainage layer geotextile with stone.	HWL and ELF	10/26/11	NRAP-2011-011 was rescinded by James L. Green via email on November 17, 2011.					Rescinded
2011-012	Erosion/settlement monument EM-ELF08 had a measured soil thickness loss of 5.0 inches on September 29, 2011. The non-routine action trigger level for these monuments is 0.4 foot, which is 4.8 inches. Investigation showed the soil around the monument had settled or washed away. Replacement soil will be imported to fill the depression.	ELF	10/10/11	11/21/11	11/21/11	12/15/11	01/11/12	11/22/11	All parties concur.
2011-013	Overseeding of 12.4 acres around the ELF perimeter, and hand seeding of Sand Dropseed on 37.4 acres of the ELF cap.	ELF	11/17/11	11/21/11	11/21/11	12/15/11	01/11/12	11/22/11	All parties concur.
2011-014	Areas of the ICS and Basin F require seeding where soil repairs had been made earlier in the year,	Basin F and ICS	11/21/11	11/21/11	11/21/11	12/15/11	01/11/12	11/22/11	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	and over-seeding where vegetation is less well established than surrounding areas.								
2012-001	Documentation of HWL sump sample results at LDS2, LDS3, and LDS4 from April 2011 through October 2011.	HWL	06/17/11 08/31/11 09/23/11 10/06/11 10/13/11 11/15/11	09/26/12	09/26/12	10/29/12	10/10/12	10/10/12	All parties concur.
2012-002	Documentation of ELF sump sample results at WPLDS1, WPLDS2, and LBLDS2 from July 2011 through October 2011.	ELF	08/31/11 09/23/11 10/06/11 10/13/11 11/15/11	09/26/12	09/26/12	10/29/12	10/10/12	10/10/12	All parties concur.
2012-003	The fence surrounding the HWL and ELF demarcates the AMA boundary, which needs to be expanded in six locations to improve access to monitoring wells and to provide enough space to construct an interior access road between the perimeter fence and perimeter drainage channels.	HWL and ELF	02/06/12	02/10/12	02/13/12	02/14/12	02/14/12	02/14/12	All parties concur.
2012-004	The existing HWL and ELF access road network needs to be expanded to improve access to groundwater monitoring wells and other features that require routine inspection and maintenance.	HWL and ELF	06/29/12	07/09/12	07/11/12	07/25/12	08/01/12	07/11/12	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2012-005	Plans for a prescribed burn over 127 acres of the ICS. The burn will be performed in the northeast area of ICS over the CAT and Shell covers.	ICS	12/19/11 03/01/12	03/06/12	03/06/12	03/08/12	03/14/12	03/08/12	All parties concur.
2012-006	The fence surrounding the HWL will be relocated to provide enough space to construct an interior access road between the eastern perimeter fence and perimeter drainage channel. Access to the four LCS/LDS manholes will to be improved for the safety of personnel working on the manholes.	HWL	04/16/12	05/23/12	05/29/12	05/31/12	05/31/12	05/31/12	All parties concur.
2012-007	The area around both ELF LRCH Buildings will be graded to drain and wingwalls will be constructed to divert surface water away from the buildings.	ELF	05/02/12 12/27/12	03/18/14	03/18/14	04/09/14	04/09/14	04/09/14	All parties concur.
2012-008	Frequent traffic to the top of the HWL and ELF by inspection and maintenance equipment has damaged the cap vegetation. Designated and surfaced paths to the upper portion of the landfills will be constructed to improve access to the terrace channels and upper portion of the caps, minimizing additional vegetation disturbance.	HWL and ELF	12/27/12	N/A	N/A	N/A	N/A	N/A	Suspended.
2013-001	Plans for a prescribed burn over	ICS and	01/29/13	02/13/13	02/13/13	02/13/13	02/13/13	02/13/13	All parties



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	ICS and Basin F. The burns will include the entirety of both AMAs (approximately 670 acres for ICS and 112 acres for Basin F).	Basin F							concur.
2013-002	Notification of first-time detection of MEK in HWL LDS4 during the January 2012 sampling event.	HWL	01/22/13 01/29/13	02/13/13	01/29/13	02/13/13	01/30/13	01/30/13	All parties concur.
2013-003	Notification of third-time detection of Endrin Aldehyde (ENDRNA) and NNDMEA in the HWL LDS sumps during the October 2012 and April 2012 sampling events, respectively.	HWL	01/22/13 01/29/13	02/13/13	01/29/13	02/13/13	01/30/13	01/30/13	All parties concur.
2013-004	Notification of third-time detection of Dicyclopentadiene (DCPD) in the ELF LBLDS2 during the July 2012 sampling event.	ELF	05/03/13	05/08/13	05/08/13	05/09/13	05/16/13	05/16/13	All parties concur.
2013-005	Notification that the Watch List Trigger Level for Chloroform was exceeded in ELF LBLDS2 wastewater samples during the second, third, and fourth quarterly sampling events of 2012.	ELF	05/16/13	05/16/13	05/16/13	05/16/13	05/16/13	05/16/13	All parties concur.
2013-006	Notification that the Watch List Trigger Level for Chloroform was exceeded in ELF WPLDS2 wastewater samples during the second quarterly sampling event of 2013.	ELF	05/28/13	05/28/13	05/28/13	07/18/13	07/18/13	07/18/13	All parties concur.
2013-007	Excavation of pull box on the north face of the ELF cap.	ELF		Army/Shell has decided not to pursue this action at this time.					Suspended



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2013-008	Notification of tipping bucket failure at Lysimeter 003.	ICS	09/19/13	10/24/13	10/24/13	11/20/13	11/20/13	11/20/13	All parties concur.
2013-009	Notification of non-routine action trigger exceedance for percolation at Lysimeter 003.	ICS	09/19/13 09/30/13 10/09/13	10/24/13	10/24/13	11/20/13	11/20/13	11/20/13	All parties concur.
2013-010	Notification of non-routine action trigger exceedance for percolation at Lysimeter 10.	ICS	10/04/13	11/07/13	11/07/13	11/20/13	11/20/13	11/20/13	All parties concur.
2014-001	Plans for a prescribed burn over ICS and Basin F. The burns will include the entirety of the ICS AMA (approximately 670 acres). Basin F burn is optional (112 acres).	ICS and Basin F	10/23/13 01/15/14	02/03/14	02/03/14	02/12/14	02/12/14	02/12/14	All parties concur.
2014-002	Notification that the Watch List Trigger Level for Endrin was exceeded in HWL LDS4 during the third quarterly sampling event of 2013.	HWL	01/29/14	02/05/14	02/05/14	02/12/14	02/12/14	02/12/14	All parties concur.
2014-003	Notification the PPDDT was detected in HWL LDS4 during the third quarterly sampling event of 2013.	HWL	03/27/14 05/30/14	06/02/14	06/02/14	07/29/14	07/29/14	07/29/14	All parties concur.
2014-004	Notification that chloroform exceeded the Watch List Trigger Level in LBLDS2 in the first quarter of 2013 and that TCLEE was detected in WPLDS2 above the MRL in the second quarter of 2014.	ELF	05/29/14 06/17/14	06/17/14	06/17/14	03/04/15	03/04/15	07/09/14	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2014-005	Notification that dieldrin exceeded the Watch List Trigger Level in HWL LDS2 in the first quarter of 2013.	HWL	05/29/14	06/17/14	06/17/14	07/29/14	07/29/14	07/09/14	All parties concur.
2014-006	Notification that dieldrin exceeded the prediction limit in well 25194 in the second quarter of 2014.	HWL	06/03/14 07/30/14 10/22/14 04/29/15	NRAP-2014-006 has been superseded by NRAP-2016-004.					Superseded
2014-008	Notification that percolation exceeded the Non-Routine Action Trigger Level in Lysimeters 001, 002, and 003 in June 2014.	ICS	06/09/14 07/09/14 10/28/15	05/02/16	05/04/16	06/16/16	05/26/16	05/26/16	All parties concur.
2014-009	Notification that tipping buckets failed in Lysimeters 001, 002, 003, and 003A.	ICS	07/10/14	07/28/14	07/28/14	07/29/14	07/29/14	07/29/14	All parties concur.
2014-010	Holes in the ICS cover soil	ICS	06/01/15 01/27/16						
2014-011	Notification that toluene was detected for the first time in HWL LDS2 during the July 2014 sampling event.	HWL	08/27/14 02/06/15	02/19/15	02/19/15	03/04/15	03/04/15	03/04/15	All parties concur.
2015-001	Notification that alpha-chlordane exceeded the Watch List Trigger Level in HWL LDS4 in the second quarter of 2015.	HWL	07/13/15	08/11/15	08/11/15	08/20/15	08/20/15	08/11/15	All parties concur.
2015-002	Notification that cyanide was detected for the first time in ELF sump LBLDS2 during the April/May 2015 sampling event.	ELF	07/24/15	08/11/15	08/11/15	08/20/15	08/20/15	08/11/15	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2015-003	Notification that tipping buckets failed in Lysimeters 001, 002, 003, and 003A.	ICS	07/16/15	08/11/15	08/11/15	08/11/15	08/11/15	08/11/15	All parties concur.
2015-004	Plans for a prescribed burn over ICS. The burn will include the entirety of the ICS AMA (approximately 670 acres).	ICS	09/15/15	09/17/15	09/17/15	10/15/15	10/13/15	10/13/15	All parties concur.
2015-005	Notification that aldrin exceeded the Watch List Trigger Level in HWL LDS4 in the third quarter of 2015.	HWL	07/13/15	09/17/15	09/17/15	10/15/15	10/13/15	10/13/15	All parties concur.
2015-006	Notification that PPDDT, PPDDE, and MEXCLR was detected for the first or third time in ELF LDS sumps during the July 2015 sampling event.	ELF	09/03/15 09/17/15	09/17/15	09/17/15	10/15/15	10/13/15	10/13/15	All parties concur.
2015-007	Modifications to the ICS Type II Inspection scheduled for the fall of 2015	ICS	09/10/15 10/28/15	05/02/16	05/03/16	05/24/16 (email)	05/03/16	05/03/16	All parties concur.
2016-001	Notification that MEXCLR was detected in HWL sump LDS4 during the October 2015 sampling event.	HWL	04/07/16	04/12/16	04/12/16	05/24/16 (email)	05/03/16	04/20/16	All parties concur.
2016-002	Plans for a prescribed burn over ICS. The burn will include the entirety of the ICS AMA (approximately 670 acres).	ICS	09/10/15 10/28/15 01/27/16	02/18/16	02/18/16	03/10/16	03/10/16	03/10/16	All parties concur.
2016-003	Notification that MEK and TCLEA were detected in ELF sump LBLDS2 during the October 2015	ELF	04/13/16	04/12/16	04/12/16	05/24/16 (email)	05/03/16	04/20/16	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
	sampling event.								
2016-004	Dieldrin exceeded the prediction limit in well 25194. Army/Shell will sample subsurface soil and stormwater runoff, and new well 25184 will be installed.	HWL	06/03/14 08/26/15	07/21/16	07/21/16	07/27/16	09/22/16	08/10/16	All parties concur.
2016-005	Notification that TDGCL was detected in the HWL LDS for the first time during the April 2016 sampling event. ACLDAN and PB were also detected above the watch list trigger level.	HWL	07/27/16 08/24/16	08/31/16	08/31/16	09/22/16	09/22/16	09/22/16	All parties concur.
2016-006	Notification that PPDDT was detected for the third time and CR was detected for the first time in the ELF LDS system during the April 2016 sampling event.	ELF	07/27/16 08/24/16	08/31/16	08/31/16	09/22/16	09/22/16	09/22/16	All parties concur.
2016-007	Notification that ENDRLN and DLDRN concentrations exceeded the watch list trigger level in LDS4 in the October 2016 sampling event.	HWL	01/04/17	01/04/17	01/04/17	01/19/17	01/19/17	01/19/17	All parties concur.
2017-001	Notification that ENDRLN concentrations exceeded the watch list trigger level in LDS4 in the January 2017 sampling event.	HWL	03/13/17	03/14/17	03/14/17	04/26/17	03/23/17 (email) 04/26/17 (wet ink)	03/21/17 (email) 04/26/17 (wet ink)	All parties concur.
2017-002	Notification that DLDRN concentrations exceeded the watch list trigger level in LDS4 in the July 2017 sampling event.	HWL	09/05/17	09/26/17	09/26/17	10/25/17	10/25/17	10/25/17	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2019-001	Plans for a prescribed burn over ICS. The burn will include the entirety of the ICS AMA (approximately 670 acres).	ICS	03/04/19	03/04/19	03/04/19	05/02/19	03/14/19	03/07/19	All parties concur.
2019-002	Plans for a prescribed burn over Basin F. The burn will include the entirety of the Basin F AMA (approximately 112 acres).	Basin F	03/04/19	03/04/19	03/04/19	05/02/19	03/14/19	03/07/19	All parties concur.
2019-003	Notification that HG was detected for the first time in the ELF sump LB LDS2 during the February 2018 sampling event.	ELF	03/07/19	03/11/19	03/11/19	05/02/19	04/16/19	04/16/19	All parties concur.
2019-004	Installation of monitoring well 36255 near the southeast corner of the Shell Trenches slurry wall.	SDT	07/25/19	08/14/19	08/14/19	08/14/19	08/14/19	08/14/19	All parties concur.
2020-001	Borehole drilling and installation of well 36258 in the west central Shell Disposal Trenches.	SDT	02/20/20	03/23/20	03/24/20	03/25/20	03/25/20	03/25/20	All parties concur.
2020-002	Notification that ICS erosion monument ER90 exceeded the non-routine trigger level of greater than 3.0 inches of soil thickness loss.	ICS	10/21/20	10/22/20	10/23/20	10/23/20	10/23/20	10/26/20	All parties concur.
2021-001	Intrusive activity at well 36305 to investigate power failure at the extraction well.	ICS	06/17/21	06/18/21	06/21/21	06/21/21	06/22/21	06/23/21	All parties concur.
2021-002	Intrusive activity to install new electrical conduit in cover soil between extraction well 36305 and the control panel.	ICS	07/28/21	07/30/21	08/02/21	08/02/21	08/04/21	08/02/21	All parties concur.



OPERATIONS & MAINTENANCE CONTRACTOR FOR ROCKY MOUNTAIN ARSENAL

NON-ROUTINE ACTION PLAN LOG

Projects: Long-Term Maintenance of the HWL, ELF, ICS, and Basin F RCRA-Equivalent Cover

WBS: 4.01.01, 4.01.02, 4.01.03, and 4.01.04

Number	Description of Condition and Non-Routine Action	Cover/Cap Affected	Consultation Date(s)	Concurrence Dates					Status
				Covers Manager	Army PM	EPA	CDPHE	TCHD	
2021-003	Plans for a prescribed burn over ICS. The burn will include the entirety of the ICS AMA (approximately 670 acres).	ICS	09/30/21	10/04/21	10/04/21	10/04/21	10/05/21	10/04/21	All parties concur.
2021-004	Plans for a prescribed burn over Basin F. The burn will include the entirety of the Basin F AMA (approximately 112 acres).	Basin F	09/30/21	10/04/21	10/04/21	10/04/21	10/05/21	10/04/21	All parties concur.
2021-005	Plans to oversee approximately 100 acres in the southwest corner of the ICS after sparse growth in 2021.	ICS	05/13/21 06/02/21 06/03/21 07/28/21 07/29/21 10/04/21	10/07/21	10/07/21	10/12/21	10/12/21	10/12/21	All parties concur.
2022-001	Notification that the copper concentration exceeded the watch list trigger level in LDS1 in the March 2021 sampling event.	HWL	01/17/22 01/26/22	01/26/22	01/27/22	01/31/22	02/02/22	02/03/22	All parties concur.

This page intentionally left blank.