

**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-1

Photo No. 1  
(11-August-2015)

Description:

View looking east across the western portion of the 801 Drum Burial Site from River Road. Note monitoring well AP-6631.



Photo No. 2  
(11-August-2015)

Description:

View looking north across the western portion of the 801 Drum Burial Site and River Road.



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-1

Photo No. 3  
(11-August-2015)

Description:  
View looking south across the western portion of the 801 Drum Burial Site and River Road.



Photo No. 4  
(11-August-2015)

Description:  
View looking east at the Chena River from the northern portion of the 801 Drum Burial Site. Note monitoring well AP-6065 associated with OU-3 Valve Pit A.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-2

Photo No. 5  
(11-August-2015)

Description:

View looking east  
across DRMO  
Salvage Yards 4  
and 5.



Photo No. 6  
(11-August-2015)

Description:

Example of a  
“frost jacked”  
probe at DRMO 5  
(Probe D, not  
included in the  
2014 sampling  
event).



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-2

Photo No. 7  
(11-August-2015)

Description:

View looking  
north across  
DRMO Salvage  
Yard 1.



Photo No. 8  
(11-August-2015)

Description:

View looking east  
across DRMO  
Salvage Yards 1  
and 2.



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-2

Photo No. 9  
(11-August-2015)

Description:

View looking east  
across DRMO  
Salvage Yard 3.



Photo No. 10  
(11-August-2015)

Description:

View of typical  
fencing and a sign  
at the OU-2  
DRMO Salvage  
Yard.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-2

Photo No. 11  
(11-August-2015)

Description:

View looking west at fencing at the Building 1168 site along Trainor Gate Road. Note monitoring well AP-6809.



Photo No. 12  
(11-August-2015)

Description:

View looking northeast across the Building 1168 site.



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-2

Photo No. 13  
(11-August-2015)

Description:

View of locked and labeled monitoring well AP-6809.



Photo No. 14  
(11-August-2015)

Description:

View of monitoring well AP-7143 with damaged bollard (not sampled in 2014).





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3

Photo No. 15  
(11-August-2015)

Description:

View looking southeast at Valve Pit A. Note VPA-MP2 and VPA-MP5.



Photo No. 16  
(11-August-2015)

Description:

View looking north at Valve Pit B.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3

Photo No. 17  
(11-August-2015)

Description:

View looking west at Valve Pit C. Note VPC-MP2.



Photo No. 18  
(11-August-2015)

Description:

View of underground fuel piping at the ROLF.



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3

Photo No. 19  
(11-August-2015)

Description:

View of a bird habitat under construction at the ROLF.



Photo No. 20  
(11-August-2015)

Description:

View of typical vegetation and concrete construction materials staged on ROLF.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3

Photo No. 21  
(11-August-2015)

Description:

Typical view of  
vegetation at the  
ROLF.



Photo No. 22  
(11-August-2015)

Description:

View of the  
ROLF  
informational  
sign.



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3

Photo No. 23  
(11-August-2015)

Description:

View looking east across a training area just south of the Milepost 3.0 excavation. Note monitoring well AP-8711.



Photo No. 24  
(11-August-2015)

Description:

Example of a “frost jacked” monitoring well at Milepost 2.7.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3/OU-5 (Birch Hill Tank Farm)

Photo No. 25  
(11-August-2015)

Description:

View looking north at a former truck fill stand on the southern portion of the Birch Hill Tank Farm.



Photo No. 26  
(11-August-2015)

Description:

View of locked and labeled monitoring well AP-10229MW (GWP-121).



**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3/OU-5 (Birch Hill Tank Farm)

Photo No. 27  
(11-August-2015)

Description:

View of a former  
AST location in  
the southern Birch  
Hill Tank Farm.



Photo No. 28  
(11-August-2015)

Description:

View of a  
concrete pad and  
underground fuel  
lines in the  
southern Birch  
Hill Tank Farm.





**PHOTOGRAPHIC RECORD  
Fort Wainwright**

OU-3/OU-5 (Birch Hill Tank Farm)

Photo No. 29  
(11-August-2015)

Description:

Typical monitoring wells on the southern Birch Hill Tank Farm. Note monitoring wells AP-5782, AP-5783, and AP-7952.



Photo No. 30  
(11-August-2015)

Description:

View of typical underground fuel piping located on the southern Birch Hill Tank Farm.

