

BSEN

GRID # 11-12

FT STEWART, GA

TEAM LEADER

MeekDATE 6/15/11

	MEC	
	MD	32 ¹⁵
	TARGET DEBRIS	18 ¹⁵
	# DIGS	94
	BH	1 (done)

SW

NOTES

① trash pit pulled wire - still Hot
 ② Tree needs moved Hot - EXCAVATED

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/15/11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER

GRID # 12-12

FT STEWART, GA

DATE 6/15/11

[illegible]

NOTES

① 1ea RKT Excavated

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

[Signature]

BSEN GRID # 13-12
TEAM LEADER week

BSEN GRID # 13-12
TEAM LEADER week

BSEN GRID # 13-12 FT STEWART, GA
TEAM LEADER mkk DATE 6/15/11

BSEN GRID # 13-12 FT STEWART, GA
TEAM LEADER mkk DATE 6/15/11

[illegible]

5W

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

DATE _____

PASS/FAIL

DATE _____

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 8-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										8 #	
										# DIGS	
										45	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 10-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

	MEC	
	MD	
	1 ROCKET	
	TARGET DEBRIS	
	13 [#]	
	# DIGS	
	60	
	✓ 1 DIG	ROCKET 3' DEEP
	⊙	DONE MS

NOTES

① WIRE CONTINUE FROM 10-12

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 July 11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

BSEN

GRID # 11-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										38#	
										# DIGS	
										60	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 12-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										21	
										# DIGS	
										50	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-16-11</u>	PASS/FAIL	DATE <u>22 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>Downey Burton</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 13-13

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										10	
										# DIGS	
										40	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

BSEN

GRID # 15-9


FT STEWART, GA

TEAM LEADER

Top

DATE _____

1345 - 1400

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-10-11

PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

TEAM LEADER

GRID #


169

FT STEWART, GA

DATE

6-10-11

1345 - 1600



NOTES

Boards

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-10-11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Loge</u>	GRID # <u>17-11</u>	FT STEWART, GA DATE <u>6-6-11</u>
---------------------------------	---------------------	--------------------------------------

12-30 - 12-55

	MEC	φ	
	MD	4	
	TARGET DEBRIS	φ	
	# DIGS	21	
	B.H.	1	RKT 3' Deep

NOTES

(1) RCKET. (needs excavating)	

TEAM LEADER	QC	QA
PASS/FAIL DATE <u>6-6-11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE _____ SIGNATURE <u>[Signature]</u>

5-1
5-1
11-2

BSEN TEAM LEADER <u>Rogers</u>	GRID # <u>19-11</u>	FT STEWART, GA DATE <u>6-6-11</u>
-----------------------------------	---------------------	--------------------------------------

0930. - 1030

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B H.	

NOTES

1. broken up bucket parts (need excavating)

TEAM LEADER	QC	QA
PASS/FAIL _____ DATE <u>6-6-11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL _____ DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL _____ DATE _____ SIGNATURE <u>[Signature]</u>

7 - 1-4
 9 - 2-1
 12 - 2

BSEN

GRID # 17-12

FT STEWART, GA

TEAM LEADER W. J. [Signature]

DATE 6-3-11

~~340~~ AM 1450 - 1430

	MEC	
	MD	> 11b
	TARGET DEBRIS	
	# DIGS	3

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-3-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

TEAM LEADER

GRID # 1812

FT STEWART, GA

DATE 2.3.11

$$1325 - 15 \cdot 15$$
[illegible]

NOTES

(1) Rocket back landing, FRAB

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.3.1

PASS/FAIL

DATE 22 July

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

PK Son

SIGNATURE 

BSEN

GRID # 20-15

FT STEWART, GA

TEAM LEADER Thomas BraggDATE 6-20-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

Silt Fence has Rebar holding it up. New Fence is 10' from this grid. No significant finds.
 22 Jun 11 - Can only clear to within 3 feet of fence and rebar.

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 21-15

FT STEWART, GA

TEAM LEADER Thomas BagleyDATE 6-20-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

New Fence RUNS Through this. NO finds

22 Jun 11 - Can only clear to within 3 feet of fence & rebar.

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE


SIGNATURE

BSEN

GRID # 12-9

FT STEWART, GA

TEAM LEADER MeellDATE 6/10/11

	MEC	
	MD	1
	TARGET DEBRIS	
	# DIGS	1
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/10/11


PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 8-10

FT STEWART, GA

TEAM LEADER

MakDATE 6/13/11

										MEC	
										<u>Ø</u>	
										MD	
										<u>16</u>	
										TARGET DEBRIS	
										<u>Ø</u>	
										# DIGS	
										<u>31</u>	
									<u>1</u>	<u>BH</u>	<u>RKT 3' Deep</u>
								<u>Ø</u>	<u>RKT 3'</u>	<u>Ø</u>	<u>DOVE ARS</u>

NOTES

1 - 1 MK2 RKT22 Jun 11 - Rocket was not marked!22 Jun 11 - Excavator Team dug out rocket.

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/13/11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

Mak

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 9-10


FT STEWART, GA

TEAM LEADER

Meek

DATE

6/13/11

										MEC	
											
										MD	
											
										TARGET DEBRIS	
											
										# DIGS	
										26	
										BH	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/13/11~~PASS/FAIL~~

DATE


22 Jun 11~~PASS/FAIL~~

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 10-10

FT STEWART, GA

TEAM LEADER MeekDATE 6/13/11

										MEC	
										MD	
										12 ¹⁶⁵	
										TARGET DEBRIS	
										# DIGS	
										17	

Handwritten notes on grid: An arrow points to a circle containing an 'X' with 'RKT 3'' written below it. Another circle contains the number '1'.

SW

NOTES

① Wire pit

22 Jun 11 - Fail - piece of sheet metal found buried.

" " " REMOVED RKT 3' DEEP ~~AS~~" " " BROKEN WIRE SAME AREA ~~AS~~" " " REMAGED GRID ~~AS~~

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/13/11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

6-22-11 * Re-Inspection 0935 Hours on 22 Jun 11.
 Passed QC-QA.

BSEN

GRID # 11-10

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/13/11

										MEC	
											
										MD	
										<u>8</u> ^{lbs}	
										TARGET DEBRIS	
											
										# DIGS	
										<u>21</u>	
										B.H.	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/13/11

PASS/FAIL


DATE

22 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



TEAM LEADER

GRID # 7-14

DATE 6/20/11

[illegible]

3W

NOTES

① IRCT needs excavated $\rightarrow$ Excavated
② IRCT

TEAM LEADER

QC

QA

PASS/~~FAIL~~

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN TEAM LEADER <u>Neel</u>	GRID # <u>8-14</u>	FT STEWART, GA DATE <u>6/20/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC	
											0	
											MD	
											12 ¹⁵	
											TARGET DEBRIS	
7 #												
# DIGS												
30												
0												

NOTES

TEAM LEADER		QC		QA	
PASS/FAIL	DATE <u>6/20/11</u>	PASS/FAIL	DATE <u>22 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>Neel</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

TEAM LEADER

GRID # 9-14

FT STEWART, GA

DATE 6/20/11

										MEC	
											
									• ①	MD	
						②				35 ¹⁶	
										TARGET DEBRIS	
										17 #	
										# DIGS	
										45	
			④								
						③				4 DIGS	

NOTES

1	ROCKET IN GROUND	EXCAVATED
2	11 11	
3	11 11	
4	11 11	

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE _____

(PASS/FAIL

DATE:

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER Downey Burton

GRID # 10-14

DATE 6-17-11

DATE 6-17-11

[illegible]

NOTES

- ① ROCKET IN GROUND
- ② ROCKET IN GROUND
- 3 WIRE ACROSS GRID

TEAM LEADER

QC

QA

DATE 6-17-11

DATE 22 Jun 11

PASS/FAIL

DATE _____

Downey Burton

DATE 22 July


DATE _____

SIGNATURE

GRID # 11-14

DATE 6-17-11

TEAM LEADER Downey BURTON

										MEC	
		(2) RKT 3'								MD	
										TARGET DEBRIS	
										7#	
										# DIGS	
										30	
											RKT 3' Deep
				(1)						1	DONE AS

NOTES

① WIRE

② ROCKET IN GROUND

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-17-11

(PASS)/FAIL

DATE 22 Jun

PASS/FAIL

DATE _____

SIGNATURE

Dorothy Burton

SIGNATURE

[Signature]

SIGNATURE

DATE

BSEN

GRID # 12-14

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-17-11

										MEC	
										MD	
										TARGET DEBRIS	
										12 ^{II}	
										# DIGS	
										30	
										0	

NOTES

SURVEY POINT (REBAR)

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-17-11

PASS/FAIL

DATE 22 July 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN GRID # 13-14 FT STEWART, GA
TEAM LEADER Downey Burton DATE 6-17-11

BSEN GRID # 13-14 FT STEWART, GA
TEAM LEADER Downey Burton DATE 6-17-11

BSEN GRID # 13-14 FT STEWART, GA
TEAM LEADER Downey Burton DATE 6-17-11

BSEN GRID # 13-14 FT STEWART, GA
TEAM LEADER Downey Burton DATE 6-17-11

BSEN GRID # 13-14 FT STEWART, GA
TEAM LEADER Downey Burton DATE 6-17-11

[illegible]

NOTES

① ROCKET IN GROUND

TEAM LEADER

QC

QA

~~PASS~~/FAIL

DATE 6-17-11

PASS/FAIL

DATE 22 June 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

James A. Jones

SIGNATURE

E


BSEN

GRID # 7-15

FT STEWART, GA

TEAM LEADER MeekDATE 6/20/11

NE

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/20/11


PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u>Mack</u>	GRID # <u>8-15</u>	FT STEWART, GA DATE <u>6/20/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC	
											<u>Ø</u>	
											MD	
											<u>6</u> ¹⁵⁵	
											TARGET DEBRIS	
											<u>3</u> ¹⁵	
											# DIGS	
											<u>24</u>	

JW

NOTES

TEAM LEADER

QC

QA

PASS/FAIL <u>DATE</u> <u>6/20/11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL <u>DATE</u> <u>22 July 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL <u>DATE</u> _____ SIGNATURE <u>[Signature]</u>
--	---	---

9-15

BSEN

GRID # 9-15

FT STEWART, GA

TEAM LEADER meekDATE 6/20/11

										MEC	
											
										MD	
										<u>8</u> ¹⁵	
										TARGET DEBRIS	
										<u>1</u> ¹⁵	
										# DIGS	
										<u>18</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/20/11


PASS/FAIL

DATE 22 July 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 10-15

FT STEWART, GA

TEAM LEADER NeekDATE 6/20/11

										MEC	
										MD	
										<u>22^{1b}</u>	
										TARGET DEBRIS	
										<u>13^{1b}</u>	
										# DIGS	
										<u>38</u>	
										<u>BH</u>	
										<u>2</u>	<u>Excavated</u>

NOTES

will be running thru grid marked w/ pink flags
 200 Rvts - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

PASS/FAIL

DATE

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN GRID # 11-15
TEAM LEADER Meek

BSEN GRID # 11-15
TEAM LEADER Meek

BSEN GRID # 11-15 FT STEWART, GA
TEAM LEADER Meek DATE 6/20/11

BSEN GRID # 11-15 FT STEWART, GA
TEAM LEADER Meek DATE 6/20/11

A hand-drawn map on a grid. A wavy line starts from the bottom left, goes up, then right, then up again. A circle labeled 'WIRE' is in the middle right. Another circle labeled 'WIRE' is at the bottom right. There are several small circles with crosses inside, and a larger circle with a cross inside. The word 'WIRE' is written vertically on the left side of the path.	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B.H.	
3.	EXCAVATED	

NOTES

NOTES

3rd Roellet Excavated
Wire Running thru Grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE 1/22/11

(PASS/FAIL)

DATE 22 July 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE




SIGNATURE

BSEN TEAM LEADER <u>Mark</u>	GRID # <u>12-15</u>	FT STEWART, GA DATE <u>6/21/11</u>
---------------------------------	---------------------	---------------------------------------

											MEC 	
											MD <u>24</u> ¹⁶	
											TARGET DEBRIS <u>12</u> ¹⁶	
											# DIGS <u>41</u>	
											<u>BH</u> <u>2</u>	<u>EXCAVATED!</u>

NOTES

<u>2nd BH</u>	<u>EXCAVATED</u> 	

TEAM LEADER	QC	QA
PASS/FAIL <u>DATE</u> <u>6/21/11</u> SIGNATURE 	PASS/FAIL <u>DATE</u> <u>22 Jun 11</u> SIGNATURE 	PASS/FAIL <u>DATE</u> <u> </u> SIGNATURE 

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>13-15</u>	FT STEWART, GA DATE <u>6/28/11</u>
---------------------------------	---------------------	---------------------------------------

											MEC	
												
											MD	
											<u>15</u> ^{1b}	
											TARGET DEBRIS	
											<u>2</u> ^{1b}	
											# DIGS	
											<u>36</u>	
											<u>BH</u>	
											<u>1</u>	EXCAVATED!

NOTES

1 RKT EXCAVATED 

TEAM LEADER PASS/FAIL <u> </u> DATE <u>6/28/11</u> SIGNATURE <u>DMell</u>	QC PASS/FAIL <u> </u> DATE <u>22 July 11</u> SIGNATURE <u>[Signature]</u>	QA PASS/FAIL <u> </u> DATE <u> </u> SIGNATURE <u>[Signature]</u>
--	--	--

BSEN TEAM LEADER <u>Mell</u>	GRID # <u>8-16</u>	FT STEWART, GA DATE <u>6/21/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC	
											<u>Ø</u>	
											MD	
											<u>3</u>	
											TARGET DEBRIS	
											<u>1</u>	
											# DIGS	
											<u>16</u>	
											<u>B.H</u>	
											<u>Ø</u>	

NOTES

TEAM LEADER PASS/FAIL <u> </u> DATE <u>6/21/11</u> SIGNATURE <u>Mell</u>	QC PASS/FAIL <u>Ø</u> DATE <u>22 June 11</u> SIGNATURE <u>[Signature]</u>	QA PASS/FAIL <u> </u> DATE <u> </u> SIGNATURE <u>[Signature]</u>
---	---	--

9-16

BSEN

GRID #

9-16

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/21/11

										MEC	
										MD	
										716	
										TARGET DEBRIS	
										10 ¹⁶ -5	
										# DIGS	
										42	
										BH	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL

DATE

12 June 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE



SIGNATURE

BSEN

GRID # 10-16

FT STEWART, GA

TEAM LEADER MeerDATE 6/21/11

										MEC	
											
										MD	
										<u>14</u> ¹⁵⁵	
										TARGET DEBRIS	
										<u>4</u> ¹⁵	
										# DIGS	
										<u>41</u>	
										<u>BH</u>	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/21/11~~PASS/FAIL~~

DATE


22 Jun 11~~PASS/FAIL~~

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN GRID # 11-16
TEAM LEADER Mee/C

TEAM LEADER Meel

DATE 6/21/11

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/2/11

PASS/FAIL

DATE 22/11/20

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

 SIGNATURE

BSEN

GRID # 12-16

FT STEWART, GA

TEAM LEADER MarkDATE 6/21/11

				2						MEC	
				(X)							
										MD	
										TARGET DEBRIS	
										# DIGS	
										BH	
										2	Excavated

SW

NOTES

①, ② RKT - Excavated
 Wire marked w/ pink flag left PC sticking out
 Wire running thru Grid SE-NE side of Grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL

DATE

22 July 11

PASS/FAIL

DATE

SIGNATURE

Mark

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 13-16

FT STEWART, GA

TEAM LEADER MeekDATE 6/21/11

										MEC	
											
										MD	
										<u>12/15</u>	
										TARGET DEBRIS	
											
										# DIGS	
										<u>28</u>	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/21/11


PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 14-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/10/11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B.H.	

RKT 3'
DONE AS

NOTES

① (X) Rocket IN
~~② (X) Rocket~~

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/10/11

PASS/FAIL

DATE

22 Jan 11

PASS/FAIL

DATE

SIGNATURE

Meek

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN	GRID # <u>15-17</u>	FT STEWART, GA
TEAM LEADER <u>Meek</u>		DATE <u>6/9/11</u>

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/9/11</u>	PASS/FAIL	DATE <u>22 June/11</u>	PASS/FAIL	DATE _____
SIGNATURE		SIGNATURE		SIGNATURE	

BSEN

GRID # 10-10

FT STEWART, GA

TEAM LEADER MeekDATE 6/13/11

										MEC	
										MD	
										12 ¹⁶⁵	
										TARGET DEBRIS	
										# DIGS	
										17	

Handwritten notes on grid: An arrow points to a circle containing an 'X' with 'RKT 3'' written below it. Another circle contains the number '1'.

SW

NOTES

① Wire pit
22 Jun 11 - Fail - piece of sheet metal found buried.
" " " REMOVED RKT 3' DEEP <i>AS</i>
" " " BROKEN WIRE SAME AREA <i>AS</i>
" " " REMAGED GRID <i>AS</i>

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/13/11</u>	PASS/FAIL	DATE <u>22 Jun 11</u>	PASS/FAIL	DATE
SIGNATURE		SIGNATURE		SIGNATURE	

Admitt 6-22-11 * Re-Inspection 0935 Hours on 22 Jun 11.
 Passed QC-QA.

BSEN

GRID # 10-11

FT STEWART, GA

TEAM LEADER MeekDATE 6/14/11

										MEC	
										MD	
										<u>5 lbs</u>	
										TARGET DEBRIS	
										<u>12^{lb}</u>	
										# DIGS	
										<u>39</u>	
										<u>B.H</u>	

NOTES

① Wire going across Grid (braided cable running thru grid)

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/14/11

PASS/FAIL

DATE

22 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-12

FT STEWART, GA

TEAM LEADER mpkDATE 6/15/11

										MEC	
										MD	
										23 ^{lbs}	
										TARGET DEBRIS	
										88 ^{lbs}	
										# DIGS	
										150	
										B.H.	
										Z.	done

SW

NOTES

2ea PKts - Excavated!!
braided wire Running thru Aid

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/15/11

PASS/FAIL

DATE

22 June 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

	MEC	
	MD	
	1 ROCKET	
	TARGET DEBRIS	
	13 [#]	
	# DIGS	
	60	
	✓ 1 DIG	ROCKET 3' DEEP
	⊙	DONE AS

NOTES

① WIRE CONTINUE FROM 10-12

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 July 11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

TEAM LEADER Downey Burton

GRID # 10-14

DATE 6-17-11

DATE 6-17-11

	(2)	RKT 3'	(1)	RKT 3'	MEC	
					MD	
					TARGET DEBRIS	
					10#	
					# DIGS	
					40	
					2 DIGS	RKT x 2 3' DEEP
						DONE <u>AKS</u>

NOTES

- ① ROCKET IN GROUND
- ② ROCKET IN GROUND
- 3 WIRE ACROSS GRID

TEAM LEADER

QC

QA

DATE 6-17-11

DATE 22 July 11

DATE _____

Downey Burton

DATE 20 May 11


DATE _____

BSEN

GRID # 10-15

FT STEWART, GA

TEAM LEADER WeekDATE 6/20/11

										MEC	
										MD	
										<u>22^{1b}</u>	
										TARGET DEBRIS	
										<u>13^{1b}</u>	
										# DIGS	
										<u>38</u>	
										<u>BH</u>	
										<u>2</u>	<u>Excavated</u>

NOTES

will be running thru grid marked w/ pink flags
 2nd RVts - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

PASS/FAIL

DATE

PASS/FAIL

DATE

SIGNATURE

SIGNATURE



SIGNATURE

BSEN

GRID # 10-16

FT STEWART, GA

TEAM LEADER MeerDATE 6/21/11

										MEC	
											
										MD	
										<u>14</u> ¹⁵⁵	
										TARGET DEBRIS	
										<u>415</u>	
										# DIGS	
										<u>41</u>	
										<u>BH</u>	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/21/11~~PASS/FAIL~~

DATE


22 Jun 11~~PASS/FAIL~~

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 11-10

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/13/11

										MEC	
											
										MD	
										<u>8</u> ^{lbs}	
										TARGET DEBRIS	
											
										# DIGS	
										<u>21</u>	
										B.H.	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/13/11

PASS/FAIL


DATE

22 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u> Mek </u>	GRID # <u> 11-11 </u>	FT STEWART, GA DATE <u> 6/14/11 </u>
--	---------------------------------	---

										MEC	
											
										MD	
										<u>6</u> lbs	
										TARGET DEBRIS	
										<u>3</u> lbs	
										# DIGS	
										36	
										B. H.	
											

NOTES

TEAM LEADER	QC	QA
PASS/FAIL <u> PASS </u> DATE <u> 6/14/11 </u> SIGNATURE <u> [Signature] </u>	PASS/FAIL <u> PASS </u> DATE <u> 22 Jun 11 </u> SIGNATURE <u> [Signature] </u>	PASS/FAIL <u> PASS </u> DATE <u> ____ </u> SIGNATURE <u> [Signature] </u>

BSEN

GRID # 11-12

FT STEWART, GA

TEAM LEADER

MeekDATE 6/15/11

	MEC	
	MD	32 ¹⁵
	TARGET DEBRIS	18 ¹⁵
	# DIGS	94
	BH	1 (done)

SW

NOTES

① trash pit pulled wire - still Hot
 ② Tree needs moved Hot - EXCAVATED

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/15/11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 11-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										38#	
										# DIGS	
										60	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

GRID # 11-14

DATE 6-17-11

TEAM LEADER Downey BURTON

[illegible]

NOTES

- ① WIRE
- ② ROCKET IN GROUND

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-17-11

PASS/FAIL

DATE 22 Jun/17

PASS/FAIL

DATE _____

SIGNATURE

Deemig Burton

SIGNATURE

[Signature]

SIGNATURE

DATE

BSEN GRID # 11-15
TEAM LEADER Meek

TEAM LEADER Meek

GRID # 11-15

FT STEWART, GA

DATE 6/20/11

A hand-drawn map on a grid. A wavy line starts from the bottom left, goes up, then right, then up again. A circle labeled 'WIRE' is in the middle right. Another circle labeled 'WIRE' is at the bottom right. There are several small circles with crosses inside, and a larger circle with a cross inside. The word 'WIRE' is written vertically on the left side of the grid.	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B.H.	
3	EXCAVATED	

NOTES

NOTES

3rd Roellet Excavated
Wine Running thru Grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

(PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN GRID # 11-16
TEAM LEADER Mee/C

BSEN GRID # 11-16
TEAM LEADER Mee/C

BSEN GRID # 11-16 FT STEWART, GA
TEAM LEADER Meele DATE 6/21/11

BSEN GRID # 11-16 FT STEWART, GA
TEAM LEADER Meele DATE 6/21/11

[illegible]

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/21/11

PASS/FAIL

DATE 22 June

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN TEAM LEADER <u>meek</u>	GRID # <u>12-10</u>	FT STEWART, GA DATE <u>6/13/11</u>
---------------------------------	---------------------	---------------------------------------




											MEC 	
											MD 10 lbs	
											TARGET DEBRIS 	
											# DIGS 15	
											B. H 	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL DATE <u>6/13/11</u> SIGNATURE 	PASS/FAIL DATE <u>22 July 11</u> SIGNATURE 	PASS/FAIL DATE _____ SIGNATURE 
---	---	--

FT STEWART, GA

DATE 6/14/11

	MEC		
	MD	10 ^{lbs}	
	TARGET DEBRIS	4 ^{lbs}	
	# DIGS	34	
		<u>B.H.</u> Z	RKT 3' Deep DONE RB

NOTES

1 & 2 Rocket Needs Excavated

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE _____

6/14/11

PASS/FAIL

DATE _____

22 July

PASS/FAIL

DATE _____

SIGNATURE

Small

SIGNATURE

DATE 22 Jan

SIGNATURE

DATE

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>12-12</u>	FT STEWART, GA DATE <u>6/15/11</u>
---------------------------------	---------------------	---------------------------------------

											MEC	
											Ø	
											MD	
											9 ^{lbs}	
											TARGET DEBRIS	
											2 ^{lbs}	
											# DIGS	
											63	
											B. H.	
											Ø	

NOTES

① 1ea RKT Excavated

TEAM LEADER	QC	QA
PASS/FAIL DATE <u>6/15/11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE _____ SIGNATURE <u>[Signature]</u>

BSEN

GRID # 12-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										21	
										# DIGS	
										50	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-16-11</u>	PASS/FAIL	DATE <u>22 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>Downey Burton</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 12-14

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-17-11

										MEC	
										MD	
										TARGET DEBRIS	
										12 II	
										# DIGS	
										30	
										0	

NOTES

SURVEY POINT (REBAR)

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-17-11

PASS/FAIL

DATE 22 July 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE


[Signature]

BSEN TEAM LEADER <u>Mark</u>	GRID # <u>12-15</u>	FT STEWART, GA DATE <u>6/21/11</u>
---------------------------------	---------------------	---------------------------------------

											MEC 	
											MD <u>24</u> ¹⁶	
											TARGET DEBRIS <u>12</u> ¹⁶	
											# DIGS <u>41</u>	
											<u>BH</u> <u>2</u>	<u>EXCAVATED!</u>

NOTES

<u>2nd BH</u>	<u>EXCAVATED</u> 	

TEAM LEADER	QC	QA
PASS/FAIL <u>DATE</u> <u>6/21/11</u> SIGNATURE 	PASS/FAIL <u>DATE</u> <u>22 Jun 11</u> SIGNATURE 	PASS/FAIL <u>DATE</u> <u> </u> SIGNATURE 

BSEN

GRID # 12-16

FT STEWART, GA

TEAM LEADER MarkDATE 6/21/11

				2						MEC	
				(X)							
										MD	
										TARGET DEBRIS	
										# DIGS	
										BH	
										2	Excavated

SW

NOTES

①, ② RKT - Excavated
 Wire marked w/ pink flag left PC sticking out
 Wire running thru Grid SE-NE side of Grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL

DATE

22 July 11

PASS/FAIL

DATE

SIGNATURE

Mark

SIGNATURE

[Signature]

SIGNATURE


[Signature]

BSEN

GRID # 12-9

FT STEWART, GA

TEAM LEADER MeellDATE 6/10/11

	MEC	
	MD	<u>1</u>
	TARGET DEBRIS	
	# DIGS	<u>1</u>
		

SW

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/10/11


PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # ~~13-11~~ 13-11 FT STEWART, GA

TEAM LEADER

DATE

										MEC	
										MD	
										13 ^{lbs}	
										TARGET DEBRIS	
										5 ^{Lbs}	
										# DIGS	
										43	
										B.H.	
											RICT 3'-4' deep DONE

SW

NOTES

2 Rocket needs Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

PASS/FAIL

DATE

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN TEAM LEADER <u> week </u>	GRID # <u>13-12</u>	FT STEWART, GA DATE <u>6/15/11</u>
---	---------------------	---------------------------------------

	MEC	Ø
	MD	
	12 ^{lbs}	
	TARGET DEBRIS	
	3 ^{lbs}	
	# DIGS	
	38	
	B. H.	
	Ø	

SW

NOTES

TEAM LEADER	QC	QA
PASS/FAIL _____ DATE <u>6/15/11</u> SIGNATURE <u>Small</u>	PASS/FAIL _____ DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL _____ DATE _____ SIGNATURE <u>[Signature]</u>

BSEN

GRID # 13-13

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										10	
										# DIGS	
										40	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

Downey Burton

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

BSEN

GRID # 13-14

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-17-11

										MEC	
										MD	
										TARGET DEBRIS	
										23 #	
										# DIGS	
										40	
										① DIG	RKT 3' Deep Done <i>AB</i>

NOTES

① ROCKET IN GROUND

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-17-11

SIGNATURE

Downey Burton

PASS/FAIL

DATE 22 June 11

SIGNATURE

[Signature]

PASS/FAIL

DATE _____

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>13-15</u>	FT STEWART, GA DATE <u>6/28/11</u>
---------------------------------	---------------------	---------------------------------------

	MEC	
	MD	
	<u>15^{lb}</u>	
	TARGET DEBRIS	
	<u>2^{lb}</u>	
	# DIGS	
	<u>36</u>	
	<u>BH</u>	
	<u>1</u>	EXCAVATED!

NOTES

<u>1 RKT EXCAVATED</u>

TEAM LEADER		QC		QA	
PASS/FAIL	DATE <u>6/28/11</u>	PASS/FAIL	DATE <u>22 July 11</u>	PASS/FAIL	DATE
SIGNATURE <u>D. Meek</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 13-16

FT STEWART, GA

TEAM LEADER MeekDATE 6/21/11

										MEC	
											
										MD	
										<u>12/15</u>	
										TARGET DEBRIS	
											
										# DIGS	
										<u>28</u>	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/21/11


PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



TEAM LEADER

GRID # 14-16

DATE 6/21/11

52

2nd RV's — Excavated

QC

QA

PASS/~~FAIL~~

DATE _____

(PASS/FAIL)

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 14-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/10/11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B.H.	

RKT 3'
DONE AS

NOTES

① (X) Rocket IN
~~② Rocket~~

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/10/11

PASS/FAIL

DATE

22 Jan 11

PASS/FAIL

DATE

SIGNATURE

Meek

SIGNATURE

John

SIGNATURE

John

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>15-17</u>	FT STEWART, GA DATE <u>6/9/11</u>
---------------------------------	---------------------	--------------------------------------

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL <u> </u> DATE <u>6/9/11</u>	PASS/FAIL <u> </u> DATE <u>22 June 11</u>	PASS/FAIL <u> </u> DATE <u> </u>
SIGNATURE	SIGNATURE	SIGNATURE

BSEN

GRID # 15-9


FT STEWART, GA

TEAM LEADER

Top

DATE _____

1345 - 1400

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-10-11

PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

TEAM LEADER

GRID #


169

FT STEWART, GA

DATE

6-10-11

1345 - 1600



NOTES

Fence

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-10-11

PASS/FAIL

DATE

22 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Loge</u>	GRID # <u>17-11</u>	FT STEWART, GA DATE <u>6-6-11</u>
---------------------------------	---------------------	--------------------------------------

12-30 - 12-55

	MEC	φ	
	MD	4	
	TARGET DEBRIS	φ	
	# DIGS	21	
	B.H.	1	RKT 3' DEEP

NOTES

(1) RCKET. (needs excavating)	

TEAM LEADER	QC	QA
PASS/FAIL DATE <u>6-6-11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE _____ SIGNATURE <u>[Signature]</u>

5-1
5-1
11-2

BSEN

GRID # 17-12

FT STEWART, GA

TEAM LEADER McGraw

DATE 6-3-11

~~1340~~ AM 1450 - 1430

	MEC	
	MD	> 11b
	TARGET DEBRIS	
	# DIGS	3

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-3-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

McGraw

SIGNATURE

[Signature]

SIGNATURE

[Signature]

TEAM LEADER

GRID # 1812

FT STEWART, GA

DATE 2.3.11

$$1325 - 15 \cdot 15$$
[illegible]

NOTES

(1) Rocket back landing, FRAB

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.3.1

PASS/FAIL

DATE 22 July

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

PK Son

SIGNATURE _____

BSEN TEAM LEADER <u>Rogers</u>	GRID # <u>19-11</u>	FT STEWART, GA DATE <u>6-6-11</u>
-----------------------------------	---------------------	--------------------------------------

0930. - 1030

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	B H.	

NOTES

1/2 broken up bucket parts (need excavating)

TEAM LEADER	QC	QA
PASS/FAIL _____ DATE <u>6-6-11</u>	PASS/FAIL _____ DATE <u>22 Jun 11</u>	PASS/FAIL _____ DATE _____
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>

7 - 1-4
 9 - 2-1
 12 - 2

BSEN

GRID RECORD

Fort Stewart, GA

Date: 6-2-11 Work Area/Grid #: 19-13 Team Leader: Roger
 Date/Time Start: 6-2-11 1510 Date/Time Stop: 6-3-11 0835
 # of Digs: 83 LBS of MD: LBS of RR: 9 lbs.

DESCRIPTION OF ITEMS/AREAS CLEARED:

X
 ① BH
 3' RET
 UNDER Tree

① Back hoe dig

SW Corner of Grid

MEC ITEMS: DATE	DIGS	LBS MD	LBS RR	MEC	%COMPLETE
6-2-11 1610	60	—	7	—	75%
6-3-11 0835-0835	23		2		25%
	83		9 lbs		100% Total

TEAM LEADER SIGNATURE:

Pross QL 22 Jun 11

60 Digs
 7 lbs Scrap

BSEN

GRID # 20-15

FT STEWART, GA

TEAM LEADER Thomas BraggDATE 6-20-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

Silt Fence has Rebar holding it up. New Fence is 10' from this grid. No significant finds.
 22 Jun 11 - Can only clear to within 3 feet of fence and rebar.

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 21-15

FT STEWART, GA

TEAM LEADER Thomas BagleyDATE 6-20-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

New Fence RUNS Through this. NO finds

22 Jun 11 - Can only clear to within 3 feet of fence & rebar.

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN	GRID # <u>7-14</u>	FT STEWART, GA
TEAM LEADER <u>Moek</u>		DATE <u>6/20/11</u>

										MEC	
										MD	
										8 ^{lbs}	
										TARGET DEBRIS	
										2 ^{lbs}	
										# DIGS	
										24	
										BH	
										1	
											RICT 3' DEEP DONE AS

SW

NOTES

① RICT needs excavated & excavated ② RICT

TEAM LEADER		QC		QA	
PASS/FAIL	DATE <u>6/20/11</u>	PASS/FAIL	DATE <u>22 July 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 7-15

FT STEWART, GA

TEAM LEADER MeekDATE 6/20/11

	MEC	
	MD	
	<u>2¹⁶</u>	
	TARGET DEBRIS	
	<u>1¹⁵</u>	
	# DIGS	
	<u>10</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/20/11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 8-10

FT STEWART, GA

TEAM LEADER

Mak

DATE

6/13/11

										MEC	
										MD	
										<u>16</u>	
										TARGET DEBRIS	
										# DIGS	
										<u>31</u>	
									<u>1</u>	BH	RKT 3' Deep
									RKT 3'		DOVE ARS

NOTES

1 - 1 MK2 RKT22 Jun 11 - Rocket was not marked!22 Jun 11 - Excavator Team dug out rocket.

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/13/11

SIGNATURE

PASS/FAIL

DATE

22 Jun 11

SIGNATURE

PASS/FAIL

DATE

SIGNATURE

BSEN GRID # 8-11
TEAM LEADER Mike

BSEN GRID # 8-11
TEAM LEADER Mike

BSEN GRID # 8-11 FT STEWART, GA
TEAM LEADER mkek DATE _____

BSEN GRID # 8-11 FT STEWART, GA
TEAM LEADER mkek DATE _____

[illegible]

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/~~FAIL~~

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE


SIGNATURE

22

BSEN TEAM LEADER <u>Week</u>	GRID # <u>8-12</u>	FT STEWART, GA DATE <u>6/15/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC	
												
											MD	
											<u>615</u>	
											TARGET DEBRIS	
											<u>15</u> ¹⁵	
											# DIGS	
											<u>44</u>	
												

NOTES

TEAM LEADER	QC	QA
PASS/FAIL <u>DATE 6/15/11</u> SIGNATURE 	PASS/FAIL <u>DATE 22 July 11</u> SIGNATURE 	PASS/FAIL <u>DATE</u> SIGNATURE 

BSEN

GRID # 8-13

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-16-11

										MEC	
										MD	
										TARGET DEBRIS	
										8 #	
										# DIGS	
										45	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-16-11

PASS/FAIL

DATE 22 Jun 11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>8-14</u>	FT STEWART, GA DATE <u>6/20/11</u>
---------------------------------	--------------------	---------------------------------------

<td style="width: 10%; text-align: center; vertical-align: middle;">MEC</td> <td style="width: 30%;"></td>	MEC	
		
	MD	
	<u>12¹⁵</u>	
	TARGET DEBRIS	
	<u>7 #</u>	
	# DIGS	
	<u>30</u>	
	<u>0</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL DATE <u>6/20/11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	PASS/FAIL DATE _____ SIGNATURE <u>[Signature]</u>
--	--	---

BSEN

GRID # 8-15

FT STEWART, GA

TEAM LEADER MackDATE 6/20/11

										MEC	
										<u>Ø</u>	
										MD	
										<u>6</u> ¹⁵⁵	
										TARGET DEBRIS	
										<u>3</u> ¹⁵	
										# DIGS	
										<u>24</u>	

JW

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/20/11

PASS/FAIL

DATE

22 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Mell</u>	GRID # <u>8-16</u>	FT STEWART, GA DATE <u>6/21/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC	
											<u>Ø</u>	
											MD	
											<u>3</u>	
											TARGET DEBRIS	
											<u>1</u>	
											# DIGS	
											<u>16</u>	
											<u>B.H</u>	
											<u>Ø</u>	

NOTES

TEAM LEADER PASS/FAIL <u> </u> DATE <u>6/21/11</u> SIGNATURE <u>Mell</u>	QC PASS/FAIL <u>Ø</u> DATE <u>22 June 11</u> SIGNATURE <u>[Signature]</u>	QA PASS/FAIL <u> </u> DATE <u> </u> SIGNATURE <u>[Signature]</u>
---	---	--

BSEN

GRID # 9-10


FT STEWART, GA

TEAM LEADER

Meek

DATE

6/13/11

										MEC	
											
										MD	
											
										TARGET DEBRIS	
											
										# DIGS	
										26	
										BH	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/13/11~~PASS/FAIL~~

DATE


22 Jun 11~~PASS/FAIL~~

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 9-11

FT STEWART, GA

TEAM LEADER W. Beck

DATE _____

										MEC	
											
										MD	
										<u>10</u> ¹⁶⁵	
										TARGET DEBRIS	
										<u>2</u> ¹⁶⁵	
										# DIGS	
										<u>25</u>	
										<u>B.H.</u>	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

PASS/FAIL

DATE 22 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u>Meek</u>	GRID # <u>9-12</u>	FT STEWART, GA DATE <u>6/15/11</u>
---------------------------------	--------------------	---------------------------------------

											MEC 	
											MD <u>12</u> ¹⁶	
											TARGET DEBRIS <u>25</u> ¹⁶	
			⊗								# DIGS <u>86</u>	
				⊗							<u>BH</u> <u>2</u> (dorse)	

NOTES

<u>2 RRTs EXCAVED!!!</u> 

TEAM LEADER PASS/FAIL <u> </u> DATE <u>6/15/11</u> SIGNATURE <u>Meek</u>	QC PASS/FAIL <u> </u> DATE <u>22 Jun 11</u> SIGNATURE <u>[Signature]</u>	QA PASS/FAIL <u> </u> DATE <u> </u> SIGNATURE <u>[Signature]</u>
---	---	--

DATE 6-16-11

PASS/FAIL	DATE <u>6-16-11</u>	PASS/FAIL	DATE <u>22 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>Downey Burton</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

TEAM LEADER

GRID # 9-14

FT STEWART, GA

DATE 6/20/11

										MEC	
											
									• ①	MD	
						②				35 ¹⁶	
										TARGET DEBRIS	
										17 #	
										# DIGS	
										45	
			④								
						③				4 DIGS	

NOTES

1	ROCKET IN GROUND
2	" "
3	" "
4	" "

EXCAVATED

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE _____

(PASS/FAIL

DATE:

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

9-15

BSEN

GRID #

9-15

FT STEWART, GA

TEAM LEADER

meek

DATE

6/20/11

										MEC	
											
										MD	
										8 ¹⁵	
										TARGET DEBRIS	
										1 ¹⁵	
										# DIGS	
										18	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/20/11

PASS/FAIL


DATE

22 July 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



9-16

BSEN

GRID #

9-16

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/21/11

										MEC	
										MD	
										716	
										TARGET DEBRIS	
										10 ¹⁶ -5	
										# DIGS	
										42	
										BH	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL

DATE

12 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN TEAM LEADER <u>Roger</u>	GRID # <u>6-8</u>	FT STEWART, GA DATE <u>6-22-11</u>
----------------------------------	-------------------	---------------------------------------

0645 - 0745

											MEC	
											Ø	
											MD	
											50	
											TARGET DEBRIS	
											Ø	
											# DIGS	
											69	
											BA-digs	
											Ø	

NOTES

TEAM LEADER	QC	QA
PASS/FAIL DATE <u>6-22-11</u> PASS/FAIL DATE <u>23 July 11</u> PASS/FAIL DATE _____		
SIGNATURE <u>[Signature]</u> SIGNATURE <u>[Signature]</u> SIGNATURE <u>[Signature]</u>		

20-10
 22-10
 27-30
 69-50

BSEN

GRID # 3-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-21-110645 - 0730

										MEC	
										<u>Ø</u>	
										MD	
										<u>8</u>	
										TARGET DEBRIS	
										<u>Ø</u>	
										# DIGS	
										<u>69</u>	
										<u>Bulldozer</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-21-11

PASS/FAIL

DATE

23 July 11

PASS/FAIL

DATE

SIGNATURE

RK

SIGNATURE

[Signature]

SIGNATURE

[Signature]17-1
32-4
20-3

BSEN

GRID # 4-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-21-110730-0815

										MEC	
										<u>0</u>	
										MD	
										<u>9</u>	
										TARGET DEBRIS	
										<u>0</u>	
										# DIGS	
										<u>78</u>	
										<u>84 diggs</u>	

NOTES

1. Small pieces of wine

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-21-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

R K Eyer

SIGNATURE

John A. Jr

SIGNATURE

Joe63-7
15-2

BSEN

GRID # 5-8

FT STEWART, GA

TEAM LEADER RogerDATE 6-21-11

0815 - 0900

										MEC	
										8	
										MD	
										18	
										TARGET DEBRIS	
										0	
										# DIGS	
										94	
										Bridges	
										0	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



30-7
32-5
32-6

BSEN	GRID # <u>7-8</u>	FT STEWART, GA
TEAM LEADER <u>Roger</u>		DATE <u>6-21-11</u>

1315 - 1430

										MEC	
										Ø	
										MD	
										18	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										57	
										13 Hdg	
										Ø	

NOTES

TEAM LEADER	QC	QA
PASS/FAIL	PASS/FAIL	PASS/FAIL
DATE <u>6-21-11</u>	DATE <u>23 Jun 11</u>	DATE _____
SIGNATURE _____	SIGNATURE _____	SIGNATURE _____

32-15
13-2
12-1
?

TEAM LEADER Guzman Tm

GRID # 2-9

DATE 6-14-10

[illegible]

NOTES

- ① Cable needing excavation
- ② Frag needing excavation

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-14-10

PASS/FAIL

DATE 23 July

PASS/FAIL

DATE .

SIGNATURE

SIGNATURE

SIGNATURE

PASS/FAIL	DATE <u>6-14-10</u>	PASS/FAIL	DATE <u>23 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 3-9

FT STEWART, GA

TEAM LEADER Rogers

DATE 6-21-11

1230- 1315


										MEC	
											
										MD	
										7	
										TARGET DEBRIS	
											
										# DIGS	
										47	
										Bad dig	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-21-11</u>	PASS/FAIL	DATE <u>23 June 11</u>	PASS/FAIL	DATE _____
SIGNATURE 		SIGNATURE 		SIGNATURE 	

17-2
16-3
14-2

BSEN

GRID # 4-9

FT STEWART, GA

TEAM LEADER RogerDATE 6-21-11

0945 - 1130

										MEC	
										<u>Ø</u>	
										MD	
										<u>33</u>	
										TARGET DEBRIS	
										<u>Ø</u>	
										# DIGS	
										<u>73</u>	
										Btdigs	
										<u>Ø</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Roger

SIGNATURE

John G. Jones

SIGNATURE

[Signature]32-12
20-11
21-20

TEAM LEADER

GRID # 5-9

DATE 6-21-11

0900 - 0945

[illegible]

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 July 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

30-7

25-29

26-5

BSEN

GRID # 6-9

FT STEWART, GA

TEAM LEADER RogerDATE 6-22-11

0745 - 0830

										MEC	
										Ø	
										MD	
										8	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										33	
										Bldigs	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-22-11</u>	PASS/FAIL	DATE <u>23 June 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>RK</u>		SIGNATURE <u>James A. Jones</u>		SIGNATURE <u>W</u>	

10-2
12-4
11-2

BSEN

TEAM LEADER

RogerGRID # 7-9

FT STEWART, GA

DATE 6.22-110830 - 0950

										MEC	
										Ø	
										MD	
										7	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										51	
										BHd. 35	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.22-11

PASS/FAIL

DATE

23 July 11

PASS/FAIL

DATE

SIGNATURE

pu

SIGNATURE

[Signature]

SIGNATURE

[Signature]

8-2
15-2
28-3

BSEN

GRID # 8-9

FT STEWART, GA

TEAM LEADER

RogerDATE 6-22-110950 - 1030

										MEC	
										<u>8</u>	
										MD	
										<u>7</u>	
										<u>RA 13</u>	
										TARGET	
										DEBRIS	
										<u>8</u>	
										# DIGS	
										<u>29</u>	
										Bldg	
										<u>8</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-22-11</u>	PASS/FAIL	DATE <u>23 July 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>KR</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

5-1
14-3
24-5
10-3

BSEN

GRID # 9-9

FT STEWART, GA

TEAM LEADER RosenDATE 6-22-111030 - 1130

										MEC	
										Ø	
										MD	
										16	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										45	
										BHOLIGS	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-22-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rosen

SIGNATURE

[Signature]

SIGNATURE

[Signature]
15-11
15-2
15-3

BSEN

GRID # 10-9

FT STEWART, GA

TEAM LEADER

PeggyDATE 6-22-11

1230- 1330

										MEC	
										Ø	
										MD	
										15	
										TARGET DEBRIS	
										20	
										# DIGS	
										54	
										RA digs	
										1	Dug 3' deep completed

NOTES

1. RKT. needs dug. (dug up)

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-22-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

20-8
18-4
16-3
4

BSEN

TEAM LEADER

GRID # 11-9

FT STEWART, GA

DATE 6-22-11

1330 - 1400

										MEC	
										0	
										MD	
										13	
										TARGET DEBRIS	
										40	
										# DIGS	
										41	
										BHDS	
										2	2:14 @ 3' completed

NOTES

1. KKT. Needs dug	(dug)
2. KKT. Needs dug	(dug)

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-22-11

PASS/FAIL

DATE 23-7-11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

10-3

13-3

18-7

BSEN

GRID # 3-14

FT STEWART, GA

TEAM LEADER Guzman, Tim

DATE 6-20-11

										MEC	
										0/65	
										MD	
										3/58	
										TARGET DEBRIS	
										8/65	
										# DIGS	
										118	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 23 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 4-14

FT STEWART, GA

TEAM LEADER Guzman TomDATE 6/20/11

										MEC	
										0	
										MD	
										25 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										121	

NOTES

① hole

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/20/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 5-14

FT STEWART, GA

TEAM LEADER Guzman Tan IDATE 6-21-11

										MEC	
										0 lbs	
										MD	
										6 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										88	
										1 Exc	

NOTES

① M2 Rocket needing excavation

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/21/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER Guzman

Tem 1

DATE 6-21-11

NOTES

(1) M2 Rocket needing excavation

QA

DATE 6-21-11

SIGNATURE

DATE 23 Jun

SIGNATURE

PASS/FAIL

DATE _____

SIGNATURE

BSEN

GRID # 3-15

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/21/11

										MEC	
										0 lbs	
										MD	
										15 lbs	
										TARGET DEBRIS	
										1 lb	
										# DIGS	
										128	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 5-15

FT STEWART, GA

TEAM LEADER GuzmanDATE 6/24/11

										MEC	
										0 lbs	
										MD	
										30 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										107	
										WET	
										ANDS	

NOTES

① Heavy Wire contamination

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/24/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 6-15

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/21/11

										MEC	
										0 lbs	
										MD	
										2 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										70	

NOTES

① Wire in ground. Continues into grid 5-15

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/21/11</u>	PASS/FAIL	DATE <u>23 July 11</u>	PASS/FAIL	DATE
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 3-16

FT STEWART, GA

TEAM LEADER Guzman Ten 1DATE 6-22-11

										MEC	
										0 lbs	
										MD	
										2 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										108	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 4-16

FT STEWART, GA

TEAM LEADER Guzman Ten 1DATE 6/22/11

										MEC	
										0	
										MD	
										10 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										148	

NOTES

① Heavy Wine Contamination

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER

Guzman Tim!

DATE 6/22/11

[illegible]

① Heavy Wire contamination

QC

QA

PASS/FAIL

DATE _____

$$6 \overline{) 22} \overline{) 11}$$

PASS/FAIL

DATE _____

23 June 11

PASS/FAIL

DATE 2/2

SIGNATURE

SIGNATURE

SIGNATURE

10

BSEN

GRID # 2-17

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-13-11

											MEC	
											MD	
											TARGET DEBRIS	
											4 #	
											# DIGS	
											40	
											2 BH	
											DIGS	

NOTES

① WIRE PIT
② WIRE PIT

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-13-11

PASS/FAIL

DATE 23-Jul-11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 4-17

FT STEWART, GA

TEAM LEADER Guzman TmDATE 6/22/11

										MEC	
										0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										5 lbs	
										# DIGS	
										132	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 July 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER Guzman Tm 1

GRID # 5-17

DATE 6/22/11

DATE 6/22/11

[illegible]

NOTES

None

TEAM LEADER

QC

QA

(PASS/FAIL)

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE *M 17*

SIGNATURE 

SIGNATURE _____

BSEN

GRID # 6-17

FT STEWART, GA

TEAM LEADER Guzman TmDATE 6/22/11

										MEC	
										6165	
										MD	
										5165	
										TARGET DEBRIS	
										0165	
										# DIGS	
										48	

NOTES

<u>None</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 8-17

FT STEWART, GA

TEAM LEADER W. KellDATE 6/22/11

										MEC	
										MD	
										5 ¹⁵	
										TARGET	
										DEBRIS	
										1 ¹⁵	
										# DIGS	
										20	
										B.H.	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL

DATE

23 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID #

9-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/22/11

										MEC	
										MD	
										40 ¹⁶	
										TARGET DEBRIS	
										1 ¹⁶	
										# DIGS	
										46	
										B.H	
										5	Excavated

NOTES

SEA RKTs

~~Excavated~~

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/11/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/22/11

										MEC	
											
										MD	
										<u>7¹⁵</u>	
										TARGET DEBRIS	
											
										# DIGS	
										<u>33</u>	
										BH	
											

NOTES

Bees Nest - Ace studs 7x 0800Wire running thru Grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/24/11

PASS/FAIL


DATE

23 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



TEAM LEADER

GRID # 11-17

FT STEWART, GA

DATE 6/22/11

							(X)		MEC	
							(X)		0	
									MD	
									28 ^{lbs}	
									TARGET DEBRIS	
							(X)		8 ^{lb}	
									# DIGS	
									42	
								(X)	3H	
						(X)	(X)	(X)	4	<u>EXCAVATED</u>

SW

NOTES

4 RPTs need to be dug

TEAM LEADER

QC

QA

PASS/~~FAIL~~

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 12-17

FT STEWART, GA

TEAM LEADER

Mull

DATE

6/22/11

										MEC	
											
										MD	
										<u>25</u> ¹⁶	
										TARGET DEBRIS	
										<u>10</u> ¹⁶	
										# DIGS	
										<u>29</u>	
										<u>34</u> <u>3</u>	
											EXCAVATED

NOTES

~~30 KIC+~~

Bee's nest marked 4 pink flags

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/22/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Mull

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

BSEN

GRID # 13-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/10/11

	MEC	<u>0</u>	
	MD	<u>10</u>	
	TARGET DEBRIS	<u>0</u>	
	# DIGS	<u>33</u>	
	BH	<u>3</u>	RKT'S REMOVED 3' DONE <u>MS</u>

NOTES

① Rocket next to tree in roots
 ② Rocket

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/10/11

PASS/FAIL

DATE 23 July 11

PASS/FAIL

DATE

SIGNATURE

S Meek

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 12-18

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/10/11

										MEC	
										MD	
										13	
										TARGET DEBRIS	
										5	
										# DIGS	
										37	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/10/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 2-19

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-13-11

										MEC	
										MD	
										TARGET DEBRIS	
										6#	
										# DIGS	
										45	
	①									1 BH	

NOTES

① HOT ROCKS

TEAM LEADER Downey Burton

QC

QA

PASS/FAIL

DATE 6-13-11

PASS/FAIL

DATE 23 Jan 11

PASS/FAIL

DATE

SIGNATURE

Burton

SIGNATURE

John A. [Signature]

SIGNATURE

[Signature]

12-19

BSEN TEAM LEADER <u>Wick</u>	GRID # <u>12-19</u>	FT STEWART, GA DATE <u>6/10/11</u>
---------------------------------	---------------------	---------------------------------------

	MEC		
	MD		
	TARGET DEBRIS		
	# DIGS	5	

NOTES

23 Jun 11 - Area is in upper left corner. <i>Jeff</i>

TEAM LEADER	QC	QA
PASS/FAIL <u> </u> DATE <u>6/10/11</u>	PASS/FAIL <u> </u> DATE <u>23 Jun 11</u>	PASS/FAIL <u> </u> DATE <u> </u>
SIGNATURE <i>[Signature]</i>	SIGNATURE <i>[Signature]</i>	SIGNATURE <i>[Signature]</i>

BSEN

GRID # 10-17

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/22/11

										MEC	
											
										MD	
										<u>7¹⁵</u>	
										TARGET DEBRIS	
											
										# DIGS	
										<u>33</u>	
										BH	
											

NOTES

Bees Nest - Ace studs 7x 0800
 wire running thru grid

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/24/11

PASS/FAIL


DATE

23 July 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 10-9

FT STEWART, GA

TEAM LEADER

PeggyDATE 6-22-11

1230- 1330

										MEC	
										Ø	
										MD	
										15	
										TARGET DEBRIS	
										20	
										# DIGS	
										54	
										BA Digs	
										1	Dug 3' deep completed

NOTES

1. RKT. needs dug. (dug up)

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-22-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

20-8
18-4
16-3
4

TEAM LEADER

GRID # 11-17

FT STEWART, GA

DATE 6/22/11

							(X)		MEC	
							(X)		0	
									MD	
									28 ^{lbs}	
									TARGET DEBRIS	
							(X)		8 ^{lb}	
									# DIGS	
									42	
								(X)	3H	
						(X)	(X)	(X)	4	<u>EXCAVATED</u>

SW

NOTES

4 RPTs need to be dug

TEAM LEADER

QC

QA

PASS/~~FATE~~

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

TEAM LEADER

GRID # 11-18

FT STEWART, GA

DATE 6/

										MEC	
										MD	
										<u>60</u> ¹³	
										TARGET DEBRIS	
										<u>15</u> ¹⁵	
										# DIGS	
										<u>47</u>	
										<u>6</u>	<u>EXCAVATED</u>

NOTES

6 RKT EXCAVATED

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/22/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

TEAM LEADER

GRID # 11-9

FT STEWART, GA

DATE 6-22-11

1330 - 1400

										MEC	
										0	
										MD	
										13	
										TARGET DEBRIS	
										40	
										# DIGS	
										41	
										BHDS	
										2	2:14 @ 3' completed

NOTES

1. KKT. Needs dug	(dug)
2. KKT. Needs dug	(dug)

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-22-11

PASS/FAIL

DATE 23-7-11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

10-3

13-3

18-7

BSEN

GRID # 12-17

FT STEWART, GA

TEAM LEADER

Mull

DATE

6/22/11

										MEC	
											
										MD	
										<u>25</u> ¹⁶	
										TARGET DEBRIS	
										<u>10</u> ¹⁶	
										# DIGS	
										<u>29</u>	
										<u>34</u> <u>3</u>	
											EXCAVATED

NOTES

~~30 KIC+~~

Bee's nest marked 4 pink flags

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/22/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Mull

SIGNATURE

James A. Jones

SIGNATURE

[Signature]

BSEN

GRID # 12-18

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/10/11

										MEC	
										<u>0</u>	
										MD	
										<u>13</u>	
										TARGET DEBRIS	
										<u>5</u>	
										# DIGS	
										<u>37</u>	
										<u>08</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/10/11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

12-19

BSEN TEAM LEADER <u>W. Beck</u>	GRID # <u>12-19</u>	FT STEWART, GA DATE <u>6/10/11</u>
------------------------------------	---------------------	---------------------------------------

	MEC		
	MD		
	TARGET DEBRIS		
	# DIGS	5	

NOTES

23 Jun 11 - Area is in upper left corner. <i>Jeff</i>

TEAM LEADER	QC	QA
PASS/FAIL <u> </u> DATE <u>6/10/11</u>	PASS/FAIL <u> </u> DATE <u>23 Jun 11</u>	PASS/FAIL <u> </u> DATE <u> </u>
SIGNATURE <i>[Signature]</i>	SIGNATURE <i>[Signature]</i>	SIGNATURE <i>[Signature]</i>

BSEN

GRID # 13-17

FT STEWART, GA

TEAM LEADER MeekDATE 6/10/11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	BH	
	3	
		PKTS REMOVED
		3' DONE MS

NOTES

① Rocket next to tree in roots
 ② Rocket

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/10/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 2-17

FT STEWART, GA

TEAM LEADER Downey BURTONDATE 6-13-11

											MEC	
											MD	
											TARGET DEBRIS	
											4 #	
											# DIGS	
											40	
											2 BH	
											DIGS	

NOTES

① WIRE PIT
② WIRE PIT

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-13-11

PASS/FAIL

DATE 23 July 11

PASS/FAIL

DATE

SIGNATURE

Downey Burton

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 2-19

FT STEWART, GA

TEAM LEADER Downey BurtonDATE 6-13-11

										MEC	
										MD	
										TARGET DEBRIS	
										6#	
										# DIGS	
										45	
	①									1 BH	

NOTES

① HOT ROCKS

TEAM LEADER Downey Burton

QC

QA

PASS/FAIL

DATE 6-13-11

PASS/FAIL

DATE 23 Jan 11

PASS/FAIL

DATE

SIGNATURE

Burton

SIGNATURE

John A. [Signature]

SIGNATURE

[Signature]

TEAM LEADER Guzman Tm

GRID # 2-9

DATE 6-14-10

[illegible]

NOTES

- ① Cable needing excavation
- ② Frag needing excavation

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-14-10

PASS/FAIL

DATE 23 July

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 3-14

FT STEWART, GA

TEAM LEADER Guzman, Tim

DATE 6-20-11

										MEC	
										0/65	
										MD	
										3/58	
										TARGET DEBRIS	
										8/65	
										# DIGS	
										118	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-20-11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 3-15

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/21/11

										MEC	
										0 lbs	
										MD	
										15 lbs	
										TARGET DEBRIS	
										1 lb	
										# DIGS	
										128	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 3-16

FT STEWART, GA

TEAM LEADER Guzman Ten 1DATE 6-22-11

										MEC	
										0 lbs	
										MD	
										2 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										108	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 3-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-21-110645 - 0730

										MEC	
										<u>Ø</u>	
										MD	
										<u>8</u>	
										TARGET DEBRIS	
										<u>Ø</u>	
										# DIGS	
										<u>69</u>	
										<u>Bulldozer</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-21-11

PASS/FAIL

DATE

23 July 11

PASS/FAIL

DATE

SIGNATURE

RK

SIGNATURE

[Signature]

SIGNATURE

[Signature]17-1
32-4
20-3

BSEN

GRID # 3-9

FT STEWART, GA

TEAM LEADER Rogers

DATE 6-21-11

1230- 1315

										MEC	
										Ø	
										MD	
										7	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										47	
										Bad dig	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-21-11</u>	PASS/FAIL	DATE <u>23 June 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

17-2
16-3
14-2

BSEN

GRID # 4-14

FT STEWART, GA

TEAM LEADER Guzman TomDATE 6/20/11

										MEC	
										0	
										MD	
										25 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										121	

NOTES

① hole

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/20/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u>Guzman</u> <u>Ten</u> <u>1</u>	GRID # <u>4-16</u>	FT STEWART, GA DATE <u>6/22/11</u>
---	--------------------	---------------------------------------

											MEC	
											0	
											MD	
											10 lbs	
											TARGET DEBRIS	
											2 lbs	
											# DIGS	
											148	



NOTES

① Heavy Wine Contamination

TEAM LEADER	QC	QA
PASS/FAIL 0 DATE <u>6/22/11</u>	PASS/FAIL 0 DATE <u>23 Jun 11</u>	PASS/FAIL 0 DATE _____
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>

BSEN

GRID # 4-17

FT STEWART, GA

TEAM LEADER Guzman TmDATE 6/22/11

										MEC	
										0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										5 lbs	
										# DIGS	
										132	

NOTES

None

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 4-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-21-110730-0815

										MEC	
										<u>0</u>	
										MD	
										<u>9</u>	
										TARGET DEBRIS	
										<u>0</u>	
										# DIGS	
										<u>78</u>	
										<u>84 diggs</u>	

NOTES

1. Small pieces of wine

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-21-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

R K Eyer

SIGNATURE

John A. Jr

SIGNATURE

19063-7
15-2

BSEN

GRID # 4-9

FT STEWART, GA

TEAM LEADER

Roger

DATE

6-21-11

0945 - 1130

										MEC	
										<u>Ø</u>	
										MD	
										<u>33</u>	
										TARGET DEBRIS	
										<u>Ø</u>	
										# DIGS	
										<u>73</u>	
										Btdigs	
										<u>Ø</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-21-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Roger

SIGNATURE

James J.

SIGNATURE

QA

32-12
20-11
21-20

BSEN

GRID # 5-14

FT STEWART, GA

TEAM LEADER Guzman Tan IDATE 6-21-11

										MEC	
										0 lbs	
										MD	
										6 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										88	
										1 Exc	

NOTES

① M2 Rocket needing excavation

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/21/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 5-15

FT STEWART, GA

TEAM LEADER GuzmanDATE 6/24/11

										MEC	
										0 lbs	
										MD	
										30 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										107	
										WET	
										ANDS	

NOTES

① Heavy Wire contamination

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/24/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER

Guzman Tim!

DATE 6/22/11

[illegible]

① Heavy Wire contamination

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

6/22/11

PASS/FAIL

DATE _____

23 June 11

PASS/FAIL

DATE 2

SIGNATURE

SIGNATURE

SIGNATURE

DATE 2

TEAM LEADER Guzman Tm 1

GRID # 5-17

FT STEWART, GA

DATE 6/22/11

[illegible]

NOTES

None

TEAM LEADER

QC

QA

(PASS/FAIL)

DATE 6/22/11

PASS/FAIL

DATE 23/11/17

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE *msz*

SIGNATURE 

SIGNATURE _____

BSEN

GRID # 5-8

FT STEWART, GA

TEAM LEADER RogerDATE 6-21-11

0815 - 0900

										MEC	
										Ø	
										MD	
										18	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										94	
										Bridges	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



30-7
32-5
32-6

BSEN

GRID # 5-9

FT STEWART, GA

TEAM LEADER

RogerDATE 6-21-110900 - 0945

										MEC	
										$\emptyset$	
										MD	
										32	
										TARGET DEBRIS	
										$\emptyset$	
										# DIGS	
										91	
										Backlogs	
										$\emptyset$	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



30-7

25-20

20-5

BSEN

GRID # 6-14

FT STEWART, GA

TEAM LEADER Guzman

Tm 1

DATE 6-21-11

										MEC	
										016s	
										MD	
										516s	
										TARGET DEBRIS	
										216s	
										# DIGS	
										89	
										1 Exc	
										WET LANDS	

NOTES

(1) M2 Rocket needing excavation

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-21-11

PASS/FAIL

DATE 23 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-15

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/21/11

										MEC	
										0 lbs	
										MD	
										2 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										70	

NOTES

① Wire in ground. Continues into grid 5-15

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/21/11</u>	PASS/FAIL	DATE <u>23 July 11</u>	PASS/FAIL	DATE
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 6-17

FT STEWART, GA

TEAM LEADER Guzman TmDATE 6/22/11

										MEC	
										6165	
										MD	
										5165	
										TARGET DEBRIS	
										0165	
										# DIGS	
										48	

NOTES

<u>None</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 23 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

TEAM LEADER

GRID # 6-8

FT STEWART, GA

DATE 6-22-11

0645 - 0745

[illegible]

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

6.22-11

PASS/FAIL

DATE _____

23 July

PASS/FAIL

DATE _____

SIGNATURE

[Signature]

SIGNATURE

DATE 25 Aug 1964

~~SIGNATURE~~

DATE _____

20-10
22-18
27-30
49-50

BSEN

GRID # 6-9

FT STEWART, GA

TEAM LEADER RogerDATE 6-22-11

0745 - 0830

										MEC	
										Ø	
										MD	
										8	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										33	
										Bldg Digs	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-22-11</u>	PASS/FAIL	DATE <u>23 June 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>RK</u>		SIGNATURE <u>James A. Jones</u>		SIGNATURE <u>W</u>	

10-2
12-4
11-2

BSEN	GRID # <u>7-8</u>	FT STEWART, GA
TEAM LEADER <u>Roger</u>		DATE <u>6-21-11</u>

1315 - 1430

										MEC	
										Ø	
										MD	
										18	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										57	
										13 Hdg	
										Ø	

NOTES

TEAM LEADER	QC	QA
PASS/FAIL	PASS/FAIL	PASS/FAIL
DATE <u>6-21-11</u>	DATE <u>23 Jun 11</u>	DATE _____
SIGNATURE _____	SIGNATURE _____	SIGNATURE _____

32-15
13-2
12-1
?

BSEN

TEAM LEADER

RogerGRID # 7-9

FT STEWART, GA

DATE 6.22-110830 - 0950

										MEC	
										Ø	
										MD	
										7	
										TARGET DEBRIS	
										Ø	
										# DIGS	
										51	
										BHd. 35	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.22-11

PASS/FAIL

DATE

23 July 11

PASS/FAIL

DATE

SIGNATURE

pu

SIGNATURE

[Signature]

SIGNATURE

[Signature]

8-2
15-2
28-3

BSEN

GRID # 8-17

FT STEWART, GA

TEAM LEADER W. KellDATE 6/22/11

										MEC	
										MD	
										5 ¹⁵	
										TARGET	
										DEBRIS	
										1 ¹⁵	
										# DIGS	
										20	
										B.H.	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/21/11

PASS/FAIL


DATE

23 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 8-9

FT STEWART, GA

TEAM LEADER

RogerDATE 6-22-110950 - 1030

										MEC	
										<u>8</u>	
										MD	
										<u>7</u>	
										<u>RA 13</u>	
										TARGET	
										DEBRIS	
										<u>8</u>	
										# DIGS	
										<u>29</u>	
										Bldg	
										<u>8</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-22-11</u>	PASS/FAIL	DATE <u>23 July 11</u>	PASS/FAIL	DATE _____
SIGNATURE	<u>K. [Signature]</u>	SIGNATURE	<u>[Signature]</u>	SIGNATURE	<u>[Signature]</u>

3-1
14-3
2-1-5
10-3

BSEN

GRID # 9-17

FT STEWART, GA

TEAM LEADER MeekDATE 6/22/11

										MEC	
										<u>0</u>	
										MD	
										<u>40¹⁶</u>	
										TARGET DEBRIS	
										<u>1¹⁶</u>	
										# DIGS	
										<u>46</u>	
										<u>B.H</u>	
										<u>5</u>	
											<u>Excavated</u>

NOTES

<u>SEA RKTs</u>	<u>Excavated</u>

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/11/11</u>	PASS/FAIL	DATE <u>23 Jun 11</u>	PASS/FAIL	DATE
SIGNATURE <u>Meek</u>		SIGNATURE <u>John A. Jones</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 9-9

FT STEWART, GA

TEAM LEADER

RosenDATE 6-22-111030 - 1130

										MEC	
										$\emptyset$	
										MD	
										16	
										TARGET DEBRIS	
										$\emptyset$	
										# DIGS	
										45	
										BHOLIGS	
										$\emptyset$	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-22-11

PASS/FAIL

DATE

23 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rosen

SIGNATURE

[Signature]

SIGNATURE

[Signature]15-11
15-2
15-3

BSEN

GRID # 9-18

FT STEWART, GA

TEAM LEADER MeekDATE 6/23/11

										MEC	
										<u>0</u>	
										MD	
										<u>18¹⁶</u>	
										TARGET DEBRIS	
										<u>11¹⁶</u>	
										# DIGS	
										<u>29</u>	
										<u>BH</u>	
										<u>3</u>	
											Excavated

SW

NOTES

3 Rkts - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 8-20

FT STEWART, GA

TEAM LEADER MullDATE 6/23/11

										MEC	
											
										MD	
										25 ¹⁵	
										TARGET DEBRIS	
										6 ¹⁵	
										# DIGS	
										43	
										3	
											EXCAVATED

NOTES

3 RKTs EXCAVATED

TEAM LEADER

QC

QA

PASS/FAIL

DATE

PASS/FAIL

DATE

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 7-20

FT STEWART, GA

TEAM LEADER Meek

DATE 6/23/11

										MEC	
											
										MD	
										21	
										TARGET DEBRIS	
										3 ¹³	
										# DIGS	
										56	
										BH	
										2	excavated

NOTES

 RK+

X RK+

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u>Guzman Tm</u>	GRID # <u>4-20</u>	FT STEWART, GA DATE <u>6/27/11</u>
--------------------------------------	--------------------	---------------------------------------

											MEC	
											0 lbs	
											MD	
											8 lbs	
											TARGET DEBRIS	
											30 lbs	
											# DIGS	
											88	

NOTES

① M2 Rocket Excavated

TEAM LEADER	QC	QA
PASS/FAIL <u> </u> DATE <u>6/27/11</u>	PASS/FAIL <u> </u> DATE <u>28 July 11</u>	PASS/FAIL <u> </u> DATE <u> </u>
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>

BSEN

GRID # 3-20

FT STEWART, GA

TEAM LEADER Guzman Tm IDATE 6/27/11

										MEC	
										0	
										MD	
										10 lbs	
			①							TARGET DEBRIS	
										1 lbs	
			09d					③		# DIGS	
										108	
										1 Exc	AB Pos

NOTES

- (1) Survey Marker
 (2) Wire contaminated pit
 (3) M2 Rocket needing Excavation
 * M2 Rocket excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/27/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID #

11-19

FT STEWART, GA

TEAM LEADER

Weell

DATE

6/23/11

										MEC	
											
										MD	
										30 ^{1b}	
										TARGET DEBRIS	
										6 ^{1b}	
										# DIGS	
										43	
										BH	
										2	

SW

NOTES

2 RKTs

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL


DATE

28 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 10-19

FT STEWART, GA

TEAM LEADER Meo/cDATE 6/23/11

											MEC	
											☒	
			☒								MD	
											45 ¹⁶	
											TARGET	
											DEBRIS	
											15 ¹⁶	
											# DIGS	
											66	
											BH	
											5	

NOTES

<u>See RLY</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 9-19

FT STEWART, GA

TEAM LEADER

Mack

DATE

6/23/11

										MEC	
			(X)							(X)	
										MD	
										27 ¹⁵	
										TARGET DEBRIS	
										5 ¹⁵	
										# DIGS	
										63	
										344	3 RKT 3' deep
										4	Small piece
											DONE RK

SW

NOTES

3 RKT
1 Hit not cleared under stump

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 July

PASS/FAIL

DATE

SIGNATURE

Mack

SIGNATURE

John D. Jr

SIGNATURE

[Signature]

BSEN

GRID # 8-19

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
											
										MD	
										33 ¹⁶	
										TARGET DEBRIS	
										10 ¹⁶	
										# DIGS	
										69	
										BH	2 BKT 3'-4' Deep
											DONE MS

SV

NOTES

<u>2nd BKT</u>

TEAM LEADER


QC

QA

PASS/FAIL

DATE

SIGNATURE




PASS/FAIL

DATE

28 July 11

SIGNATURE



PASS/FAIL

DATE

SIGNATURE



BSEN

GRID # 7-19

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
											
										MD	
										<u>18</u> ^{1b}	
										TARGET DEBRIS	
										<u>3</u> ^{1b}	
										# DIGS	
										<u>27</u>	
											

NOTES

⊗ TRASH pile pulled a bunch of pipe out

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-14

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/27/11

										MEC	
										0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
		③		②			①			144	
										3 Exc	AL Dig

NOTES

①, ②, & ③ MZ Rockets needing excavation
 * Rockets Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/27/11

PASS/FAIL

DATE 28 July

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 5-19

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/27/11

										MEC	
			①							0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										3 lbs	
										# DIGS	
										121	
			②								

NOTES

M2 Rockets excavated (1) + (2)

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 4-19

FT STEWART, GA

TEAM LEADER

Guzman, TimDATE 6/27/11

										MEC	
										0 lbs	
										MD	
										5 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										128	

NOTES

① Wire contaminated area

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 3-19

FT STEWART, GA

TEAM LEADER Guzman TimDATE 6/27/11

							①			MEC	
										0165	
										MD	
										15165	
										TARGET DEBRIS	
										95165	
										# DIGS	
										348	
							③				

NOTES

① + ③ Survey markers

② Debris arod from crashed drone

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-18

FT STEWART, GA

TEAM LEADER MeekDATE 6/22/11

										MEC	
										MD	
										23 ¹⁵	
										TARGET DEBRIS	
										# DIGS	
										27	
										BH	3 RKT 3'-7' Deep
										3	DONE

NOTES

3 RKTs

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 28 July 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 8-18

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
										$\emptyset$	
										MD	
										13^{15}	
										TARGET DEBRIS	
										2^{15}	
										# DIGS	
										27	
										$3H$	
										2	Excavated

SLW

NOTES

2ea 7x6s - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Meek

SIGNATURE

James A. Jones

SIGNATURE


W. A. Jones

BSEN

GRID # 7-18

FT STEWART, GA

TEAM LEADER WeekDATE 6/23/11

										MEC 	
										MD <u>615</u>	
										TARGET DEBRIS 	
										# DIGS <u>17</u>	
										<u>34</u> 	

NOTES

TEAM LEADER


QC

QA


~~PASS/FAIL~~DATE 6/23/11 PASS/FAILDATE 28/Jul/11~~PASS/FAIL~~

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-18

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/23/11

										MEC	
										0 lbs	
										MD	
										25 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										132	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/23/11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 5-18

FT STEWART, GA

TEAM LEADER Guzman TamDATE 6/23/11

					②					MEC	
										0 lbs	
										MD	
										8 lbs	
				①						TARGET DEBRIS	
										0 lbs	
										# DIGS	
										132	
										1 Exc	

NOTES

- ① M2 Rocket needing excavation
 ② Braided cable in base of tree
 * M7 Rocket excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER Guzman

GRID # 3-18

FT STEWART, GA

DATE 6/23/11

[illegible]

NOTES

① Survey Nail

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jan 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

SIGNATURE 

BSEN

GRID # 3-17

FT STEWART, GA

TEAM LEADER Guzman, TmDATE 6/23/11

										MEC	
										0 lbs	
										MD	
										15 lbs	
										TARGET DEBRIS	
										5 lbs	
										# DIGS	
										206	

NOTES

① Wire contaminated ② Survey Nail

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-18

FT STEWART, GA

TEAM LEADER MeekDATE 6/22/11

										MEC	
										MD	
										23 ¹⁵	
										TARGET DEBRIS	
										# DIGS	
										27	
										BH	3 RKT 3'-7' Deep
										3	DONE

NOTES

3 RKTs

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/22/11

PASS/FAIL

DATE 28 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 10-19

FT STEWART, GA

TEAM LEADER Meo/cDATE 6/23/11

											MEC	
											☒	
			☒								MD	
											45 ¹⁶	
											TARGET	
											DEBRIS	
											15 ¹⁶	
											# DIGS	
											66	
											BH	
											5	

NOTES

<u>See RLY</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID #

11-19

FT STEWART, GA

TEAM LEADER

Weell

DATE

6/23/11

										MEC	
											
										MD	
										30 ^{1b}	
										TARGET DEBRIS	
										6 ^{1b}	
										# DIGS	
										43	
										BH	
										2	

SW

NOTES

2 RKTs

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL


DATE

28 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 3-17

FT STEWART, GA

TEAM LEADER Guzman, TmDATE 6/23/11

										MEC	
										0 lbs	
										MD	
										15 lbs	
										TARGET DEBRIS	
										5 lbs	
										# DIGS	
										206	

NOTES

① Wire contaminated ② Survey Nail

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

TEAM LEADER Guzman

GRID # 3-18

FT STEWART, GA

DATE 6/23/11

[illegible]

NOTES

① Survey Nail

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jan 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

10

BSEN

GRID # 3-19

FT STEWART, GA

TEAM LEADER Guzman TimDATE 6/27/11

							①			MEC	
										0165	
										MD	
										15165	
										TARGET DEBRIS	
										95165	
										# DIGS	
										348	
							③				

NOTES

① + ③ Survey markers
 ② Debris arod from crashed drone

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 3-20

FT STEWART, GA

TEAM LEADER Guzman Tm IDATE 6/27/11

										MEC	
										0	
										MD	
										10 lbs	
			①							TARGET DEBRIS	
										1 lbs	
			09d					③		# DIGS	
										108	
								②		1 Exc	AB Pos

NOTES

- (1) Survey Marker
 (2) Wire contaminated pit
 (3) M2 Rocket needing Excavation
 * M2 Rocket excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/27/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 4-19

FT STEWART, GA

TEAM LEADER Guzman, TimDATE 6/27/11

										MEC	
										0 lbs	
										MD	
										5 lbs	
										TARGET DEBRIS	
										2 lbs	
										# DIGS	
										128	

NOTES

① Wire contaminated area

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN TEAM LEADER <u>Guzman Tmj</u>	GRID # <u>4-20</u>	FT STEWART, GA DATE <u>6/27/11</u>
---------------------------------------	--------------------	---------------------------------------

											MEC	
											0 lbs	
											MD	
											8 lbs	
											TARGET DEBRIS	
											30 lbs	
											# DIGS	
											88	

NOTES

① M2 Rocket Excavated

TEAM LEADER	QC	QA
PASS/FAIL <u> </u> DATE <u>6/27/11</u>	PASS/FAIL <u> </u> DATE <u>28 July 11</u>	PASS/FAIL <u> </u> DATE <u> </u>
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>

BSEN

GRID # 5-18

FT STEWART, GA

TEAM LEADER Guzman TamDATE 6/23/11

					②					MEC	
										0 lbs	
										MD	
										8 lbs	
				①						TARGET DEBRIS	
										0 lbs	
										# DIGS	
										132	
										1 Exc	

NOTES

- ① M2 Rocket needing excavation
 ② Braided cable in base of tree
 * M7 Rocket excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 5-19

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/27/11

										MEC	
			①							0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										3 lbs	
										# DIGS	
										121	
			②								

NOTES

M2 Rockets excavated (1) + (2)

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/27/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 6-18

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/23/11

										MEC	
										0 lbs	
										MD	
										25 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
										132	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6/23/11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 6-14

FT STEWART, GA

TEAM LEADER Guzman Tm 1DATE 6/27/11

										MEC	
										0 lbs	
										MD	
										10 lbs	
										TARGET DEBRIS	
										0 lbs	
										# DIGS	
		③		②			①			144	
										3 Exc	AL Dig

NOTES

①, ②, & ③ MZ Rockets needing excavation
 * Rockets Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/27/11

PASS/FAIL

DATE 28 July

PASS/FAIL

DATE

SIGNATURE

SIGNATURE


SIGNATURE

BSEN

GRID # 7-18

FT STEWART, GA

TEAM LEADER WeekDATE 6/23/11

										MEC	
											
										MD	
										<u>615</u>	
										TARGET DEBRIS	
											
										# DIGS	
										<u>17</u>	
										<u>34</u>	
											

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL


DATE

28/Jul/11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 7-19

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
											
										MD	
										<u>18</u> ^{1b}	
										TARGET DEBRIS	
										<u>3</u> ^{1b}	
										# DIGS	
										<u>27</u>	
											

NOTES

⊗ TRASH pile pulled a bunch of pipe out

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 7-20

FT STEWART, GA

TEAM LEADER MeekDATE 6/23/11

										MEC	
											
										MD	
										21	
										TARGET DEBRIS	
										3 ¹³	
										# DIGS	
										56	
										BH	
										2	excavated

NOTES

⊗ RKT
 x RKT

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6/23/11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 8-18

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
										$\emptyset$	
										MD	
										13^{15}	
										TARGET DEBRIS	
										2^{15}	
										# DIGS	
										27	
										$3H$	
										2	Excavated

SLW

NOTES

2ea 7x6s - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 8-19

FT STEWART, GA

TEAM LEADER

Meek

DATE

6/23/11

										MEC	
											
										MD	
										33 ¹⁶	
										TARGET DEBRIS	
										10 ¹⁶	
										# DIGS	
										69	
										BH	2 BKT 3'-4' Deep
											DONE MS

SV

NOTES

<u>2nd BKT</u>

TEAM LEADER


QC

QA

PASS/FAIL

DATE

SIGNATURE




PASS/FAIL

DATE

28 July 11

SIGNATURE



PASS/FAIL

DATE

SIGNATURE



BSEN

GRID # 8-20

FT STEWART, GA

TEAM LEADER MullDATE 6/23/11

										MEC	
											
										MD	
										25 ¹⁵	
										TARGET DEBRIS	
										6 ¹⁵	
										# DIGS	
										43	
										3	
											EXCAVATED

NOTES

3 RKTs EXCAVATED

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL


DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 9-18

FT STEWART, GA

TEAM LEADER MeekDATE 6/23/11

										MEC	
										<u>Ø</u>	
										MD	
										<u>18¹⁶</u>	
										TARGET DEBRIS	
										<u>11¹⁶</u>	
										# DIGS	
										<u>29</u>	
										<u>BH</u>	
										<u>3</u>	
											Excavated

SW

NOTES

3 RKts - Excavated

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/23/11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 9-19

FT STEWART, GA

TEAM LEADER MackDATE 6/23/11

										MEC	
			(X)							(X)	
										MD	
										27 ¹⁵	
										TARGET DEBRIS	
										5 ¹⁵	
										# DIGS	
										63	
										344	3 RKT 3' deep
										4	Small piece
											DONE RK

SW

NOTES

3 RKT
1 Hit not cleared under stump

TEAM LEADER

QC

QA

PASS/FAIL

DATE

PASS/FAIL

DATE

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN
TEAM LEADER

GRID # 5-21

FT STEWART, GA
DATE 6/28/11

										DATE	
										MEC	
										MD	
										TARGET DEBRIS	
										# DIGS	
										BH	

NOTES

NOTES

[illegible]

TEAM LEADER

QC

QA

PASS/FAIL

DATE /

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

Small

DATE 29-10-11


ATURE

BSEN

GRID # 4-21

FT STEWART, GA

TEAM LEADER MeekDATE 6/28/11

										MEC	
											
										MD	
											
										TARGET DEBRIS	
											
										# DIGS	
										24	
										BH	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/28/11~~PASS/FAIL~~

DATE


29 July~~PASS/FAIL~~

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 3-21

FT STEWART, GA

TEAM LEADER MikeDATE 6/28/11

										MEC	
										<u>05</u>	
										MD	
										<u>15¹⁵</u>	
										TARGET DEBRIS	
										<u>3¹⁵</u>	
										# DIGS	
										<u>30</u>	
										<u>BSH</u>	
										<u>0</u>	

5W

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~DATE 6/28/11~~PASS/FAIL~~DATE 29 July 11~~PASS/FAIL~~

DATE _____

SIGNATURE MikeSIGNATURE [Signature]SIGNATURE [Signature]

BSEN

GRID # 3-22

FT STEWART, GA

TEAM LEADER

Meel

DATE

6/28/11

										MEC	
										<u>0</u>	
										MD	
										<u>12</u> ¹⁵	
										TARGET DEBRIS	
										<u>2</u> ¹⁵	
										# DIGS	
										<u>26</u>	
										<u>BH</u>	
										<u>0</u>	

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE

6/28/11~~PASS/FAIL~~

DATE

29 Jun 11~~PASS/FAIL~~

DATE

SIGNATURE

S Meel

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 4-22

FT STEWART, GA

TEAM LEADER

mkek

DATE

6/28/11

	MEC	<u>0</u>
	MD	<u>8¹⁶</u>
	TARGET DEBRIS	<u>1¹⁶</u>
	# DIGS	<u>19</u>
	<u>13H</u>	<u>1</u>

1 EA RKT 3' DEEP
DONE AB

NOTES

1ea RKT
Area saturated w/ wire

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/28/11

PASS/FAIL

DATE

29 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 6-20

FT STEWART, GA

TEAM LEADER MeekDATE 6/28/11

										MEC	
										Ø	
										MD	
										21 ¹⁶	
										TARGET DEBRIS	
										6 ¹⁶	
										# DIGS	
										39	
											3 EA RKT 3'-5' DEEP
										3	DONE ARS

50

NOTES

3ea RKT

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/28/11

PASS/FAIL

DATE

29 Jun 11

PASS/FAIL

DATE

SIGNATURE

Meek

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN TEAM LEADER <u>Meek</u>	GRID # <u>6/21</u>	FT STEWART, GA DATE <u>6/28/11</u>
---------------------------------	--------------------	---------------------------------------

										MEC	
										Ⓟ	
										MD	
										26 ¹⁶	
										TARGET DEBRIS	
										7 ¹⁶	
										# DIGS	
										37	
										BH Z	2 RKT 3' DEEP DONE AS

SW

NOTES

① RKT
② RKT

TEAM LEADER		QC		QA	
PASS/FAIL	DATE <u>6/28/11</u>	PASS/FAIL	DATE <u>29 July 11</u>	PASS/FAIL	DATE _____
SIGNATURE <u>Meek</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

BSEN

GRID # 5-20

FT STEWART, GA

TEAM LEADER

W. Beck

DATE

6/28/11

										MEC	
										<u>0</u>	
										MD	
										<u>16</u> ¹⁶	
										TARGET DEBRIS	
										<u>3</u> ¹⁶	
										# DIGS	
										<u>28</u>	
										<u>BA</u> <u>1</u>	1 RKT 3' DEEP DONE <u>MS</u>

NOTES

<u>7/2/11</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/28/11

PASS/FAIL

DATE

29 July 11

PASS/FAIL

DATE

SIGNATURE

W. Beck

SIGNATURE

James G. [Signature]

SIGNATURE

[Signature]

BSEN

GRID # 3-21

FT STEWART, GA

TEAM LEADER MikeDATE 6/28/11

										MEC	
										<u>05</u>	
										MD	
										<u>15¹⁵</u>	
										TARGET DEBRIS	
										<u>3¹⁵</u>	
										# DIGS	
										<u>30</u>	
										<u>BSH</u>	
										<u>0</u>	

NOTES

TEAM LEADER


QC

QA

~~PASS/FAIL~~DATE 6/28/11~~PASS/FAIL~~DATE 29 July 11~~PASS/FAIL~~

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 3-22

FT STEWART, GA

TEAM LEADER

Meel

DATE

6/28/11

										MEC	
											
										MD	
										<u>12</u> ¹⁵	
										TARGET DEBRIS	
										<u>2</u> ¹⁵	
										# DIGS	
										<u>26</u>	
										<u>BH</u>	
											

NOTES

TEAM LEADER

QC

QA

~~PASS/FAIL~~

DATE


6/28/11~~PASS/FAIL~~

DATE


29 Jun 11~~PASS/FAIL~~

DATE


SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 4-21

FT STEWART, GA

TEAM LEADER MeekDATE 6/28/11

										MEC	
											
										MD	
											
										TARGET DEBRIS	
											
										# DIGS	
										24	
										BH	
											

NOTES

TEAM LEADER


QC

QA


~~PASS/FAIL~~DATE 6/28/11~~PASS/FAIL~~DATE 29 Jun 11~~PASS/FAIL~~

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 4-22

FT STEWART, GA

TEAM LEADER

mkek

DATE

6/28/11

	MEC	<u>0</u>
	MD	<u>8¹⁶</u>
	TARGET DEBRIS	<u>1¹⁶</u>
	# DIGS	<u>19</u>
	<u>13H</u>	<u>1</u>

1 EA RKT 3' DEEP
DONE AB

NOTES

1 EA RKT
Area saturated w/ wire

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/28/11

PASS/FAIL

DATE

29 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 5-20

FT STEWART, GA

TEAM LEADER

W. Beck

DATE

6/28/11

										MEC	
										<u>0</u>	
										MD	
										<u>16</u> ¹⁶	
										TARGET DEBRIS	
										<u>3</u> ¹⁶	
										# DIGS	
										<u>28</u>	
										<u>BA</u> <u>1</u>	1 RKT 3' DEEP DONE <u>MS</u>

NOTES

<u>7/2/11</u>

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6/28/11

PASS/FAIL

DATE

29 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN
 TEAM LEADER Meek GRID # 5-21 FT STEWART, GA
 DATE 6/28/11

										MEC	
										7	
										MD	
										10 ¹⁵	
										TARGET DEBRIS	
										1 ¹⁵	
										# DIGS	
										28	
										BH	
										8	

NOTES

TEAM LEADER	QC	QA
PASS/FAIL	PASS/FAIL	PASS/FAIL
DATE <u>6/28/11</u>	DATE <u>29 July 11</u>	DATE _____
SIGNATURE <u>Meek</u>	SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>

TEAM LEADER

GRID # 6-20

FT STEWART, GA

DATE 6/28/11

										MEC	
										0	
							(X)			MD	
										21 ¹⁶	
										TARGET DEBRIS	
										6 ¹⁶	
										# DIGS	
							(X)			39	
									(X)		
										3	3 EA RKT 3'-5' DEEP DONE ASK

۵۷

NOTES

3ea RKT

TEAM LEADER

QC

QA

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN GRID # 6/21
TEAM LEADER Mell

GRID # 6/21

FT STEWART, GA
DATE 6/28/11

TEAM LEADER

DATE 6/28/11

										MEC	
										(X)	
										MD	
										26 ¹⁶	
										TARGET DEBRIS	
										7 ¹⁶	
										# DIGS	
										37	
									Z	BH	2 RKT 3' DEEP DONE ARJ
									(X)	Z	

SW

NOTES

- ① RKF
- ② RKT

TEAM LEADER

QC

QA

PASS/FAIL

DATE:

PASS/FAIL

DATE _____

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 6-16 DK

FT STEWART, GA

TEAM LEADER _____

DATE 6-23-11

0828 - (100)

	MEC	
	MD	10
	TARGET DEBRIS	Ø
	# DIGS	→ 24
	Bldg. gr	2

Excavated

NOTES

1. Hot rocks
2. Anchor in ground
3. 2nd woman in hole
5. Pipe
6. metal plate
7. pipe
8. Area in parking lot needs dug

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 7-18 DK

FT STEWART, GA

TEAM LEADER RogerDATE 6-23-11

0650 - 0710

	MEC	0
	MD	5
	TARGET DEBRIS	0
	# DIGS	12
	Bldgs	Excavated

NOTES

1. Int rocks
2. Elec. cable out side of grid.
3. Concrete block w/ rebar
4. Large channel bar "needs dug."

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

6-1
6-4

BSEN

GRID # 5-15 DK

FT STEWART, GA

TEAM LEADER

PogerDATE 6-23-111000 - 1300

	MEC	
	<u>8</u>	
	MD	
	<u>3</u>	
	TARGET DEBRIS	
<u>8</u>		
# DIGS		
<u>5</u>		
Bldg	<u>1</u>	<u>Excavated</u>

1000

NOTES

1. Unknown item deep in parking lot suggest excavator dig this one

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jan 11

PASS/FAIL

DATE

SIGNATURE

AK

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 2-7

FT STEWART, GA

TEAM LEADER

RogerDATE 6-27-11

	MEC	<u>0</u>
	MD	<u>4</u>
	TARGET DEBRIS	<u>0</u>
	# DIGS	<u>4</u>
	Bldgs	<u>0</u>

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Roger

SIGNATURE

Jonathan

SIGNATURE

Mike

BSEN

GRID # 2-8 DK

FT STEWART, GA

TEAM LEADER

Rosen

DATE 6-27-4

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-27-4</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE
SIGNATURE		SIGNATURE		SIGNATURE	

BSEN

GRID # 32

FT STEWART, GA

TEAM LEADER

Rizer

DATE 6.27-11

										MEC	
										MD	
										TARGET DEBRIS	
										# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 Jan 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 4-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-27-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

Roger

SIGNATURE

[Signature]

SIGNATURE

[Signature]


BSEN

GRID # 3-9 DK

FT STEWART, GA

TEAM LEADER

RoghDATE 6-27-11

	MEC	
		
	MD	
	2	
	TARGET DEBRIS	
		
# DIGS		
6		
B#dys		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 4-9 DK

FT STEWART, GA

TEAM LEADER Roger

DATE 6-27-11

	MEC	ϕ
	MD	10
	TARGET DEBRIS	ϕ
	# DIGS	20
		1/1
		1/1
		ϕ

NOTES

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-27-11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE <u> </u>
SIGNATURE		SIGNATURE		SIGNATURE	

BSEN

GRID # 3-10 DK

FT STEWART, GA

TEAM LEADER

Reyer-DATE 6.27.11

	MEC	
	<u>8</u>	
	MD	
	<u>2</u>	
	TARGET DEBRIS	
<u>8</u>		
# DIGS		
<u>3</u>		
<u>Bundy</u>		
<u>8</u>		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Knee

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 4-10 DK

FT STEWART, GA

TEAM LEADER

LoganDATE 6.27.11

										MEC	
										Ø	
										MD	
										6	
										TARGET	
										DEBRIS	
										Ø	
										# DIGS	
										10	
										34 deg.	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

RA Ex

SIGNATURE

James

SIGNATURE


QA

BSEN

GRID # 510 D/C

FT STEWART, GA

TEAM LEADER RogerDATE 6.27.11

	MEC	
		
	MD	
		
	TARGET DEBRIS	
		
# DIGS		
		
Blacks		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.27.11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 4-4 DK

FT STEWART, GA

TEAM LEADER RiceDATE 6.27.11

	MEC	<u>8</u>
	MD	<u>12</u>
	TARGET DEBRIS	<u>8</u>
	# DIGS	<u>24</u>
	<u>Blacks</u>	<u>8</u>

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rice

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 5-11 DK

FT STEWART, GA

TEAM LEADER Kogel

DATE 6.27.11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Borehole	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 July

PASS/FAIL

DATE

SIGNATURE

SIGNATURE


SIGNATURE

BSEN

GRID # 4-12 OK

FT STEWART, GA

TEAM LEADER RosenDATE 6-27-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Btdlys	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 4-13 DK

FT STEWART, GA

TEAM LEADER

RosenDATE 6-23-6-27-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 6-14 DK

FT STEWART, GA

TEAM LEADER

RogerDATE 6-23-111360 - 1400

	MEC	☒
	MD	☒
	TARGET DEBRIS	☒
	# DIGS	☒
		☒

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-15 DK

FT STEWART, GA

TEAM LEADER RogerDATE 6-23-11

										MEC	
										MD	
										TARGET DEBRIS	
										# DIGS	
										By days	

NOTES

- ① Hot Rocks.
 ② Pipe. Long piece.
 ③ Pipe.

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-23-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 5-16 DK

FT STEWART, GA

TEAM LEADER RogersDATE 6-23-11

0820-1000

MEC

MD

TARGET DEBRIS

DIGS

12

Bibby

NOTES

6/15

① Det fence Area

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN


GRID # 5-17 DK

FT STEWART, GA

TEAM LEADER

RogerDATE 6-23-11

0710 - 0820

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Bl dgs	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-17 DK

FT STEWART, GA

TEAM LEADER

RogakDATE 6-23-11

0710 - 0820

	MEC	<u>Ø</u>
	MD	<u>20</u>
	TARGET DEBRIS	<u>Ø</u>
	# DIGS	<u>90</u>
	Bldgs	<u>Ø</u>

NOTES

1. Hot rocks in road

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rogak

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN


GRID # 7-17 DK

FT STEWART, GA

TEAM LEADER Ryer

DATE 6-23-11

0710-0820

	MEC	
		
	MD	
	1	
	TARGET DEBRIS	
		
# DIGS		
4		
BH dig		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-23-11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-18 DK

FT STEWART, GA

TEAM LEADER RoseDATE 6-23-11

	MEC	$\emptyset$
	MD	2
	TARGET DEBRIS	$\emptyset$
	# DIGS	7
	Bldgs	$\emptyset$

NOTES

1. Hot Rocks in Road

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-23-11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE
SIGNATURE <u>Rose</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	


4-1
3-1

BSEN

GRID # 2-7

FT STEWART, GA

TEAM LEADER RogerDATE 6-27-11

	MEC	<u>0</u>
	MD	<u>4</u>
	TARGET DEBRIS	<u>0</u>
	# DIGS	<u>4</u>
	Bldgs	<u>0</u>

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Roger

SIGNATURE

Jonathan

SIGNATURE

Mike

BSEN


GRID # 2-8 DK

FT STEWART, GA

TEAM LEADER

Roger

DATE 6-27-4

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-27-4

PASS/FAIL

DATE

28 Jun 11


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 3-10 DK

FT STEWART, GA

TEAM LEADER

Reyer-DATE 6.27.11

	MEC	
	<u>8</u>	
	MD	
	<u>2</u>	
	TARGET DEBRIS	
	<u>8</u>	
	# DIGS	
	<u>3</u>	
	<u>Bundy</u>	
	<u>8</u>	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Knee

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

TEAM LEADER

GRID #

32

FT STEWART, GA

DATE

6.27-11

										MEC	
										MD	
										TARGET DEBRIS	
										# DIGS	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 Jan 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE


BSEN

GRID # 3-9 DK

FT STEWART, GA

TEAM LEADER

RoghDATE 6-27-11

	MEC	
		
	MD	
	2	
	TARGET DEBRIS	
		
# DIGS		
6		
B#dys		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 4-10 DK

FT STEWART, GA

TEAM LEADER

LoganDATE 6.27.11

										MEC	
										Ø	
										MD	
										6	
										TARGET	
										DEBRIS	
										Ø	
										# DIGS	
										10	
										34 deg.	
										Ø	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6.27.11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

RA Ex

SIGNATURE

James

SIGNATURE

QA

BSEN

GRID # 4-4 DK

FT STEWART, GA

TEAM LEADER RigeDATE 6.27-11

	MEC	<u>8</u>
	MD	<u>12</u>
	TARGET DEBRIS	<u>8</u>
	# DIGS	<u>24</u>
	<u>Blacks</u>	<u>8</u>

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.27-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rige

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 4-12 OK

FT STEWART, GA

TEAM LEADER Rosen

DATE 6-27-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Btdlys	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE


BSEN

GRID # 4-13 DK

FT STEWART, GA

TEAM LEADER

RosenDATE 6-23-6-27-11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE

6-27-11

PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 4-8

FT STEWART, GA

TEAM LEADER

RogerDATE 6-27-11

	MEC	
		
	MD	
		
	TARGET DEBRIS	
		
# DIGS		
		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-27-11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 4-9 DK

FT STEWART, GA

TEAM LEADER Roger

DATE 6-27-11

	MEC	ϕ
	MD	10
	TARGET DEBRIS	ϕ
	# DIGS	20
		1/1
		1/1
		ϕ

NOTES

TEAM LEADER

QC

QA


PASS/FAIL	DATE <u>6-27-11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE <u> </u>
SIGNATURE		SIGNATURE		SIGNATURE	

BSEN

GRID # 510 D/C

FT STEWART, GA

TEAM LEADER RogerDATE 6.27.11

	MEC	
		
	MD	
		
	TARGET DEBRIS	
		
	# DIGS	
		
	Blacks	
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.27.11

PASS/FAIL

DATE 28 Jun 11


PASS/FAIL

DATE _____


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 5-11 DK

FT STEWART, GA

TEAM LEADER Kogel

DATE 6.27.11

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Boulders	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6.27.11

PASS/FAIL

DATE 28 July

PASS/FAIL

DATE _____

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 5-15 DK

FT STEWART, GA

TEAM LEADER

PogerDATE 6-23-111000 - 1300

	MEC	
	<u>8</u>	
	MD	
	<u>3</u>	
	TARGET DEBRIS	
<u>8</u>		
# DIGS		
<u>5</u>		
Bldg		
<u>1</u>		Excavated

1000

NOTES

1. Unknown item deep in parking lot suggest excavator dig this one

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jan 11

PASS/FAIL

DATE

SIGNATURE

AK

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 5-16 DK

FT STEWART, GA

TEAM LEADER RogersDATE 6-23-11

Handwritten notes on the grid: "0820-1000", "Barely", "Need to be", "Pasture", "6/15", "6/14".

MEC	Ø
MD	6
TARGET DEBRIS	Ø
# DIGS	12
Bibby	Ø

NOTES

① Det fence Area

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July 11

PASS/FAIL

DATE

SIGNATURE

[Signature]

SIGNATURE

[Signature]

SIGNATURE

[Signature]


BSEN

GRID # 5-17 DK

FT STEWART, GA

TEAM LEADER RogerDATE 6-23-11

0710 - 0820

	MEC	
	MD	
	TARGET DEBRIS	
	# DIGS	
	Bl dgs	

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-23-11

PASS/FAIL

DATE 28 Jun 11

PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE




BSEN

GRID # 6-14 DK

FT STEWART, GA

TEAM LEADER

RogerDATE 6-23-111360 - 1400

	MEC	☒
	MD	☒
	TARGET DEBRIS	☒
	# DIGS	☒
		☒

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July


PASS/FAIL

DATE

SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 6-15 DK

FT STEWART, GA

TEAM LEADER

RogerDATE 6-23-11

										MEC	
										MD	
										TARGET DEBRIS	
										# DIGS	
										By days	

NOTES

① Hot Rocks.
② Pipe. Long piece.
3. Pipe.

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 6-16 DK

FT STEWART, GA

TEAM LEADER _____

DATE 6-23-11

0828 - (100)

	MEC Ø	
	MD 10	
	TARGET DEBRIS Ø	
	# DIGS → 24	
	Bldg. gr 2	Excavated

NOTES

1. Hot rocks
2. Anchor in ground
3. 2nd woman in hole
5. Pipe
6. metal plate
7. pipe
8. Area in parking lot needs dug

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 July

PASS/FAIL

DATE

SIGNATURE

SIGNATURE

SIGNATURE

BSEN

GRID # 6-17 DK

FT STEWART, GA

TEAM LEADER

RogakDATE 6-23-11

0710 - 0820

	MEC	<u>Ø</u>
	MD	<u>20</u>
	TARGET DEBRIS	<u>Ø</u>
	# DIGS	<u>90</u>
	Bldgs	<u>Ø</u>

NOTES

1. Hot rocks in road

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jun 11

PASS/FAIL

DATE

SIGNATURE

Rogak

SIGNATURE

[Signature]

SIGNATURE

[Signature]

BSEN

GRID # 6-18 DK

FT STEWART, GA

TEAM LEADER RoseDATE 6-23-11

	MEC	$\emptyset$
	MD	2
	TARGET DEBRIS	$\emptyset$
	# DIGS	7
	Bldgs	$\emptyset$

NOTES

1. Hot Rocks in Road

TEAM LEADER

QC

QA

PASS/FAIL	DATE <u>6-23-11</u>	PASS/FAIL	DATE <u>28 Jun 11</u>	PASS/FAIL	DATE
SIGNATURE <u>Rose</u>		SIGNATURE <u>[Signature]</u>		SIGNATURE <u>[Signature]</u>	

4-1
3-1



BSEN

GRID # 7-17 DK

FT STEWART, GA

TEAM LEADER RyerDATE 6-23-11

0710-0820

	MEC	
		
	MD	
	1	
	TARGET DEBRIS	
		
# DIGS		
4		
BH dig		
		

NOTES

TEAM LEADER

QC

QA

PASS/FAIL

DATE

6-23-11

PASS/FAIL

DATE

28 Jun 11


PASS/FAIL

DATE


SIGNATURE



SIGNATURE



SIGNATURE



BSEN

GRID # 7-18 DK

FT STEWART, GA

TEAM LEADER RogerDATE 6-23-11

0650 - 0710

	MEC	Ø
	MD	5
	TARGET DEBRIS	Ø
	# DIGS	12
	Bldgs	Excavated

NOTES

1. Int rocks
2. Elec. cable outside of grid.
3. Concrete block w/ rebar
4. Large channel bar "needs dug."

TEAM LEADER

QC

QA

PASS/FAIL

DATE 6-23-11

PASS/FAIL

DATE 28 July 11

PASS/FAIL

DATE _____

SIGNATURE

SIGNATURE

SIGNATURE

6-1
6-4

Quality Control Daily Report

Log Number/Date: #0001 / 21 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 started screening the MEC contaminated dirt pile with magnetometers. There is a lot of "hot rocks" and construction debris in the dirt.
- b. **South Pond site:** N/A
- c. **10th Engineer (70 acre) site:** Teams 1 & 2 Started a Schoenstat assisted surface sweep today of the 70 acre site. This sweep is to facilitate the grubbing crew.
- d. **Dog Kennel (10 acre) site:** N/A

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
930 Cat- ,966 Cat-		

5. QC Activities at the South Pond Site: None.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
		0


6. QC Activities at the 10th Engineer Site: The QC inspector was Al Smith.

Total Grids Swept	Grids Passed QC	Grids Failing QC
79	N/A	


7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC

Contractor Certification: On behalf of the Contractor, I certify that this report is complete and correct. The equipment and materials used, and work performed during this reporting period is in compliance with the Work Plan to the best of my knowledge, except as noted in this report.




James R. Jepson
UXO Quality Control Manager



Alfred A. Smith
UXO Quality Control Manager

Acknowledged and Concur:



Benjamin Leon-Guerrero
Site Manager

Quality Control Daily Report

Log Number/Date: #0002 / 22 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 continued screening the MEC contaminated dirt pile with magnetometers. A Cat 966 Loader and our Cat 930 loader were used to start moving clean dirt to the clean pile for the Team Chief and QC to inspect.
- b. **South Pond site:** N/A
- c. **10th Engineer (70 acre) site:** Teams 1 & 2 continuing their schonstedt assisted sweep.
- d. **Dog Kennel (10 acre) site:** N/A

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
930 Cat-55, 966 Cat-57	930 Cat-181.5, 966 Cat-285	466.5

5. QC Activities at the South Pond Site: None.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
		0

6. QC Activities at the 10th Engineer Site: The QC inspector was Al Smith.

Total Grids Swept	Grids Passed QC	Grids Failing QC
147	N/A	


7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC

Contractor Certification: On behalf of the Contractor, I certify that this report is complete and correct. The equipment and materials used, and work performed during this reporting period is in compliance with the Work Plan to the best of my knowledge, except as noted in this report.




James R. Jepson
UXO Quality Control Manager



Alfred A. Smith
UXO Quality Control Manager

Acknowledged and Concur:



Benjamin Leon-Guerrero
Site Manager

Quality Control Daily Report

Log Number/Date: #0003 / 23 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 continued screening the MEC contaminated dirt pile with magnetometers. A Cat 966 Loader and our Cat 930 loader were used to continue moving clean dirt to the clean pile for the Team Chief and QC to inspect. Four M2 BAT's were found at the site.
- b. **South Pond site:** N/A
- c. **10th Engineer (70 acre) site:** Teams 1 & 2 continuing sweeps of site.
- d. **Dog Kennel (10 acre) site:** N/A

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
930 Cat-121, 966 Cat-129	1044.3	1510.8

5. QC Activities at the South Pond Site: None.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
		0


6. QC Activities at the 10th Engineer Site: The QC inspector was Al Smith.

Total Grids Swept	Grids Passed QC	Grids Failing QC
124	N/A	


7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC

Contractor Certification: On behalf of the Contractor, I certify that this report is complete and correct. The equipment and materials used, and work performed during this reporting period is in compliance with the Work Plan to the best of my knowledge, except as noted in this report.




James R. Jepson
UXO Quality Control Manager



Alfred A. Smith
UXO Quality Control Manager

Acknowledged and Concur:



Benjamin Leon-Guerrero
Site Manager

Quality Control Daily Report

Log Number/Date: #0004 / 25 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 continued screening the MEC contaminated dirt pile with magnetometers. A Cat 966 Loader and our Cat 930 loader were used to continue moving clean dirt to the clean pile for the Team Chief and QC to inspect. Eight M2 BAT's were found at the site today.
- b. **South Pond site:** N/A
- c. **10th Engineer (70 acre) site:** Teams 1 & 2 continuing sweep. Grub team starting Grubbing. Sweep team expected to finish 70 acre and move to 10 acre site. Grubbing team grubbed 18 grids.
- d. **Dog Kennel (10 acre) site:** N/A

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
930 Cat-127, 966 Cat-149	1164.1	2674.9

QC Fail – At 1102 hours, I found a M2 BAT rocket buried on the leading edge of the clean pile. The operation was halted and everyone was briefed by the team chief to slow down when checking the dirty pile, and for the loader operators to take shallow cuts of not more than 1 foot. Operations resumed, and no further problems were noted.

5. QC Activities at the South Pond Site: None.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
		0


6. QC Activities at the 10th Engineer Site: The QC inspector was Al Smith.

Total Grids Swept	Grids Passed QC	Grids Failing QC


7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC

Contractor Certification: On behalf of the Contractor, I certify that this report is complete and correct. The equipment and materials used, and work performed during this reporting period is in compliance with the Work Plan to the best of my knowledge, except as noted in this report.




James R. Jepson
UXO Quality Control Manager



Alfred A. Smith
UXO Quality Control Manager

Acknowledged and Concur:



Benjamin Leon-Guerrero
Site Manager

Quality Control Daily Report

Log Number/Date: #0005 / 26 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 continued screening the MEC contaminated dirt pile with magnetometers. A Cat 966 Loader and our Cat 930 loader were used to continue moving clean dirt to the clean pile for the Team Chief and QC to inspect. Six M2 BAT rockets were found at the site today. Lightning caused a 2 hour safety stand down.
- b. **South Pond site:** N/A
- c. **10th Engineer (70 acre) site:** Brush crew continued clearing 70 acre site today. Completed 25 grids.
- d. **Dog Kennel (10 acre) site:** Teams 1 & 2 swept 10 acre site.

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
930 Cat-53, 966 Cat-89	619.9	3294.8

QC Fail – At 0923 hours, I found a M2 BAT rocket buried in the clean pile. The operation was stopped and the team members were assembled to discuss what happened and how to improve the process. Apparently, one of the loaders started scraping up dirt just a few feet before the area the Tech II had cleared. Loader operators will insure the Tech II shows them exactly where to cut before scraping up a load. We had no problems the rest of the day.

5. QC Activities at the South Pond Site: None.

Total Loader Buckets	Cubic Yards Screened	Total Cubic Yards Screened
		0


6. QC Activities at the 10th Engineer Site: The QC inspector was Al Smith.

Total Grids Swept	Grids Passed QC	Grids Failing QC


7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC


Contractor Certification: On behalf of the Contractor, I certify that this report is complete and correct. The equipment and materials used, and work performed during this reporting period is in compliance with the Work Plan to the best of my knowledge, except as noted in this report.



James R. Jepson
UXO Quality Control Manager




Alfred A. Smith
UXO Quality Control



Thomas L. Bagby
UXO Quality Control

Acknowledged and Concur:



Thomas Bagby
Site Manager

Quality Control Daily Report

Log Number/Date: #0006 / 27 Apr 11

Name/Location of Work Area: Fort Stewart, Georgia

1. Work Performed Today:

- a. **HQ Building site:** Team 3 continued screening the MEC contaminated dirt pile with magnetometers. Two Cat 966 Loaders were used to continue moving clean dirt to the clean pile for the Team Chief and QC to inspect. Four M2 BAT rockets were found in the work area today.
- b. **South Pond site:** Team 1 started screening the MEC contaminated dirt with magnetometers. One Cat 966 Loader was used to move clean dirt to the clean pile for the team leader and QC to inspect. 1 M2 BAT rocket was found in the work area today
- c. **10th Engineer (70 acre) site:** Brush crew continued clearing 70 acre site today. Completed 16 grids.
- d. **Dog Kennel (10 acre) site:**

Demo Operations: N/A

2. Special Inspections: N/A

3. Follow-Up Inspections: N/A

4. QC Activities at the HQ Building Site: The QC inspector was James Jepson.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
Two each 966 Cat-267	1335	4629.8

5. QC Activities at the South Pond Site: The QC inspector was Alfred Smith.

Total Loader Buckets	Cubic Yards Screened Today	Total Cubic Yards Screened
966 Cat- 60	300	300

6. QC Activities at the 10th Engineer Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC

7. QC Activities at the Dog Kennel Site: None.

Total Grids Swept	Grids Passed QC	Grids Failing QC