## ATTENTION!!

## INDIVIDUAL WEAPON SYSTEM (IWS) MILES DO (S) & DO NOT (S)

MILES Issue / Turn-In 0730-1530 General Issue / Turn-In 0730-1600

## <mark>DO (S)</mark>

- 1. Equipment must be clean & dry prior to turn-in to TSC.
- 2. Remove all Batteries (<u>except Halo batteries</u>) from components and place in SAT (small arms transmitter) pockets inside of transit case on top of SAT.
- 3. Inventory all components prior to turn-in. (Units responsibility)
- 4. Transit Case will be cleaned inside and out prior to packing components.

## <mark>DO NOT (S)</mark>

- 1. <u>Do not</u> pack any components in the transit case wet. If inclement weather will not permit you to pack dry, please remove components ASAP upon returning to your unit AO.
- 2. <u>Do not</u> stack transit cases more than 3 high.
- 3. <u>Do not</u> throw away any Lithium-thionyl chloride batteries, return them to TSC.
- 4. <u>Do not</u> attempt to remove the batteries from the (Halo) Harness Assembly. The batteries are only authorized to be removed by a MILES Technician.

Note: TSC will not accept any wet, mildew components or transit cases. (Period)

\*\* Failure to comply will constitute equipment rejection by TSC personnel.

Signature: \_\_\_\_\_