

# ASBESTOS

## (Floor Tile & Mastic Removal)

### POSSIBLE AREAS OF CONCERN

Asbestos-containing floor tile is common on Fort Campbell. The glue (mastic) that holds the tile in place may also contain asbestos.

### CHARACTERIZATION

Asbestos-containing materials are managed as a Special Waste.

### HANDLING PROCEDURES

**Step 1** Contact **DPW Work Management Branch** or **Environmental Division TSCA** to determine if floor tile is asbestos containing.

**Step 2** If the floor tile has become loose from the floor, place in a plastic bag and call the **DPW Asbestos Maint. Team** for pickup.

**Step 3** If the floor tile has become deteriorated, damaged or otherwise in poor condition, unit FMT should submit Work Order to **DPW Service Order Section** or call **DPW Service Orders** to submit a service request for removal/replacement of asbestos containing material.

**NOTE:** Activities such as sanding or grinding, drilling, or sawing of asbestos containing floor tile **SHALL NOT** be allowed. Further, Self-Help removal of asbestos-containing tiles is prohibited.



Contact the Environmental  
Division (TSCA Program) or DPW  
work Management Branch

### GENERAL INFORMATION

For additional information, see protocol sheet A-11 or contact **Environmental Division TSCA**

## ASBESTOS AND LEAD-BASED PAINT

### (Building Remodeling/Maintenance/Demolition)

#### POSSIBLE AREAS OF CONCERN

Asbestos and Lead-based Paint may be found on any building on the installation. There may be increased health risks associated with not following the recommended handling procedures.

#### CHARACTERIZATION

Asbestos-containing materials are managed as special wastes. Lead-based paint waste is managed as a hazardous waste.

#### HANDLING PROCEDURES

**Step 1** Contact DPW Work Management Branch or Environmental Division TSCA for more info.

To determine if lead-based paint is present, contact Environmental Division TSCA.

**Step 2** FMT or a DPW Customer Service Representative will submit work order (DA 4283) to DPW Work Management Branch or call DPW Service Orders to submit a service request.

**Step 3** DPW Work Management Branch will review work orders and provide notice to proceed as appropriate.

**Step 4** Maintain work order number(s) to monitor status.



Contact the Environmental Division (TSCA Program) or DPW work Management Branch

#### GENERAL INFORMATION

Activities such as sanding, grinding, drilling, or sawing of asbestos-containing materials or lead-based paint are *not allowed*. Self-Help removal of asbestos-containing tiles is prohibited. Only trained and certified abatement workers may disturb or remove these materials (asbestos, lead).

For additional information contact Environmental Division TSCA.