

ASBESTOS AND LEAD-BASED PAINT

(Building Remodeling/Maintenance/Demolition)

POSSIBLE AREAS OF CONCERN

Asbestos and Lead-based Paint may be found on any building on the installation. There may be increased health risks associated with not following the recommended handling procedures.

CHARACTERIZATION

Asbestos-containing materials are managed as special wastes. Lead-based paint waste is managed as a hazardous waste.

HANDLING PROCEDURES

Step 1 Contact DPW Work Management Branch or Environmental Division TSCA for more info.

To determine if lead-based paint is present, contact Environmental Division TSCA.

Step 2 FMT or a DPW Customer Service Representative will submit work order (DA 4283) to DPW Work Management Branch or call DPW Service Orders to submit a service request.

Step 3 DPW Work Management Branch will review work orders and provide notice to proceed as appropriate.

Step 4 Maintain work order number(s) to monitor status.



Contact the Environmental Division (TSCA Program) or DPW work Management Branch

GENERAL INFORMATION

Activities such as sanding, grinding, drilling, or sawing of asbestos-containing materials or lead-based paint are *not allowed*. Self-Help removal of asbestos-containing tiles is prohibited. Only trained and certified abatement workers may disturb or remove these materials (asbestos, lead).

For additional information contact Environmental Division TSCA.