

SAFETY RECALL MESSAGE

10 September 2025

StopBox USA Recalls AR-15 Chamber Lock Pros Due to Risk of Serious Injury and Death (Recall Alert)

Company Recall Date: 4 September 2025

Recall Number: 25-458

Name of Product: AR-15 Chamber Lock Pro Firearm Locks

Hazard: A manufacturing defect allows the recalled chamber locks to be forcibly removed allowing unauthorized or unintended access to the firearm, posing a risk of serious injury or death.

Consumer Contact: StopBox USA toll-free at [877-919-4637](tel:877-919-4637) from 9 a.m. to 5 p.m. PT Monday through Friday, email at support@stopboxusa.com, online at <https://stopboxusa.com/pages/stopbox-ar-15-chamber-lock-recall> or at <https://stopboxusa.com> and click on “NOTICES / RECALL INFO” at the bottom of the page for more information.

Description: This recall involves certain AR-15 Chamber Lock Pro firearm locks shipped between June 2 and July 15, 2025. Consumers can find their shipping date by contacting StopBox by phone, email, or online at <https://stopboxusa.com/pages/stopbox-ar-15-chamber-lock-recall>. This is a device designed to lock into the chamber of an AR-15 style rifle and prevent it from firing. The product is made of anodized aluminum machined parts, was sold in red and black, and has five buttons that correspond to each finger. It has the StopBox “S” logo and “CHAMBER LOCK PRO AR-15” laser etched on the back of the product.

Remedy: Consumers should immediately stop using the recalled AR-15 Chamber Lock Pro and secure their firearm using other means. Consumers should contact StopBox USA to receive a prepaid return shipping label and instructions to return their recalled AR-15 Chamber Lock Pro for their choice of a full refund or replacement AR-15 Chamber Lock Pro.

Incidents/Injuries: None reported

Sold At: StopBox USA in store and online,
And from dealers nationwide

June 2025 through July 2025 for about \$150.



SAFETY RECALL MESSAGE

10 September 2025

URMYWO Baby Loungers Recalled Due to Risk of Serious Injury or Death from Suffocation and Fall Hazard (Recall Alert)

Company Recall Date: 4 September 2025

Recall Number: 25-456

Name of Product: URMWYO Baby Loungers

Hazard: The baby loungers violate the mandatory standard for Infant Sleep Products because the sides are shorter than the minimum side height limit to secure the infant; the sleeping pad's thickness exceeds the maximum limit, posing a suffocation hazard; and an infant could fall out of an enclosed opening at the foot of the lounger or become entrapped. The portable loungers do not have a stand, posing a fall hazard. These violations create an unsafe sleeping environment for infants, posing a risk of serious injury or death.

Consumer Contact: Pomona via email at urmyworecall@yundnetwork.com.

Description: This recall involves URMWYO baby loungers in the style "grey feather." The baby loungers are made of a gray cloth cover printed with feathers with a foam sleeping pad and padded bumpers. "URMYWO" and "Model No: UMCZC01AE" are printed on labels located on the side of the lounger.

Remedy: Consumers should stop using the baby loungers immediately and contact Pomona for a full refund. Consumers should remove the sleeping pad, cut up the sides of the baby loungers and the sleeping pad and email a photo of the destroyed lounger to urmyworecall@yundnetwork.com to obtain a full refund.

Incidents/Injuries: None reported

Sold At: Amazon from **January 2024 through April 2025** for between **\$30 and \$50**.



SAFETY RECALL MESSAGE

10 September 2025

Makita U.S.A., Recalls Cordless Grease Guns and Grease Gun Hoses Due to Laceration Hazard (Recall Alert)

Company Recall Date: 4 September 2025

Recall Number: 25-455

Name of Product: Makita Professional Cordless Grease Gun and Makita Gun Hoses

Hazard: The flexible grease gun hose can develop a hole allowing grease to be ejected while using the grease gun, posing a laceration hazard.

Consumer Contact: Makita U.S.A., Inc. toll-free at [800-462-5482](tel:800-462-5482) from 8 a.m. to 7:45 p.m. ET, Monday through Friday, or by email at greasegunrecall@makitausa.com.

Consumers may also visit the company's website at www.makitatools.com/recall or go to www.makitatools.com and click on "Important Safety Notice/Recall" located at the top right of the page under "Support" for recall details and additional information.

Description: This recall involves Makita Professional Cordless Grease Guns with model numbers XPG01S1, XPG01SR1 and XPG01Z, and Makita Grease Gun Hoses with model numbers 191A79-9, 191A80-4, 191W59-7 and 191W58-9. All affected models have spring ends. The model number is located on the manufacturer label on the right side of the grease guns. Visit <https://www.cpsc.gov/Recalls/2025/Makita-USA-Inc-Recalls-Cordless-Grease-Guns-and-Grease-Gun-Hoses-Due-to-Laceration-Hazard> to view the ranges of serial numbers are included in this recall. The serial number is located on the battery mounting port on the grease guns.

Remedy: Consumers should immediately stop using the recalled Makita Cordless Grease Guns and Makita Grease Gun Hoses and contact Makita for a free replacement hose.

Incidents/Injuries: The firm has received five reports of incidents worldwide of the grease gun hose failing, including five laceration injuries. All five incidents were reported outside the United States.

Sold At: Hardware and home improvement stores nationwide and on various websites from **June 2020 through January 2025 for between \$60 and \$390.**

