



SAFETY RECALL MESSAGE

19 May 2025



LivingCaring Adult Portable Bed Rails Recalled Due to Risk of Serious Injury or Death (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 25-282

Name of Product: LivingCaring Adult Portable Bed Rails

Hazard: The recalled bed rails violate federal regulations for adult portable bed rails, posing a serious entrapment hazard and risk of death by asphyxiation. When the bed rails are attached to a bed, users can become entrapped within the bed rail or between the bed rail and the side of the mattress. In addition, the bed rails do not bear the required hazard warning labels.


Consumer Contact: Shanghai Kai Rong Xin Xi Ke Ji via email at Jerryhe@sourcing-cn.com.

Description: This recall involves LivingCaring branded adult portable bed rails sold for use on adult beds. The bed support railing has a foldable frame made of white metal and black foam padding on the grip handle. The rails are adjustable with the width between about 29 to 41 inches and the height between about 30 to 37 inches. The bed rail comes with a storage bag and a magnetic motion sensor light.

Remedy: Consumers should immediately stop using the recalled adult portable bed rails. To receive a refund, consumers should send a photo of the disposed bed rail or an Amazon purchase receipt to the recalling firm by email at Jerryhe@sourcing-cn.com. Shanghai Kai Rong Xin Xi Ke Ji Co. Ltd. and Amazon are contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: Online at www.Livingcaring.com and www.Amazon.com from **May 2024 through March 2025 for about \$71.**





SAFETY RECALL MESSAGE

19 May 2025

BuddyLove Recalls Children's Mini Danica Loungewear Due to Risk of Serious Injuries or Death (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-287

Name of Product: Children's Mini Danica Loungewear Sets

Hazard: The recalled children's pajama sets violate flammability standards for children's sleepwear, posing a burn hazard and risk of serious injuries or death to children.

Consumer Contact: BuddyLove toll-free at 866-516-6244 from 9:30 a.m. to 4:30 p.m. CT Monday through Friday, email at Recall@buddylove.com, or online at <https://buddylove.com/pages/recall> or <https://buddylove.com> and click on "Recall" at the top of the page for more information.

Description: This recall involves children's two-piece pajama sets sold in children's sizes 3 to 12.

The pajama set consists of a long-sleeved, button-up top and matching pants. They have detachable feathers on the wrist and ankle, two front shirt pockets, and buttons down the center seam of the shirt. Styles include BK1105 (Sugar Berry), BK1106 (Tartan), BK1107 (Frostbite), BK1108 (Kris Kringle) and BK1109 (Prowl). The size and "BuddyLove" are printed on the neck label. The side seam label displays 100% Polyester fiber content, washing instructions, the Style # and "Made in China".

Remedy: Consumers should stop using the recalled pajamas immediately and contact BuddyLove for information on how to dispose of the product to obtain a full refund or store credit for the original purchase price. Consumers should destroy the garments by cutting them in half and email a photo of the destroyed garment to Recall@buddylove.com. Upon receipt of the photo, consumers will be issued a full refund of the purchase price. BuddyLove is contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: BuddyLove and other boutique clothing stores nationwide and online at <https://Buddylove.com> from **October 2023 through July 2024 for about \$95.**





SAFETY RECALL MESSAGE

19 May 2025



Child Safety Gates Recalled Due to Risk of Serious Injury or Death from Entrapment (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-286

Name of Product: Child Safety Gates

Hazard: The recalled child safety gates violate the federal safety regulation for expansion gates and expandable enclosures because a child's torso can fit through the opening between the gate slat and side wall, a child's torso can fit through the secondary opening, the locking mechanism does not fully engage and/or the gate does not resist a push-out force. These failures pose a risk of serious injury or death due to entrapment and fall hazards.



Consumer Contact: Third-party seller's email. (Specific email addresses are provided at <https://www.cpsc.gov>)

Description: This recall involves multiple child safety gates sold by five different third-party sellers on Amazon.com. The gates have model numbers and cohort information listed on their tracking label, located on the bottom rail. The gates are all made of steel and ABS plastic and were sold in white and black colors. They can be pressure-mounted and/or drill-mounted and vary in several sizes. Some gates have a secondary pet door.

Remedy: Consumers should stop using the recalled gates immediately and contact the third-party seller by email for information on how to dispose of the product and submit proof of destruction to obtain a full refund. The third-party sellers and Amazon are contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: Amazon.com from **June 2021 through March 2025 for between \$67 and \$200.**





SAFETY RECALL MESSAGE

19 May 2025



FidgetThings Recalls Chill Pill Magnetic Haptic Fidget Toys Due to Risk of Serious Injury or Death from Ingestion (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-285

Name of Product: Chill Pill Magnetic Haptic Fidget Toys Red Bumpy

Hazard: The recalled magnetic fidget pill toy violates the mandatory federal regulation for magnets, posing an ingestion hazard to children. When high-powered magnets are swallowed, the ingested magnets can attract each other, or another metal object, and become lodged in the digestive system. This can result in perforations, twisting and/or blockage of the intestines, infection, blood poisoning and death.

Consumer Contact: FidgetThings via email at fidgetthings@gmail.com or online at www.fidgetthings.com/pages/magnet-safety or www.fidgetthings.com and click on "Magnet Safety" at the bottom of the page for more information.

Description: This recall involves FidgetThings Chill Pill Magnetic Haptic Fidget Toys Red Bumpy. The magnetic fidget pill toy is in the shape of a pill capsule that can be separated into two magnetic halves. One magnetic half is the white base and the other magnetic half is red and bumpy. The magnets are interchangeable with other FidgetThings magnetic fidget pill toys of different colors and textures. The magnetic fidget pill toy was sold encased in a mock prescription bottle with a mock label. The magnets make a clacking sound when brought together. The magnetic fidget pill toy measures about two inches and the mock prescription bottle measures about 3 inches. The mock prescription bottle has "3DPrint Bumpy" printed on the label.

Remedy: Consumers should stop using the magnetic fidget pill toys immediately and take them away from children. Contact FidgetThings via email at fidgetthings@gmail.com to receive a pre-paid label to return the toy, or for instructions on how to dispose of the toy, to receive a full refund. FidgetThings is notifying all known purchasers directly.

Incidents/Injuries: None reported

Sold At: Exclusively online at www.FidgetThings.com from **October 2022 through February 2025 for about \$10.**





SAFETY RECALL MESSAGE

19 May 2025



Polaris Recalls Ranger Recreational Off-Road Vehicles Due to Injury Hazard (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-284

Name of Product: Model Year 2023-2025 Ranger XP 1000 NorthStar and Ranger XP 1000 NorthStar Crew Recreational Off-Road Vehicles (ROVs)

Hazard: The lower seat belt anchor fasteners were not properly tightened, which can result in the seat belt separating from the vehicle frame, failing to protect riders. Without that protection, riders can be ejected from the vehicle in a crash, posing an injury hazard.

Consumer Contact: Polaris Industries at 800-765-2747 from 7 a.m. to 7 p.m. CT Monday through Friday, online at www.polaris.com and click on "Product Safety News" located under the "Safety" column at the bottom of the page, or <https://www.polaris.com/en-us/recalls/off-road/polaris-recalls-some-model-year-2022-2025-rzr-pro-r-and-rzr-pro-4-vehicles/> or <https://www.polaris.com/en-us/recalls/> to check if your vehicle identification number (VIN) is included in any recalls. Consumers can contact Polaris' owner connections team at Owner.Connections@polaris.com or via an online forum accessible at <https://www.polaris.com/en-us/off-road/owner-resources/help-center/email>.

Description: This recall involves certain VINs of Polaris Model Year 2023-2025 Ranger XP 1000 NorthStar and Ranger XP 1000 NorthStar Crew ROVs. The recalled vehicles were sold in black, blue, brown, camouflage, gray, orange, red, tan and white. The vehicles were sold in three and six-seat configurations and have "POLARIS" stamped on the front grille. The VIN is printed on the left rear frame (on the driver's side of the vehicle) under the cargo box.

Remedy: Consumers should immediately stop using the recalled ROVs and contact an authorized Polaris dealer to schedule a free inspection and repair at the dealer's location. Polaris advises that consumers may continue to operate the recalled ROVs prior to inspection and repair at the dealer, only if they conduct an inspection by following the Seat Belt Fastener Verification Instructions located on the firm's website. To continue operating the recalled ROVs prior to getting the repair, the fasteners must be secure where the seat belt anchor is attached to the vehicle frame. Polaris has contacted registered owners directly.

Incidents/Injuries: The firm has identified two vehicles with loose seat belt fasteners. No injuries have been reported.

Sold At: Polaris dealers nationwide from **August 2022 through March 2025 for between \$28,000 and \$38,000.**





SAFETY RECALL MESSAGE

19 May 2025



Fat Brain Recalls Rollers Tile Toys Due to Magnet Ingestion Hazard (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-281

Name of Product: PlayTab Rollers Tile Toys

Hazard: The recalled rollers tile toy violates the mandatory federal regulation for toy magnets because it contains a magnet that can become loose, posing an ingestion hazard to children. When high-powered magnets are swallowed, the ingested magnets can attract each other, or other metal objects, and become lodged in the digestive system. This can result in perforations, twisting, and/or blockage of the intestines, infection, blood poisoning, and death.

Consumer Contact: Fat Brain Toy Co. at 800-590-5987 from 8 a.m. to 5 p.m. CT Monday through Friday, email at recall@fatbraintoys.com, or online at https://fatbraintoys.com/info/toy_safety/play_tab_roller_tile_recall.cfm or fatbraintoys.com and click "Recall" at the top of the page for more information.

Description: This recall involves individual PlayTab Rollers Tile toys sold for use with the PlayTab Modular Activity Board. The rollers tile was sold individually or also as a set of three with the PlayTab Sensory Set 3. The tile has blue, red and green rubberized and textured rollers that are designed for children to touch and spin.

Remedy: Consumers should stop using the rollers tile toys immediately and contact the firm for instructions on how to dispose of the product to obtain a \$10 credit for use at fatbraintoys.com, or a replacement PlayTab tile. Fat Brain Toy Co. is contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: Specialty toy, book and educational stores nationwide and online at fatbraintoys.com from **July 2024 through November 2024**. The individual roller tiles sold for about \$6. The Sensory Set 3 sold for about \$18.





SAFETY RECALL MESSAGE

19 May 2025



KTM Recalls Off-Road Motorcycles Due to Crash Hazard (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-283

Name of Product: GASGAS and Husqvarna Off-Road Motorcycles

Hazard: The front brake caliper can crack, reducing the braking system's effectiveness, posing a crash hazard.

Consumer Contact: GASGAS and Husqvarna Motorcycles toll-free at 888-985-6090 from 8 a.m. to 5 p.m. ET Monday through Friday, or online at <https://www.gasgas.com/en-us.html> or <https://www.husqvarna-motorcycles.com/en-us.html> and click on "Safety Recall Information" located at the bottom of the page. Consumers can check the vehicle identification number or VIN at <https://www.husqvarna-motorcycles.com/en-us/service/Service-and-safety-check.html> or <https://www.gasgas.com/en-us/service/service-and-safety-check.html> to determine if their unit is affected.

Description: This recall involves model years 2022, 2023, 2024 and 2025 Off-Road Motorcycles. The GASGAS off-road motorcycles are red with the white GASGAS logo on both sides of the shrouds. The Husqvarna motorcycles are white, blue and yellow with the Husqvarna logo on both sides of the shrouds.

The 2022 model year recalled motorcycles have the letter N in the 10th position of the vehicle identification number (VIN).

The 2023 model year recalled motorcycles have the letter P in the 10th position of the vehicle identification number (VIN).

The 2024 model year recalled motorcycles have the letter R in the 10th position of the vehicle identification number (VIN).

The 2025 model year recalled motorcycles have the letter S in the 10th position of the vehicle identification number (VIN).

The VIN number is located on the right side of the steering head.

Remedy: Consumers should immediately stop riding the recalled motorcycles and contact an authorized GASGAS Motorcycles or Husqvarna Motorcycles dealer to schedule a free inspection and free repair at the dealership. It is necessary to have the front brake caliper inspected by an authorized dealer to determine if it is defective or not defective. KTM/GASGAS and Husqvarna Mobility are contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: GASGAS and Husqvarna authorized dealers nationwide from **January 2022 through August 2024** for between **\$10,000 and \$13,000**.





SAFETY RECALL MESSAGE

19 May 2025



Leon Rading Recalls Digital Wall Clocks Due to Risk of Injury or Death from Ingestion Hazard (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-280

Name of Product: Digital Wall Clocks

Hazard: The recalled digital wall clocks violate the mandatory federal regulations for consumer products containing button cell or coin batteries. The remote control for the clock has a lithium coin battery that can be easily accessed by children, posing an ingestion hazard. In addition, the recalled products do not have the warnings required under Reese's Law. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death.

Consumer Contact: Leon Rading by email at recall@lianaocoltd.com.

Description: This recall involves digital wall clocks with model number PH-05. The digital wall clocks are rectangular and black in color. A yellow label on the rear of the clock states "Contact for warranty! support@te-rich.com." The clocks come with a black nine-button remote control. "MODEL: PH-05" is printed on the white product packaging.

Remedy: Consumers should immediately stop using the recalled digital wall clock's remote control, remove the lithium coin battery from the remote and dispose of or recycle it in accordance with local hazardous waste procedures. Consumers should write "RECALLED" in permanent marker on the remote and then email a photo of the remote being disposed of in the trash to recall@lianaocoltd.com to receive a full refund for the recalled digital clock. Leon Rading and Amazon are contacting all known purchasers directly.

Incidents/Injuries: None reported

Sold At: Exclusively at [www.Amazon.com](https://www.amazon.com) from **November 2024 through January 2025 for about \$33.**





SAFETY RECALL MESSAGE

19 May 2025



NICREW Submersible RGB LED Lights Recalled Due to Risk of Serious Injury or Death (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-279

Name of Product: NICREW 15" Submersible RGB LED Lights with remote controls

Hazard: The Submersible RGB LED Light's remote control has a lithium coin battery that can be easily accessed by children, posing an ingestion hazard. This violates the mandatory federal regulations for consumer products containing button cell or coin batteries. In addition, the recalled products do not have the required warnings. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death.

Consumer Contact: Nicrew at nicrew@support.com, or online at www.nicrew.com/n21743-recall/ or www.nicrew.com and click on Product Recalls at the bottom of the page for more information.

Description: This recall involves NICREW Submersible RGB LED Lights with model number N21743. The lights were sold in a 15-inch black tube and have a black remote control with 21 buttons and a CR2032 lithium coin battery.

Remedy: Consumers should immediately stop using the recalled product, remove the battery from the remote control and place it in an area that children cannot access. Contact Nicrew for a free replacement of the remote and information on how to properly dispose of the product. Consumers need to email the Amazon order number and a photo showing the remote was destroyed by the consumer to nicrew@support.com to obtain the replacement. Nicrew and Amazon are contacting all known purchasers directly.

Note: Button cell and coin batteries are hazardous. These batteries should be disposed of or recycled by following local hazardous waste procedures.

Incidents/Injuries: None reported

Sold At: Online at www.Amazon.com from May 2024 through August 2024 for about \$17.





SAFETY RECALL MESSAGE

19 May 2025



Boyro Baby Recalls Highchairs Due to Risk of Serious Injury or Death from Fall and Entrapment Hazards (Recall Alert)

Company Recall Date: 15 May 2025

Recall Number: 23-278

Name of Product: Boyro Baby Convertible High Chairs

Hazard: The highchairs pose a deadly fall hazard to babies because the restraint system is not attached to the product and the locks or latches can fail. In addition, the highchairs pose an entrapment hazard because the opening between the seat and tray is large enough that a child can become entrapped in it. These are violations of the federal regulations for highchairs.

Consumer Contact: Boyro Baby by email at boyrobaby@outlook.com, or online at www.boyrobaby.com/testimonial or www.boyrobaby.com and click on "Safety Recalls" for more information.

Description: This recall involves Boyro Baby-branded highchairs. The 4-in-1 highchairs were sold in green, gray and pink and have a removable seat cushion, a detachable tray, a footrest and storage space underneath the seat. They convert from a highchair into a low chair, rocking chair and slide.

Remedy: Consumers should stop using and disassemble the recalled highchairs immediately and contact Boyro Baby for instructions on receiving a full refund. The instructions will include instructions on cutting the restraint system and seat cushions, and emailing photos of the disassembled and destroyed pieces of the highchair to boyrobaby@outlook.com. Once the photos have been received, Boyro Baby will issue a refund.

Incidents/Injuries: None reported

Sold At: Exclusively online at Amazon.com from **October 2023 through November 2024** for between \$70 and \$90.

