



**DEPARTMENT OF THE ARMY**  
US ARMY INSTALLATION MANAGEMENT COMMAND  
HEADQUARTERS, UNITED STATES ARMY GARRISON, FORT GREGG-ADAMS  
3312 A AVENUE, SUITE 208  
FORT GREGG-ADAMS VA 23801

AMIM-GAG-ZA

MEMORANDUM FOR RECORD

SUBJECT: United States Army Garrison Fort Gregg-Adams, Directorate of Public Works, Standard Operating Procedures for Mold Identification and Retention

1. References.

- a. Headquarters Department of the Army (HQDA) Execution Order (EXORD) 030-23: Improving COMPO 01 Army Readiness Facilities, 07 Oct 22
- b. HQDA EXORD 273-20: Ten Year Facility Investment Planning, 20 Nov 20
- c. Secretary of the Army-Chief of Staff of the Army (SECARMY-CSA) Memorandum: Facility Investment Priorities for the US Army, 16 Sep 20
- d. Army Regulation (AR) 210-20, (Real Property Master Planning for Army Installations), 16 May 05
- e. AR 600-20 (Army Command Policy), 24 Jul 20
- f. Installation Management Command (IMCOM) Warning Order (WARNO) 01 to Operations Order (OPORD) 23-007: IMCOM FY23 Operation Counter Mold, 16 Nov 22
- g. Army Barracks Management Program (ABMP) Handbook V2, 12 Jan 21
- h. U.S. Army Public Health Center Technical Guide (TG) 277, (Industrial Hygiene Public Health: Army Mold Remediation Guidance), Feb 19
- i. U.S. Army Public Health Center Technical Guide (TG) 278, (Industrial Hygiene)
- j. Health: Mold Assessment Guide, Oct 18

2. Purpose.

- a. This SOP prescribes policy and procedures for the prevention, identification, and remediation of building materials contaminated with mold.

AMIM-GAG-ZA

SUBJECT: United States Army Garrison Fort Gregg-Adams, Directorate of Public Works, Standard Operating Procedures for Mold Identification and Retention

3. Overview.

- a. Army leaders continue to inspect Army maintained barracks, housing, and facilities for mold, unhealthy, and unsafe, living conditions. Data collected from recent inspections provides the Army valuable information to understand the level of mold contamination in our facilities.
- b. A proactive response is critical in preventing and eliminating the growth of mold. All mold remediation be conducted as safely and quickly as possible.

4. USAG DPW point of contact is Mr. Allen Mills, Supervisor Environmental Protection Specialist at 804-734-3560, james.a.mills80.civ@army.mil.

HOYMAN.JAMES.D  
AVID [REDACTED] Digitally signed by  
HOYMAN.JAMES.DAVID [REDACTED]  
Date: 2023.06.13 17:57:35 -04'00'

JAMES D. HOYMAN  
COL, EN  
Commanding