

CUSTOMER RESPONSIBILITIES FOR DEVICE CUTAWAY REQUEST:

Before bringing your device to the Fabrication Shop please complete the following:

1. Drain all fluids and any hazardous materials
2. Release all pressures and springs from device
3. Loosen and finger tighten all bolts and screws in the area that you would like displayed
4. Make sure that the area to be cut is properly marked with a black marker so that it can be easily seen and in order to achieve a clean functional cut

Mounting:

Most device cutaways are mounted on a frame and stand for display, customer may suggest frame height required.