



Fort Wainwright, Alaska

USAG ALASKA INSTALLATION SAFETY OFFICE

SAFETY ALERT



Polaris Recalls Ranger Recreational Off-Highway Vehicles and ProXD Utility Vehicles Due to Crash Hazard (Recall Alert)

Name of product: Model Year 2020-2021 RANGER 1000, RANGER CREW 1000, RANGER XP 1000, and RANGER CREW XP 1000 and Model Year 2020 ProXD 2000G, ProXD 2000G H, ProXD 4000G, and ProXD 4000G H

Hazard: The throttle pedal can return to the idle position more slowly than anticipated once the pedal is released or stick in the depressed position, posing a crash hazard.

Remedy: Repair

Recall date: March 4, 2021

Units: About 15,800 (In addition, 711 units were sold in Canada)

Consumer Contact:

Polaris at 800-765-2747 from 7 a.m. to 7 p.m. CT Monday through Friday or online at www.polaris.com and click on "Off Road Safety Recalls" or <https://www.polaris.com/en-us/off-road-recalls/> to check your vehicle identification number "VIN" or go to "Product Safety Recalls" page to see if your vehicle is included in any recalls or online at <https://www.polaris.com/en-us/recalls/off-road/>.

Recall Details

Description: This recall involves Model Year 2020-2021 RANGER 1000, RANGER CREW 1000, RANGER XP 1000, and RANGER CREW XP 1000 recreational off-highway vehicles and Model Year 2020 ProXD 2000G, ProXD 2000G H, ProXD 4000G, and ProXD 4000G H off-road utility vehicles. The vehicles were sold in the following colors: black, blue, burgundy, camo, gray, green, orange, red, sand, tan, titanium, and white. The RANGER vehicles have three or six seats and the ProXD vehicles have two or four seats. The RANGER and ProXD vehicles have "POLARIS" stamped on the front grille. The model number and VIN are printed on a portion of the left rear frame (on the driver's side of the vehicle) under the cargo box.

Remedy: Consumers should immediately stop using the recalled vehicles and contact a Polaris dealer to schedule a free repair. Polaris is notifying all dealers and contacting registered owners directly.

Incidents/Injuries: The firm has received 52 reports of throttle pedals returning to the idle position slowly or sticking, including six reports of vehicle crashes resulting in minor property damage. No injuries have been reported.

Sold At: Polaris dealers nationwide from April 2020 through January 2021 for between \$13,000 and \$31,000.

Manufacturer(s): Polaris Inc., of Medina, Minn.

Manufactured In: United States and Mexico

Recall number: 21-724

For more information contact the Installation Safety Office 353-7085/7083/7087 or visit



United States
CONSUMER PRODUCT SAFETY COMMISSION

<https://www.cpsc.gov/recalls>



Recalled Model Year 2020 Ranger 1000



Recalled Model Year 2020 Ranger CREW 1000



Recalled Model Year 2020 RANGER XP 1000



Recalled Model Year 2020 RANGER CREW XP 1000



Recalled Model Year 2021 Ranger 1000



Recalled Model Year 2021 Ranger CREW 1000



Recalled Model Year 2021 RANGER XP 1000



Recalled Model Year 2021 RANGER CREW XP 1000



Recalled Model Year 2020 ProXD 2000G and 2000G H



Recalled Model Year 2020 ProXD 4000G and 4000G H