



DEPARTMENT OF THE ARMY
INSTALLATION MANAGEMENT COMMAND PACIFIC
HEADQUARTERS, UNITED STATES ARMY GARRISON DAEGU
UNIT #15746
APO AP 96218-5746

IMDA-ESF

21 January 2020

MEMORANDUM FOR All USAG Daegu Units/Organizations

SUBJECT: Area IV Fire Extinguisher servicing and replacement

1. This memorandum provides all tenant units and organizations with information on servicing and replacement of fire extinguishers.
2. The USAG Daegu Fire Department will provide annual inspections of all facility fire extinguishers, each unit facility manager is responsible for ensuring serviceability and monthly fire extinguisher inspections. All replacement and servicing costs are the responsibility of each tenant unit and organization. The USAG Daegu Fire & Emergency Services is not funded, nor authorized to provide replacement fire extinguishers.
3. Fire Extinguishers require hydrostatic testing every 12 years. The only Department of Transportation (DOT) approved hydrostatic testing facility in Korea is the Sin Yang Oxygen Company in Seoul. Due to the service cost, USAG Daegu recommends to replace extinguishers as needed or when hydrostatic testing is required.
4. Recommended local vendors for Factory Mutual (FM) and Underwriters Laboratory (UL) approved fire extinguishers are below:
 - a. Osan GSA Store, email: osan.servmart@gsa.gov DSN: 784-8599 or +82-31-661-8599
 - b. Osan Grainger Store, DSN: 784-1682
 - c. Woojin High Tech Co LTD, Chungcheong Nam-Do, +82-41-556-0118 (AMEREX Extinguisher)
 - d. K&A Trading Corp, Ulsan City, +82-52-269-5119 (AMEREX Extinguisher)
5. The point of contact for this memorandum is Mr. Sin, Ik Chu, Assistant Prevention Chief, USAG Daegu, DSN: 763-4703 or Cell: 010-5054-1970 or email: ikchu.sin.in@mail.mil.

A handwritten signature in black ink, appearing to read "MICHAEL P. DIEHL", is written over a horizontal line.

MICHAEL P. DIEHL
Chief, Fire & Emergency Services
USAG Daegu