Lulive Recalls Dressers Due to Risk of Serious Injury or Death from Tip-Over and Entrapment (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-447

Name of Product: Lulive 12-Drawer Dressers

Hazard: The recalled dressers are unstable if they are not anchored to the wall, posing serious tipover and entrapment hazards that can result in injuries or death to children. The dressers violate the mandatory standard required by the STURDY Act.

Consumer Contact: Lulive toll-free at 866-610-4348 from 9 a.m. to 4:30 p.m. PT Monday through Friday, email at lulive12recall@sina.com or online https://lulive.com/pages/recalls or at https://lulive.com and click "Recall" at the top of the page for more information.

Description: This recall involves Lulive 12-drawer dressers. The recalled dressers were sold in white and have a metal frame and wooden top, 12 collapsing fabric drawers of different sizes with handles, four side-pockets, and two hooks. The dressers measure about 12 inches by 39 inches by 45 inches and weigh 30 pounds. "KF-X9Y1" is printed on the product packaging.

Remedy: Consumers should stop using the recalled dressers immediately if they are not anchored to the wall and place them in an area that children cannot access. Consumers can contact Lulive for instructions on how to dispose of the dressers to receive a full refund. Consumers must submit a photo to lulive12recall@sina.com of the product demonstrating disposal.

Incidents/Injuries: None reported

Sold At: Amazon from March 2025 through June 2025 for between \$90 and \$100.

DT Swiss Recalls Carbon Wheels Due to Crash Hazard (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-445

Name of Product: DT Swiss Carbon Fiber Road Wheels

Hazard: A defect in the wheel can compromise the wheel's structural integrity, posing a crash hazard.

Consumer Contact: DT Swiss toll-free at 800-000-1994 from 8:30 a.m. to 3:30 p.m. MT Monday through Friday, email at Recall@dtswiss.com, or online at https://www.dtswiss.com/recall or www.dtswiss.com and click on "Recall" at the bottom of the page for more information.

Description: This recall involves DT Swiss Carbon Fiber Road Wheels. The wheels have model codes ERC 35mm/45mm, CRC 35mm/45mm, and ARC 50mm/55mm/65mm. These wheels were sold aftermarket and as original equipment on various high-end road bicycle brands. The DT Swiss ID code and the model code are located on the wheel rim on a small label located on the outside of the rim, which indicates "DT Swiss ID" followed by a 7-digit code. All wheels with DT Swiss ID code 2740000 or higher are affected by this recall.

Remedy: Consumers should stop using the recalled wheels and contact DT Swiss to coordinate a replacement. Consumers should register the recalled wheels with DT Swiss at www.dtswiss.com/recall.

Incidents/Injuries: The firm has received six reports of the outermost carbon layer separating around the rim flange. No injuries have been reported.

Sold At: Independent bicycle dealers nationwide and sold as original equipment on various bicycle brands from **September 2024 to July 2025 for between \$1,000 and \$1,880**.

C.A.M.P. Recalls Nimbus Lock Carabiners Due to Risk of Serious Injury or Death from Fall (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-444

Name of Product: Nimbus Lock Carabiners

Hazard: The carabiner's automatic closing mechanism can break and prevent the gate from closing, posing a risk of serious injury or death due to falling.

Consumer Contact: C.A.M.P. toll free at <u>877-421-2267</u> from 9 a.m. to 5 p.m. PT Monday through Friday, email at <u>warranties@campusa.com</u>, or online at <u>www.camp-usa.com/nimbus-lock-safety-recall-information</u> or <u>www.camp-usa.com</u> and click on "Safety Recalls" at the bottom of the page.

Description: This recall involves Nimbus Lock Carabiners sold in Gun Metal/Green, Gun Metal/Fuchsia and Gun Metal/Blue. The affected carabiners were sold individually or as part of the Nimbus Lock 3 Pack, the Locker Draw KS, the Energy CR3 Pack and the Energy Nova Pack. Only the carabiners are included in this recall. The affected carabiners have the following batch numbers 10 23, 12 23, 02 24, 09 24, 10 24, 12 24, 01 25, 02 25 and 06 25. The batch number is found on the side of the bottom of the carabiner.

Remedy: Consumers should immediately stop using the recalled Nimbus Lock Carabiners and contact C.A.M.P. Consumers will be asked to fill out the recall form at www.camp-usa.com/nimbus-lock-safety-recall-registration-form, print a prepaid return shipping label and return the recalled product. C.A.M.P will inspect returned units and ship them back to consumers, if they pass inspection. Any units that do not pass inspection will be replaced free of charge.

Incidents/Injuries: The firm has received 21 reports of the closing mechanism breaking. No injuries have been reported.

Sold At: REI, Portland Mountain Shop, How Not 2 and other stores nationwide and online at Camp-usa.com, Backcountry.com, Amazon.com, REI.com, Moutainshop.net, Hownot2.com and other websites from **January 2024 through July 2025 for between \$16 and \$86.**

TTI Outdoor Power Equipment Recalls RYOBI Pressure Washers Due to Projectile Hazard (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-452

Name of Product: RYOBI Electric Pressure Washers

Hazard: The pressure washer's capacitor can overheat and burst, causing parts to be forcefully ejected, posing a risk of serious injury from impact to the user and bystanders.

Consumer Contact: TTI Outdoor Power Equipment toll-free at 800-597-9624 from 9 a.m. to 5 p.m. ET Monday through Friday or online at https://www.ryobitools.com/recall or https://www.ryobitools.com/ and click on "Important Recall Information" at the bottom of the page for more information.

Description: This recall involves Ryobi brushless electric pressure washers, models RY142300 and RY142711VNM. The recalled pressure washers are green and have a spray nozzle, a detergent tank with a blue cap and storage for accessories. Ryobi is printed on the front of the unit. The model and following serial numbers can be found on the data plate located on the side of the motor housing. Please visit https://www.cpsc.gov/Recalls/2025/TTI-Outdoor-Power-Equipment-Recalls-RYOBI-Pressure-Washers-Due-to-Projectile-Hazard-Risk-of-Serious-Injury for a complete list of Model Number/Name and Serial Number Range.

Remedy: Consumers should immediately stop using the recalled pressure washers and visit https://www.ryobitools.com/recall to determine if their pressure washer is included in the recall and to receive a free repair kit, including shipping and installation instructions. The repair kit consists of a replacement capacitor. Proof of purchase (receipt) is not required.

Incidents/Injuries: TTI Outdoor Power Equipment has received 135 reports of capacitors overheating, including 41 reports of explosions, resulting in 32 injuries and/or fractures to the fingers, hands, face, and eyes.

Sold At: Home Depot and Direct Tools Factory Outlet stores nationwide, and online at homedepot.com and directtoolsoutlet.com from **July 2017 through June 2024 for between approximately \$300 and \$400.**

Electric Motors for Gable and Roof Mounted Attic Fans Recalled Due to Fire Hazard (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-451

Name of Product: Electric motors for gable- and roof-mounted attic fans

Hazard: The recalled electric motor's safety cutoff may pose a risk of short circuit and fire hazard while in use.

Consumer Contact: Air Vent toll-free at <u>877-247-4878</u> from 8 a.m. to 5 p.m. ET, Monday through Friday, or online at <u>https://powermaxmotorrecall.expertinquiry.com</u> or at <u>https://gibraltarbuildingproducts.com/ventilation-category/</u> and click on "Important Safety Information" for more information.

Description: This recall involves electric motors used in gable- and roof-mounted attic fans sold only from August 2003 through December 2013 with model numbers: DOW-136-0-34-XIN, DOW-136-0-26-XIN, DOW-136-0-40-XIN, DOW-136-0-40-XIN-3/4", and D-RE-PSC-127/20-4P1SP. The recalled attic fan motors can be identified by the distinctive vent pattern on the motor end bells. Only attic fan motors with the distinctive vent pattern on the motor end bells are subject to the recall.

Remedy: Consumers should immediately stop using the recalled electric motors and contact Air Vent for a refund. Consumers will be asked to fill out the online registration and verification form with photos of the recalled attic fan motor. Upon confirmation that the consumer has a recalled attic fan motor, the consumer will receive a refund.

Incidents/Injuries: The firm has received 159 reports of incidents related to the recalled attic fan motors involving burning or fire. No injuries have been reported.

Sold At: Various stores and wholesalers nationwide, including ABC Supply, Lowe's, and Beacon, in-store and online from August 2003

through December 2013 for between about \$74 and \$92.





Party Favors Lite-Up Torches and Laser Pointers Recalled Due to Risk of Serious Injury or Death from Battery Ingestion (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-450

Name of Product: Party Favors Lite-Up Torches and Mini Laser Pointers

Hazard: The recalled lite-up torches contain button cell batteries in violation of the mandatory standard for toys and the recalled mini laser pointers contain button cell batteries in violation of the mandatory standard for consumer products because the button cell batteries can be accessed easily by children. Additionally, the laser pointers do not have the warnings required under Reese's Law. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns, and death.

Consumer Contact: MTC Trading at <u>650-866-4800</u> from 9 a.m. to 5 p.m. PT Monday through Friday, email at <u>mtcmans@gmail.com</u>, or online at <u>www.mtcmans.com/recall</u> or <u>www.mtcmans.com</u> and click "Recall" for more information.

Description: This recall involves Party Favors lite-up torches and mini laser pointers. The affected models are: Model PF-1082: A single lite-up torch sold in white, blue or orange, measuring about 5 inches long and 2 inches wide. Model PF-1227: A two-pack of lite-up torches sold in orange and green, measuring about 4 inches long and an inch wide. Model PF-1153: A three-pack of lite-up torches sold in orange, blue and green, measuring about 3 inches long and an inch wide. Model PF-1084: Mini laser pointers sold in blue, green, red and silver, measuring about 3 inches long and an inch wide. All products come with pre-installed button cell batteries. The model number can be found printed on the hang tag.

Remedy: Consumers should immediately stop using the Lite-Up Torches and Mini Laser Pointers, take them away from children and place them where children cannot access them. Consumers may contact MTC Trading to request a full refund. Consumers will need to email a photograph confirming disposal of the lite-up torches or mini laser pointers to mtcmans@gmail.com to receive the refund.

Incidents/Injuries: None reported

Sold At: All Star Toys, Brooklyn, NY; Home Bargain, San Francisco, CA; One Dollar Only, San Francisco, CA; Almacenes Colon, Carolina, PR; Dollar Mart, Houston, TX; and various stores nationwide from **June 2024 through May 2025 for about \$1.**





CT-ENERGY Lithium Coin Battery Chargers Recalled Due to Risk of Serious Injury or Death from Battery Ingestion (Recall Alert)

Company Recall Date: 28 August 2025

Recall Number: 25-449

Name of Product: CT-ENERGY Lithium Coin Battery Chargers with Rechargeable 2032 Batteries

Hazard: The recalled battery charger violates the mandatory standard for consumer products containing button cell or coin battery because the charger has lithium coin batteries that can be accessed easily by children. In addition, the coin batteries provided with the battery charger are not in child-resistant packaging, and the packaging does not have the warnings as required by Reese's Law. When button cell or coin batteries are swallowed, the ingested batteries can cause serious injuries, internal chemical burns and death.

Consumer Contact: CT New Energy Technology by email at info@ct-energy.cn, or online at www.ct-energy.cn/about/22.html?land=enus or www.ct-energy.cn and click "Urgent Product Safety Recall Notice" at the top of the page for more information.

Description: This recall involves CT-ENERGY Lithium Coin Battery Chargers with model number "nc-02". The product includes the charger, four rechargeable 2032 lithium-ion batteries, and a USB cable. The brand name "CT-ENERGY" is on the front of the product and the model number "nc-02" is printed on the back.

Remedy: Consumers should immediately stop using the charger and remove the batteries and place them in an area that children cannot access. Contact CT New Energy Technology for a full refund, Child-Resistant Safety Case, or replacement kit. The complimentary repair kits and replacement kits will be available after August 30, 2025. Consumers will be asked to submit photos of the batteries' destruction completely submerged in tap water to info@ct-energy.cn. Soaking the batteries in water for 24 hours discharges the battery.

Incidents/Injuries: None reported

Sold At: Amazon.com and Walmart.com from March 2024 through May 2025 for about \$17.

