

DIG PERMIT/UTILITY LOCATE

AR 420-1



**Know what's below.
Call before you dig.**

Possible areas of concern and characterization

Failure to locate underground utilities (water/sewer, electric, gas, phone, steam/chill water, control cables, petroleum/POL, cable TV) and environmental/historical sensitive areas archeological sites, former solid waste disposal sites) can cause dangerous situations to personnel and the environment. Additional information can be found in Army Regulation AR 420-1. Utility Locations are required before any digging, excavation, or earthwork is performed within the cantonment or training areas. All utilities must be properly marked. Digging may create erosion issues. This applies to all organizations performing excavation of soil on Fort Knox.

HANDLING PROCEDURES

Step 1 Contact the EMD NEPA Manager at 502-624-5174, 10-15 days prior to starting work.

Step 2 CALL 811 or 800-752-6007. Requests MUST be initiated within 10 working days before excavation is to begin.

Step 3 Call DPW at 502-624-1171 for gas, water, or sewer connects.

Step 4 In addition you must call:

- *Natural Gas* - 502-624-5954 for gas lines
- *NEC* at 502-624-3338 for post telephone lines
- *Cultural Resources (Historical)* at 502-624-6581
- *Restoration* at 502-624-1929/8537
- *Meade County RECC* Electric Lines at 270-422-2162
- *Natural Resources (Forestry)* at 502-624-7368/4500
- *Range Control (Training Areas)* at 502-624-3536

NOTES

- Drums shall be stored inside a building hazmat shed or under cover to prevent the collection of rainwater in the containment system and IAW the chemical Safety Data Sheet.

CONTACT INFORMATION

502-624-5174/3629