



DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI - Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5/12/21	Start Time 7:30	End Time 1730
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

Near Misses / Incidents / Special Topics

None

Chemical Hazards

None

Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

Special Equipment / Techniques

Backhoe

Hospital Name / Address

The Hospitals of Providence Northeast Campus

[Redacted Address]

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

ATTENDEES

Name	Signature	Company
------	-----------	---------

[Redacted Name]	[Redacted Signature]	[Redacted Company]
-----------------	----------------------	--------------------

[REDACTED]

DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012	
	Task Order W912BV20F0183	
Date: 5/13/21	Start Time 0800	End Time 1830
Site Location: El Paso, Texas	Site Safety Officer: [REDACTED]	

Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling;
Surveying trench locations

Near Misses / Incidents / Special Topics

None

Chemical Hazards

None

Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather;
geotechnical sampling, encountering asbestos and medical waste

Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters
when backing vehicles, check weather forecast at the start of the day, buddy system

Special Equipment / Techniques

Backhoe

Hospital Name / Address

The Hospitals of Providence Northeast Campus

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

ATTENDEES

Name	Signature	Company
------	-----------	---------

[REDACTED]	[REDACTED]	[REDACTED]
------------	------------	------------



DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-17-21	Start Time 0700	End Time 1600
Site Location: El Paso, Texas	Site Safety Officer:	

Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

Near Misses / Incidents / Special Topics

None

Chemical Hazards

None

Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

Special Equipment / Techniques

Excavator

Hospital Name / Address

The Hospitals of Providence Northeast Campus



Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

ATTENDEES

Name	Signature	Company
------	-----------	---------



✓



DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI - Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-18-21	Start Time 0700	End Time 1130
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

Near Misses / Incidents / Special Topics

None

Chemical Hazards

None

Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

Special Equipment / Techniques

Excavator - Case 580N

Hospital Name / Address

The Hospitals of Providence Northeast Campus

[Redacted]

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

ATTENDEES

Name	Signature	Company
------	-----------	---------



[Handwritten signature]



DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-21-21	Start Time 0700	End Time 0900
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

Near Misses / Incidents / Special Topics

None

Chemical Hazards

None

Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

Special Equipment / Techniques

Excavator

Hospital Name / Address

The Hospitals of Providence Northeast Campus

[Redacted]

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

ATTENDEES

Name	Signature	Company
------	-----------	---------

[Redacted]	[Redacted]	[Redacted]
------------	------------	------------

(Handwritten mark)



Appendix B – Photographic Log



This page intentionally left blank.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 10 May 2021
--	---	-----------------------------

Photograph No.

1

Description:

Preparing to begin trenching at TT20-21, facing south.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 10 May 2021
--	---	-----------------------------

Photograph No.

2

Description:

Plastic trash and rope observed within trench TT20-21 at the right side (east) of the trench. Surveying the western extent of waste within the trench, facing north.



<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="width: 15%; background-color: black; height: 40px;"></div> <div style="text-align: center;"> PHOTOGRAPHIC LOG Fort Bliss Municipal Solid Waste Landfill </div> </div>		
Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 10 May 2021
Photograph No. 3		
Description: Facing northeast towards the backfilled and graded area where trench TT20-22 was located.		

<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="width: 15%; background-color: black; height: 40px;"></div> <div style="text-align: center;"> PHOTOGRAPHIC LOG Fort Bliss Municipal Solid Waste Landfill </div> </div>		
Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 10 May 2021
Photograph No. 4		
Description: Extent excavation and plastic waste observed within trench TT20-23, facing west.		



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
10 May 2021

Photograph No.

5

Description:

Original location of planned trench TT20-25 was approximately 50 ft east of where the survey staff is located, facing northeast. Trench relocated due to overhead utilities.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
10 May 2021

Photograph No.

6

Description:

Actual location of trench TT20-25 while being backfilled to grade, facing northeast.



<div style="text-align: center;">  <p>PHOTOGRAPHIC LOG Fort Bliss Municipal Solid Waste Landfill</p> </div>		
Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 11 May 2021
Photograph No. 7		
Description: Rattlesnake hazard present onsite.		

<div style="text-align: center;">  <p>PHOTOGRAPHIC LOG Fort Bliss Municipal Solid Waste Landfill</p> </div>		
Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 11 May 2021
Photograph No. 8		
Description: Plastic trash observed within trench TT20-04 immediately at the white post for the landfill extent; facing southeast.		



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
11 May 2021

Photograph No.

9

Description:

Facing south within the excavation for trench TT20-05 at the designated location. No waste observed to the extent of the backhoe.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
11 May 2021

Photograph No.

10

Description:

Facing south within the excavation for trench TT20-05-2 at the alternate location, 30 feet west of TT20-05.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
11 May 2021

Photograph No.

11

Description:

Facing south within the excavation for trench TT20-06-2 at the relocated position, 28 feet west of the designated location TT20-06. No waste observed.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
11 May 2021

Photograph No.

12

Description:

Trench TT20-05-2 remaining open until replacement survey equipment arrives onsite. Caution tape installed around the perimeter, facing south. Typical.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
12 May 2021

Photograph No.

13

Description:

Asphalt debris seam
along western side
of trench TT20-07,
facing
north-northwest.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
12 May 2021

Photograph No.

14

Description:

Beginning excavation
at TT20-09, facing
east-southeast.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
12 May 2021

Photograph No.

15

Description:

Waste present within excavation at TT20-09 at the interface with the northern perimeter road, facing west.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
12 May 2021

Photograph No.

16

Description:

Trench TT20-07 remaining open until replacement survey equipment arrives onsite. Caution tape installed around the perimeter, facing south. Typical at all open excavations.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
13 May 2021

Photograph No.

17

Description:

██████████ personnel
collecting
geotechnical sample
at TT20-10, facing
east.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
13 May 2021

Photograph No.

18

Description:

Excavating at
TT20-20, facing
north.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
14 May 2021

Photograph No.

19

Description:

Backfilling operations at TT20-19, looking east.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
14 May 2021

Photograph No.

20

Description:

Backfilling and grading at TT20-20, looking north.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
14 May 2021

Photograph No.

21

Description:

Road grading
following backfilling
of TT20-3, looking
west.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
14 May 2021

Photograph No.

22

Description:

Backfill completion
at TT20-14, looking
west.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 17 May 2021
--	---	-----------------------------

Photograph No.

23

Description:

Interior pothole location IT20-49 with plastic debris at bottom, looking north.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 17 May 2021
--	---	-----------------------------

Photograph No.

24

Description:

Interior location IT20-35, scraped to six inches with visible waste on surface, looking east.





PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
17 May 2021

Photograph No.

25

Description:

Surveying debris at
IT20-09, looking
north.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project:
Limits of Waste Investigation:
Fort Bliss Municipal Solid Waste Landfill

Location:
Fort Bliss – El Paso, Texas

Date:
17 May 2021

Photograph No.

26

Description:

Surface completion
at IT20-145, looking
northwest.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 18 May 2021
--	---	-----------------------------

Photograph No.

27

Description:

Excavating IT20-07,
looking south.



PHOTOGRAPHIC LOG
Fort Bliss Municipal Solid Waste Landfill

Project: Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	Location: Fort Bliss – El Paso, Texas	Date: 18 May 2021
--	---	-----------------------------

Photograph No.

28

Description:

Surveying waste at
IT20-23 following
excavation, looking
north.

