



## DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI - Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5/11/21	Start Time 0730	End Time 1640
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
Other Required PPE					

### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

### Near Misses / Incidents / Special Topics

rottable sockets on site at entry to landfill

### Chemical Hazards

None

### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

### Special Equipment / Techniques

Burlesco

### Hospital Name / Address

The Hospitals of Providence Northeast Campus

[Redacted]

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

### ATTENDEES

Name	Signature	Company
[Redacted]		

[Redacted]



### DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI - Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5/12/21	Start Time 7:30	End Time 1730
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

#### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

#### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

#### Near Misses / Incidents / Special Topics

None

#### Chemical Hazards

None

#### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

#### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

#### Special Equipment / Techniques

Backhoe

#### Hospital Name / Address

The Hospitals of Providence Northeast Campus



Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

#### ATTENDEES

Name	Signature	Company
------	-----------	---------





# DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5/13/21	Start Time 0800	End Time 1830
Site Location: El Paso, Texas	Site Safety Officer:	

### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

### Near Misses / Incidents / Special Topics

None

### Chemical Hazards

None

### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

### Special Equipment / Techniques

Backhoe

### Hospital Name / Address

The Hospitals of Providence Northeast Campus

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

### ATTENDEES

Name	Signature	Company





## DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-17-21	Start Time 0700	End Time 1600
Site Location: El Paso, Texas	Site Safety Officer:	

### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

### Near Misses / Incidents / Special Topics

None

### Chemical Hazards

None

### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

### Special Equipment / Techniques

Excavator

### Hospital Name / Address

The Hospitals of Providence Northeast Campus

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

### ATTENDEES

Name	Signature	Company
------	-----------	---------

--	--	--



## DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI - Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-18-21	Start Time 0700	End Time 1130
Site Location: El Paso, Texas	Site Safety Officer:	

### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling;  
Surveying trench locations

### Near Misses / Incidents / Special Topics

None

### Chemical Hazards

None

### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather;  
geotechnical sampling, encountering asbestos and medical waste

### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters  
when backing vehicles, check weather forecast at the start of the day, buddy system

### Special Equipment / Techniques

Excavator - Case 580N

### Hospital Name / Address

The Hospitals of Providence Northeast Campus

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

### ATTENDEES

Name	Signature	Company
------	-----------	---------

--	--	--



### DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-20-21	Start Time 0730	End Time 1650
Site Location: El Paso, Texas	Site Safety Officer: [Redacted]	

#### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
Other Required PPE					

#### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

#### Near Misses / Incidents / Special Topics

None

#### Chemical Hazards

None

#### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

#### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

#### Special Equipment / Techniques

Excavator


#### Hospital Name / Address

The Hospitals of Providence Northeast Campus  
[Redacted]

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

#### ATTENDEES

Name	Signature	Company
[Redacted]	[Redacted]	[Redacted]





## DAILY TAILGATE SAFETY MEETING

Job Name: MSWLF LOWI – Fort Bliss, Texas	Project Number: W912BV-19-D-0012 Task Order W912BV20F0183	
Date: 5-21-21	Start Time 0700	End Time 0900
Site Location: El Paso, Texas	Site Safety Officer:	

### Minimum PPE Requirements

<input checked="" type="checkbox"/> Hard Hat	<input checked="" type="checkbox"/> Safety Glasses	<input checked="" type="checkbox"/> Hi-Viz Vest	<input checked="" type="checkbox"/> Steel Toed Boots	<input checked="" type="checkbox"/> Gloves - work	<input type="checkbox"/> Gloves - Nitrile
--	--	---	--	---	---

Other Required PPE

### Daily Tasks

Review task specific AHAs; Excavation and trenching; Geotechnical sampling; Surveying trench locations

### Near Misses / Incidents / Special Topics

None

### Chemical Hazards

None

### Physical Hazards

Vehicle operations; slips, trips, and falls; excavation and biological; weather; geotechnical sampling, encountering asbestos and medical waste

### Hazard Mitigation

Use of proper PPE, situational awareness, good housekeeping practices, use spotters when backing vehicles, check weather forecast at the start of the day, buddy system

### Special Equipment / Techniques

Excavator

### Hospital Name / Address

The Hospitals of Providence Northeast Campus

Approximate distance from Site: 6 miles; Approximate drive time: 11 minutes

### ATTENDEES

Name	Signature	Company
------	-----------	---------

--	--	--





## **Appendix B – Photographic Log**

---



*This page intentionally left blank.*

<div style="text-align: center;">  <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
<b>Photograph No.</b>  1		
<b>Description:</b>  Preparing to begin trenching at TT20-21, facing south.		

<div style="text-align: center;">  <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
<b>Photograph No.</b>  2		
<b>Description:</b>  Plastic trash and rope observed within trench TT20-21 at the right side (east) of the trench. Surveying the western extent of waste within the trench, facing north.		

**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
--	---	-----------------------------

**Photograph No.**  
  
3

**Description:**  
  
Facing northeast towards the backfilled and graded area where trench TT20-22 was located.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
--	---	-----------------------------

**Photograph No.**  
  
4

**Description:**  
  
Extent excavation and plastic waste observed within trench TT20-23, facing west.



<div style="background-color: black; width: 100px; height: 40px; display: inline-block;"></div> <b>PHOTOGRAPHIC LOG</b> <b>Fort Bliss Municipal Solid Waste Landfill</b>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
<b>Photograph No.</b>  5		
<b>Description:</b>  Original location of planned trench TT20-25 was approximately 50 ft east of where the survey staff is located, facing northeast. Trench relocated due to overhead utilities.		

<div style="background-color: black; width: 100px; height: 40px; display: inline-block;"></div> <b>PHOTOGRAPHIC LOG</b> <b>Fort Bliss Municipal Solid Waste Landfill</b>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 10 May 2021
<b>Photograph No.</b>  6		
<b>Description:</b>  Actual location of trench TT20-25 while being backfilled to grade, facing northeast.		

**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

**Project:**  
Limits of Waste Investigation:  
Fort Bliss Municipal Solid Waste Landfill

**Location:**  
Fort Bliss – El Paso, Texas

**Date:**  
11 May 2021

**Photograph No.**

7

**Description:**

Rattlesnake hazard  
present onsite.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

**Project:**  
Limits of Waste Investigation:  
Fort Bliss Municipal Solid Waste Landfill

**Location:**  
Fort Bliss – El Paso, Texas

**Date:**  
11 May 2021

**Photograph No.**

8

**Description:**

Plastic trash  
observed within  
trench TT20-04  
immediately at the  
white post for the  
landfill extent; facing  
southeast.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 11 May 2021
--	---	-----------------------------

**Photograph No.**  
  
9

**Description:**  
  
Facing south within the excavation for trench TT20-05 at the designated location. No waste observed to the extent of the backhoe.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 11 May 2021
--	---	-----------------------------

**Photograph No.**  
  
10

**Description:**  
  
Facing south within the excavation for trench TT20-05-2 at the alternate location, 30 feet west of TT20-05.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 11 May 2021
--	---	-----------------------------

**Photograph No.**  
  
11

**Description:**  
  
Facing south within the excavation for trench TT20-06-2 at the relocated position, 28 feet west of the designated location TT20-06. No waste observed.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 11 May 2021
--	---	-----------------------------

**Photograph No.**  
  
12

**Description:**  
  
Trench TT20-05-2 remaining open until replacement survey equipment arrives onsite. Caution tape installed around the perimeter, facing south. Typical.



<div style="text-align: center;">  <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 12 May 2021
<b>Photograph No.</b>  13		
<b>Description:</b>  Asphalt debris seam along western side of trench TT20-07, facing north-northwest.		

<div style="text-align: center;">  <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 12 May 2021
<b>Photograph No.</b>  14		
<b>Description:</b>  Beginning excavation at TT20-09, facing east-southeast.		

**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

**Project:** Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill  
**Location:** Fort Bliss – El Paso, Texas  
**Date:** 12 May 2021

**Photograph No.**  
15

**Description:**  
Waste present within excavation at TT20-09 at the interface with the northern perimeter road, facing west.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

**Project:** Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill  
**Location:** Fort Bliss – El Paso, Texas  
**Date:** 12 May 2021

**Photograph No.**  
16

**Description:**  
Trench TT20-07 remaining open until replacement survey equipment arrives onsite. Caution tape installed around the perimeter, facing south. Typical at all open excavations.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 13 May 2021
--	---	-----------------------------

**Photograph No.**  
  
17

**Description:**  
  
Ayuda personnel collecting geotechnical sample at TT20-10, facing east.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 13 May 2021
--	---	-----------------------------

**Photograph No.**  
  
18

**Description:**  
  
Excavating at TT20-20, facing north.



<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="width: 15%; background-color: black; height: 40px;"></div> <div style="text-align: center;"> <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 14 May 2021
<b>Photograph No.</b>  19		
<b>Description:</b>  Backfilling operations at TT20-19, looking east.		

<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="width: 15%; background-color: black; height: 40px;"></div> <div style="text-align: center;"> <b>PHOTOGRAPHIC LOG</b>  <b>Fort Bliss Municipal Solid Waste Landfill</b> </div> </div>		
<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 14 May 2021
<b>Photograph No.</b>  20		
<b>Description:</b>  Backfilling and grading at TT20-20, looking north.		

**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 14 May 2021
--	---	-----------------------------

**Photograph No.**  
  
21

**Description:**  
  
Road grading following backfilling of TT20-3, looking west.



**PHOTOGRAPHIC LOG**  
**Fort Bliss Municipal Solid Waste Landfill**

<b>Project:</b> Limits of Waste Investigation: Fort Bliss Municipal Solid Waste Landfill	<b>Location:</b> Fort Bliss – El Paso, Texas	<b>Date:</b> 14 May 2021
--	---	-----------------------------

**Photograph No.**  
  
22

**Description:**  
  
Backfill completion at TT20-14, looking west.

