



FORSUM

DATA PACKAGE #2 FOR PRELIMINARY ASSESSMENT



3d Inf Div (Mech)

**of the
MCA Barracks Site (HAA-15)
Hunter Army Airfield, Georgia**

Prepared for



U.S. ARMY CORPS OF ENGINEERS
SAVANNAH DISTRICT

Contract No. DACA21-95-D-0022
Delivery Order 0061

December 2002



**DATA PACKAGE #2 FOR PRELIMINARY ASSESSMENT
OF THE
MCA BARRACKS SITE (HAA-15)
HUNTER ARMY AIRFIELD, GEORGIA**

Prepared for

**U.S. Army Corps of Engineers, Savannah District
and
Fort Stewart Directorate of Public Works
Under Contract Number DACA21-95-D-0022
Delivery Order 0061**

Prepared by



**Science Applications International Corporation
151 Lafayette Drive
Oak Ridge, TN 37830**

December 2002



LEGEND

- ESTIMATED VERTICAL PROFILE/MONITORING WELL LOCATIONS
(WELL 16 WAS COVERED BY CONSTRUCTION DEBRIS BEFORE SURVEY)
- ⊕ VERTICAL PROFILE/MONITORING WELL LOCATION
- VERTICAL PROFILE ONLY LOCATION




U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
SAVANNAH, GEORGIA

U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
SAVANNAH, GEORGIA

MCA BARRACKS SITE LOCATION MAP

DRAWN BY: J. LAMB	REV. NO./DATE: 0/12/04/02	CAD FILE: 97028/DGNS/Q81C001.DGN
----------------------	------------------------------	-------------------------------------



XX-16	
XX1612	21-23'
No Detects	
XX1622	37-39'
No Detects	
XX1632	44-46'
No Detects	

XX-17	
XX1712	34-36'
1,1,1-TCA	0.62J
XX1722	44-46'
1,2-DCE	0.45J
E	0.74J
TCE	3.4

XX-18	
XX1812	23-25'
1,2-DCE	100
B	0.56J
TCE	5.1
XX1822	35-37'
1,2-DCE	37.7
XX1832	43-45'
No Detects	

XX-19	
XX1912	25-27'
1,1-DCA	0.36J
1,2-DCE	23.1
B	0.58J
E	0.28J
TCE	0.48J
X	1.2J
XX1922	33-35'
1,2-DCE	2.3
E	0.22J
TCE	4.6
X	0.54J
XX1932	41-43'
No Detects	

XX-20	
XX2012	33-35'
1,2-DCE	16.8
TCE	457
XX2022	39-40.5'
1,1-DCE	1.0
1,2-DCE	29.8
B	0.55J
PCE	0.27J
TCE	818
XX2032	41-43'
1,2-DCE	50
B	1.9J
TCE	476

XX-21	
XX2112	31-33'
1,2-DCE	2.2
B	0.39J
E	0.61J
PCE	2.3
TCE	1.3
X	1.8J
XX2122	41-43'
E	0.41J
T	2.1
X	2.1J
XX2132	45-47'
1,2-DCE	636
TCE	122

XX-22	
XX2212	26.5-28.5'
1,1-DCE	3.4
1,2-DCE	148
TCE	1040
XX2222	29.5-31.5'
1,2-DCE	15.8
2-B	11.6
A	54.8
B	0.65J
T	1.5
TCE	26.7
XX2232	34-36'
1,1-DCA	0.25J
1,1-DCE	2.4
1,2-DCE	85.7
A	4.0J
TCE	511

XX-23	
XX2312	29-31'
1,1-DCE	0.66J
1,2-DCE	61.4
A	4.4J
TCE	272
XX2322	35-37'
1,1-DCE	0.73J
1,2-DCE	68.4
A	3.6
CM	0.44J
TCE	91.8
XX2332	43-45'
A	2.3J

XX-24	
XX2412	29-31'
A	4.1J
CM	0.61J
XX2422	39-41'
A	4.1J
XX2432	44-46'
A	3.9J

XX-25	
XX2512	27-29'
1,2-DCE	0.78J
A	8.2
T	0.18J
TCE	0.68J
XX2522	37-39'
1,2-DCE	2.6
4-M-2-P	1.6J
A	13.6
B	0.3J
XX2532	45-47'
A	17.1

XX-26	
XX2612	24-29'
1,2-DCE	1.8J
A	102
PCE	0.55J
TCE	9.5
XX2622	30-35'
1,2-DCE	2.3
TCE	17.8
XX2632	37-42'
1,2-DCE	1.6J
TCE	10.3

LEGEND


- ESTIMATED VERTICAL PROFILE/MONITORING WELL LOCATIONS
(WELL 16 WAS COVERED BY CONSTRUCTION DEBRIS BEFORE SURVEY)
- ⊕ VERTICAL PROFILE/MONITORING WELL LOCATION
- VERTICAL PROFILE ONLY LOCATION

1,1,1-Trichloroethane
1,1-Dichloroethane
1,1-Dichloroethene
1,2-Dichloroethene
2-Butanone
4-Methyl-2-Pentanone
Acetone
Benzene
Chloromethane
Ethylbenzene
Tetrachloroethene
Toluene
Trichloroethene
Xylenes, Total

1,1,1-TCA
1,1-DCA
1,1-DCE
1,2-DCE
2-B
4-M-2-P
A
B
CM
E
PCE
T
TCE
X

NOTES:

1. CONCENTRATIONS IN ug/L
2. XX-01 TO XX-03 WERE SAMPLED
IN SEPTEMBER 1999
3. XX-04 TO XX-15 WERE SAMPLED
IN FEBRUARY 2000.



U.S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
SAVANNAH, GEORGIA

MCA BARRACKS GROUNDWATER ANALYTICAL RESULTS (NOVEMBER 2001)

DRAWN BY: J. LAMB
REV. NO./DATE: 0/11/18/02
CAD FILE: 97028/DGNS/Q81C001A.DGN

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (September 1999)

Station:	XX-01	XX-01	XX-01	XX-01	XX-01	XX-01	XX-01
Sample ID:	XX0112	XX0122	XX0132	XX0142	XX0162	XX0172	XX0182
Sample Interval (ft BGS)	11.0 - 15.0	16.0 - 20.0	21.0 - 25.0	26.0 - 30.0	36.0 - 40.0	41.0 - 45.0	46.0 - 50.0
Sample Date:	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	2 U	20 U	1.4 J	2 U	2 U	2 U	2 U
1,1,2,2-Tetrachloroethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,1,2-Trichloroethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,1-Dichloroethane	2 U	20 U	2 U	0.52 J	2 U	2 U	2 U
1,1-Dichloroethene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloroethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloroethene	2.9 =	403 =	98.2 =	69.5 =	41.8 =	2 =	0.71 J
1,2-Dichloropropane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,3-cis-Dichloropropene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
1,3-trans-Dichloropropene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
2-Butanone	5 R	50 R	5 R	5 U	5 R	5 R	5 R
2-Hexanone	5 U	50 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	50 U	5 U	5 U	5 U	5 U	5 U
Acetone	5 R	50 U	5 R	5 U	5 U	5 U	5 U
Benzene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Bromodichloromethane	5 U	50 U	5 U	5 U	5 U	5 U	5 U
Bromoform	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Bromomethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Carbon Disulfide	5 U	50 U	5 U	5 U	5 U	1.3 J	3.8 J
Carbon Tetrachloride	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Chlorobenzene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Chloroethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Chloroform	0.71 J	20 U	2 U	2 U	2 U	2 U	2 U
Chloromethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Dibromochloromethane	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Ethylbenzene	2 U	20 U	2 U	2 U	0.53 J	2 U	2 U
Methylene Chloride	4.5 U	9 J	4.6 U	2 U	2 U	2 U	1.1 J
Styrene	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Tetrachloroethene	2 U	20 U	1 J	1.2 J	2 U	2 U	2 U
Toluene	2 U	20 U	2 U	2 U	0.71 J	2 U	2 U
Trichloroethene	33.9 =	560 =	258 =	139 =	39.4 =	2 U	2 U
Vinyl Chloride	2 U	20 U	2 U	2 U	2 U	2 U	2 U
Xylenes, Total	6 U	60 U	6 U	6 U	2.8 J	0.7 J	6 U

**MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (September 1999)**

[illegible]

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (September 1999)

Station:	XX-03	XX-03	XX-03	XX-03	XX-03	XX-03	XX-03	XX-03
Sample ID:	XX0312	XX0322	XX0332	XX0342	XX0352	XX0362	XX0372	XX0382
Sample Interval (ft BGS)	10.0 - 15.0	16.0 - 20.0	21.0 - 25.0	26.0 - 30.0	31.0 - 35.0	36.0 - 40.0	41.0 - 45.0	46.0 - 50.0
Sample Date:	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99	26-Sep-99
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,1,2,2-Tetrachloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,1,2-Trichloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,1-Dichloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,1-Dichloroethene	2 U	2 U	2 U	2.2 =	9.8 =	3.5 J	2 U	2 U
1,2-Dichloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloroethene	1.4 J	11.2 =	2 =	80.7 =	274 =	88.8 =	2 =	2 U
1,2-Dichloropropane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,3-cis-Dichloropropene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,3-trans-Dichloropropene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
2-Butanone	5 R	5 R	5 R	5 R	5 R	5 U	5 U	5 R
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	5 U	5 R	5 U	5 R	5 R	5 U	5 U	5 R
Benzene	4.8 =	1.6 J	1.2 J	1.1 J	0.83 J	0.79 J	0.74 J	2 U
Bromodichloromethane	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Bromoform	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Bromomethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Carbon Disulfide	5 U	1.2 J	5 U	0.82 J	5 U	5 UJ	5 U	1.1 J
Carbon Tetrachloride	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Chlorobenzene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Chloroethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Chloroform	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Chloromethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Dibromochloromethane	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Ethylbenzene	1.4 J	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Methylene Chloride	2 U	4.3 U	0.75 J	3.5 U	4.4 U	2 U	2 U	2 U
Styrene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Tetrachloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Toluene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Trichloroethene	36.5 =	116 =	85.3 =	674 =	2440 =	997 =	22.4 =	4.7 =
Vinyl Chloride	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
Xylenes, Total	2.6 J	6 U	6 U	6 U	6 U	6 U	6 U	0.6 J

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-04	XX-04	XX-04	XX-04	XX-04	XX-04	XX-04	XX-04	XX-04
Sample ID:	XX0412	XX0422	XX0432	XX0442	XX0452	XX0462	XX0472	XX0482	XX0492
Sample Interval (ft BGS)	3.5 - 7.0	8.5 - 12.0	13.5 - 17.0	18.5 - 22.0	23.5 - 27.0	28.5 - 32.0	33.5 - 37.0	38.5 - 42.0	43.5 - 47.0
Sample Date:	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	5.1 U	6.9 U	5.7 U	3.6 J	3.2 J	4.4 J	2.8 J	4.2 J	2.9 J
Benzene	1.7 =	5.3 =	1 U	1 U	1 U	1 U	0.2 J	0.38 J	0.16 J
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	0.18 J	8.7 =	0.086 J	0.063 J	0.065 J	0.11 J	0.064 J	0.06 J	0.062 J
Methylene Chloride	5 U	5 U	5 U	1.1 J	1.1 J	1.3 J	5 U	2 J	1.9 J
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.22 J	0.2 J
Tetrachloroethene	1 U	1 U	4.1 =	7.9 =	1 U	1 U	1 U	1 U	1 U
Toluene	0.51 J	2.2 =	0.6 J	0.37 J	0.35 J	0.63 J	0.42 J	0.28 J	0.27 J
Trichloroethene	1 U	1 U	0.25 J	0.24 J	1 U	1 U	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	23.6 =	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-05	XX-05	XX-05	XX-05	XX-05	XX-05	XX-05	XX-05	XX-05
Sample ID:	XX0512	XX0522	XX0532	XX0542	XX0552	XX0562	XX0572	XX0582	XX0592
Sample Interval (ft BGS)	6.5 - 10.0	11.5 - 15.0	16.5 - 20.0	21.5 - 25.0	26.5 - 30.0	31.5 - 35.0	36.5 - 40.0	43.0 - 45.0	46.5 - 50.0
Sample Date:	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00	20-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	5.6 J	5 J	4.3 J	3 J	5.2 J	3.9 J	5.3 J	4.3 J	3.9 J
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	0.62 J	1.3 =	0.57 J
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	0.056 J	0.078 J	0.074 J	0.061 J	0.075 J	0.071 J	0.064 J	0.06 J	0.061 J
Methylene Chloride	1.4 J	2.2 J	2.4 J	1.4 J	1.8 J	1.7 J	1.6 J	1.6 J	5 U
Styrene	0.16 J	0.22 J	0.26 J	0.22 J	0.17 J	0.18 J	0.18 J	0.15 J	0.13 J
Tetrachloroethene	1 U	1 U	0.88 J	1 U	1 U	1 U	1 U	1 U	1 U
Toluene	0.34 J	0.43 J	0.4 J	0.28 J	0.41 J	0.29 J	0.39 J	0.35 J	0.35 J
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-06	XX-06	XX-06	XX-06	XX-06	XX-06	XX-06	XX-06	XX-06
Sample ID:	XX0612	XX0622	XX0632	XX0642	XX0652	XX0662	XX0672	XX0682	XX0692
Sample Interval (ft BGS)	5.5 - 9.0	10.5 - 14.0	15.5 - 19.0	20.5 - 24.0	25.5 - 29.0	30.5 - 34.0	35.5 - 39.0	40.5 - 44.0	45.5 - 49.0
Sample Date:	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	5 U	5 U	1.1 J	1.7 J	5 UJ	1.9 J	5 U	1.8 J	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 UJ	5 UJ	5 U	5 U	5 U	5 UJ	5 UJ	5 UJ	5 UJ
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Methylene Chloride	1 J	1.5 J	5 U	5 U	5 U	1.3 J	1.6 J	1.7 J	1.2 J
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Toluene	1 U	1 U	0.76 J	0.33 J	0.29 J	0.3 J	1 U	0.3 J	0.35 J
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-07	XX-07	XX-07	XX-07	XX-07	XX-07	XX-07	XX-07	XX-07
Sample ID:	XX0712	XX0722	XX0732	XX0742	XX0752	XX0762	XX0772	XX0782	XX0792
Sample Interval (ft BGS)	4.8 - 8.0	9.5 - 13.0	14.5 - 18.0	19.5 - 23.0	24.5 - 28.0	29.5 - 33.0	34.5 - 38.0	39.5 - 43.0	44.5 - 48.0
Sample Date:	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	0.62 J	5 U	1.6 J	0.32 J	5 UJ	0.94 J	5 UJ	0.51 J	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 UJ	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	1.7 J
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Toluene	1 U	1 U	0.28 J	1 U	0.38 J	0.55 J	0.43 J	0.53 J	1 U
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-08	XX-08	XX-08	XX-08	XX-08	XX-08	XX-08	XX-08	XX-08
Sample ID:	XX0812	XX0822	XX0832	XX0842	XX0852	XX0862	XX0872	XX0882	XX0892
Sample Interval (ft BGS)	8.0 - 11.5	13.0 - 16.5	18.0 - 21.5	23.0 - 26.5	28.0 - 31.5	33.0 - 36.5	38.0 - 41.5	43.0 - 46.5	48.0 - 51.5
Sample Date:	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	IS	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
Acetone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	1.4 J	5 U	IS	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5.3 U	5 U	IS	5.1 U
Styrene	1 U	1 U	1 U	1 U	1 U	0.08 J	1 U	IS	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Toluene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	IS	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-09	XX-09	XX-09	XX-09	XX-09	XX-09	XX-09	XX-09	XX-09
Sample ID:	XX0912	XX0922	XX0932	XX0942	XX0952	XX0962	XX0972	XX0982	XX0992
Sample Interval (ft BGS)	4.5 - 8.0	9.5 - 13.0	14.5 - 18.0	19.5 - 23.0	24.5 - 28.0	29.5 - 33.0	34.5 - 38.0	39.5 - 43.0	44.5 - 48.0
Sample Date:	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00	18-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 U	IS	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
2-Hexanone	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	IS	5 UJ
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
Acetone	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	5 UJ	IS	5 UJ
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	0.21 J
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Carbon Disulfide	5 U	5 U	0.92 J	2.5 J	5 U	5 U	1.9 J	IS	1.4 J
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Chloromethane	1 UJ	1 UJ	1 UJ	1 UJ	1 UJ	1 UJ	1 UJ	IS	1 UJ
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U
Styrene	1 U	1 U	1 U	0.12 J	1 U	1 U	1 U	IS	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Toluene	1 U	0.28 J	0.34 J	0.37 J	0.83 J	0.34 J	0.8 J	IS	0.47 J
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	IS	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-10	XX-10	XX-10	XX-10	XX-10	XX-10	XX-10	XX-10	XX-10
Sample ID:	XX1012	XX1022	XX1032	XX1042	XX1052	XX1062	XX1072	XX1082	XX1092
Sample Interval (ft BGS)	6.5 - 10.0	11.5 - 15.0	16.5 - 20.0	21.5 - 25.0	26.5 - 30.0	31.5 - 35.0	36.5 - 40.0	41.5 - 45.0	46.5 - 50.0
Sample Date:	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00	19-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2 U	2 U	2 UJ	2.1 J	2.7 =
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
Acetone	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	0.19 J	0.85 J	15.8 J	17.6 =
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	0.093 J	1 UJ	1 UJ	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 UJ	5 UJ	5 U
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Toluene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Trichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	0.3 J	0.28 J
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1 UJ	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	0.29 J	0.29 J	0.29 J	0.36 J

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-11	XX-11	XX-11	XX-11	XX-11	XX-11	XX-11	XX-11	XX-11
Sample ID:	XX1112	XX1122	XX1132	XX1142	XX1152	XX1162	XX1172	XX1182	XX1192
Sample Interval (ft BGS)	6.0 - 7.0	11.0 - 14.5	16.0 - 19.5	21.0 - 24.5	26.0 - 29.5	31.0 - 34.5	36.0 - 39.5	41.0 - 44.5	46.0 - 49.5
Sample Date:	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,1-Dichloroethene	1 U	1 U	0.34 J	1 U	1 U	1 U	IS	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,2-Dichloroethene	2 U	0.45 J	1.9 J	0.36 J	2 U	2 U	IS	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
2-Butanone	6.7 =	5 U	5 U	5 U	5 U	5 U	IS	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U	5 U
Acetone	5 U	12.6 =	5 U	5 U	5 U	5 U	IS	5 U	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	IS	0.19 J	1 =
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Carbon Disulfide	5 U	5 U	1.2 J	5 U	5 U	5 U	IS	1.7 J	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	IS	5 U	5 U
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Toluene	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Trichloroethene	1 U	30.4 =	134 =	27.4 =	1 U	0.85 J	IS	1.7 =	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	IS	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	IS	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-12	XX-12	XX-12	XX-12	XX-12	XX-12	XX-12	XX-12	XX-12
Sample ID:	XX1212	XX1222	XX1232	XX1242	XX1252	XX1262	XX1272	XX1282	XX1292
Sample Interval (ft BGS)	6.5 - 10.0	11.5 - 15.0	16.5 - 20.0	21.5 - 25.0	26.5 - 30.0	31.5 - 35.0	36.5 - 40.0	41.5 - 45.0	46.5 - 50.0
Sample Date:	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	0.18 J	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	3.8 =	21.8 =	8.6 =	2 U	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	4.3 J	6.4 J	1.4 J	1.2 J	5 U	5 U	5 U	5 U	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	1 U	0.16 J	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Toluene	1 U	0.32 J	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Trichloroethene	1 U	1 U	220 =	537 =	86 =	1 U	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-13	XX-13	XX-13	XX-13	XX-13	XX-13	XX-13	XX-13	XX-13
Sample ID:	XX1312	XX1322	XX1332	XX1342	XX1352	XX1362	XX1372	XX1382	XX1392
Sample Interval (ft BGS)	4.0 - 5.0	6.5 - 10.0	11.5 - 15.0	16.5 - 20.0	21.5 - 25.0	26.5 - 30.0	31.5 - 35.0	36.5 - 40.0	41.5 - 45.0
Sample Date:	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00	16-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	2 U	2 U	2 U	2 U	2.4 =	2.1 =	2 U	2 U	2 U
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	8.9 =	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	9.4 J	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 U	0.98 J	5 U	5 U	1.4 J	5 U	5 U	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	0.17 J	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Toluene	0.75 J	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Trichloroethene	1 U	0.2 J	1 U	0.4 J	39.7 =	71 =	1 U	1 U	1 U
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-14	XX-14	XX-14	XX-14	XX-14	XX-14	XX-14	XX-14	XX-14
Sample ID:	XX1412	XX1422	XX1432	XX1442	XX1452	XX1462	XX1472	XX1482	XX1492
Sample Interval (ft BGS)	4.0 - 7.5	9.0 - 12.5	14.0 - 17.5	19.0 - 22.5	24.0 - 27.5	29.0 - 32.5	34.0 - 37.5	39.0 - 42.5	44.0 - 47.5
Sample Date:	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,1,2-Trichloroethane	1 U	1 U	1 U	0.24 J	50 U	50 U	1 U	1 U	IS
1,1-Dichloroethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,1-Dichloroethene	1 U	1 U	1.4 =	4 =	50 U	50 U	1 U	1 U	IS
1,2-Dichloroethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,2-Dichloroethene	2 U	4.9 =	50.6 =	23.8 =	22.1 J	25.3 J	11.8 =	2 U	IS
1,2-Dichloropropane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
2-Butanone	5 U	5 U	5 U	5 U	250 U	250 U	5 U	5 U	IS
2-Hexanone	5 U	5 U	5 U	5 U	250 U	250 U	5 U	5 U	IS
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	250 U	250 U	5 U	5 U	IS
Acetone	5 UJ	5 UJ	2.3 J	5 UJ	250 UJ	250 UJ	4.1 J	5 UJ	IS
Benzene	1 U	1 U	1 U	0.5 J	50 U	50 U	0.82 J	1 U	IS
Bromodichloromethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Bromoform	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Bromomethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Carbon Disulfide	5 U	5 U	5 U	5 U	250 UJ	250 UJ	5 UJ	5 UJ	IS
Carbon Tetrachloride	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Chlorobenzene	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Chloroethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Chloroform	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Chloromethane	1 U	1 U	1 U	1 U	50 UJ	50 UJ	1 UJ	1 UJ	IS
Dibromochloromethane	1 U	1 U	1 U	1 U	50 U	50 U	1 U	1 U	IS
Ethylbenzene	1 U	1 U	1 U	0.18 J	50 U	50 U	1 U	1 U	IS
Methylene Chloride	5 U	5 U	5 U	5 U	250 U	250 U	5 U	5 U	IS
Styrene	1 U	1 U	0.18 J	1 U	4.9 J	50 U	1 U	1 U	IS
Tetrachloroethene	1 U	0.71 J	7.5 =	32.5 =	50 U	50 U	1 U	1 U	IS
Toluene	1 U	1 U	1 U	0.35 J	50 U	50 U	0.42 J	1 U	IS
Trichloroethene	1 U	183 =	1040 J	3600 =	3700 =	2830 =	8.3 =	0.6 J	IS
Vinyl Chloride	1 U	1 U	1 U	2.1 =	50 U	50 U	1 U	1 U	IS
Xylenes, Total	3 U	3 U	3 U	3 U	150 U	150 U	3 U	3 U	IS

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (February 2000)

Station:	XX-15	XX-15	XX-15	XX-15	XX-15	XX-15	XX-15	XX-15	XX-15
Sample ID:	XX1512	XX1522	XX1532	XX1542	XX1552	XX1562	XX1572	XX1582	XX1592
Sample Interval (ft BGS)	6.5 - 10.0	11.5 - 15.0	16.5 - 20.0	21.5 - 25.0	26.5 - 30.0	31.5 - 35.0	36.5 - 40.0	41.5 - 45.0	46.5 - 50.0
Sample Date:	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00	17-Feb-00
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,1-Dichloroethene	1 U	1 U	1 U	1 U	1 U	6.1 =	1 U	1 U	IS
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,2-Dichloroethene	7.8 =	7.6 =	9.7 =	9 =	2 U	501 =	63.9 =	7.2 =	IS
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS
Acetone	0.8 J	5 U	1.5 J	5 U	5 U	5 U	1.8 J	5 U	IS
Benzene	1 U	1 U	1 U	1 U	1 U	0.66 J	0.4 J	1 U	IS
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Chloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	IS
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U	5 U	5 U	IS
Styrene	1 U	1 U	1 U	1 U	1 U	1 U	0.21 J	1 U	IS
Tetrachloroethene	1.6 =	1.4 =	1.8 =	2.1 =	1 U	1 U	1 U	1 U	IS
Toluene	1 U	1 U	1 U	1 U	1 U	1 U	0.34 J	1 U	IS
Trichloroethene	157 =	83 =	118 =	198 =	1 U	406 =	1 =	1 U	IS
Vinyl Chloride	2.4 =	3 =	3.4 =	1 U	1 U	1 U	1 U	1 U	IS
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U	3 U	3 U	IS

IS = insufficient recovery for
groundwater sample

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (November/December 2001)

[illegible]

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (November/December 2001)

Station:	XX-19	XX-19	XX-19	XX-20	XX-20	XX-20	XX-21	XX-21	XX-21
Sample ID:	XX1912	XX1922	XX1932	XX2012	XX2022	XX2032	XX2112	XX2122	XX2132
Sample Interval (ft BGS)	25.0 - 27.0	33.0 - 35.0	41.0 - 43.0	33.0 - 35.0	39.0 - 40.5	41.0 - 43.0	31.0 - 33.0	41.0 - 43.0	45.0 - 47.0
Sample Date:	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01	9-Nov-01
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,1,2-Trichloroethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,1-Dichloroethane	0.36 J	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,1-Dichloroethene	1 U	1 U	1 U	5 U	1 =	5 U	1 U	1 U	10 U
1,2-Dichloroethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,2-Dichloroethene	23.1 =	2.3 =	2 U	16.8 =	29.8 =	50 =	2.2 =	2 U	636 =
1,2-Dichloropropane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
2-Butanone	5 U	5 U	5 U	25 U	5 U	25 U	5 U	5 U	50 U
2-Hexanone	5 U	5 U	5 U	25 U	5 U	25 U	5 U	5 U	50 U
4-Methyl-2-pentanone	5 U	5 U	5 U	25 U	5 U	25 U	5 U	5 U	50 U
Acetone	11.4 U	6.5 U	9.2 U	26.1 U	6.4 U	32.6 U	10.7 U	5.8 U	50 U
Benzene	0.58 J	1 U	1 U	5 U	0.55 J	1.9 J	0.39 J	1 U	10 U
Bromodichloromethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Bromoform	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Bromomethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Carbon Disulfide	5 U	5 U	5 U	25 U	5 U	25 U	5 U	5 U	50 U
Carbon Tetrachloride	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Chlorobenzene	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Chloroethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Chloroform	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Chloromethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Dibromochloromethane	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Ethylbenzene	0.28 J	0.22 J	1 U	5 U	1 U	5 U	0.61 J	0.41 J	10 U
Methylene Chloride	5 U	5 U	5 U	25 U	5 U	25 U	5 U	5 U	50 U
Styrene	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Tetrachloroethene	1 U	1 U	1 U	5 U	0.27 J	5 U	2.3 =	1 U	10 U
Toluene	1.4 U	1.2 U	1 U	5 U	1 U	5 U	1.6 U	2.1 =	10 U
Trichloroethene	0.48 J	4.6 =	1 U	457 =	818 =	476 =	1.3 =	1 U	122 =
Vinyl Chloride	1 U	1 U	1 U	5 U	1 U	5 U	1 U	1 U	10 U
Xylenes, Total	1.2 J	0.54 J	3 U	15 U	3 U	15 U	1.8 J	2.1 J	30 U

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (November/December 2001)

[illegible]

MCA Barracks, Hunter Army Airfield
Groundwater Analytical Results (November/December 2001)

Station:	XX-25	XX-25	XX-25	XX-26	XX-26	XX-26
Sample ID:	XX2512	XX2522	XX2532	XX2612	XX2622	XX2632
Sample Interval (ft BGS)	29.0 - 31.0	35.0 - 37.0	43.0 - 45.0	23.7 - 28.7	29.9 - 34.8	37.4 - 42.3
Sample Date:	10-Nov-01	10-Nov-01	10-Nov-01	16-Dec-01	16-Dec-01	16-Dec-01
Units:	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
1,1,1-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2,2-Tetrachloroethane	1 U	1 U	1 U	1 U	1 U	1 U
1,1,2-Trichloroethane	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U
1,1-Dichloroethene	0.66 J	0.73 J	1 U	1 U	1 U	1 U
1,2-Dichloroethane	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichloroethene	61.4 =	68.4 =	2 U	1.8 J	2.3 =	1.6 J
1,2-Dichloropropane	1 U	1 U	1 U	1 U	1 U	1 U
1,3-cis-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U
1,3-trans-Dichloropropene	1 U	1 U	1 U	1 U	1 U	1 U
2-Butanone	5 U	5 U	5 U	5 U	5 U	5 U
2-Hexanone	5 U	5 U	5 U	5 U	5 U	5 U
4-Methyl-2-pentanone	5 U	5 U	5 U	5 U	5 U	5 U
Acetone	4.4 J	3.6 J	2.3 J	102 =	26.2 U	5 U
Benzene	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	1 U	1 U	1 U	1 U	1 U	1 U
Bromoform	1 U	1 U	1 U	1 U	1 U	1 U
Bromomethane	1 U	1 U	1 U	1 U	1 U	1 U
Carbon Disulfide	5 U	5 U	5 U	5 U	5 U	5 U
Carbon Tetrachloride	1 U	1 U	1 U	1 U	1 U	1 U
Chlorobenzene	1 U	1 U	1 U	1 U	1 U	1 U
Chloroethane	1 U	1 U	1 U	1 U	1 U	1 U
Chloroform	1 U	1 U	1 U	1 U	1 U	1 U
Chloromethane	1 U	0.44 J	1 U	1 U	1 U	1 U
Dibromochloromethane	1 U	1 U	1 U	1 U	1 U	1 U
Ethylbenzene	1 U	1 U	1 U	1 U	1 U	1 U
Methylene Chloride	5 U	5 U	5 U	5 U	5 U	5 U
Styrene	1 U	1 U	1 U	1 U	1 U	1 U
Tetrachloroethene	1 U	1 U	1 U	0.55 J	1 U	1 U
Toluene	1 U	1 U	1 U	1 U	1 U	1 U
Trichloroethene	272 =	91.8 =	1 U	9.5 =	17.8 =	10.3 =
Vinyl Chloride	1 U	1 U	1 U	1 U	1 U	1 U
Xylenes, Total	3 U	3 U	3 U	3 U	3 U	3 U

**MCA Barracks, Hunter Army Airfield
Well Construction Details**

Well Number	Date Installed	Vertical Profile Boring Depth (ft BGS)	Monitoring Well Screened Interval (ft BGS)	Type of Completion	Coordinates (NAD 88)		Ground Surface Elevation (NAVD 88)	Top of Casing Elevation (NAVD 88)
					Northing	Easting		
XX-01	09/26/99	50.0	n/a	vertical profile	a	a	a	n/a
XX-02	09/26/99	50.0	n/a	vertical profile	739166.18	975948.07	29.3	n/a
XX-03	09/26/99	50.0	n/a	vertical profile	a	a	a	n/a
XX-04	02/20/00	47.0	1.9 - 11.9	vertical profile with adjacent 3/4" PVC shallow well	740076.23	974419.25	17.4	17.01
XX-05	02/20/00	50.0	1.8 - 11.8	vertical profile with adjacent 3/4" PVC shallow well	740032.12	974478.08	18.6	18.21
XX-06	02/20/00	49.0	1.9 - 11.9	vertical profile with adjacent 3/4" PVC shallow well	739891.71	974320.00	21.3	20.67
XX-07	02/19/00	48.0	1.8 - 11.8	vertical profile with adjacent 3/4" PVC shallow well	739821.73	974229.57	20.3	20.06
XX-08	02/18/00	51.5	3.0 - 13.0	vertical profile with adjacent 3/4" PVC shallow well	739548.31	974463.18	30.8	30.42
XX-09	02/19/00	48.0	2.0 - 12.0	vertical profile with adjacent 3/4" PVC shallow well	739770.06	974491.86	24.9	24.63
XX-10	02/18/00	50.0	2.0 - 12.0	vertical profile with adjacent 3/4" PVC shallow well	739786.94	974793.53	20.9	20.55
XX-11	02/17/00	49.5	2.0 - 12.0	vertical profile with adjacent 3/4" PVC shallow well	739600.48	975047.86	25.2	24.84
XX-12	02/17/00	50.0	2.0 - 12.0	vertical profile with adjacent 3/4" PVC shallow well	739366.36	975068.38	30.7	30.43
XX-13	02/17/00	45.0	1.8 - 11.8	vertical profile with adjacent 3/4" PVC shallow well	739591.50	975251.09	22.6	22.49
XX-14	02/16/00	47.5	1.8 - 11.8	vertical profile with adjacent 3/4" PVC shallow well	739335.49	975361.69	27.8	27.62
XX-15	02/18/00	50.0	1.9 - 11.9	vertical profile with adjacent 3/4" PVC shallow well	739374.30	975548.33	26.7	26.49

^a location destroyed before survey was complete

**MCA Barracks, Hunter Army Airfield
Well Construction Details**

Well Number	Date Installed	Vertical Profile Boring Depth (ft BGS)	Monitoring Well Screened Interval (ft BGS)	Type of Completion	Coordinates (NAD 88)		Ground Surface Elevation (NAVD 88)	Top of Casing Elevation (NAVD 88)
					Northing	Easting		
XX-16	12/04/01	46.0	40.0 - 45.0	vertical profile, overdrilled to install 2" PVC well	a	a	a	a
XX-17	12/05/01	46.0	40.0 - 45.0	vertical profile, overdrilled to install 2" PVC well	739573.51	975618.53	21.6	21.28
XX-18	12/05/01	45.0	40.0 - 45.0	vertical profile, overdrilled to install 2" PVC well	739102.02	975231.61	29.9	29.57
XX-19	12/05/01	43.0	37.0 - 42.0	vertical profile, overdrilled to install 2" PVC well	738640.80	975467.18	36.2	35.8
XX-20	12/04/01	43.0	37.0 - 42.0	vertical profile, overdrilled to install 2" PVC well	738880.77	975842.20	33.5	33.26
XX-21	12/05/01	47.0	42.9 - 47.9	vertical profile, overdrilled to install 2" PVC well	738379.40	975678.68	37.71	37.31
XX-22	12/05/01	36.0	26.0 - 31.0	vertical profile, overdrilled to install 2" PVC well	738821.20	976581.78	25.3	25.17
XX-23	12/05/01	45.0	41.4 - 46.4	vertical profile, overdrilled to install 2" PVC well	738492.94	976533.77	34.9	34.59
XX-24	12/04/01	46.0	36.8 - 41.8	vertical profile, overdrilled to install 2" PVC well	737978.60	976526.52	36.0	35.77
XX-25	12/04/01	47.0	29.0 - 34.0	vertical profile, overdrilled to install 2" PVC well	738171.47	976833.25	33.7	33.51
XX-26 (1-S)	12/05/01	n/a	23.7 - 28.7	vertical profile, overdrilled to install 2" PVC well	739351.16	975861.58	26.4	26.16
XX-26 (2-M)	12/05/01	n/a	29.9 - 34.8	vertical profile, overdrilled to install 2" PVC well	739350.94	975861.69	26.4	26.21
XX-26 (3-D)	12/05/01	n/a	37.4 - 42.3	vertical profile, overdrilled to install 2" PVC well	739350.94	975861.39	26.4	26.15

^a location destroyed before survey was complete

**MCA Barracks, Hunter Army Airfield
Groundwater Elevations**

Well Number	Date Measured	Ground Surface Elevation (NAVD 88)	Top of Casing Elevation (NAVD 88)	Screened Interval (ft BGS)	Depth to Water (ft BGS)	Groundwater Elevation (ft AMSL)
XX-04	03/30/00	17.4	17.01	1.9 - 11.9	3.77	13.24
XX-05	03/30/00	18.6	18.21	1.8 - 11.8	4.78	13.43
XX-06	03/30/00	21.3	20.67	1.9 - 11.9	4.14	16.53
XX-07	03/30/00	20.3	20.06	1.8 - 11.8	2.03	18.03
XX-08	03/30/00	30.8	30.42	3.0 - 13.0	7.59	22.83
XX-09	03/30/00	24.9	24.63	2.0 - 12.0	4.08	20.55
XX-10	03/30/00	20.9	20.55	2.0 - 12.0	2.40	18.15
XX-11	03/30/00	25.2	24.84	2.0 - 12.0	4.85	19.99
XX-12	03/30/00	30.7	30.43	2.0 - 12.0	6.55	23.88
XX-13	03/30/00	22.6	22.49	1.8 - 11.8	2.74	19.75
XX-14	03/30/00	27.8	27.62	1.8 - 11.8	4.06	23.56
XX-15	03/30/00	26.7	26.49	1.9 - 11.9	4.73	21.76

**LABORATORY ANALYTICAL REPORTS
FOR SEPTEMBER 1999 AND FEBRUARY 2000
ARE PRESENTED IN DATA PACKAGE #1
FOR PRELIMINARY ASSESSMENT REPORT (APRIL 2000)**

LABORATORY RESULTS

November/December 2001

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1612

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871002

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J331

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	u
75-01-4	-----Vinyl chloride	1.0	U	
74-83-9	-----Bromomethane	1.0	U	
75-00-3	-----Chloroethane	1.0	U	
75-35-4	-----1,1-Dichloroethylene	1.0	U	
67-64-1	-----Acetone	5.5		u F07, F07
75-15-0	-----Carbon disulfide	5.0	U	u
75-09-2	-----Methylene chloride	5	1.9 JB	u F01, F06
75-34-3	-----1,1-Dichloroethane	1.0	U	u
78-93-3	-----2-Butanone	5.0	U	
540-59-0	-----1,2-Dichloroethylene (total)	2.0	U	
67-66-3	-----Chloroform	1.0	U	
71-55-6	-----1,1,1-Trichloroethane	1.0	U	
56-23-5	-----Carbon tetrachloride	1.0	U	
107-06-2	-----1,2-Dichloroethane	1.0	U	
71-43-2	-----Benzene	1.0	U	
79-01-6	-----Trichloroethylene	1.0	U	
78-87-5	-----1,2-Dichloropropane	1.0	U	
75-27-4	-----Bromodichloromethane	1.0	U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	
108-10-1	-----4-Methyl-2-pentanone	5.0	U	
108-88-3	-----Toluene	1.0	U	
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	
79-00-5	-----1,1,2-Trichloroethane	1.0	U	
591-78-6	-----2-Hexanone	5.0	U	
127-18-4	-----Tetrachloroethylene	1.0	U	
124-48-1	-----Dibromochloromethane	1.0	U	
108-90-7	-----Chlorobenzene	1.0	U	
100-41-4	-----Ethylbenzene	1.0	U	
1330-20-7	-----Xylenes (total)	3.0	U	
100-42-5	-----Styrene	1.0	U	
75-25-2	-----Bromoform	1.0	U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1622

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871003

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J332

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	Chloromethane	1.0	U
75-01-4	Vinyl chloride	1.0	U
74-83-9	Bromomethane	1.0	U
75-00-3	Chloroethane	1.0	U
75-35-4	1,1-Dichloroethylene	1.0	U
67-64-1	Acetone	5.0	U
75-15-0	Carbon disulfide	5.0	U
75-09-2	Methylene chloride	5	JB
75-34-3	1,1-Dichloroethane	1.0	U
78-93-3	2-Butanone	5.0	U
540-59-0	1,2-Dichloroethylene (total)	2.0	U
67-66-3	Chloroform	1.0	U
71-55-6	1,1,1-Trichloroethane	1.0	U
56-23-5	Carbon tetrachloride	1.0	U
107-06-2	1,2-Dichloroethane	1.0	U
71-43-2	Benzene	1.0	U
79-01-6	Trichloroethylene	1.0	U
78-87-5	1,2-Dichloropropane	1.0	U
75-27-4	Bromodichloromethane	1.0	U
10061-01-5	cis-1,3-Dichloropropylene	1.0	U
108-10-1	4-Methyl-2-pentanone	5.0	U
108-88-3	Toluene	1.0	U
10061-02-6	trans-1,3-Dichloropropylene	1.0	U
79-00-5	1,1,2-Trichloroethane	1.0	U
591-78-6	2-Hexanone	5.0	U
127-18-4	Tetrachloroethylene	1.0	U
124-48-1	Dibromochloromethane	1.0	U
108-90-7	Chlorobenzene	1.0	U
100-41-4	Ethylbenzene	1.0	U
1330-20-7	Xylenes (total)	3.0	U
100-42-5	Styrene	1.0	U
75-25-2	Bromoform	1.0	U
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U

u
u F04, F06
u
u F01, F06
u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1632

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871004

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J333

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	1.0 U	U
75-01-4	Vinyl chloride	1.0 U	U
74-83-9	Bromomethane	1.0 U	U
75-00-3	Chloroethane	1.0 U	U
75-35-4	1,1-Dichloroethylene	1.0 U	U
67-64-1	Acetone	5.3	U
75-15-0	Carbon disulfide	5.0 U	U
75-09-2	Methylene chloride	5.0 U	U
75-34-3	1,1-Dichloroethane	1.0 U	U
78-93-3	2-Butanone	5.0 U	U
540-59-0	1,2-Dichloroethylene (total)	2.0 U	U
67-66-3	Chloroform	1.0 U	U
71-55-6	1,1,1-Trichloroethane	1.0 U	U
56-23-5	Carbon tetrachloride	1.0 U	U
107-06-2	1,2-Dichloroethane	1.0 U	U
71-43-2	Benzene	1.0 U	U
79-01-6	Trichloroethylene	1.0 U	U
78-87-5	1,2-Dichloropropane	1.0 U	U
75-27-4	Bromodichloromethane	1.0 U	U
10061-01-5	cis-1,3-Dichloropropylene	1.0 U	U
108-10-1	4-Methyl-2-pentanone	5.0 U	U
108-88-3	Toluene	1.0 U	U
10061-02-6	trans-1,3-Dichloropropylene	1.0 U	U
79-00-5	1,1,2-Trichloroethane	1.0 U	U
591-78-6	2-Hexanone	5.0 U	U
127-18-4	Tetrachloroethylene	1.0 U	U
124-48-1	Dibromochloromethane	1.0 U	U
108-90-7	Chlorobenzene	1.0 U	U
100-41-4	Ethylbenzene	1.0 U	U
1330-20-7	Xylenes (total)	3.0 U	U
100-42-5	Styrene	1.0 U	U
75-25-2	Bromoform	1.0 U	U
79-34-5	1,1,2,2-Tetrachloroethane	1.0 U	U

FORM I VOA

DATA VALIDATION
COPY

OLM03.0

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1712

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871005

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J334

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	U
75-01-4	-----Vinyl chloride	1.0	U	U
74-83-9	-----Bromomethane	1.0	U	U
75-00-3	-----Chloroethane	1.0	U	U
75-35-4	-----1,1-Dichloroethylene	1.0	U	U
67-64-1	-----Acetone	53.1	U	U
75-15-0	-----Carbon disulfide	5.0	U	U
75-09-2	-----Methylene chloride	5	1.1 JB	U
75-34-3	-----1,1-Dichloroethane	1.0	U	U
78-93-3	-----2-Butanone	7.7	U	U
540-59-0	-----1,2-Dichloroethylene (total)	2.0	U	U
67-66-3	-----Chloroform	1.0	U	U
71-55-6	-----1,1,1-Trichloroethane	0.62	J	U
56-23-5	-----Carbon tetrachloride	1.0	U	U
107-06-2	-----1,2-Dichloroethane	1.0	U	U
71-43-2	-----Benzene	1.0	U	U
79-01-6	-----Trichloroethylene	1.0	U	U
78-87-5	-----1,2-Dichloropropane	1.0	U	U
75-27-4	-----Bromodichloromethane	1.0	U	U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	U
108-10-1	-----4-Methyl-2-pentanone	5.0	U	U
108-88-3	-----Toluene	1.0	0.30 J	U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	U
79-00-5	-----1,1,2-Trichloroethane	1.0	U	U
591-78-6	-----2-Hexanone	5.0	U	U
127-18-4	-----Tetrachloroethylene	1.0	U	U
124-48-1	-----Dibromochloromethane	1.0	U	U
108-90-7	-----Chlorobenzene	1.0	U	U
100-41-4	-----Ethylbenzene	1.0	U	U
1330-20-7	-----Xylenes (total)	3.0	U	U
100-42-5	-----Styrene	1.0	U	U
75-25-2	-----Bromoform	1.0	U	U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	U

FORM 1 VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1722

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871006

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J413

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	1.0 U	u
75-01-4	Vinyl chloride	1.0 U	
74-83-9	Bromomethane	1.0 U	
75-00-3	Chloroethane	1.0 U	
75-35-4	1,1-Dichloroethylene	1.0 U	u F01, F07
67-64-1	Acetone	13.5 B	
75-15-0	Carbon disulfide	5.0 U	
75-09-2	Methylene chloride	5.0 U	
75-34-3	1,1-Dichloroethane	1.0 U	u F04, F06
78-93-3	2-Butanone	5 2.0 J	
540-59-0	1,2-Dichloroethylene (total)	0.45 J	
67-66-3	Chloroform	1.0 U	
71-55-6	1,1,1-Trichloroethane	1.0 U	u
56-23-5	Carbon tetrachloride	1.0 U	
107-06-2	1,2-Dichloroethane	1.0 U	
71-43-2	Benzene	1.0 U	
79-01-6	Trichloroethylene	3.4	u
78-87-5	1,2-Dichloropropane	1.0 U	
75-27-4	Bromodichloromethane	1.0 U	
10061-01-5	cis-1,3-Dichloropropylene	1.0 U	
108-10-1	4-Methyl-2-pentanone	5.0 U	u F04, F06
108-88-3	Toluene	1.0 0.59 J	
10061-02-6	trans-1,3-Dichloropropylene	1.0 U	
79-00-5	1,1,2-Trichloroethane	1.0 U	
591-78-6	2-Hexanone	5.0 U	u
127-18-4	Tetrachloroethylene	1.0 U	
124-48-1	Dibromochloromethane	1.0 U	
108-90-7	Chlorobenzene	1.0 U	
100-41-4	Ethylbenzene	0.74 J	u
1330-20-7	Xylenes (total)	3.0 U	
100-42-5	Styrene	1.0 U	
75-25-2	Bromoform	1.0 U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0 U	u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1812

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871007

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J335

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	U
75-01-4	-----Vinyl chloride	1.0	U	U
74-83-9	-----Bromomethane	1.0	U	U
75-00-3	-----Chloroethane	1.0	U	U
75-35-4	-----1,1-Dichloroethylene	1.0	U	U
67-64-1	-----Acetone	12.0	U	U
75-15-0	-----Carbon disulfide	5.0	U	U
75-09-2	-----Methylene chloride	5 1.5	JB	U
75-34-3	-----1,1-Dichloroethane	1.0	U	U
78-93-3	-----2-Butanone	5 2.0	J	U
540-59-0	-----1,2-Dichloroethylene (total)	100		U
67-66-3	-----Chloroform	1.0	U	U
71-55-6	-----1,1,1-Trichloroethane	1.0	U	U
56-23-5	-----Carbon tetrachloride	1.0	U	U
107-06-2	-----1,2-Dichloroethane	1.0	U	U
71-43-2	-----Benzene	0.56	J	U
79-01-6	-----Trichloroethylene	5.1		U
78-87-5	-----1,2-Dichloropropane	1.0	U	U
75-27-4	-----Bromodichloromethane	1.0	U	U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	U
108-10-1	-----4-Methyl-2-pentanone	5.0	U	U
108-88-3	-----Toluene	1.0	U	U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	U
79-00-5	-----1,1,2-Trichloroethane	1.0	U	U
591-78-6	-----2-Hexanone	5.0	U	U
127-18-4	-----Tetrachloroethylene	1.0	U	U
124-48-1	-----Dibromochloromethane	1.0	U	U
108-90-7	-----Chlorobenzene	1.0	U	U
100-41-4	-----Ethylbenzene	1.0	U	U
1330-20-7	-----Xylenes (total)	3.0	U	U
100-42-5	-----Styrene	1.0	U	U
75-25-2	-----Bromoform	1.0	U	U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	U

FORM I VOA

DATA VALIDATION COPY
MD3.0

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1822

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871008

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J336

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	-----Chloromethane	1.0 U	U
75-01-4	-----Vinyl chloride	1.0 U	U
74-83-9	-----Bromomethane	1.0 U	U
75-00-3	-----Chloroethane	1.0 U	U
75-35-4	-----1,1-Dichloroethylene	1.0 U	U
67-64-1	-----Acetone	20.0 U	U
75-15-0	-----Carbon disulfide	5.0 U	U
75-09-2	-----Methylene chloride	5 1.8 JB	U
75-34-3	-----1,1-Dichloroethane	1.0 U	U
78-93-3	-----2-Butanone	5 2.7 J	U
540-59-0	-----1,2-Dichloroethylene (total)	37.7	U
67-66-3	-----Chloroform	1.0 U	U
71-55-6	-----1,1,1-Trichloroethane	1.0 U	U
56-23-5	-----Carbon tetrachloride	1.0 U	U
107-06-2	-----1,2-Dichloroethane	1.0 U	U
71-43-2	-----Benzene	1.0 U	U
79-01-6	-----Trichloroethylene	1.0 U	U
78-87-5	-----1,2-Dichloropropane	1.0 U	U
75-27-4	-----Bromodichloromethane	1.0 U	U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0 U	U
108-10-1	-----4-Methyl-2-pentanone	5.0 U	U
108-88-3	-----Toluene	1.2	U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0 U	U
79-00-5	-----1,1,2-Trichloroethane	1.0 U	U
591-78-6	-----2-Hexanone	5.0 U	U
127-18-4	-----Tetrachloroethylene	1.0 U	U
124-48-1	-----Dibromochloromethane	1.0 U	U
108-90-7	-----Chlorobenzene	1.0 U	U
100-41-4	-----Ethylbenzene	1.0 U	U
1330-20-7	-----Xylenes (total)	3.0 U	U
100-42-5	-----Styrene	1.0 U	U
75-25-2	-----Bromoform	1.0 U	U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0 U	U

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1832

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871009

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J337

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. _____ Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L		Q
74-87-3	Chloromethane	1.0	U	U
75-01-4	Vinyl chloride	1.0	U	U
74-83-9	Bromomethane	1.0	U	U
75-00-3	Chloroethane	1.0	U	U
75-35-4	1,1-Dichloroethylene	1.0	U	U
67-64-1	Acetone	5.6		U F04, F07
75-15-0	Carbon disulfide	5.0	U	U
75-09-2	Methylene chloride	5 1.2	JB	U F01, F06
75-34-3	1,1-Dichloroethane	1.0	U	U
78-93-3	2-Butanone	5.0	U	U
540-59-0	1,2-Dichloroethylene (total)	2.0	U	
67-66-3	Chloroform	1.0	U	
71-55-6	1,1,1-Trichloroethane	1.0	U	
56-23-5	Carbon tetrachloride	1.0	U	
107-06-2	1,2-Dichloroethane	1.0	U	
71-43-2	Benzene	1.0	U	
79-01-6	Trichloroethylene	1.0	U	
78-87-5	1,2-Dichloropropane	1.0	U	
75-27-4	Bromodichloromethane	1.0	U	
10061-01-5	cis-1,3-Dichloropropylene	1.0	U	
108-10-1	4-Methyl-2-pentanone	5.0	U	
108-88-3	Toluene	1.0	U	
10061-02-6	trans-1,3-Dichloropropylene	1.0	U	
79-00-5	1,1,2-Trichloroethane	1.0	U	
591-78-6	2-Hexanone	5.0	U	
127-18-4	Tetrachloroethylene	1.0	U	
124-48-1	Dibromochloromethane	1.0	U	
108-90-7	Chlorobenzene	1.0	U	
100-41-4	Ethylbenzene	1.0	U	
1330-20-7	Xylenes (total)	3.0	U	
100-42-5	Styrene	1.0	U	
75-25-2	Bromoform	1.0	U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OT.M03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

DUPLICATE
EPA SAMPLE NO.

XX1834

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871010

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J338

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

CAS NO.	COMPOUND	Q
74-87-3	-----Chloromethane	1.0 U
75-01-4	-----Vinyl chloride	1.0 U
74-83-9	-----Bromomethane	1.0 U
75-00-3	-----Chloroethane	1.0 U
75-35-4	-----1,1-Dichloroethylene	1.0 U
67-64-1	-----Acetone	5.8
75-15-0	-----Carbon disulfide	5.0 U
75-09-2	-----Methylene chloride	5 1.5 JB
75-34-3	-----1,1-Dichloroethane	1.0 U
78-93-3	-----2-Butanone	5.0 U
540-59-0	-----1,2-Dichloroethylene (total)	2.0 U
67-66-3	-----Chloroform	1.0 U
71-55-6	-----1,1,1-Trichloroethane	1.0 U
56-23-5	-----Carbon tetrachloride	1.0 U
107-06-2	-----1,2-Dichloroethane	1.0 U
71-43-2	-----Benzene	1.0 U
79-01-6	-----Trichloroethylene	1.0 U
78-87-5	-----1,2-Dichloropropane	1.0 U
75-27-4	-----Bromodichloromethane	1.0 U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0 U
108-10-1	-----4-Methyl-2-pentanone	5.0 U
108-88-3	-----Toluene	1.0 U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0 U
79-00-5	-----1,1,2-Trichloroethane	1.0 U
591-78-6	-----2-Hexanone	5.0 U
127-18-4	-----Tetrachloroethylene	1.0 U
124-48-1	-----Dibromochloromethane	1.0 U
108-90-7	-----Chlorobenzene	1.0 U
100-41-4	-----Ethylbenzene	1.0 U
1330-20-7	-----Xylenes (total)	3.0 U
100-42-5	-----Styrene	1.0 U
75-25-2	-----Bromoform	1.0 U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0 U

u
u
u F04, F07
u
u F01, F06
u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1912

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871014

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J414

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	u ↓ F01, F07
75-01-4	-----Vinyl chloride	1.0	U	
74-83-9	-----Bromomethane	1.0	U	
75-00-3	-----Chloroethane	1.0	U	
75-35-4	-----1,1-Dichloroethylene	1.0	U	
67-64-1	-----Acetone	11.4	B	
75-15-0	-----Carbon disulfide	5.0	U	
75-09-2	-----Methylene chloride	5.0	U	
75-34-3	-----1,1-Dichloroethane	0.36	J	
78-93-3	-----2-Butanone	2.1	J	
540-59-0	-----1,2-Dichloroethylene (total)	23.1		5 ↓ F04, F06
67-66-3	-----Chloroform	1.0	U	
71-55-6	-----1,1,1-Trichloroethane	1.0	U	
56-23-5	-----Carbon tetrachloride	1.0	U	
107-06-2	-----1,2-Dichloroethane	1.0	U	
71-43-2	-----Benzene	0.58	J	
79-01-6	-----Trichloroethylene	0.48	J	
78-87-5	-----1,2-Dichloropropane	1.0	U	
75-27-4	-----Bromodichloromethane	1.0	U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	
108-10-1	-----4-Methyl-2-pentanone	5.0	U	u ↓ F04, F07
108-88-3	-----Toluene	1.4		
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	
79-00-5	-----1,1,2-Trichloroethane	1.0	U	
591-78-6	-----2-Hexanone	5.0	U	
127-18-4	-----Tetrachloroethylene	1.0	U	
124-48-1	-----Dibromochloromethane	1.0	U	
108-90-7	-----Chlorobenzene	1.0	U	
100-41-4	-----Ethylbenzene	0.28	J	
1330-20-7	-----Xylenes (total)	1.2	J	
100-42-5	-----Styrene	1.0	U	u ↓ F04, F07
75-25-2	-----Bromoform	1.0	U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1922

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871015

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J341

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	u
75-01-4	-----Vinyl chloride	1.0	U	u
74-83-9	-----Bromomethane	1.0	U	u
75-00-3	-----Chloroethane	1.0	U	u
75-35-4	-----1,1-Dichloroethylene	1.0	U	u
67-64-1	-----Acetone	6.5	U	u
75-15-0	-----Carbon disulfide	5.0	U	u
75-09-2	-----Methylene chloride	5.0	JB	u
75-34-3	-----1,1-Dichloroethane	1.0	U	u
78-93-3	-----2-Butanone	5.0	U	u
540-59-0	-----1,2-Dichloroethylene (total)	2.3	U	u
67-66-3	-----Chloroform	1.0	U	u
71-55-6	-----1,1,1-Trichloroethane	1.0	U	u
56-23-5	-----Carbon tetrachloride	1.0	U	u
107-06-2	-----1,2-Dichloroethane	1.0	U	u
71-43-2	-----Benzene	1.0	U	u
79-01-6	-----Trichloroethylene	4.6	U	u
78-87-5	-----1,2-Dichloropropane	1.0	U	u
75-27-4	-----Bromodichloromethane	1.0	U	u
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	u
108-10-1	-----4-Methyl-2-pentanone	5.0	U	u
108-88-3	-----Toluene	1.2	U	u
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	u
79-00-5	-----1,1,2-Trichloroethane	1.0	U	u
591-78-6	-----2-Hexanone	5.0	U	u
127-18-4	-----Tetrachloroethylene	1.0	U	u
124-48-1	-----Dibromochloromethane	1.0	U	u
108-90-7	-----Chlorobenzene	1.0	U	u
100-41-4	-----Ethylbenzene	0.22	J	u
1330-20-7	-----Xylenes (total)	0.54	J	u
100-42-5	-----Styrene	1.0	U	u
75-25-2	-----Bromoform	1.0	U	u
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX1932

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871016

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J415

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	-----Chloromethane	1.0 U	U ↓ U F01, F07 U
75-01-4	-----Vinyl chloride	1.0 U	
74-83-9	-----Bromomethane	1.0 U	
75-00-3	-----Chloroethane	1.0 U	
75-35-4	-----1,1-Dichloroethylene	1.0 U	
67-64-1	-----Acetone	9.2 B	
75-15-0	-----Carbon disulfide	5.0 U	
75-09-2	-----Methylene chloride	5.0 U	
75-34-3	-----1,1-Dichloroethane	1.0 U	
78-93-3	-----2-Butanone	5.0 U	
540-59-0	-----1,2-Dichloroethylene (total)	2.0 U	U ↓ U F04, F06 U
67-66-3	-----Chloroform	1.0 U	
71-55-6	-----1,1,1-Trichloroethane	1.0 U	
56-23-5	-----Carbon tetrachloride	1.0 U	
107-06-2	-----1,2-Dichloroethane	1.0 U	
71-43-2	-----Benzene	1.0 U	
79-01-6	-----Trichloroethylene	1.0 U	
78-87-5	-----1,2-Dichloropropane	1.0 U	
75-27-4	-----Bromodichloromethane	1.0 U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0 U	
108-10-1	-----4-Methyl-2-pentanone	5.0 U	1.0 0.32 J U ↓ U F04, F06 U
108-88-3	-----Toluene	1.0 U	
10061-02-6	-----trans-1,3-Dichloropropylene	1.0 U	
79-00-5	-----1,1,2-Trichloroethane	1.0 U	
591-78-6	-----2-Hexanone	5.0 U	
127-18-4	-----Tetrachloroethylene	1.0 U	
124-48-1	-----Dibromochloromethane	1.0 U	
108-90-7	-----Chlorobenzene	1.0 U	
100-41-4	-----Ethylbenzene	1.0 U	
1330-20-7	-----Xylenes (total)	3.0 U	
100-42-5	-----Styrene	1.0 U	U
75-25-2	-----Bromoform	1.0 U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0 U	

FORM I VOA

DATA VALIDATION OLM03.0
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2012

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871011

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J411

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. _____ Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 5.0

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	5.0	U
75-01-4	Vinyl chloride	5.0	U
74-83-9	Bromomethane	5.0	U
75-00-3	Chloroethane	5.0	U
75-35-4	1,1-Dichloroethylene	5.0	U
67-64-1	Acetone	26.1	B
75-15-0	Carbon disulfide	25.0	U
75-09-2	Methylene chloride	25.0	U
75-34-3	1,1-Dichloroethane	5.0	U
78-93-3	2-Butanone	25.0	U
540-59-0	1,2-Dichloroethylene (total)	16.8	
67-66-3	Chloroform	5.0	U
71-55-6	1,1,1-Trichloroethane	5.0	U
56-23-5	Carbon tetrachloride	5.0	U
107-06-2	1,2-Dichloroethane	5.0	U
71-43-2	Benzene	5.0	U
79-01-6	Trichloroethylene	457	
78-87-5	1,2-Dichloropropane	5.0	U
75-27-4	Bromodichloromethane	5.0	U
10061-01-5	cis-1,3-Dichloropropylene	3.0	U
108-10-1	4-Methyl-2-pentanone	25.0	U
108-88-3	Toluene	5.0	U
10061-02-6	trans-1,3-Dichloropropylene	5.0	U
79-00-5	1,1,2-Trichloroethane	5.0	U
591-78-6	2-Hexanone	25.0	U
127-18-4	Tetrachloroethylene	5.0	U
124-48-1	Dibromochloromethane	5.0	U
108-90-7	Chlorobenzene	5.0	U
100-41-4	Ethylbenzene	5.0	U
1330-20-7	Xylenes (total)	15.0	U
100-42-5	Styrene	5.0	U
75-25-2	Bromoform	5.0	U
79-34-5	1,1,2,2-Tetrachloroethane	5.0	U

FORM I VOA

CLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2022

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871012

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J339

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.

COMPOUND

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

74-87-3	-----Chloromethane	1.0	U	
75-01-4	-----Vinyl chloride	1.0	U	
74-83-9	-----Bromomethane	1.0	U	
75-00-3	-----Chloroethane	1.0	U	
75-35-4	-----1,1-Dichloroethylene	1.0		
67-64-1	-----Acetone	6.4		
75-15-0	-----Carbon disulfide	5.0	U	
75-09-2	-----Methylene chloride	5 1.0	JB	
75-34-3	-----1,1-Dichloroethane	1.0	U	
78-93-3	-----2-Butanone	5.0	U	
540-59-0	-----1,2-Dichloroethylene (total)	29.8		
67-66-3	-----Chloroform	1.0	U	
71-55-6	-----1,1,1-Trichloroethane	1.0	U	
56-23-5	-----Carbon tetrachloride	1.0	U	
107-06-2	-----1,2-Dichloroethane	1.0	U	
71-43-2	-----Benzene	0.55	J	
79-01-6	-----Trichloroethylene	818 0.27	J	
78-87-5	-----1,2-Dichloropropane	1.0	U	
75-27-4	-----Bromodichloromethane	1.0	U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	
108-10-1	-----4-Methyl-2-pentanone	5.0	U	
108-88-3	-----Toluene	1.0	U	
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	
79-00-5	-----1,1,2-Trichloroethane	1.0	U	
591-78-6	-----2-Hexanone	5.0	U	
127-18-4	-----Tetrachloroethylene	0.27	J	
124-48-1	-----Dibromochloromethane	1.0	U	
108-90-7	-----Chlorobenzene	1.0	U	
100-41-4	-----Ethylbenzene	1.0	U	
1330-20-7	-----Xylenes (total)	3.0	U	
100-42-5	-----Styrene	1.0	U	
75-25-2	-----Bromoform	1.0	U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2032

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871013

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J412

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 5.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

74-87-3	Chloromethane	5.0	U	u
75-01-4	Vinyl chloride	3.0	U	u
74-83-9	Bromomethane	3.0	U	u
75-00-3	Chloroethane	5.0	U	u
75-35-4	1,1-Dichloroethylene	5.0	U	u
67-64-1	Acetone	32.6	B	u
75-15-0	Carbon disulfide	25.0	U	u
75-09-2	Methylene chloride	25.0	U	u
75-34-3	1,1-Dichloroethane	5.0	U	u
78-93-3	2-Butanone	25.0	U	u
540-59-0	1,2-Dichloroethylene (total)	50.0	U	u
67-66-3	Chloroform	5.0	U	u
71-55-6	1,1,1-Trichloroethane	5.0	U	u
56-23-5	Carbon tetrachloride	5.0	U	u
107-06-2	1,2-Dichloroethane	5.0	U	u
71-43-2	Benzene	1.9	J	u
79-01-6	Trichloroethylene	5.0	U	u
78-87-5	1,2-Dichloropropane	5.0	U	u
75-27-4	Bromodichloromethane	5.0	U	u
10061-01-5	cis-1,3-Dichloropropylene	5.0	U	u
108-10-1	4-Methyl-2-pentanone	25.0	U	u
108-88-3	Toluene	5.0	U	u
10061-02-6	trans-1,3-Dichloropropylene	5.0	U	u
79-00-5	1,1,2-Trichloroethane	5.0	U	u
591-78-6	2-Hexanone	25.0	U	u
127-18-4	Tetrachloroethylene	5.0	U	u
124-48-1	Dibromochloromethane	5.0	U	u
108-90-7	Chlorobenzene	5.0	U	u
100-41-4	Ethylbenzene	5.0	U	u
1330-20-7	Xylenes (total)	15.0	U	u
100-42-5	Styrene	5.0	U	u
75-25-2	Bromoform	5.0	U	u
79-34-5	1,1,2,2-Tetrachloroethane	5.0	U	u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

KX2112

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871017

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J416

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	Chloromethane	1.0	U	
75-01-4	Vinyl chloride	1.0	U	
74-83-9	Bromomethane	1.0	U	
75-00-3	Chloroethane	1.0	U	
75-35-4	1,1-Dichloroethylene	1.0	U	
67-64-1	Acetone	10.7	B	
75-15-0	Carbon disulfide	5.0	U	
75-09-2	Methylene chloride	5.0	U	
75-34-3	1,1-Dichloroethane	1.0	U	
78-93-3	2-Butanone	2.0	J	
540-59-0	1,2-Dichloroethylene (total)	2.2		
67-66-3	Chloroform	1.0	U	
71-55-6	1,1,1-Trichloroethane	1.0	U	
56-23-5	Carbon tetrachloride	1.0	U	
107-06-2	1,2-Dichloroethane	1.0	U	
71-43-2	Benzene	0.39	J	
79-01-6	Trichloroethylene	1.3		
78-87-5	1,2-Dichloropropane	1.0	U	
75-27-4	Bromodichloromethane	1.0	U	
10061-01-5	cis-1,3-Dichloropropylene	1.0	U	
108-10-1	4-Methyl-2-pentanone	5.0	U	
108-88-3	Toluene	1.6		
10061-02-6	trans-1,3-Dichloropropylene	1.0	U	
79-00-5	1,1,2-Trichloroethane	1.0	U	
591-78-6	2-Hexanone	5.0	U	
127-18-4	Tetrachloroethylene	2.3		
124-48-1	Dibromochloromethane	1.0	U	
108-90-7	Chlorobenzene	1.0	U	
100-41-4	Ethylbenzene	0.61	J	
1330-20-7	Xylenes (total)	1.8	J	
100-42-5	Styrene	1.0	U	
75-25-2	Bromoform	1.0	U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2122

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871018

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J342

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U	u
75-01-4	-----Vinyl chloride	1.0	U	
74-83-9	-----Bromomethane	1.0	U	
75-00-3	-----Chloroethane	1.0	U	
75-35-4	-----1,1-Dichloroethylene	1.0	U	
67-64-1	-----Acetone	5.8		u F04, F07
75-15-0	-----Carbon disulfide	5.0	U	u
75-09-2	-----Methylene chloride	5	1.6 JB	u F01, F06
75-34-3	-----1,1-Dichloroethane	1.0	U	u
78-93-3	-----2-Butanone	5.0	U	
540-59-0	-----1,2-Dichloroethylene (total)	2.0	U	
67-66-3	-----Chloroform	1.0	U	
71-55-6	-----1,1,1-Trichloroethane	1.0	U	
56-23-5	-----Carbon tetrachloride	1.0	U	
107-06-2	-----1,2-Dichloroethane	1.0	U	
71-43-2	-----Benzene	1.0	U	
79-01-6	-----Trichloroethylene	1.0	U	
78-87-5	-----1,2-Dichloropropane	1.0	U	
75-27-4	-----Bromodichloromethane	1.0	U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	
108-10-1	-----4-Methyl-2-pentanone	5.0	U	
108-88-3	-----Toluene	2.1		u = F04, F08
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	
79-00-5	-----1,1,2-Trichloroethane	1.0	U	
591-78-6	-----2-Hexanone	5.0	U	
127-18-4	-----Tetrachloroethylene	1.0	U	
124-48-1	-----Dibromochloromethane	1.0	U	
108-90-7	-----Chlorobenzene	1.0	U	
100-41-4	-----Ethylbenzene	0.41	J	u
1330-20-7	-----Xylenes (total)	2.1	J	
100-42-5	-----Styrene	1.0	U	
75-25-2	-----Bromoform	1.0	U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

DATA VALIDATION OLM03.0
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2132

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871019

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J349

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 10.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	10.0	U	u ↓ Fol, Fob
75-01-4	-----Vinyl chloride	10.0	U	
74-83-9	-----Bromomethane	10.0	U	
75-00-3	-----Chloroethane	10.0	U	
75-35-4	-----1,1-Dichloroethylene	10.0	U	
67-64-1	-----Acetone	50.0	U	
75-15-0	-----Carbon disulfide	50.0	U	
75-09-2	-----Methylene chloride	50.0	U	
75-34-3	-----1,1-Dichloroethane	10.0	U	
78-93-3	-----2-Butanone	50.0	U	
540-59-0	-----1,2-Dichloroethylene (total)	636		u ↓ Fol, Fob
67-66-3	-----Chloroform	10.0	U	
71-55-6	-----1,1,1-Trichloroethane	10.0	U	
56-23-5	-----Carbon tetrachloride	10.0	U	
107-06-2	-----1,2-Dichloroethane	10.0	U	
71-43-2	-----Benzene	10.0	U	
79-01-6	-----Trichloroethylene	122		
78-87-5	-----1,2-Dichloropropane	10.0	U	
75-27-4	-----Bromodichloromethane	10.0	U	
10061-01-5	-----cis-1,3-Dichloropropylene	10.0	U	
108-10-1	-----4-Methyl-2-pentanone	50.0	U	u ↓ Fol, Fob
108-88-3	-----Toluene	10.0	U	
10061-02-6	-----trans-1,3-Dichloropropylene	10.0	U	
79-00-5	-----1,1,2-Trichloroethane	10.0	U	
591-78-6	-----2-Hexanone	50.0	U	
127-18-4	-----Tetrachloroethylene	10.0	U	
124-48-1	-----Dibromochloromethane	10.0	U	
108-90-7	-----Chlorobenzene	10.0	U	
100-41-4	-----Ethylbenzene	10.0	U	
1330-20-7	-----Xylenes (total)	30.0	U	
100-42-5	-----Styrene	10.0	U	
75-25-2	-----Bromoform	10.0	U	
79-34-5	-----1,1,2,2-Tetrachloroethane	10.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2212

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871020

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J343

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/15/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

74-87-3	-----Chloromethane	1.0	U	4
75-01-4	-----Vinyl chloride	1.0	U	4
74-83-9	-----Bromomethane	1.0	U	4
75-00-3	-----Chloroethane	1.0	U	4
75-35-4	-----1,1-Dichloroethylene	3.4		4
67-64-1	-----Acetone	5 4.8	J	4
75-15-0	-----Carbon disulfide	5.0	U	4
75-09-2	-----Methylene chloride	5 1.9	JB	4
75-34-3	-----1,1-Dichloroethane	1.0	U	4
78-93-3	-----2-Butanone	5.0	U	4
540-59-0	-----1,2-Dichloroethylene (total)	148		4
67-66-3	-----Chloroform	1.0	U	4
71-55-6	-----1,1,1-Trichloroethane	1.0	U	4
56-23-5	-----Carbon tetrachloride	1.0	U	4
107-06-2	-----1,2-Dichloroethane	1.0	U	4
71-43-2	-----Benzene	1.0	U	4
79-01-6	-----Trichloroethylene	1040 2.0	D	4
78-87-5	-----1,2-Dichloropropane	1.0	U	4
75-27-4	-----Bromodichloromethane	1.0	U	4
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U	4
108-10-1	-----4-Methyl-2-pentanone	5.0	U	4
108-88-3	-----Toluene	1.0 0.24	J	4
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U	4
79-00-5	-----1,1,2-Trichloroethane	1.0	U	4
591-78-6	-----2-Hexanone	5.0	U	4
127-18-4	-----Tetrachloroethylene	1.0	U	4
124-48-1	-----Dibromochloromethane	1.0	U	4
108-90-7	-----Chlorobenzene	1.0	U	4
100-41-4	-----Ethylbenzene	1.0	U	4
1330-20-7	-----Xylenes (total)	3.0	U	4
100-42-5	-----Styrene	1.0	U	4
75-25-2	-----Bromoform	1.0	U	4
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U	4

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

EPA SAMPLE NO.

XX2222

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L		Q
74-87-3	Chloromethane	1.0	U	
75-01-4	Vinyl chloride	1.0	U	
74-83-9	Bromomethane	1.0	U	
75-00-3	Chloroethane	1.0	U	
75-35-4	1,1-Dichloroethylene	1.0	U	
67-64-1	Acetone	54.8		
75-15-0	Carbon disulfide	5.0	U	
75-09-2	Methylene chloride	5.0	U	
75-34-3	1,1-Dichloroethane	1.0	U	
78-93-3	2-Butanone	11.6		
540-59-0	1,2-Dichloroethylene (total)	15.8		
67-66-3	Chloroform	1.0	U	
71-55-6	1,1,1-Trichloroethane	1.0	U	
56-23-5	Carbon tetrachloride	1.0	U	
107-06-2	1,2-Dichloroethane	1.0	U	
71-43-2	Benzene	0.65	J	
79-01-6	Trichloroethylene	26.7		
78-87-5	1,2-Dichloropropane	1.0	U	
75-27-4	Bromodichloromethane	1.0	U	
10061-01-5	cis-1,3-Dichloropropylene	1.0	U	
108-10-1	4-Methyl-2-pentanone	5.0	U	
108-88-3	Toluene	1.5		
10061-02-6	trans-1,3-Dichloropropylene	1.0	U	
79-00-5	1,1,2-Trichloroethane	1.0	U	
591-78-6	2-Hexanone	5.0	U	
127-18-4	Tetrachloroethylene	1.0	U	
124-48-1	Dibromochloromethane	1.0	J	
108-90-7	Chlorobenzene	1.0	U	
100-41-4	Ethylbenzene	1.0	U	
1330-20-7	Xylenes (total)	3.0	U	
100-42-5	Styrene	1.0	U	
75-25-2	Bromoform	1.0	U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U	

OLM03.0

33

EPA SAMPLE NO.

XX2232

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Lab Sample ID: 51875002

Lab File ID: 8J432

Date Received: 11/10/01

Date Analyzed: 11/15/01

Dilution Factor: 1.0

Soil Aliquot Volume: (uL)

USE

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

74-87-3-----	Chloromethane	1.0	U
75-01-4-----	Vinyl chloride	1.0	U
74-83-9-----	Bromomethane	1.0	U
75-00-3-----	Chloroethane	1.0	U
75-35-4-----	1,1-Dichloroethylene	2.4	
67-64-1-----	Acetone	4.0	J
75-15-0-----	Carbon disulfide	5.0	U
75-09-2-----	Methylene chloride	5.0	U
75-34-3-----	1,1-Dichloroethane	0.25	J
78-93-3-----	2-Butanone	5.0	U
540-59-0-----	1,2-Dichloroethylene (total)	85.7	
67-66-3-----	Chloroform	1.0	U
71-55-6-----	1,1,1-Trichloroethane	1.0	U
56-23-5-----	Carbon tetrachloride	1.0	U
107-06-2-----	1,2-Dichloroethane	1.0	U
71-43-2-----	Benzene	1.0	U
79-01-6-----	Trichloroethylene	5.0	U
78-87-5-----	1,2-Dichloropropane	1.0	U
75-27-4-----	Bromodichloromethane	1.0	U
10061-01-5-----	cis-1,3-Dichloropropylene	1.0	U
108-10-1-----	4-Methyl-2-pentanone	5.0	U
108-88-3-----	Toluene	1.0	U
10061-02-6-----	trans-1,3-Dichloropropylene	1.0	U
79-00-5-----	1,1,2-Trichloroethane	1.0	U
591-78-6-----	2-Hexanone	5.0	U
127-18-4-----	Tetrachloroethylene	1.0	U
124-48-1-----	Dibromochloromethane	1.0	U
108-90-7-----	Chlorobenzene	1.0	U
100-41-4-----	Ethylbenzene	1.0	U
1330-20-7-----	Xylenes (total)	3.0	U
100-42-5-----	Styrene	1.0	U
75-25-2-----	Bromoform	1.0	U
79-34-5-----	1,1,2,2-Tetrachloroethane	1.0	U

[illegible]

OLMC3.C

DATA VALIDATION
COPY

EPA SAMPLE NO.

XX2312

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

CAS NO.

COMPOUND

Q

74-87-3-----	Chloromethane	1.0	U
75-01-4-----	Vinyl chloride	1.0	U
74-83-9-----	Bromomethane	1.0	U
75-00-3-----	Chloroethane	1.0	U
75-35-4-----	1,1-Dichloroethylene	1.0	U
67-64-1-----	Acetone	8.2	
75-15-0-----	Carbon disulfide	5.0	U
75-09-2-----	Methylene chloride	5.0	U
75-34-3-----	1,1-Dichloroethane	1.0	U
78-93-3-----	2-Butanone	2.0	J
540-59-0-----	1,2-Dichloroethylene (total)	0.78	J
67-66-3-----	Chloroform	1.0	U
71-55-6-----	1,1,1-Trichloroethane	1.0	U
56-23-5-----	Carbon tetrachloride	1.0	U
107-06-2-----	1,2-Dichloroethane	1.0	U
71-43-2-----	Benzene	1.0	U
79-01-6-----	Trichloroethylene	0.68	J
78-87-5-----	1,2-Dichloropropane	1.0	U
75-27-4-----	Bromodichloromethane	1.0	U
10061-01-5-----	cis-1,3-Dichloropropylene	1.0	U
108-10-1-----	4-Methyl-2-pentanone	5.0	U
108-88-3-----	Toluene	0.18	J
10061-02-6-----	trans-1,3-Dichloropropylene	1.0	U
79-00-5-----	1,1,2-Trichloroethane	1.0	U
591-78-6-----	2-Hexanone	5.0	U
127-18-4-----	Tetrachloroethylene	1.0	U
124-48-1-----	Dibromochloromethane	1.0	U
108-90-7-----	Chlorobenzene	1.0	U
100-41-4-----	Ethylbenzene	1.0	U
1330-20-7-----	Xylenes (total)	3.0	U
100-42-5-----	Styrene	1.0	U
75-25-2-----	Bromoform	1.0	U
79-34-5-----	1,1,2,2-Tetrachloroethane	1.0	U

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

EPA SAMPLE NO.

XX2322

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2332

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Matrix: (soil/water) WATER Lab Sample ID: 51875011

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 8J441

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/16/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	1.0	U
75-01-4	Vinyl chloride	1.0	U
74-83-9	Bromomethane	1.0	U
75-00-3	Chloroethane	1.0	U
75-35-4	1,1-Dichloroethylene	1.0	U
67-64-1	Acetone	17.1	U
75-15-0	Carbon disulfide	5.0	U
75-09-2	Methylene chloride	5.0	U
75-34-3	1,1-Dichloroethane	1.0	U
78-93-3	2-Butanone	5.0	U
540-59-0	1,2-Dichloroethylene (total)	2.0	U
67-66-3	Chloroform	1.0	U
71-55-6	1,1,1-Trichloroethane	1.0	U
56-23-5	Carbon tetrachloride	1.0	U
107-06-2	1,2-Dichloroethane	1.0	U
71-43-2	Benzene	1.0	U
79-01-6	Trichloroethylene	1.0	U
78-87-5	1,2-Dichloropropane	1.0	U
75-27-4	Bromodichloromethane	1.0	U
10061-01-5	cis-1,3-Dichloropropylene	1.0	U
108-10-1	4-Methyl-2-pentanone	5.0	U
108-88-3	Toluene	1.0	U
10061-02-6	trans-1,3-Dichloropropylene	1.0	U
79-00-5	1,1,2-Trichloroethane	1.0	U
591-78-6	2-Hexanone	5.0	U
127-18-4	Tetrachloroethylene	1.0	U
124-48-1	Dibromochloromethane	1.0	U
108-90-7	Chlorobenzene	1.0	U
100-41-4	Ethylbenzene	1.0	U
1330-20-7	Xylenes (total)	3.0	U
100-42-5	Styrene	1.0	U
75-25-2	Bromoform	1.0	U
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A

XX2412

Soil Aliquot Volume: (uL)

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

5
4
↓
5
4
4 F01, F06

OLM03.0

45

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2422

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Matrix: (soil/water) WATER Lab Sample ID: 51875004

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 8J434

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/16/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	1.0 U	uL
75-01-4	Vinyl chloride	1.0 U	
74-83-9	Bromomethane	1.0 U	
75-00-3	Chloroethane	1.0 U	
75-35-4	1,1-Dichloroethylene	1.0 U	
67-64-1	Acetone	4.1 J	
75-15-0	Carbon disulfide	5.0 U	
75-09-2	Methylene chloride	5.0 U	
75-34-3	1,1-Dichloroethane	1.0 U	
78-93-3	2-Butanone	5.0 U	
540-59-0	1,2-Dichloroethylene (total)	2.0 U	
67-66-3	Chloroform	1.0 U	
71-55-6	1,1,1-Trichloroethane	1.0 U	
56-23-5	Carbon tetrachloride	1.0 U	
107-06-2	1,2-Dichloroethane	1.0 U	
71-43-2	Benzene	1.0 U	
79-01-6	Trichloroethylene	1.0 U	
78-87-5	1,2-Dichloropropane	1.0 U	
75-27-4	Bromodichloromethane	1.0 U	
10061-01-5	cis-1,3-Dichloropropylene	1.0 U	
108-10-1	4-Methyl-2-pentanone	5.0 U	
108-88-3	Toluene	1.0 U	
10061-02-6	trans-1,3-Dichloropropylene	1.0 U	
79-00-5	1,1,2-Trichloroethane	1.0 U	
591-78-6	2-Hexanone	5.0 U	
127-18-4	Tetrachloroethylene	1.0 U	
124-48-1	Dibromochloromethane	1.0 U	
108-90-7	Chlorobenzene	1.0 U	
100-41-4	Ethylbenzene	1.0 U	
1330-20-7	Xylenes (total)	3.0 U	
100-42-5	Styrene	1.0 U	
75-25-2	Bromoform	1.0 U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0 U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2432

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Matrix: (soil/water) WATER Lab Sample ID: 51875005

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 8J435

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/16/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	-----Chloromethane	1.0 U	u ↓ u
75-01-4	-----Vinyl chloride	1.0 U	
74-83-9	-----Bromomethane	1.0 U	
75-00-3	-----Chloroethane	1.0 U	
75-35-4	-----1,1-Dichloroethylene	1.0 U	
67-64-1	-----Acetone	3.9 J	
75-15-0	-----Carbon disulfide	5.0 U	
75-09-2	-----Methylene chloride	5.0 U	
75-34-3	-----1,1-Dichloroethane	1.0 U	
78-93-3	-----2-Butanone	5.0 U	
540-59-0	-----1,2-Dichloroethylene (total)	2.0 U	
67-66-3	-----Chloroform	1.0 U	
71-55-6	-----1,1,1-Trichloroethane	1.0 U	
56-23-5	-----Carbon tetrachloride	1.0 U	
107-06-2	-----1,2-Dichloroethane	1.0 U	
71-43-2	-----Benzene	1.0 U	
79-01-6	-----Trichloroethylene	1.0 U	
78-87-5	-----1,2-Dichloropropane	1.0 U	
75-27-4	-----Bromodichloromethane	1.0 U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0 U	
108-10-1	-----4-Methyl-2-pentanone	5.0 U	↓
108-88-3	-----Toluene	1.0 U	
10061-02-6	-----trans-1,3-Dichloropropylene	1.0 U	
79-00-5	-----1,1,2-Trichloroethane	1.0 U	
591-78-6	-----2-Hexanone	5.0 U	
127-18-4	-----Tetrachloroethylene	1.0 U	
124-48-1	-----Dibromochloromethane	1.0 U	
108-90-7	-----Chlorobenzene	1.0 U	
100-41-4	-----Ethylbenzene	1.0 U	
1330-20-7	-----Xylenes (total)	3.0 U	
100-42-5	-----Styrene	1.0 U	↓
75-25-2	-----Bromoform	1.0 U	
79-34 5	-----1,1,2,2-Tetrachloroethane	1.0 U	

FORM I VOA

DATA VALIDATION
COPY

OLM03.0

EPA SAMPLE NO.

XX2512

Soil Aliquot Volume: _____ (uL)

USE

74-87-3-----	Chloromethane	1.0	U
75-01-4-----	Vinyl chloride	1.0	U
74-83-9-----	Bromomethane	1.0	U
75-00-3-----	Chloroethane	1.0	U
75-35-4-----	1,1-Dichloroethylene	0.66	J
67-64-1-----	Acetone	4.4	J
75-15-0-----	Carbon disulfide	5.0	U
75-09-2-----	Methylene chloride	5.0	U
75-34-3-----	1,1-Dichloroethane	1.0	U
78-93-3-----	2-Butanone	5.0	U
540-59-0-----	1,2-Dichloroethylene (total)	61.4	
67-66-3-----	Chloroform	1.0	U
71-55-6-----	1,1,1-Trichloroethane	1.0	U
56-23-5-----	Carbon tetrachloride	1.0	U
107-06-2-----	1,2-Dichloroethane	1.0	U
71-43-2-----	Benzene	1.0	U
79-01-6-----	Trichloroethylene	272	219 E D
78-87-5-----	1,2-Dichloropropane	1.0	U
75-27-4-----	Bromodichloromethane	1.0	U
10061-01-5-----	cis-1,3-Dichloropropylene	1.0	U
108-10-1-----	4-Methyl-2-pentanone	5.0	U
108-88-3-----	Toluene	1.0	U
10061-02-6-----	trans-1,3-Dichloropropylene	1.0	U
79-00-5-----	1,1,2-Trichloroethane	1.0	U
591-78-6-----	2-Hexanone	5.0	U
127-18-4-----	Tetrachloroethylene	1.0	U
124-48-1-----	Dibromochloromethane	1.0	U
108-90-7-----	Chlorobenzene	1.0	U
100-41-4-----	Ethylbenzene	1.0	U
1330-20-7-----	Xylenes (total)	3.0	U
100-42-5-----	Styrene	1.0	U
75-25-2-----	Bromoform	1.0	U
79-34-5-----	1,1,2,2-Tetrachloroethane	1.0	U

OLM03.0

51

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2522

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Matrix: (soil/water) WATER Lab Sample ID: 51875007

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 8J437

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. Date Analyzed: 11/16/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

74-87-3	Chloromethane	0.44	J
75-01-4	Vinyl chloride	1.0	U
74-83-9	Bromomethane	1.0	U
75-00-3	Chloroethane	1.0	U
75-35-4	1,1-Dichloroethylene	0.73	J
67-64-1	Acetone	3.6	J
75-15-0	Carbon disulfide	5.0	U
75-09-2	Methylene chloride	5.0	U
75-34-3	1,1-Dichloroethane	1.0	U
78-93-3	2-Butanone	5.0	U
540-59-0	1,2-Dichloroethylene (total)	68.4	
67-66-3	Chloroform	1.0	U
71-55-6	1,1,1-Trichloroethane	1.0	U
56-23-5	Carbon tetrachloride	1.0	U
107-06-2	1,2-Dichloroethane	1.0	U
71-43-2	Benzene	1.0	U
79-01-6	Trichloroethylene	91.8	D
78-87-5	1,2-Dichloropropane	1.0	U
75-27-4	Bromodichloromethane	1.0	U
10061-01-5	cis-1,3-Dichloropropylene	1.0	U
108-10-1	4-Methyl-2-pentanone	5.0	U
108-88-3	Toluene	1.0	U
10061-02-6	trans-1,3-Dichloropropylene	1.0	U
79-00-5	1,1,2-Trichloroethane	1.0	U
591-78-6	2-Hexanone	5.0	U
127-18-4	Tetrachloroethylene	1.0	U
124-48-1	Dibromochloromethane	1.0	U
108-90-7	Chlorobenzene	1.0	U
100-41-4	Ethylbenzene	1.0	U
1330-20-7	Xylenes (total)	3.0	U
100-42-5	Styrene	1.0	U
75-25-2	Bromoform	1.0	U
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U

USE
Q

Handwritten notes and arrows on the right margin of the table.

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO. .

XX2532

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51875

Matrix: (soil/water) WATER Lab Sample ID: 51875008

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 8J510

Level: (low/med) LOW Date Received: 11/10/01

% Moisture: not dec. _____ Date Analyzed: 11/16/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	-----Chloromethane	1.0 U	u
75-01-4	-----Vinyl chloride	1.0 U	u
74-83-9	-----Bromomethane	1.0 U	u
75-00-3	-----Chloroethane	1.0 U	u
75-35-4	-----1,1-Dichloroethylene	1.0 U	u
67-64-1	-----Acetone	2.3 J	u
75-15-0	-----Carbon disulfide	5.0 U	u
75-09-2	-----Methylene chloride	5 1.8 JB	u Fol, F06
75-34-3	-----1,1-Dichloroethane	1.0 U	u
78-93-3	-----2-Butanone	5.0 U	u
540-59-0	-----1,2-Dichloroethylene (total)	2.0 U	
67-66-3	-----Chloroform	1.0 U	
71-55-6	-----1,1,1-Trichloroethane	1.0 U	
56-23-5	-----Carbon tetrachloride	1.0 U	
107-06-2	-----1,2-Dichloroethane	1.0 U	
71-43-2	-----Benzene	1.0 U	
79-01-6	-----Trichloroethylene	1.0 U	
78-87-5	-----1,2-Dichloropropane	1.0 U	
75-27-4	-----Bromodichloromethane	1.0 U	
10061-01-5	-----cis-1,3-Dichloropropylene	1.0 U	
108-10-1	-----4-Methyl-2-pentanone	5.0 U	
108-88-3	-----Toluene	1.0 U	
10061-02-6	-----trans-1,3-Dichloropropylene	1.0 U	
79-00-5	-----1,1,2-Trichloroethane	1.0 U	
591-78-6	-----2-Hexanone	5.0 U	
127-18-4	-----Tetrachloroethylene	1.0 U	
124-48-1	-----Dibromochloromethane	1.0 U	
108-90-7	-----Chlorobenzene	1.0 U	
100-41-4	-----Ethylbenzene	1.0 U	
1330-20-7	-----Xylenes (total)	3.0 U	
100-42-5	-----Styrene	1.0 U	
75-25-2	-----Bromoform	1.0 U	
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0 U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2612

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 53618

Matrix: (soil/water) WATER Lab Sample ID: 53618003

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 80408

Level: (low/med) LOW Date Received: 12/17/01

% Moisture: not dec. _____ Date Analyzed: 12/20/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L

CAS NO. COMPOUND Q

74-87-3	Chloromethane	1.0	U	
75-01-4	Vinyl chloride	1.0	U	
74-83-9	Bromomethane	1.0	U	
75-00-3	Chloroethane	1.0	U	
75-35-4	1,1-Dichloroethylene	1.0	U	
67-64-1	Acetone	102	B	
75-15-0	Carbon disulfide	5.0	U	
75-09-2	Methylene chloride	5.0	U	
75-34-3	1,1-Dichloroethane	1.0	U	
78-93-3	2-Butanone	5.0	U	
540-59-0	1,2-Dichloroethylene (total)	1.8	J	
67-66-3	Chloroform	1.0	U	
71-55-6	1,1,1-Trichloroethane	1.0	U	
56-23-5	Carbon tetrachloride	1.0	U	
107-06-2	1,2-Dichloroethane	1.0	U	
71-43-2	Benzene	1.0	U	
79-01-6	Trichloroethylene	9.5		
78-87-5	1,2-Dichloropropane	1.0	U	
75-27-4	Bromodichloromethane	1.0	U	
10061-01-5	cis-1,3-Dichloropropylene	1.0	U	
108-10-1	4-Methyl-2-pentanone	5.0	U	
108-88-3	Toluene	1.0	U	
10061-02-6	trans-1,3-Dichloropropylene	1.0	U	
79-00-5	1,1,2-Trichloroethane	1.0	U	
591-78-6	2-Hexanone	5.0	U	
127-18-4	Tetrachloroethylene	0.55	J	
124-48-1	Dibromochloromethane	1.0	U	
108-90-7	Chlorobenzene	1.0	U	
100-41-4	Ethylbenzene	1.0	U	
1330-20-7	Xylenes (total)	3.0	U	
100-42-5	Styrene	1.0	U	
75-25-2	Bromoform	1.0	U	
79-34-5	1,1,2,2-Tetrachloroethane	1.0	U	

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2622

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 53618

Matrix: (soil/water) WATER Lab Sample ID: 53618004

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 80313

Level: (low/med) LOW Date Received: 12/17/01

% Moisture: not dec. _____ Date Analyzed: 12/19/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: _____ (uL) Soil Aliquot Volume: _____ (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	-----Chloromethane	1.0	U
75-01-4	-----Vinyl chloride	1.0	U
74-83-9	-----Bromomethane	1.0	U
75-00-3	-----Chloroethane	1.0	U
75-35-4	-----1,1-Dichloroethylene	1.0	U
67-64-1	-----Acetone	26.2	B
75-15-0	-----Carbon disulfide	5.0	U
75-09-2	-----Methylene chloride	5.0	U
75-34-3	-----1,1-Dichloroethane	1.0	U
78-93-3	-----2-Butanone	5.0	U
540-59-0	-----1,2-Dichloroethylene (total)	2.3	U
67-66-3	-----Chloroform	1.0	U
71-55-6	-----1,1,1-Trichloroethane	1.0	U
56-23-5	-----Carbon tetrachloride	1.0	U
107-06-2	-----1,2-Dichloroethane	1.0	U
71-43-2	-----Benzene	1.0	U
79-01-6	-----Trichloroethylene	17.8	U
78-87-5	-----1,2-Dichloropropane	1.0	U
75-27-4	-----Bromodichloromethane	1.0	U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U
108-10-1	-----4-Methyl-2-pentanone	5.0	U
108-88-3	-----Toluene	1.0	U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U
79-00-5	-----1,1,2-Trichloroethane	1.0	U
591-78-6	-----2-Hexanone	5.0	U
127-18-4	-----Tetrachloroethylene	1.0	U
124-48-1	-----Dibromochloromethane	1.0	U
108-90-7	-----Chlorobenzene	1.0	U
100-41-4	-----Ethylbenzene	1.0	U
1330-20-7	-----Xylenes (total)	3.0	U
100-42-5	-----Styrene	1.0	U
75-25-2	-----Bromoform	1.0	U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

EPA SAMPLE NO.

XX2632

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 53618

Matrix: (soil/water) WATER Lab Sample ID: 53618005

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 80314

Level: (low/med) LOW Date Received: 12/17/01

% Moisture: not dec. Date Analyzed: 12/19/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO. COMPOUND CONCENTRATION UNITS:
(ug/L or ug/Kg) UG/L Q

74-87-3	-----Chloromethane	1.0	U
75-01-4	-----Vinyl chloride	1.0	U
74-83-9	-----Bromomethane	1.0	U
75-00-3	-----Chloroethane	1.0	U
75-35-4	-----1,1-Dichloroethylene	1.0	U
67-64-1	-----Acetone	5.0	U
75-15-0	-----Carbon disulfide	5.0	U
75-09-2	-----Methylene chloride	5.0	U
75-34-3	-----1,1-Dichloroethane	1.0	U
78-93-3	-----2-Butanone	5.0	U
540-59-0	-----1,2-Dichloroethylene (total)	1.6	U
67-66-3	-----Chloroform	1.0	U
71-55-6	-----1,1,1-Trichloroethane	1.0	U
56-23-5	-----Carbon tetrachloride	1.0	U
107-06-2	-----1,2-Dichloroethane	1.0	U
71-43-2	-----Benzene	1.0	U
79-01-6	-----Trichloroethylene	10.3	U
78-87-5	-----1,2-Dichloropropane	1.0	U
75-27-4	-----Bromodichloromethane	1.0	U
10061-01-5	-----cis-1,3-Dichloropropylene	1.0	U
108-10-1	-----4-Methyl-2-pentanone	5.0	U
108-88-3	-----Toluene	1.0	U
10061-02-6	-----trans-1,3-Dichloropropylene	1.0	U
79-00-5	-----1,1,2-Trichloroethane	1.0	U
591-78-6	-----2-Hexanone	5.0	U
127-18-4	-----Tetrachloroethylene	1.0	U
124-48-1	-----Dibromochloromethane	1.0	U
108-90-7	-----Chlorobenzene	1.0	U
100-41-4	-----Ethylbenzene	1.0	U
1330-20-7	-----Xylenes (total)	3.0	U
100-42-5	-----Styrene	1.0	U
75-25-2	-----Bromoform	1.0	U
79-34-5	-----1,1,2,2-Tetrachloroethane	1.0	U

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

1A
VOLATILE ORGANICS ANALYSIS DATA SHEET

TRIP BLANK

EPA SAMPLE NO.

HTM0001

Lab Name: GENERAL ENGINEERING LABOR Contract: N/A

Lab Code: N/A Case No.: N/A SAS No.: N/A SDG No.: 51871

Matrix: (soil/water) WATER Lab Sample ID: 51871001

Sample wt/vol: 5.000 (g/ml) ML Lab File ID: 2J330

Level: (low/med) LOW Date Received: 11/12/01

% Moisture: not dec. Date Analyzed: 11/14/01

GC Column: DB-624 ID: 0.25 (mm) Dilution Factor: 1.0

Soil Extract Volume: (uL) Soil Aliquot Volume: (uL)

CAS NO.	COMPOUND	CONCENTRATION UNITS: (ug/L or ug/Kg) UG/L	Q
74-87-3	Chloromethane	1.0 U	u
75-01-4	Vinyl chloride	1.0 U	u
74-83-9	Bromomethane	1.0 U	u
75-00-3	Chloroethane	1.0 U	u
75-35-4	1,1-Dichloroethylene	1.0 U	u
67-64-1	Acetone	16.2	u
75-15-0	Carbon disulfide	5.0 U	u
75-09-2	Methylene chloride	5 1.7 JB	u F01, F06
75-34-3	1,1-Dichloroethane	1.0 U	u
78-93-3	2-Butanone	3.5 J	u
540-59-0	1,2-Dichloroethylene (total)	2.0 U	u
67-66-3	Chloroform	1.0 U	u
71-55-6	1,1,1-Trichloroethane	1.0 U	u
56-23-5	Carbon tetrachloride	1.0 U	u
107-06-2	1,2-Dichloroethane	1.0 U	u
71-43-2	Benzene	1.0 U	u
79-01-6	Trichloroethylene	1.0 U	u
78-87-5	1,2-Dichloropropane	1.0 U	u
75-27-4	Bromodichloromethane	1.0 U	u
10061-01-5	cis-1,3-Dichloropropylene	1.0 U	u
108-10-1	4-Methyl-2-pentanone	5.0 U	u
108-88-3	Toluene	0.17 J	u
10061-02-6	trans-1,3-Dichloropropylene	1.0 U	u
79-00-5	1,1,2-Trichloroethane	1.0 U	u
591-78-6	2-Hexanone	5.0 U	u
127-18-4	Tetrachloroethylene	1.0 U	u
124-48-1	Dibromochloromethane	1.0 U	u
108-90-7	Chlorobenzene	1.0 U	u
100-41-4	Ethylbenzene	1.0 U	u
1330-20-7	Xylenes (total)	3.0 U	u
100-42-5	Styrene	1.0 U	u
75-25-2	Bromoform	1.0 U	u
79-34-5	1,1,2,2-Tetrachloroethane	1.0 U	u

FORM I VOA

OLM03.0

DATA VALIDATION
COPY

PROJECT NAME: MCA Barracks, HAA-15				REQUESTED PARAMETERS												LABORATORY NAME: General Engineering Laboratory			
PROJECT NUMBER: 01-1624-04-2725-240																LABORATORY ADDRESS: 2040 Savage Road Charleston, SC 29417			
PROJECT MANAGER: Patty Stoll																PHONE NO: (843) 556-8171			
Sampler (Signature) <i>Cynthia L. Abbott</i>		(Printed Name) Cynthia L. Abbott																	
Sample ID	Date Collected	Time Collected	Matrix	No. of Bottles/ Vials													OVA SCREENING	OBSERVATIONS, COMMENTS SPECIAL INSTRUCTIONS	
001 HTM0001	11/08/01	0800	water	2													Na	Na	
002 XX1612		1538		2															
003 XX1622		1610		2															
004 XX1632		1643		2															
005 XX1712		1815		2															
006 XX1722	11/09/01	0710		2															
007 XX1812		0750		2															
008 XX1822		0837		2															
009 XX1832		0855		2															
010 XX1834		0855		2														Field dup.	
011 XX2012		1030		2														Na	
012 XX2022		1048		2															
013 XX2032		1118		2															
RELINQUISHED BY: <i>Cynthia L. Abbott</i>		Date/Time 11/10/01		RECEIVED BY: <i>Paula L. Hubbard</i>		Date/Time 11/10/01		TOTAL NUMBER OF CONTAINERS: 69				Cooler Temperature: 7°C							
COMPANY NAME: SAIC		1300		COMPANY NAME: GEL		1315		Cooler ID: 487				FEDEX NUMBER:							
RECEIVED BY:		Date/Time		RELINQUISHED BY:		Date/Time		page 1 of 3											
COMPANY NAME:				COMPANY NAME:															
RELINQUISHED BY: <i>Paula L. Hubbard</i>		Date/Time 11/10/01		RECEIVED BY: <i>Mike Kinsler</i>		Date/Time 11-10-01													
COMPANY NAME: GEL		1600		COMPANY NAME: GEL		1600													



800 Oak Ridge Turnpike, Oak Ridge, TN 37831 (423) 481-4600

COC NO.: GmxA001

page 2 of 3



COC NO.: GMCA 001

[illegible]

CHAIN OF CUSTODY RECORD

53618%

COC NO.: HMCA11

PROJECT NAME: HAAT USTs 25&26 MCA BARRACKS				REQUESTED PARAMETERS												LABORATORY NAME: General Engineering Laboratory																					
PROJECT NUMBER: 01-1624-04-2725-246				No. of Bottles/Vials: <table border="1"> <tr> <td>BTEX</td> <td>PAH</td> <td>TPH-GRO</td> <td>PAH, TPH-DRO</td> <td>PAH, TPH-DRO, TOC</td> <td>Dissolved Iron</td> <td>VOC</td> <td>Oil & Grease</td> <td>Phenols</td> <td>PH</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>												BTEX	PAH	TPH-GRO	PAH, TPH-DRO	PAH, TPH-DRO, TOC	Dissolved Iron	VOC	Oil & Grease	Phenols	PH											LABORATORY ADDRESS: 2040 Savage Road Charleston, SC 29407	
BTEX	PAH	TPH-GRO	PAH, TPH-DRO													PAH, TPH-DRO, TOC	Dissolved Iron	VOC	Oil & Grease	Phenols	PH																
PROJECT MANAGER: Patty Stoll																PHONE NO: (843) 556-8171																					
Sampler (Signature) <i>Patty Stoll</i> (Printed Name) PATRICIA STOLL																OVA SCREENING		OBSERVATIONS, COMMENTS, SPECIAL INSTRUCTIONS																			
Sample ID	Date Collected	Time Collected	Matrix																																		
HDW010	12/16/01	1000	water																	7	Quick Turn																
HDW011	12/16/01	174530	water																	7	Quick Turn																
XX2612	12/16/01	1135	water																	2	7day																
XX2622	12/16/01	1136	water																	2	7day																
XX2632	12/16/01	1137	water																	2	7day																
HTB111	12/16/01	1100	water																	2																	
<i>Patty Stoll</i> 12/17/01																																					
RELINQUISHED BY: <i>Patty Stoll</i>		Date/Time: 12/17/01		RECEIVED BY: <i>Mustafa Ahmad</i>		Date/Time: 12/17/01		TOTAL NUMBER OF CONTAINERS: 22				Cooler Temperature: 4°C																									
COMPANY NAME: SAIC		1145		COMPANY NAME: GEL		1430		Cooler ID: 9-14-00				FEDEX NUMBER: N/A																									
RECEIVED BY: <i>Pat Hochstetler</i>		Date/Time: 12/17/01		RELINQUISHED BY:		Date/Time:																															
COMPANY NAME: <i>Pat Hochstetler</i>		1145		COMPANY NAME:																																	
RELINQUISHED BY: <i>Pat Hochstetler</i>		Date/Time: 12/17/01		RECEIVED BY:		Date/Time:																															
COMPANY NAME: <i>GEL</i>		1430		COMPANY NAME:																																	

12/20/01

**WELL DIAGRAMS FOR LOCATIONS XX-04 THROUGH XX-15
ARE PRESENTED IN DATA PACKAGE #1
FOR PRELIMINARY ASSESSMENT REPORT (APRIL 2000)**

WELL DIAGRAMS FOR LOCATIONS XX-16 THROUGH XX-26

MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-16


BEGIN: 12/4/01

END: 12/4/01

COORDINATES: N:
E:

REFERENCE POINT:

ELEVATION:



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-17


BEGIN: 12/4/01

END: 12/5/01

COORDINATES: N: 739573.51537
E: 975618.53153

REFERENCE POINT: TOC

ELEVATION: 21.28



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-18


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 739102.02754
E: 975231.61641

REFERENCE POINT: TOC

ELEVATION: 29.57



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-19


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 738640.80029
E: 975467.1856

REFERENCE POINT: TOC

ELEVATION: 35.80



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-20


BEGIN: 12/4/01

END: 12/4/01

COORDINATES: N: 738880.77632
E: 975842.20413

REFERENCE POINT: TOC

ELEVATION: 33.26



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-21


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 738379.40565
E: 975678.68812

REFERENCE POINT: TOC

ELEVATION: 37.31



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-22


BEGIN: 12/4/01

END: 12/5/01

COORDINATES: N: 738821.20368
E: 976581.78865

REFERENCE POINT: TOC

ELEVATION: 25.17



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-23


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 738492.94836
E: 976533.77957

REFERENCE POINT: TOC

ELEVATION: 34.59



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-24


BEGIN: 12/4/01

END: 12/4/01

COORDINATES: N: 737978.60144
E: 976526.52586

REFERENCE POINT: TOC

ELEVATION: 35.77



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-Z5


BEGIN: 12/4/01

END: 12/4/01

COORDINATES: N: 738171.47742
E: 976833.25449

REFERENCE POINT: TOC

ELEVATION: 33.51



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-26 1-5


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 739351.16600
E: 975861.58259

REFERENCE POINT: TOC

ELEVATION: 26.14



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-26 Z-M


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 739350.94779
E: 975861.69096

REFERENCE POINT: TOC

ELEVATION: 26.21



MONITORING WELL

PROJECT: HAAF MCA Barracks

WELL NUMBER: XX-Z6 3-D


BEGIN: 12/5/01

END: 12/5/01

COORDINATES: N: 739350.94779
E: 975861.39875

REFERENCE POINT: TOC

ELEVATION: 26.15



MEMBRANE INTERFACE PROBE

Columbia Technologies was subcontracted to conduct an investigation of subsurface contamination at the MCA Barracks site, Hunter Army Airfield. This investigation involved delineating the depth of contamination using membrane interface probe (MIP) and soil conductivity (SC) technologies. The purposes of this investigation were to characterize subsurface soils in the vadose and saturated zones to and delineate the nature and extent of groundwater contamination at the site.

The MIP/SC probe is 1.5 in. in diameter and approximately 12 in. in length. The probe is driven into the ground at the nominal rate of 1 ft/min using a Geoprobe® or similar direct-push rig.

The SC portion of the tool uses a dipole measurement arrangement. An alternating electrical current is passed from the center, isolated pin of the SC probe to the probe body. The voltage response of the soil to the imposed current is measured across the same two points. The probe is reasonably accurate for measurement of SCs in the range of 5 to 400 mS/m. In general, at a given location, lower conductivities indicate larger-sized particles such as sands, while higher conductivities are indicative of finer-sized particles such as silts and clays.

The MIP portion of the probe was developed and patented by Geoprobe Systems, Inc. The operating principle is based on heating the soil and/or water around a semipermeable polymer membrane to 121°C, allowing volatile organic compound (VOC) vapors to partition across the membrane. Bulk fluids do not travel across the membrane, allowing the MIP to be used in both unsaturated and saturated soils. Movement across the membrane is rapid due to the thinness of the membrane. Using nitrogen gas as a carrier gas, which sweeps across the back of the membrane, the VOCs are carried to the installed detectors. It takes about 35 sec for the nitrogen gas stream to travel through about 100 ft of inert tubing and reach the detectors.

Columbia Technologies uses three detectors—a photoionization detector (PID), a flame ionization detector (FID) and an electron capture detector (ECD)—mounted on a laboratory-grade gas chromatograph (GC) (Shimadzu Model 14A). The output signal from the detectors is captured by a MIP data logging system installed on a MIP field computer or a laptop computer. Data are displayed continuously in real time during each push of the probe. In addition, the data logs can be printed for display and analysis following the data logging run or exported to common spreadsheet software for further analysis.

The PID detector consists of a special ultraviolet (UV) lamp mounted on a thermostat-controlled, low-volume, flow-through cell. The temperature is adjustable from ambient to 250°C. The 10.6 eV UV lamp emits energy at a wavelength of 120 nm, which is sufficient to ionize most aromatics (e.g., benzene, toluene, xylenes) and many other molecules e.g., H₂S, hexane, ethanol) whose ionization potential is below 10.6 eV. The PID also emits a lower response for chlorinated compounds such as trichloroethene (TCE) and tetrachloroethene. Methanol and water, which have ionization potentials greater than 10.6 eV, do not respond to the PID. Detection limits for aromatics are in the low picogram range. Because the PID is nondestructive, it is often run first in series with other detectors for multiple analyses from a single injection. Use of the PID is mandated in several U.S. Environmental Protection Agency methods (e.g., 8021, TP-14) because of its sensitivity and selectivity.

The most commonly used GC detector is the FID, which responds linearly from its minimum detectable quantity of about 100 pg. The FID response is very stable from day to day and is not susceptible to contamination from dirty samples or column bleed. This detector responds to any molecule with a

carbon-hydrogen bond, but poorly to compounds such as H_2S , CCl_4 , or NH_3 . The carrier gas effluent from the GC column is mixed with hydrogen and burned. Hydrogen supports a flame and ionizes the analyte molecules. A collector electrode attracts the negative ions to the electrometer amplifier producing an analog signal, which is directed to the data system input.

The ECD consists of a sealed stainless steel cylinder containing radioactive nickel-63. The nickel-63 emits beta particles (electrons) that collide with the carrier gas molecules, ionizing them in the process. This process forms a stable cloud of free electrons in the ECD cell. When electro-negative compounds (especially chlorinated, fluorinated, or brominated molecules) such as carbon tetrachloride and TCE enter the cell, they immediately combine with some of the free electrons, temporarily reducing the number remaining in the electron cloud. The detector electronics, which maintain a constant current of about 1 nA through the electron cloud, are forced to pulse at a faster rate to compensate for the decreased number of free electrons. The pulse rate is converted to an analog output that is transmitted to the data system.

MIP/SC profiling was conducted at 12 locations (XX-14 through XX-25) in November 2001 to an average depth of 50 ft. Upon review of the initial data, it was determined that the instruments were not calibrated to detect contaminant concentrations at the levels that were found at the MCA Barracks site. Another round of MIP/SC profiling was conducted at three locations (XX-13, XX-14, and XX-26) in April 2002.

Drilling was completed using a Geoprobe® truck-mounted rig. The results from each location are shown on the following pages. Detector 1 provides the PID readings, detector 2 the FID readings, and detector 3 the ECD readings.

Hunter Army Airfield
MIP Log 14B


MIP Display Log (English)

C:\dirim95\LOGFILES\MIP-14B.dat


CHOOSE LOG (F1)

PRINT (F2)


EXIT (F5)




Hunter Army Airfield
MIP Log 16



Hunter Army Airfield
MIP Log 17



Hunter Army Airfield
MIP Log 18



Hunter Army Airfield
MIP Log 19






MIP Display Log (English)

C:\dirim95\LOGFILES\MIP-19.dat


CHOOSE LOG (F1)

PRINT (F2)

EXIT (F5)



Hunter Army Airfield
MIP Log 20



Hunter Army Airfield MIP 21


MIP Display Log (English)

C:\dirim95\LOGFILES\MIP-21.dat


CHOOSE LOG (F1)

PRINT (F2)

EXIT (F5)



Hunter Army Airfield
MIP Log 22



Hunter Army Airfield MIP Log 23


MIP Display Log (English)

C:\dirim95\LOGFILES\MIP-23.dat


CHOOSE LOG (F1)

PRINT (F2)


EXIT (F5)




Hunter Army Airfield
MIP Log 24




Hunter Army Airfield
MIP Log 25



Hunter Army Airfield
MIP Log XX-13A
April 11, 2002



Hunter Army Airfield
MIP Log XX-14A
April 11, 2002



Hunter Army Airfield
MIP Log XX-26A
April 11, 2002

